



Minnesota Pollution Control Agency

July 6, 1993

Mr. Ralph Larson
Ralph Larson Chevrolet
531 South Main Street
Hector, Minnesota 55342

Dear Mr. Larson:

RE: Petroleum Tank Release Site Closure
Site: Ralph Larson Chevrolet, Hector
Site ID#: LEAK00002426

The Minnesota Pollution Control Agency (MPCA) staff has determined that the cleanup performed in response to the petroleum tank release at the site referenced above has adequately addressed the petroleum contamination, and therefore the file regarding this release will be closed.

On April 16, 1990, a petroleum tank release was reported to the MPCA. Since then, the following corrective actions have been taken in response to the release:

1. One 500 gallon waste oil underground storage tank was removed from the site.
2. Approximately 65 cubic yards of petroleum contaminated soil were removed and land applied at Kasal Farm. Contaminated soil remains on site at low levels. Field results indicate 54 parts per million (ppm) total hydrocarbons as gasoline (THC/gas). A sample taken from the base of the excavation for lab analysis contained .54 ppm THC/gas, below MPCA action levels.


Based on the currently available information, we concur that these actions have adequately addressed the petroleum tank release. Therefore, MPCA staff does not intend to require any more investigation or clean-up work in response to this release. However, the MPCA reserves the right to reopen this file and require additional work if in the future more work is determined to be necessary, and this letter does not release any party from liability for this contamination.

Because you performed the requested work, the state may reimburse you for a major portion of your costs. The Petroleum Tank Release Cleanup Act establishes a fund which in certain circumstances provides partial reimbursement for petroleum tank release clean-up costs. This fund is administered by the Petroleum Tank Release Compensation Board (Petro Board). More specific eligibility rules are available from the Petro Board (612/297-1119 or 612/297-4203).

Mr. Ralph Larson
Page 2
July 6, 1993

Thank you for your cooperation with the MPCA in responding to this petroleum tank release to protect the public health and the environment of the state of Minnesota. If you have any questions regarding this correspondence, please call me at 612/297-8611.

Sincerely,



Mark Koplitz
Pollution Control Specialist
Tanks and Spills Section
Hazardous Waste Division

MK:vb

cc: Robln Hanson, Department of Commerce
Mary Saeger, Hector City Administrator
Doug Knutson, Renville County Courthouse

Mr. Ralph Larson
Ralph Larson Chevrolet
531 South Main Street
Hector, Minnesota 55342

Dear Mr. Larson:

RE: Corrective Action Approval
Site: Ralph Larson Chevrolet, Hector
Site ID#: LEAK00002426

The Minnesota Pollution Control Agency (MPCA) staff has reviewed the report received August 7, 1990, outlining the corrective actions taken in response to the petroleum tank release at the above-referenced site. We understand that the following steps have been completed:

1. One 500 gallon waste oil underground storage tank was removed from the site.
2. Approximately 65 cubic yards of petroleum contaminated soil was removed and land applied at Kasal Farm. Contaminated soil remains on site at low levels. Field results indicate 54 parts per million (ppm) total hydrocarbons as gasoline (THC-G). A sample taken from the base of the excavation for lab analysis contained .54 ppm THC-G, below MPCA action levels.

It appears, based on available information, that the work already performed, along with completion of the work discussed above, will adequately address the site. We therefore do not expect any additional cleanup enforcement action by the MPCA will be necessary. However, if subsequently obtained information indicates that the release has not been fully addressed the MPCA may require additional work or changes in the ongoing work.

In approving the completion of the corrective action, the MPCA does not assume any liability for the design or implementation of this remedy. You remain solely responsible for ensuring that this action results in a successful cleanup and that it does not result in any harm to public health or the environment.

Please provide the soil monitoring results for the land applied soils when available.

If you have any questions, please contact me at 612/643-3426.

Sincerely,

Mark Koplitz
Pollution Control Specialist
Tanks and Spills Section
Hazardous Waste Division

cc: Barbara A. Ryan, MECC (3901 University Ave. N.E., MPLS., MN 55421)

To Typing 10/12/90

RECEIVED

AUG 07 1990

**MPCA, HAZARDOUS
WASTE DIVISION**

**Response Action Report
UST Excavation Assessment/
Corrective Action Plan
Ralph Larson Chevrolet
Hector, Minnesota**

**MECC PROJECT NO.: 1070-0490
LEAK I.D. #00002426**



**MIDWEST ENVIRONMENTAL
CONTROL CORPORATION**

Mr. Ralph Larson
Owner
Ralph Larson Chevrolet
5315 Main Street
Hector, MN 55342

June 18, 1990

m e c c
3901 University Ave. N.E.
Minneapolis, MN 55421
(612) 781-1647

MECC Project #1070-0490

Re: Response Action Report
Underground Storage Tank Excavation Observation
Ralph Larson Chevrolet
Hector, Minnesota

Dear Mr. Larson:

We have completed our environmental engineering assessment of the underground storage tank removal and soil excavation observation at the above-mentioned site. This report contains a summary of our test results and our environmental evaluation for the existing conditions encountered.

If you have any questions or wish to discuss any particular aspect of the project, please contact us at (612) 781-1647. We look forward to being of continued service to you.

Sincerely,

MIDWEST ENVIRONMENTAL CONTROL CORPORATION

Barbara A. Ryan
Environmental Geologist

Philip N. Cavendor, Director
Environmental Engineering Services

BAR/lh

RESPONSE ACTION REPORT

UNDERGROUND STORAGE TANK REMOVAL ASSESSMENT

AND

EXCAVATION OBSERVATION/CORRECTIVE ACTION PLAN

Ralph Larson Chevrolet

Hector, Minnesota

MECC Project No. 1070-0490

MPCA Tanks and Spills Leak No. 00002426

Prepared For:

Ralph Larson Chevrolet

531 South Main

Hector, Minnesota 55342

Prepared By:

MIDWEST ENVIRONMENTAL CONTROL CORPORATION

3901 University Avenue N. E.

Minneapolis, Minnesota 55421

(612) 781-1647

June 18, 1990

TABLE OF CONTENTS

	<u>Page</u>
1.0 INTRODUCTION	1
1.1 General	1
1.2 Authorization	1
1.3 Scope of Services	2
2.0 SITE BACKGROUND	3
2.1 Site Location and Description	3
2.2 Tank Background Information	3
3.0 CONTAMINATED SOIL EXCAVATION OBSERVATION	4
3.1 Underground Storage Tank Removal	4
3.2 Soil Conditions	4
3.3 Petroleum Contamination	5
3.4 Soil Excavation Results	6
3.5 Potential Drinking Water Impacts	6
4.0 CONCLUSIONS AND RECOMMENDATIONS	7
5.0 CORRECTIVE ACTION FOR CONTAMINATED SOILS	8
6.0 PETROFUND REIMBURSEMENT	9
7.0 QUALIFICATIONS	10

Response Action Report
Underground Storage Tank Excavation Observation

1.0 Introduction

1.1 General

The purpose of this report is to present the results of the petroleum contaminated soil excavation observation conducted by Midwest Environmental Control Corporation (MECC) for Ralph Larson Chevrolet located at 531 South Main St., Hector, Minnesota. This report is designed to provide adequate and detailed information as specified in the Minnesota Pollution Control Agency (MPCA) "Excavation of Petroleum Contaminated Soils," guidelines dated 12/12/88 and in Title 40 Code of Federal Regulations (CFR) 280.71.

1.2 Authorization

MECC was authorized by Mr. Ralph Larson to proceed with and undertake the explorative and interim response activities on April 16, 1990, regarding a suspected waste oil release from an underground storage tank at Ralph Larson Chevrolet.

1.3 Scope of Services

The scope of services performed by MECC personnel in relation to this underground storage tank site included:

- o Background information collection;
- o An on-site inspection by an Environmental Geologist;
- o Removal observations of the underground storage tank;
- o Evaluation of soil samples from the tank basin for evidence of hydrocarbon contamination based on visual appearances, odor, and photoionization detection (HNu Model 101);
- o Analyzing selected soil samples for Benzene, Toluene, Ethylbenzene, Xylenes, Total Hydrocarbons as Gasoline, Volatile Hydrocarbons (by method 465C), Methyl Tertiary Butyl Ether (MTBE), Lead, Chromium, Cadmium, and Polychlorinated Biphenyl (PCB);
- o Preparation of a report presenting data, methodologies, results and conclusions of the work performed at this site.

2.0 Site Background

2.1 Site Location and Description

The site is located at 531 South Main within Hector City Limits (Figure 1). The surface elevation of the site is approximately 1080 feet NGVD. The site is presently occupied by Ralph Larson Chevrolet. Residential buildings are located to the east of the site.

2.2 Tank Background Information

One underground storage tank (UST) existed at the site prior to removal. The UST on site was 500 gallons in capacity and constructed of painted steel. The tank was utilized for waste oil storage and located on the east side of the building (Figure 2). We understand that there are no other known UST's located at this facility. The tank was registered with the MPCA in 1986 and assigned unique registration number MNUST 9509. Based on information included in the Underground Storage Tank Information Form (Appendix A), the tank was installed in 1981. No information is available concerning product inventory control for this tank.




Figure 1

SITE LOCATION MAP

Ralph Larson Chevrolet
MECC Project # 1070-0490

Date: 5/18/90

Prepared By:
Barb Ryan

Scale: 1"=2000'

Reviewed By:



**MIDWEST ENVIRONMENTAL
CONTROL CORPORATION**

3901 University Avenue NE
Minneapolis, Minnesota 55421
(612) 761-1647




Figure 2

**Ralph Larson Chevrolet
Tank Location Diagram
MECC Project # 1070-0490**



**MIDWEST ENVIRONMENTAL
CONTROL CORPORATION**

3901 University Avenue NE
Minneapolis, Minnesota 55421
(612) 781-1847

Project No. 1070-0490	Prepared By: BAR
Date: 5/18/90	Reviewed By:

3.0 Contaminated Soil Excavation Observation

3.1 Underground Storage Tank Removal

The tank was removed by J & M Trucking of Brownnton, MN on April 16, 1990. The tank and associated dispensing piping were pumped dry and transported by J & M Tanks to their shop in Stewart, Minnesota where it was to be cleaned and dismantled for scrap. The MPCA was notified of a petroleum release at the site on April 16, 1990. The results of the tank removal are presented on the completed "Underground Storage Tank Removal Form" in Appendix B. The tank was in fair to poor condition with some pitting and corrosion. After the tank was completely removed from the tank basin, contamination was noted within native soils immediately adjacent to the tank.

3.2 Soil Conditions

The soil profile at this site consists of 1 foot of coarse sand and gravel underlain by a 1-1/2 foot layer of green clay. Lean organic clays predominate for depths of 2-1/2 feet to 5 feet. Green clay is found from 5 feet to 9 feet which is the bottom of the excavation pit. No ground water was evident in the tank basin during or after excavating operations.

3.3 Petroleum Contamination

Elevated levels of hydrocarbon soil contamination were detected within the storage tank basin. An HNu Model 101 equipped with a 10.2 eV lamp was utilized to screen the soil samples. The results of the field screening for hydrocarbon contamination are presented in Table 1. The excavated soils gave photoionization readings ranging from 16.8 to 54.0 parts per million (ppm). Soil screening detected background readings of 0.5 to 0.8 ppm. The final bottom sample in the tank basin at a depth of 9 feet, gave a reading of 54 ppm. An Ultraviolet Illuminator was also used to indicate total volatile and subvolatile petroleum hydrocarbons in the collected samples. These results are also presented in Table 1. Soil samples were collected from the base and sidewalls of the tank basin and the excavated contaminated soil pile. The soil samples were analyzed for Benzene, Toluene, Ethylbenzene, Xylenes (BTEX), Total Hydrocarbons (THC) as Fuel Oil and as Gasoline, Volatile Hydrocarbons (by method 465c), Methyl Tertiary Butyl Ether, Lead, Cadmium, Chromium and Polychlorinated Biphenyl (PCBs). The results of these analyses are presented in Table 2. The laboratory report is included in Appendix C.

Table #1

Soil Screening Results

MECC Project No: 1070-0490

MECC Project Name: Ralph Larson Chevrolet

Sample I.D. No.	Sample Location	Sample Depth	Visual Detection		Odor Detection			Soil Type	HNu Readings in ppm		UVI Fluorescence				
			Y	N	N	W	M		S	Back-ground	Head-space	N	VW	M	S
SWS-1	Sidewall South	6'		X	X				0.8	20.0	X				
* SWN-4	Sidewall North	7'		X	X				0.7	16.8	X				
* BS-1	Bottom Sample	9'		X		X			0.8	54.0		X			
SWW	Sidewall West	7'		X	X				0.7	17.0			X		
SWE	Sidewall East	7'		X	X				0.5	15.8				X	
* SP-1	Soil Sample	NA		X		X			0.8	58.0				X	

COMMENTS: * - Samples submitted for chemical analysis

- N - Non-Detect
- VW - Very Weak
- W - Weak
- M - Medium
- S - Strong

TABLE 2

**RESULTS OF CHEMICAL ANALYSES
RALPH LARSON CHEVROLET, INC.
HECTOR, MN
TANK BASIN**

<u>Parameter</u>	<u>SP-1</u>	<u>BS-1</u>	<u>SW-N</u>
<u>Benzene</u>	<0.01	0.006	<0.005
<u>Toluene</u>	<0.01	<0.005	<0.005
<u>Ethylbenzene</u>	<0.01	<0.005	<0.005
<u>Xylenes</u>	<0.01	<0.005	<0.005
<u>Total Hydrocarbons as gasoline</u>	<0.50A	0.54	<0.50
<u>as fuel oil</u>	<2.0	<2.0	<2.0
<u>Lead</u>	140	--	--
<u>Cadmium</u>	0.73	--	--
<u>PCB's</u>	<1.0	--	--
<u>MTBE</u>	0.044	--	--
<u>Chromium</u>	13	--	--

INDEX: SW-N - North Sidewall Sample

BS-1 - Bottom Sample

SP-1 - Soil Pile Sample

A - Sample may contain an amount of this parameter below the detection limit.

< Not detected at this level.

- o All Units Reported In Parts Per Million (PPM)
- o Analyses Conducted By SERCO Laboratories, Inc.

3.4 Soil Excavation Results

During the excavation a sewer line was broken, the line was replaced by J & M with 2 foot lengths of cement pipe. The piping was covered above and below with plastic sheeting and then native clay.

Based on visual, odor and HNu screening results, approximately 65 yards of contaminated soil were excavated from the area around the tank basin. The contaminated soils were placed on an impermeable surface and covered with 6.0 ml poly sheeting to prevent vapor problems and infiltration. The contaminated soils were temporarily stockpiled at this location until MPCA approval was given for proper remediation of the soils.


3.5 Potential Drinking Water Impacts

The building's drinking water is supplied via the City of Hector local water distribution system. The nearest water supply wells are located approximately 0.3 miles from the site. Best available information indicates that the local wells are generally completed at depths of approximately 400 feet and the static water level in these wells ranges between 47 and 60 feet. However, insufficient hydrologic information is available to adequately establish a local or regional groundwater gradient. Due to the drilled and completed depths of the surrounding local water wells, it seems highly unlikely that an impact from the release at this site would affect the groundwater in these wells. The logs of the available surrounding water wells were obtained from the Minnesota Geological Survey; they are presented in Appendix D along with a map showing their locations. A receptor survey is presented in Appendix E.

4.0 Conclusions and Recommendations

The petroleum contamination noted at this site appears to be mainly from a piping leak associated with the tank and/or tank failure. The soil excavation results indicate that the majority of the detectable petroleum contaminated soil was excavated from tank basin. Low HNu readings were observed on all of the side walls and the bottom of the basin; however, further excavation could not take place due to the threat of undermining the building foundation to the west and the presence of gas and sewer lines to the south and east. In addition, the analytical results generally indicate that petroleum hydrocarbon concentrations found in the soil samples are considerably lower than the corresponding photoionization readings.

Laboratory results of the soil samples indicate that minor hydrocarbon contamination remains within the detectable analytical limits below the tank basin (0.54 ppm). No additional impacts to public health, welfare or the environment appear evident as a result of this release. Due to the apparent low levels of petroleum contamination remaining in the tank basin at this site, we recommend that no additional explorative or remedial activities be conducted.



Location	Depth	ppm	Lab
A	6'	20.0	
C	9'	54.0	0.54
D	7'	17.0	
E	7'	16.8	<2.0
F	7'	15.8	

FIGURE 3

RALPH LARSON CHEVROLET

SAMPLE LOCATION DIAGRAM

MECC PROJECT NO. 1070-0490

Project No. 1070-0490	Prepared By: BAR
Date: 7/9/90	Reviewed By:



**MIDWEST ENVIRONMENTAL
CONTROL CORPORATION**
3901 University Avenue NE
Minneapolis, Minnesota 55421
(612) 761-1647

5.0 Corrective Action Plan for Contaminated Soils

A Corrective Action Plan (CAP) for remediation of the approximately 65 cubic yards of contaminated soils is by means of land application at Kasal farms in Stewart, MN. The land application was approved by the MPCA on June 8, 1990. The land application form, approval letter, and sieve analysis are presented in appendix F.

The contaminated soils will be disked monthly during the land application season, to provide adequate aeration and mixing for the breakdown of hydrocarbons. Soil samples will be collected during the first year, as per MPCA recommendations, to document the contamination remaining in the soil.

6.0 Petrofund Reimbursement

The Petrofund Board was established by the 1989 Minnesota State Legislature for the purpose of administering the Petroleum Tank Release Compensation Fund. The objective of the program is to partially reimburse responsible persons for costs associated in responding to a petroleum release.

To be eligible for reimbursement, a Corrective Action Plan (CAP) must be approved of by the MPCA for the site. The corrective action must adequately address the release in terms of public health, welfare and the environment. This includes defining the extent of the petroleum release, which may involve exploratory soil borings and/or groundwater monitoring wells, and potential impacts to nearby structures or water supply wells. It must also be shown the operation of the tank was performed properly including maintaining inventory control procedures prior to the remedial action. In addition, the tank must have been in compliance with applicable state and federal tank regulations at the time of the petroleum release and the MPCA was properly notified of the release. Once these items have been addressed and the MPCA requirement for cooperation has been met, application to the Board may be prepared and eligible costs submitted for partial reimbursement.

7.0 Qualifications

The environmental services performed by our engineers, hydrogeologists and geotechnicians for this project have been conducted in a manner consistent with the degree of care and technical skill appropriately exercised by environmental professionals currently practicing in this area under similar budget and time constraints. Recommendations contained in this report represent our professional judgement and are generally based upon available information and technically accepted hydrogeologic and engineering practices at the present time and location. Other than this, no warranty is implied or expressed.

This report was prepared by:




Barbara A. Ryan

Environmental Geologist

Date: June 18, 1990

This report was reviewed by:




Philip N. Cavendor, Director

Environmental Engineering Services


Date: June 18, 1990

Ralph Larson Chevrolet
MECC Project No. 1070-0490

PHOTOGRAPHS



Site photo before excavation began




500 gallon waste oil UST




500-gallon UST



Broken sewer line



Repairing the broken sewer line



Backfilled tank basin

APPENDIX A

UNDERGROUND STORAGE TANK NOTIFICATION FORM



MINNESOTA POLLUTION CONTROL AGENCY
 HAZARDOUS WASTE DIVISION
 TANKS AND SPILLS SECTION
 520 LAFAYETTE ROAD NORTH
 ST. PAUL, MINNESOTA 55155

MPCA USE

(READ INSTRUCTIONS ON REVERSE BEFORE STARTING)

A. CHOOSE APPROPRIATE TRANSACTION TYPE(S)

- Initial Notification
- Change in Tank Ownership (Date ___/___/___)
- Install New Tank
- Upgrade Tank (Date ___/___/___) Remove Tank (Date 4/16/90)
- Close in Place (Date ___/___/___) Other Changes (Please Specify)

B. Name of Tank Site
 Ralph Larson Chevrolet INC

C. Name of Owner
 Ralph Larson Chevrolet INC

Tank Site Address
 531 South Main.

Mailing Address
 531 South Main

City
 Hector

City
 Hector

State
 MN

Zip
 55342

Phone (Include Area Code)
 612-848-6251

Zip
 55342

Phone (Include Area Code)
 612-848-6251

D. Tank Number 001	E. Date Tank Installed 6/14/81	2. Capacity (Gallons) 500	3. Material of Construction (Tank) Painted Steel	4. Corrosion Protection Internal	YES / NO YES / NO
	5. Material of Construction (Piping) Galvanized Steel	6. Dispenser Type Suction	7. Substance Stored Waste Oil	8. Secondary Containment	NO

F. RELEASE DETECTION (CHOOSE ALL THAT APPLY)

- Vapor Monitoring
- Automatic Line Leak Det
- Tank Tightness Testing & Inventory Controls
- Automatic Tank Gauging
- Interstitial Monitoring (Double Wall Tank)
- Ground-Water Monitoring
- Interstitial Monitoring (Sec. Containment)
- Line Tightness Test
- Manual Tank Gauging (Less than 550 gal.)
- Other Method(s)-Specify
 HNU Readings during Tank removal
- Manual Tank Gauging & Tank Tightness Test (551 to 2000 ga.)

G. COMMENTS

LEAK SITE # 2426

I certify under penalty of law that I have personally examined & am familiar with the information submitted in this & all attached documents, & that based on my inquiry of those individuals immediately responsible for obtaining the information, I believe that the submitted information is true, accurate, and complete.

Print Name & Official Title of owner or owner's authorized representative

Ralph Larson Owner

Owner/Representative Signature Date

PQ-00410-01 (7/89)

Continue Completing Form on Page 2 - OVER

H. TANK INSTALLER		I. TANK REMOVER	
Tank Installer		Tank Remover J + M TANKS	
Mailing Address		Mailing Address - Box 219	
City		City Stewart	
State		State TN	
Zip	Phone (Include Area Code)	Zip	Phone (Include Area Code)
		55385	612-562-2573
I certify under penalty of law that all work listed on the manufacturer's installation checklist and American Petroleum Institute Bulletin 1615 has been completed for this tank to the best of my belief and knowledge.		Remover - Printed Name Kandy Korson	
Installer - Printed Name		Remover Signature - Date Kandy Korson 4-16-92	
Installer Signature - Date		J. FINANCIAL RESPONSIBILITY (If applicable)	
		Financial responsibility requirements have been complied with for this tank (please specify). Method Insurer Policy Number	

DIRECTIONS TO COMPLETE NOTIFICATION FORM: NOTE THIS FORM MAY BE COPIED

Proper completion and submission of this notification form fulfill the requirements of both state and federal law (Minn. Stat. Sec. 116.48 and 42 USC Sec. 6991a) concerning underground storage tank notifications. All notifications must be typed or printed legibly with a ballpoint pen. Use one form for each tank being reported. Complete all items. Completed forms are to be mailed to MPCA at the address on the front of this form.

- Check the box or boxes which most closely describe the action being reported.
- Give the name, complete address and phone number of the site where the tank is located.
- Give the name, complete address and phone number of the tank owner (individual, corporation, agency or other organization).
- Assign a number (up to 3 characters) for each tank reported.
- Provide the following information about the tank:
 - date installed (mm/dd/yy)
 - capacity of the tank in gallons
 - material of tank construction (FRP, steel, STIP-3, etc.)
 - circle the correct choice indicating if the tank has internal and/or external corrosion protection (black iron, galvanized, etc.);
 - material of piping construction (black iron, piping has corrosion circle the correct choice indicating if the piping has corrosion protection
 - type of system or pump used to dispense product (submersible, suction, etc.)
 - substance currently or most recently stored in the tank (gasoline, diesel, kerosene, etc.)
 - type of secondary containment, if any (vault, double wall, liner, etc.)
- Check the box or boxes describing the type of leak detection systems in use. For explanation of systems, see 40, CFR Part 280, Subpart D.
- Type or neatly print any comments pertaining to A. through F.
- To be completed by the tank installer for all tanks installed after December 22, 1988.
- To be completed by the tank remover for all tanks removed.
- Certain tank owners or operators must meet financial responsibility requirements for the tank. Consult 40 CFR Part 280, Subpart H for specific requirements.

INFORMATION ON MPCA ID: 9509 Facility Name RALPH LARSON CHEVROLET INC

FACILITY INFORMATION

MPCA ID: TN9509 Exempt: N
 STC:
 Facility Type:
 EQUIP RENT/MOVING/STORAGE
 Date Form Received: 04/23/86

Name of Tank Site: RALPH LARSON CHEVROLET INC	Name of Owner: RALPH LARSON CHEVROLET INC
Tank Site Address: 531 S MAIN ST	Mailing Address: 531 S MAIN ST
City: HECTOR	City: HECTOR
Zip: 55342	Zip: 55342
Phone: 6128486251	Phone: 6128486251
County:65 Renville	State: MN
Twp: 0 Rng: OW Section: 1	

FACILITY REMARKS

The following comment was entered on: 04/23/86
 #12- PIPING IS NOT UNDERGROUND- SECTION C- PROPERTY LOCATION-
 BUTLER & HENRICKSONS S 285 FT OF N 390 FT OF W 171 FT OF OL 6- EX S
 100 FT OF N 205 FT OF E 101 FT

TANK INFORMATION

TANK STATUS: ACTIVE

MPCA Storage Tank Database System —Underground Tank Information

Tank Number	Install Date	Capacity (Gallons)	Material Of Construction	Corrosion Protection	
				Tank	Pipe
001	06/14/81	500	PAINTED STEEL	N	N
Piping Material	Piping Protect	Dispenser Type	Substance Stored	Secondary Containment	
GALVANIZED STEEL	N	SUCTION	Waste Oil	Tank	Pipe
RELEASE DETECTION (Choose all that apply by putting a Y in box)					
N	N	N	N	N	N
N	N	N	N	N	N
N	N	N	N	N	N
N	N	N	N	N	N
N	N	N	N	N	N
Vapor Monitoring					
Automatic Line Leak Detection					
Automatic Tank Gauging					
Ground Water Monitoring					
Line Tightness Test					
Other Methods (see Comments)					
Installer Number:					
Remover Number:					
Assurance Method: UNKNOWN					
Signature:					
Signature:					
Insurer Name:					

Ralph Larson Chevrolet
MECC Project No. 1070-0490

APPENDIX B

UNDERGROUND STORAGE TANK REMOVAL INFORMATION FORM

ADDITIONAL COMMENTS, DETAILS AND DESCRIPTIONS:

Sketch the property site and tank location(s) in the space provided below.

NORTH

W
E
S
T

E
A
S
T

SOUTH

Please fill out this form as completely as possible. Provide a copy to the local Fire Department Official and send the original form to the MPCA at the address below.

Minnesota Pollution Control Agency
Tanks and Spills Section
Hazardous Waste Division
520 Lafayette Road, St. Paul, Minnesota 55155

Ralph Larson Chevrolet
MECC Project No. 1070-0490

APPENDIX C

LABORATORY RESULTS



SERC Laboratories

1931 West County Road C2, St. Paul, Minnesota 55113 (612) 636-7173

LABORATORY ANALYSIS REPORT NO: 864 PAGE 1
05/11/90

Midwest Environmental Control Corporation
3901 University Avenue N.E.
Minneapolis, MN 55421

DATE COLLECTED: 04/16/90
DATE RECEIVED: 04/17/90
COLLECTED BY: CLIENT
DELIVERED BY: CLIENT
SAMPLE TYPE: SOIL

Attn: Jeff Groen
Ralph Larson, Chemist

SERC SAMPLE NO:	26260	26270	26280
SAMPLE DESCRIPTION:	SP-1	BS-1	SWN
	1070-	1070-	1070-
	0490	0490	0490

ANALYSIS:

Methyl Tertiary Butyl Ether, mg/kg	0.044	-	-
FID Scan, mg/kg, as #2 fuel oil	<2.0	<2.0	<2.0
FID Scan, mg/kg, as gasoline	<0.50(A)	0.54	<0.50
Lead, mg/kg as Pb	140	-	-
Total Chromium, mg/kg as Cr	13	-	-
Cadmium, mg/kg as Cd	0.73	-	-
Polychlorinated Biphenyl, (PCB), dry weight, mg/kg	<1.0	-	-
Chloromethane, ug/kg	<6.0	-	-
Dichlorodifluoromethane, ug/kg	<5.0	-	-
Vinyl chloride, ug/kg	<10	-	-
Bromomethane, ug/kg	<10	-	-
Chloroethane, ug/kg	<4.0	-	-
Dichlorofluoromethane, ug/kg	<10	-	-
Methylene chloride, ug/kg	<50	-	-
Trichlorofluoromethane, ug/kg	<7.0	-	-
Allyl chloride, ug/kg	<2.0	-	-
1,1 Dichloroethylene, ug/kg	<2.0	-	-
1,1 Dichloroethane, ug/kg	<1.0	-	-
1,2 Dichloroethylene, trans, ug/kg	<1.0	-	-
1,2 Dichloroethylene, cis, ug/kg	<1.0	-	-
Chloroform, ug/kg	<5.0	-	-
1,1,2 Trichlorotrifluoroethane, ug/kg	<50	-	-
1,2 Dichloroethane, ug/kg	<2.0	-	-
Dibromomethane, ug/kg	<2.0	-	-
1,1,1 Trichloroethane, ug/kg	<1.0	-	-

< means "not detected at this level". 1 mg = 1000 ug.



Member



SERCO Laboratories

1931 West County Road C2, St. Paul, Minnesota 55113 (612) 636-7173

PAGE 2

LABORATORY ANALYSIS REPORT NO: 864

05/11/90

SERCO SAMPLE NO:	26260	26270	26280
SAMPLE DESCRIPTION:	SP-1 1070- 0490	BS-1 1070- 0490	SWN 1070- 0490

ANALYSIS:

Carbon tetrachloride, ug/kg	<2.0	-	-
Bromodichloromethane, ug/kg	<2.0	-	-
Dichloroacetoneitrile, ug/kg	<2.0	-	-
2,3 Dichloro-1-Propylene, ug/kg	<2.0	-	-
1,2 Dichloropropane, ug/kg	<1.0	-	-
1,1 Dichloro-1-Propylene, ug/kg	<2.0	-	-
1,3 Dichloro-1-propylene, trans, ug/kg	<9.0	-	-
Trichloroethylene, ug/kg	<4.0	-	-
1,3 Dichloropropane, ug/kg	<2.0	-	-
Dibromochloromethane, ug/kg	<4.0	-	-
1,1,2 Trichloroethane, ug/kg	<1.0	-	-
1,3 Dichloro-1-propylene, cis, ug/kg	<15	-	-
1,2,Dibromoethane, ug/kg	<2.0	-	-
2 Chloroethylvinyl ether, ug/kg	<4.0	-	-
Bromoform, ug/kg	<5.0	-	-
1,1,1,2 Tetrachloroethane, ug/kg	<1.0	-	-
1,2,3 Trichloropropane, ug/kg	<2.0	-	-
1,1,2,2 Tetrachloroethane, ug/kg	<2.0	-	-
Tetrachloroethylene, ug/kg	<2.0	-	-
Pentachloroethane, ug/kg	<2.0	-	-
Chlorobenzene, ug/kg	<10	-	-
Acetone, ug/kg	<1000	-	-
Tetrahydrofuran, ug/kg	<50	-	-
Methyl ethyl ketone, ug/kg	<50	-	-
Benzene, ug/kg	<10	-	-
Methyl isobutyl ketone, ug/kg	<50	-	-
Toluene, ug/kg	<10	-	-
Ethylbenzene, ug/kg	<10	-	-
Cumene, ug/kg	<10	-	-
m-Xylene, ug/kg	<10	-	-

< means "not detected at this level". 1 mg = 1000 ug.



Member



SERCOC Laboratories

1931 West County Road C2, St. Paul, Minnesota 55113 (612) 636-7173

LABORATORY ANALYSIS REPORT NO: 864
05/11/90

SERCOC SAMPLE NO:	26260	26270	26280
SAMPLE DESCRIPTION:	SP-1 1070- 0490	BS-1 1070- 0490	SWN 1070- 0490

ANALYSIS:

o,p-Xylene, ug/kg	<10	-	-
1,3 Dichlorobenzene, ug/kg	<10	-	-
1,2 Dichlorobenzene, ug/kg	<10	-	-
1,4 Dichlorobenzene, ug/kg	<10	-	-
Ethyl ether, ug/kg	<100	-	-

Benzene, mg/kg	-	0.006	<0.005
Ethylbenzene, mg/kg	-	<0.005	<0.005
Toluene, mg/kg	-	<0.005	<0.005
Xylene, mg/kg	-	<0.005	<0.005

(A) Sample may contain an amount of this parameter below the detection limit.

All analyses were performed using EPA or other accepted methodologies. Samples that may be of an environmentally hazardous nature will be returned to you. Other samples will be stored for 30 days from the date of this report, then disposed of by SERCO LABORATORIES. Please contact me if other arrangements are needed.

Report submitted by,

Diane J. Anderson
Project Manager



< means "not detected at this level", 1 mg = 1000 ug.

Member


Ralph Larson Chevrolet
MECC Project No. 1070-0490

APPENDIX D

**WATER WELL LOCATION MAP
AND WELL LOGS**

UNITED STATES
 DEPARTMENT OF THE INTERIOR
 GEOLOGICAL SURVEY

STATE
 DEPARTMENT



Scale



Figure 4

Water Well Location Map

Ralph Larson Chevrolet
 MECC Project # 1070-0490

**MIDWEST ENVIRONMENTAL
 CONTROL CORPORATION**

3901 University Avenue NE
 Minneapolis, Minnesota 55421
 (612) 781-1647


Date: 6/5/90

Prepared By:
 Barb Ryan

Scale: 1"=2,000'

Reviewed By:

1. LOCATION OF WELL
County Name Kandiyohi Section 36 Township T15N Range R34W
Distance and Direction from Road Intersections or Street Address and City of Well Location
1/2 mile S of Highway 29



FORMATION LOG	COLOR	THICKNESS OF FORMATION	FROM	TO
Black dirt QFUV SOIL ORFD			0	2
Sandy yellow clay QFUV CLAY SAND			2	13
Sandy blue clay QFUV CLAY SAND			13	57
Sand QFUV SAND			57	58'6"
Sandy blue clay QFUV CLAY SAND			58'6"	80
Sand QFUV SAND			80	81
Sandy blue clay w/rocks QFUV CLAY SAND			81	238
Sand QFUV SAND			238	239
Sandy blue clay QFUV CLAY SAND			239	242
Sand w/clay lenses QFUV SAND CLAY			242	250
Sandy blue clay QFUV CLAY SAND			250	269
Sand QFUV SAND			269	271
Sandy blue clay QFUV CLAY SAND			271	342
Vary fine sand w/wood & clay QFUV SAND, WOOD CLAY			342	380
Fine sand QFUV SAND			380	389
Granite WUD GNIS			389	392



3. PROPERTY OWNER'S NAME
City Hector, Minnesota

4. WELL DEPTH (completed) _____ ft. Date of Completion (9/4/11)

5. 1. Cable tool 4. Reverse 7. Drives 10. Dmk
2. Hollow rod 5. Air 8. Bored 11.
3. Rotary 6. Jetted 9. Power Auger

6. USE
1. Domestic 4. Public Supply 7. Industry
2. Irrigation 5. Air Conditioning 8. Commercial
3. Test Well 6.

7. CASING DIAM. Threaded 1 Welded 2 Above/Below Surface _____ ft.
Black 1 In. to _____ ft. depth Weight _____ lbs./ft.
In. to _____ ft. depth Drive Shoe? Yes No
In. to _____ ft. depth Or open hole from _____ ft. to _____ ft.

8. SCREEN Material _____ Dia. _____ Length _____ FITTINGS!
ft. and _____ ft. Static Water Level _____ ft. Date Measured _____
ft. below land surface
ft. after hrs. pumping _____ g.p.m.
ft. after hrs. pumping _____ g.p.m.


9. WELL HEAD COMPLETION
1. Patless adapter 2. Basement offset 3. At least 12" above grade
12. Well grouted? Yes No Cu. Yds. _____
1. Heat cement 2. Bentonite 3.
Depth: from _____ ft. to _____ ft. direction _____ type _____
Well disinfected upon completion? Yes No

13. Nearest source of possible contamination _____ feet _____ direction _____ type _____
14. PUMP Model Number _____ HP _____ Volts _____
Length of drop pipe _____ ft. capacity _____ g.p.m.
Material of drop pipe _____
Type: 1. Submersible 3. Turbine 5. Reciprocating
2. Jet 4. Centrifugal 6.

15. REMARKS, OBSERVATION, SOURCE OF DATA, etc.
This well was drilled under jurisdiction and this report is true to the best of my knowledge and belief.

THEIN WELL CO., INC. 12013
Licensee Business Name
Address Clara City, Minnesota
Signed _____ Date _____

1. LOCATION OF WELL
County Name Renville Fraction NE 20 1/4 NE 27 Township Number T 115 N Range Number R 33 W
Distance and Direction from Road Intersections or Street Address and City of Well Location 115-32-29 a d b b c c



FORMATION LOG	COLOR	HARDNESS OF FORMATION	FROM	TO
Black dirt			0	1 1/2
Grayish yellow clay			1 1/2	3
Sandy brownish gray clay			3	15
Sandy blue clay			15	54
Sand			54	54 1/2
Sandy blue clay			54 1/2	85 1/2
Sand			85 1/2	89
Sandy blue clay			89	93 1/2
Sand Rocks			93 1/2	95
Sandy blue clay w/sand seams			95	148
Rock			148	149
Sandy blue clay			149	213
Sand			213	214 1/2
Sandy blue clay			214 1/2	240
Soft sandy blue clay			240	268
Blue w/green clay			270	274
Sandy blue clay			274	285
Sand			285	286 1/2
Sandy blue clay			286 1/2	330

Ordinate 741
COPIED
15. REMARKS: LOCATION, SOURCE, DATA, DATE

3. PROPERTY OWNER'S NAME
Address Carroll County Hester, Minnesota

1. WELL DEPTH (completed) _____ ft. Date of Completion _____
 5. Cable tool Reverse Driven 10" dug
 Hollow rod Air Bored 11"
 Rotary Jetted Power Auger
 6. USE Domestic Public Supply Industry
 Irrigation Air Conditioning Commercial
 Test Well

7. CASING DIAM. _____
 Threaded 1 _____
 Black 2 _____
 in. to _____ ft. depth
 in. to _____ ft. depth
 in. to _____ ft. depth
 Drive-Shop? Yes No

8. SCREEN Make _____ or open hole from _____ ft. to _____ ft.
 Type _____ Dia. _____
 Slot/Gauge _____ Length _____ FITTINGS: _____
 Set between _____ ft. and _____ ft.
 _____ ft. and _____ ft.
 _____ ft. and _____ ft.

9. STATIC WATER LEVEL _____
 ft. below above _____ Date Measured _____
 land surface
 10. PUMPING LEVEL (below land surface) _____
 ft. after _____ hrs. pumping _____ s.p.m.
 ft. after _____ hrs. pumping _____ s.p.m.

11. WELL HEAD COMPLETION
 Pitless adapter 2 _____ Basement offset 3 _____ At least 12" above grade
 Well grouted Yes No _____ cu. yds.

1. Test cement Bentonite 3 _____
 Depth: from _____ ft. to _____ ft.
 from _____ ft. to _____ ft.

13. Nearest source of possible contamination _____ feet _____ direction _____ type
 Well disinfected upon completion? Yes No

14. PUMP Date installed _____
 Not installed

Manufacturer's Name _____
 Model Number _____ HP _____ Volts _____
 Length of drop pipe _____ ft. capacity _____ s.p.m.

Material of drop pipe _____
 Type: 1 Submersible 3 L.S. Turbine 5 Reciprocating
 2 Jet 4 Centrifugal 6

16. WATER WELL CONTRACTOR'S CERTIFICATION
 This well was drilled under my jurisdiction and this report is true to the best of my knowledge and belief.

7 Renwick Co 12013
 License No. _____
 Address: Carroll County, Minn
 Signed: Michael Weiss Date _____
 Authorized Representative


WATER WELL RECORD
Minnesota Statutes 156A.01-.09

MINNESOTA UNIQUE WELL NO.

102061

1. LOCATION OF WELL:
County Name: Kennecott Section Number: 29 Township Number: 715 N. Range Number: R 32 W
Distance and Direction from Road Intersections of Street Address and City of Well Location:
1/4 mi. E

Show exact location of well in section grid with "X".
Sketch map of well location.



FORMATION LOG	COLOR	HARDNESS OF FORMATION	FROM	TO
Black dirt			0	14
Gray clay QFUV CLAY			14	17
Sandy yellow clay QFUV CLAY			17	17
Sandy blue clay QFUV CLAY SAND			17	35 1/2
Sand QFUV SAND			35 1/2	43
Sandy blue clay QFUV CLAY SAND			43	53
Rocks QFUV SAND			53	53
Sandy blue clay QFUV CLAY SAND			53	66 1/2
Sand QFUV SAND			66 1/2	67 1/2
Sandy blue clay QFUV CLAY SAND			67 1/2	77
Rock QFUV SAND			77	77 1/2
Sandy blue clay QFUV CLAY SAND			77 1/2	80
Rock			80	80
Sandy blue clay QFUV CLAY SAND			80	84 1/2
Sand QFUV SAND			84 1/2	89
Sandy blue clay QFUV CLAY SAND			89	106 1/2
Rock			106 1/2	107
Sandy blue clay QFUV CLAY SAND			107	180
Rock			180	181
Sandy blue clay QFUV CLAY SAND			181	183
Sand QFUV SAND			183	185
Sandy blue clay QFUV CLAY SAND			185	221
Sand QFUV SAND			221	223
Sandy blue clay w/sand QFUV SAND			223	278 1/2
Sand QFUV SAND			278 1/2	282
Sandy blue clay QFUV CLAY SAND			282	342
Sand w/wood & clay QFUV SAND			342	385
Sand QFUV SAND			385	392
Wood & Clay QFUV CLAY WOOD			392	393
Granite broken			393	393

12. No further test bore

3. PROPERTY OWNER'S NAME: City Hector, Minnesota
Address: 5 City Hector, Minnesota
Date of Completion: _____

4. WELL DEPTH (completed) _____ ft.
 5. USE: Domestic Public Supply Industry
 Irrigation Air Conditioning Commercial
 Sewer Well Other _____
 6. LBS: Reverse Drive 10" Dug
 Hollow rod Air Bored 11"
 Pottery Jetted Power Auger 9"

7. CASING DIAM. _____ ft.
 HEIGHT: Above/Below Surface _____ ft.
 Weight _____ lbs./ft.
 Drive Shafts: Yes No
 Or open hole from _____ ft. to _____ ft.
 Make _____
 Type _____ Dis. _____
 Size/Gauge _____ Length _____ FITTINGS:
 Set between _____ ft. and _____ ft.
 _____ ft. and _____ ft.
 _____ ft. and _____ ft.

8. STATIC WATER LEVEL _____ ft.
 _____ ft. below above Date Measured _____
 _____ ft. after _____ hrs. pumping _____ g.p.m.
 _____ ft. after _____ hrs. pumping _____ g.p.m.

9. WELL HEAD COMPLETION
 Pitless adapter Basement offset At least 12" above grade
 Well grouted Yes No Cu. Yds. _____
 Best cement Bentonite _____
 from _____ ft. to _____ ft.

10. Nearest source of possible contamination _____ feet _____ direction
 Well disinfected upon completion: Yes No

11. PUMP
 Date installed _____
 Not installed
 Manufacturer's Name _____ HP _____ Volts _____
 Model Number _____
 Length of drop pipe _____ ft. capacity _____
 Material of drop pipe _____
 Type: 1 Submersible 3 U.S. Turbine 5 Reciprocating
 2 Jet 4 Centrifugal 6

16. WATER WELL CONTRACTOR'S CERTIFICATION
 This well was drilled under my jurisdiction and this report is true to the best of my knowledge and belief.

15. NAME, ADDRESS, SOURCE OF DATA, ETC.
 Name: Thain Well Co., Inc. 12013
 License Business Name: _____
 Address: Clara City, Minnesota
 License No. _____
 Signed: Michael Wenz Date: _____
 Authorized Representative

Use a second sheet, if needed.

OK

145-32-29-900000
ADDRESS: DIVISION OF WATERS

209515
94-12
File No. HECTOR

JUL 25 1960

WELL LOG STATEMENT

WILL REPORT PROMPTLY TO DIRECTOR, DIVISION OF WATERS, STATE OFFICE BLDG., ST. PAUL 1, MINN.

Well No. 115.32.29.104

DIVISION OF WATERS

Location of Well Hector, Minn. 115-32-29-900000 Locate Well on Plat of Section

Outside

County St. Louis Hector City or Town

0				

Sec. 29
Twp. 115
Range 32

Describe Further by Lot, Block, Nearest Highway, Street and Number

SW PA 57-840

Drilled for Village of Hector

Driller Thein Well Co, Inc

NO2

Address Clara City, Minn.

Date of Completion Sept, 1959

REPORT OF FINAL PUMPING TEST
Date of Test Sept, 59

Site Upland, Valley, Hillside, Etc.

Duration of Test 24 hrs. Min.

Type of Well Drilled

Rate of Pumping 500 GPM

Drill Rig Used Solid tool

Diameter: Top 12" Bottom 60" Ft.

Depth of Well 400'

Static Water Level 160' Ft.

Ground Elevation Level

Time required for Recovery Gal. per day

COPIED

Height of Casing Above Ground or Below R. R., Highway, Lake, Etc.

Quality of Water (Hard or Soft, Fresh or Salty, Etc.)
Temperature of Water Were Measurements Made of Effect on Other Nearby Wells During Test? Give Details.

Was Laboratory Analysis Made? no

F. What Purpose Will Water Be Used? domestic

I. Well Pumped? yes Pump Capacity GPM 250

W. Well Sealed on Completion? yes

X. Well Overflow Without Pumping? no Yes or No

Natural Flow GPM

Director		Hydro Stud
Deputy		Reports
Secretary		Methods
Records		Ground W.
Publ.	<u>✓</u>	Surface W.
Library	<u>✓</u>	Surveys
Permits		Dialing
Inspection		<u>Remille Co</u>
Drainage		<u>Swilligan</u>

209575

WELL LOG

Geologic Formations Kind, Color, Hard or Soft	Thickness of Formation	Depth in Feet		Casing Diam.	Water Conditions Found
		From	To		
Grey sandy clay & shale		0	360'	12"	none
Fine sand		360'	400'		Water.
					B
					Indicate Size, Type, & Location of Any Screens, Gravel Packs, Grouting, or Other Development

I hereby certify that, to the best of my knowledge, the data presented in this statement is a true and correct representation of conditions encountered in the construction of this well.

Dated at Clara City, Minn. this 22 day of July, 1960

(Firm Name) Theln Well Co., Inc
 By P. Theln

715602

Well No.

Latitude-longitude:

HYDROGEOLOGIC CARD

SAVE AS ON MASTER CARD

Province: 112 Section: 30

Drainage Basin: 23 J Subbasin: 31

(D) (C) (E) (F) (H) (K) (L)
 Topo of depression, stream channel, dunes, flat hilltop, sink, swamp,
 well site: (P) (S) (T) (U) (V)
 offshore, pediment, hillside, terrace, undulating, valley flat

MAJOR AQUIFER: 32 system 34 series 39 aquifer, formation, group 30 31
 Aquifer Thickness: 34 ft

Lithology: 33 Origin: 34 Depth to top of: 41 ft

MINOR AQUIFER: 37 system 44 series 43 aquifer, formation, group 46 47
 Aquifer Thickness: 37 ft

Lithology: 31 Origin: 34 Depth to top of: 37 ft

Intervals Screened: 33

Depth to consolidated rock: 40 ft Source of data: 44

Depth to basement: 43 ft Source of data: 40

Surficial material: 70-71 Infiltration characteristics: 72

Coefficient Trans: 73 Spd/ft 75 Coefficient Storage: 76 78

Perm: 79 spd/ft²; Spec cap: 79 Number of geologic cards: 79

log

top soil + yellow clay ← QTUV CLAY 0 - 30

blue clay QTUV CLAY 30 - 170


Hard sticky blue clay QTUV CLAY 170 - 340

fine sand QTUV SAND 340 - 380

medium sand QTUV SAND 380 - 390

broken granite PWD 390 - 405

No. 4



Form is designed to be used in the field
 and is not intended to be used in the laboratory
 Form 12, 550 in. 7/54

APPENDIX E

RECEPTOR SURVEY




Figure 5
City of Hector
Storm Sewer
System
 Ralph Larson Chevrolet
 MECC Project # 1070-0490



**MIDWEST ENVIRONMENTAL
 CONTROL CORPORATION**
 3901 University Avenue NE
 Minneapolis, Minnesota 55421
 (612) 781-1847

Date:	6/5/90	Prepared By:	Barb Ryan
Scale:	1"=600'	Reviewed By:	





Figure 6
City of Hector
Water Works
System
 Ralph Larson Chevrolet
 MECC Project # 1070-0490

Date: 6/5/90	Prepared By: Barb Ryan
Scale: 1"=600'	Reviewed By:

MIDWEST ENVIRONMENTAL CONTROL CORPORATION
 3901 University Avenue NE
 Minneapolis, Minnesota 55421
 (612) 781-1847

APPENDIX F

CAP FOR CONTAMINATED SOILS



Minnesota Pollution Control Agency

520 Lafayette Road, Saint Paul, Minnesota 55155

Telephone (612) 296-6300



June 8, 1990

Mr. Ralph Larson
Ralph Larson Chevrolet
531 South Main Street
Hector, Minnesota 55342

Dear Mr. Larson:

RE: Approval of Land Application of Petroleum Contaminated Soil
Site: Ralph Larson Chevrolet, Hector
Site ID#: LEAK00002426

The request submitted by your consultant dated May 22, 1990, to land apply approximately 65 cubic yards of petroleum contaminated soil is hereby approved by staff of the Minnesota Pollution Control Agency (MPCA). This approval is based upon the MPCA staff's understanding that the appropriate county and local officials have been notified and/or have given approval for the land application of this soil and is subject to the following additional conditions:


1. Stockpiled soils shall be protected from infiltration and runoff prior to land application.
2. Soil shall be applied to land located at Kasal Farm.
3. Soils shall be spread to a thickness of no more than four inches and incorporated into the top six inches of native soil per MPCA document "Land Application of Petroleum Contaminated Soil: Single Application Sites" (April 25, 1990). Soils shall be disked once per month during the growing season.
4. The land-applied soil shall be sampled and reports shall be submitted in accordance with part III.C of the MPCA land application document until analyses are 10 parts per million total petroleum hydrocarbons or lower. The MPCA form entitled "Soil Monitoring Results for Land-Applied Petroleum Contaminated Soil" should be used for reporting monitoring results.

Mr. Ralph Larson
Page 2
June 8, 1990

We believe these actions will provide adequate treatment of petroleum contaminated soils. The MPCA reserves the right to require additional work if this is determined to be necessary to protect public health and the environment. This letter does not release any party from liability for this contamination.

Please contact me at 612/643-3426, if you have any further questions.

Sincerely,



Mark Koplitz
Pollution Control Specialist
Tanks and Spills Section
Hazardous Waste Division

MP:jao

cc: Ed Homan, County Solid Waste Officer
Dan Benson, Collins Township Official
Barb Ryan, Midwest Environmental Control Corp.
Francis Kasal, Kasal Farm

APPLICATION TO LAND APPLY PETROLEUM CONTAMINATED SOIL

Minnesota Pollution Control Agency
Tanks and Spills Section
April 25, 1990

Refer to the Minnesota Pollution Control Agency (MPCA) document "Land Application of Petroleum Contaminated Soil: Single Application Sites" for specific information on acceptable soil and site criteria.

I. BACKGROUND INFORMATION

A. Tank owner/operator mailing address: B. Site from which contaminated soil originated:

Contact: Ralph Larson

Company name: Ralph Larson Chevrolet
Street/Box: 531 South Main
City, Zip: Hector, MN 55342
Telephone: 612-848-6251

Company name: Ralph Larson Chevrolet
Street: 531 South Main
City, Zip: Hector, MN 55342
County: Renville

C. Address or legal description of land spreading site:

Contact: Kasal Landfarm
Street: Box 174A
City, Zip: Stewart, MN 55385
Telephone: (612) 562-2513

D. Consultant (or other) preparing this form:
Midwest Environmental Control Corp.
Contact: Jeff Groen
Company name: MECC
Street/Box: 3901 University Avenue NE
City, Zip: Minneapolis, MN 55421
Telephone: (612) 781-1647

S 1/2 of SW 1/4 of Section 33, Township 115, Range 30, Township Name COLLINS

N1/2 of SW1/4 South of RR
Sect. 33, TWP 115, Range 30
(TH #212-6.56 AC) .30 AC

E. MPCA Site ID#: LEAK0000 2426

F. Volume of soil to be land applied (cubic yards): 65

G. Projected date of application of soil: Week of 5/27/90

H. Have there been past waste disposal activities at the proposed site?
No ___ Yes x, please explain.

II. SITE AND SOIL CHARACTERISTICS

- A. Site slope (percent): Less Than 6% 1/4 mile
- B. Distance to surface water (feet or miles):
- C. Distance to nearest building or residence (feet): 1200'
- D. Depth to seasonal high water table (feet): 18'
- Depth to field tile lines (feet): Over 4' / 25' Set Back
- E. If bedrock exists at 8 feet or less, indicate depth (feet): No
- F. Area of land to be used (square feet or acres): 120 Acres
- Spreading thickness (inches): Determined by MPCA (4" Spreading Thickness)

III. SOIL SAMPLING RESULTS

A. If soil nutrient tests were conducted, list the results below:

Sample Number	Organic Matter, Percent	Extractable Phosphorus, ppm
---------------	-------------------------	-----------------------------

<u>FARM</u>	<u>CORP</u>	<u>LAND</u>
_____	_____	_____
_____	_____	_____

April 25, 1990

If fertilizers will be applied, provide application rates:
120 lbs. nitrogen/acre, 80 lbs. P₂O₅/acre, 120 lbs. sulfur/acre

B. Circle the type(s) of petroleum contamination: unleaded gas, regular gas, diesel fuel, No. 2 fuel oil, waste oil, other (please specify) _____.

List the appropriate soil sample analytical results from the excavated contaminated soil (refer to the HPCA document "Soil and Ground Water Analysis at Petroleum Release Sites"). If the petroleum was not gasoline or fuel oil attach a separate table.

Sample Number	THC as		Toluene ppm	Xylene ppm	MTBE ppm	Lead ppm
	gas or FO ppm	Ethyl-benzene ppm				
SP-1	< 2.0	-	< 10	< 10	0.044	140
_____	_____	_____	_____	_____	_____	_____
_____	_____	_____	_____	_____	_____	_____
_____	_____	_____	_____	_____	_____	_____
_____	_____	_____	_____	_____	_____	_____

NOTE: ATTACH COPIES OF LABORATORY RESULTS AND CHAIN OF CUSTODY FORMS

IV. FIGURES

Include the following figures:

- A. Copy of county soil survey map (if the county has been mapped) with copies of the interpretation tables or interpretation sheets.
- B. Site location map with exact application location marked (scale should be approximately one inch = 50 feet)

Signature and Title of HPCA Staff Inspector (or other authorized inspector):

Mark Koplitz Date Inspected: _____

Signature and Title of County Official: Edwin Homan - copies sent:

Signature and Title of City/Township Official: Dan Benson - Copies sent:

Mail to:

Minnesota Pollution Control Agency
 Attention: (Project Manager)
 Hazardous Waste Division
 Tanks and Spills Section
 520 Lafayette Road
 St. Paul, Minnesota 55155

KASAL FARMS
Box 174A, Rural Route #1
Stewart, Mn 55395 (612) 562-2513

Multiple Leaksite Land Application
for
Petroleum Hydrocarbon Contaminated Soils

Date: 5/15/90

Spill Site Name: Larson Properties
Spill Site Location: Hwy 212 & Hwy 4, Hector, MN
MPCA Leak Number: 2415 MPCA Project Manager: Mark Koplitz
Consultant (Corporation & Individual): Midwest Environmental Control Corp. - Barbara Ryan
Tank Owner Name: Ralph Larson Address: 531 Main Street
Volume of Soil: 800 (yds.³) --- (tons) Hector, MN 55342
Petroleum Contamination (gas, diesel, etc.): Gas phone: (612) 848-6251
Soil to be Temporarily Stockpiled? Yes / No Date Stockpiled: 4-11-90
Location of Stockpile: Kasal Farms, Box 174A, RR #1, Stewart, MN 55395
Name of Soil Hauler: J & M Trucking
Projected Date of Spreading: wk of 5-21 Method of Spreading: Flow Boy Spreading
Anticipated Thickness and Acreage of Spread Soils: 4 inches 1.5 acres
Method and Timing of Incorporation: Disk cultivate, once per month
First Proposed Sampling Date of Thin Spread Soils: August, 1990


Soil Sample Type & Chemical Analytical Results (ppm)

Sample I.D.	Soil Type	Total HC	Benzene	Toluene	E-benzene	Xylene	Lead
SP-1	clay w/silt	170	<0.5	<0.5	1.1	7.6	
SP-2	clay w/silt	69	.046	.01	.59	2.4	17

Above Information Supplied By: Barbara Ryan Date: 5-15-90
(Name)

Notification of Township Official: Dan Benson Date: _____
County Official: Ed Homan Date: _____
MPCA Official: Janet Berryhill Date: _____

Soil Chemical Analysis, & Spreading Location Map Attached



**MIDWEST ENVIRONMENTAL
CONTROL CORPORATION**

m e c c
3901 University Ave. N.E.
Minneapolis, MN 55421
(612) 781-1647

SIEVE ANALYSIS

Project: Ralph Larson Chev. Job No.: 1070-0490
Originator: D. P. Waxmunski Date: 4-23-90

Soil Type: Clayey sand with some gravel

Weight of Container: 7.5 oz.
Weight of Soil (Natural): 19.3 oz. 11.8 oz.
Weight of Soil (Dry): 17.5 oz. 10 oz.
Weight of Water: 1.8 oz.
Wt. Percent Moisture: 15.3%

Weight of Soil and Sieve (Dry): 20.2 oz.
Weight of Sieve: 12.9 oz.
Weight of soil greater than 200 mesh: 7.3 oz.
Weight of soil less than 200 mesh: 2.7 oz.

Wt. Percent soil less than 200 mesh or 74 microns: 27%