#.2572 MEK

Eround Water Monitoring and closure request Report.

The depth to the state water table level is approximably 35

Ground water Plows SE with abydrauler gradient of 0.001 At/ft.


Groundwater Contamnation


WW3 were sampled on 12/2/91, 2/11/42, and 5/5/92.

Petralem Cont was not desteated in MW-1, 2, and 4

M-3-0.89-3.2 ppb 1,2-dichlorochane.

close it. Pavement no heaching, considerable better to GWT, Court Soil tevels drop of fast with depth.





SCALE 124000

FRECO ECH

File No., 711-017

Minnascolla, Minnasota

Project

SINCLAIR STATION - RICHFIELD, MINNESOTA


SITE LOCATION MAP SINCLAIR STATION


7733 PORTLAND AVENUE SOUTH


RICHFIELD, MINNESOTA


Date: JUNE, 1990


Figure No. 1











5B-1 and 5B-2-NO SHO-1, 2, 3, 4 and 5B-5 < 14. 3ppm 5B-3+5B-4 49-1250 ppm 4-36' Soil Samples 5B-3 920 ppm THC/8 9' 5B-4 97.00 TH

SB-4 97 PPM THC/q 480 PPM THC/fo - 10' SB-5 1.3 PPM THC/g 35' MW-3 2.6 PPM THC/FO 34'

Monitorny Wells

Water Table 35 1

Gw Flows South east Ground water Contamination

ND BTEX, THIT - MW: 3
3.7 ppb 1,2- Dichloroethane in MW-3 - Marke off-site Source.
Vapor Assessment

None

Ground Water Receptor

none - not required

HydroGeologic Selling

hone - not required.

appears that the increase in benzene levels in the water found in the sump pit immediately adjacent to the tank basin is the result of continuous petroleum releases from the tank system after Total Petroleum acquired the property. Buoyant forces working on the large USTs and freeze-thaw cycles cause the large USTs to heave and may result in leaks from weak joints in fill pipes and pipe lines. The petroleum release has impacted the water table aquifer above the Minnesota Department of Health Recommended Allowable Limits (RALs) for benzene and toluene. The downgradient extent of ground water contamination is currently unknown. Ground water contamination increases in MW-2 and MW-3 when the water table rises in the spring and summer and comes in contact with residual petroleum contamination in the soil. The residual petroleum contamination is probably the result of petroleum releases which occurred while Q-Petroleum-was operating the tanks. Some of the residual petroleum contamination may be the result of petroleum releases which occurred after Fotal Petroleum acquired the property in June 1988. It is impossible to determine if the subsequent petroleum releases which occurred after Total Petroleum acquired the property are contributing to the level of contamination in the water table aquifer. The water wells located within a mile radius of the site are completed in Quaternary sand and gravel sediments, and the Prairie du Chien Group and Jordan Sandstone. All the aquifers utilized by the water wells are separated from the impacted water table aquifer by 6 to 85 feet of a confining clay layer, therefore it is very unlikely that the drinking water aquifers will be impacted by the petroleum release.

Increasing levels of petroleum contamination detected in the water found in the sump pit immediately adjacent to the tank basin may be due to continuous petroleum releases from the tank system after Total Petroleum acquired the property. Therefore, the MPCA is requesting both Q-Petroleum and Total Petroleum to proceed, with the necessary additional investigation to identify and prevent any continuous petroleum releases and determine the magnitude and extent of ground water contamination and the potential vapor impact to underground structures and utilities.

The following comments present our response to the conclusions and recommendations in the report, and outline the performance objectives, technical recommendations, and motivation for the additional work.

- 1. The water table aquifer is not a drinking water aquifer or a potential drinking water aquifer because of the impermeable nature of the sandy lean clay aquifer material and its inability to yield sufficient quantities of water. Therefore, the cleanup goal will be 100 times the RALs and the compliance boundary will generally be the property boundary.
- 2. Q-Petroleum should work in conjunction with Total Petroleum to identify, prevent and mitigate any continuous petroleum releases from the tank system. Please submit any information regarding the identification and prevention of any continuous petroleum releases.
- 3. An adequate number of monitoring well(s) should be installed to define the downgradient extent of ground water contamination. The additional monitoring well(s) should be installed downgradient of MW-3. Please notify MPCA hydrogeologist Larry Quandt (612-297-8602) of the proposed location and construction of the downgradient monitoring well(s) a minimum of 10 working days prior to installation.
- 4. Ground water monitoring is required to determine the magnitude and extent

生25.72

Tank Excavation

2-4,000 gollon regular gasoline Tank
2-4,000 gollon nules ded gasoline Tank
1-6,000 gellon prenam vules ded gasoline Tank
1-1,000 gallon fuel o. 1 Tank
1-560 gallon was to 0:1 Tank.

Corroded with

Soil conditions - Fine to coarse grained sand

Soil samples 190-1900 ppm THC/FO 7-16 feet.

11-1100 ppm THC/g

most of the contamnated soil has removed.

300 which de was removed.

Remedial Investigation

5 50, 1 bornge 4 monitorny wells 31-60' beard.

General Gealogy
9' Silty, fine to medium purind soul

27' fine to coarse grained sand with trace of gravel organic vapors

of ground water contamination. Investigation ground water monitoring should be conducted in accordance with the MPCA new guidance document entitled "Leaking Underground Storage Tank Program Ground Water Monitoring" dated May 1991. The new monitoring well(s) and MW-2, MW-3, and MW-4 should be sampled a minimum of two quarters. The ground water samples should be analyzed for benzene, ethylbenzene, toluene, xylenes, methyl tertiary butyl ether, and total hydrocarbons as gasoline.

- 5. High levels of volatile hydrocarbons are present in the soil and ground water beneath the site. A vapor risk assessment should be conducted in accordance with the MPCA guidance document "Petroleum Vapor Risk Assessment and Survey" dated May 8, 1990 to determine if a vapor survey is necessary.
- 6. Inventory control records for the last 12 months should be reconciled, summarized, and submitted to the MPCA. Results of all previous tank tightness tests (including data and worksheets or calculations) should be included with the inventory control records.
- 7. The MPCA agrees with DPRA's recommendation to continue pumping the water from the sump pit and tank basin until the leak has been identified and repaired because buoyant forces and freeze-thaw cycles cause the large USTs to heave which may result in leaks from weak joints in fill pipes and pipe lines. Water samples pumped from the sump pit should be analyzed for benzene, ethylbenzene, toluene, xylenes and total hydrocarbons as gasoline. Please submit all data regarding the dewatering system and sump pit and the analytical results and volume of water treated to date.
- 8. A report summarizing and documenting the results of the work described in comments 2, 3, 4, 5, 6 and 7 should be submitted to the MPCA. The report should follow the format outlined in the MPCA guidance document "Petroleum Tank Release Reports" dated May 1991. The ground water monitoring program and need for additional corrective action will be reevaluated based on the results of this report.
- 9. If ground water contaminants exceed the cleanup goal in any of the monitoring wells, please notify MPCA hydrogeologist Larry Quandt (612-297-8602).