

**Preferred Id:** 11991

Interest Name: JORDAN TEXACO

Address1: 255 Triangle Ln

City: Jordan

State: MN

Zip: 55352

Phone: 6124927737

Interest Remarks      Date and Time Printed: 7/27/2006 12:05:41

Inventory records indicate a loss of more than .2gph. After speaking with inspector, this is considered a release and investigation is warranted. d. John Mills of Arden Environmental wishes to install recovery wells and would like a bid waiver for this. he says there is more than 1000 gals missing since September. I spoke with Joe Radermacher with Pump and Meter and he thought it was only 100gls missing. Will speak with Dan Hanon in spills to see if bid waiver is needed. (SHV)

10/28/98 RHN: I returned call from John Mills, Arden Env.; Tanks were installed in 1995 and they have been using SIR leak detection. They reviewed their records and appear to be "off" since early September. Native soil is sand and ground water is 7 feet below grade. There was a release from a fitting at the dispenser which released into the spill bucket. There was a cracked fitting in the spill bucket which released to the soil. Buildings in the area are presumedly slab on grade. A road and field are in the presumedly down gradient location. There is a McDonalds restaurant and a car parts store in the other location. Arden sampled tow storm water drains near the tanks. They run to a river 3/4 mile from the site. The drains are 2 to 3 feet below grade and might not be at risk. Arden took readings in both drains with a PID with results of 0 and 4 ppm. John explained that the reading of 4 ppm could be organics. John suggested that they install 3 wells in the area of the tanks to recover free product and would like an emergency bid waiver to perform that work. When we discussed the amount released, he suggested I contact the owner of the company Tim Yokum.

10/28/98 RHN: I called Tim Yokum. There estimate at this time is 100 gallons a day have been lost over the last 30 to 40 days. I explained the bid waiver process and told him I would fax the waiver this morning and suggested that his consultant begin work asap to recovery product. They would need to bid the remaining full investigation and corrective action. I suggested he bid that portion asap and that work would follow a fast timeline.

10/28/98 RHN: I called John Mills @ Arden. I asked that they begin work asap - within a day or two. John will call me back when they have scheduled the work. I explained that the waiver is only for free product recovery and that they will need to bid on the full RI and CAD portion of the work.

10/28/98 RHN: Emergency Bid Waiver sent to Tim Yokum and John Mills for recovery and control of petroleum: 1- on surface or ground waters. 2- infiltrating a sanitary or storm sewer. 3- infiltrating a building or structure. 4- vapors in a build-

**Preferred Id: 11991**

Interest Remarks	Date and Time Printed: 7/27/2006 12:05:41
ing, stucture or sewer.	
11/03/98 RHN: Phone call from John Mills, Arden Env.; Yesterday they installed 3 wells and one boring. The worst case well did not encounter free product. They installed a well 65 feet from the tank in a downgradient direction and encountered 1.5 feet of free product. They encountered 1.8 feet of free product in another well (not sure of location). They placed a boring another 50 feet downgradient and did not find contamination. They can either install a dedicated free product pump which they can trench to a tank or install passive collectors. It would take approximately 2 weeks to install the dedicated system. In the mean time they will perform passive bailing or use vac trucks. I asked that he speak with SGG to discuss free product recovery at the site. I asked that he contact me on a regular basis until things are under control and the bidding has been completed.	11/06/98 RHN: Phone call from John Mills @ Arden Env.; They will be installing an active free product recovery system in approx. 2 weeks. They will be performing passive recovery today at the site. John will submit the free product worksheet after the system is installed. He had performed a walking survey and there are no receptors. John also spoke with SGG on above issues.
11/10/98 RHN: SGG and I met with John Mills, Arden Env. @ the MPCA. We discussed additional work at the site. We concurred that 5 borings and 2' wells would be appropriate. They have installed 3 wells up to this point and are trenching the free product recovery system as we speak. It should be operational by late next week and in the mean time they will use vacuum trucks to suck free product from the wells. I explained that the additional RI work and free product recovery once the system is operational must be bid out and will not be covered under the Petrofund bid waiver. There has been a release across the street at a Conoco/Happa. There was a release reported in 95 when tanks were removed and then the file was closed. They discovered another release and will be requesting file closure.	1/15/99 KAR: Rec'd Free Product Recovery Worksheet.
2-3-99 LS CSR adequate sent to Commerce.	02/17/98 JPK: I met with John Mills of Arden Environmental. We discussed the uniqueness of the site and how to proceed with the investigation. We were both in agreement with some geoprobing, MW installations, and continued recovery of the free product. Need to get highway right-of-way access which takes about 6 weeks and then they will proceed.
04/21/99 AA-File transferred from RHN to Jell Abdella in Metro Dist.	

**Preferred Id: 11991**

Interest Remarks      Date and Time Printed: 7/27/2006 12:05:41

09/22/99: AA-Received RI/monitoring.

09/30/99: AA-File review.

10/12/99: AA-Can't find the file.

01/26/2000: AA-Can't find the file. I made a file for it.

02/02/00: John Kaehler

Review of monitoring report dated Sep 99. Additional info needed in the downgradient(NW) direction.  
Have call into John Mills, Arden Environmental, to discuss.

02/16/2000: John Kaehler

Spoke with John Mills today. They no longer are handling the site. Strusinski and Associates are handling it. I called Donna Strusinski to get the scoop. She said that Commerce told her she needed to get bids from environmental consultants for the additional work required to finish the project. She expects to award the bid in the next day or 2. She'll have the consultant contact me. We also discussed the additional investigation necessary to complete the RI but that wouldn't affect the bidding process.

02/22/2000: John Kaehler

Spoke with the new consultants Eric Ealy, Brad Burke, IT Corp. and discussed the site. I sent them my notes on the site. They'll keep me informed of their actions. We also discussed the need for additional work and free product recovery.

04/10/2000: AA-Mailed RMW letter, JPK letter

04/21/2000: AA-Received a one page letter. Consultant is Brad Burke. The IT Group. 1801 Old Hwy 8 NW. New Brighton. MN 55112-2307. 651-633-0792.

07/18/2000: AA-recognize the need for a little longer deadline. I have changed the deadline to 10/15/2000. This was done per the e-mail information that John Kaeler supplied after talking to the consultant.

02/13/01 John Kaehler

Talked with Tom Hudrik, consultant, and discussed the site. He faxed me a letter regarding what they are currently doing at the site. They continue to monitor the product recovery system every 2 weeks. They just recently got access rights from MnDOT to do some geoprobing. Once spring comes they should be able to proceed with further investigation.

04/30/01: John Kaehler  
Spoke with Tom Hudrik. They plan on advancing the geoprosbes shortly. They are a little late because of the high water this spring. I also told them that water samples are necessary but not to worry about soil sampling from the geoprosbes.  
09/25/2001: AA-File review. Needs a wakeup letter now.

## Preferred Id: 11991

Interest Remarks      Date and Time Printed: 7/27/2006 12:05:41  
12/07/01 John Kaehler

Review of Additional Site assessment report dated Jul 2001.

- Additional work was performed on May 30, 2001.
- 3 geoprosbes advanced, 2 on the north side of Hwy 169 and another was advanced in the median.
- No detectable vapors were observed in the 3 borings.
- GW was encountered approx 10 ft bg at the median and 3 ft bg at the probes across Hwy 169. Water samples were collected from all 3 borings. Analyses indicated no detectable amounts of GRO and VOC's.
- It doesn't appear that the plume is migrating to the surface water located across Hwy 169.

Consultant Recommendation

- No further investigation. I agree.
- Continue operation of the product removal system until no measurable product is observed. I agree
- Once no product present, idle system for at least 3 more visits. If product does not return will request closure. I agree

12/14/2001

Sent letter indicating our agreement with their recommendations.

7/15/03: (JME) Rec'd call from Brad Burke - upon reviewing the data he found that some of the monitoring well screens are below the water table. This could have a bearing on the conclusions/recommendations in their latest report, in which they assert that there is evidence of a release from a different site based on free product appearing where it hadn't previously been and vice versa. I told him to send in an update with revised conclusions. He will do so after next site visit, which is week after next.

08/18/03 John Kaehler

Spoke with Brad Burke, Enviro-Risk. We decided that their recommendations were fine except that they should resurvey the wells. I told him that I would indicate that in our response letter. He also mentioned that they had over a foot of free product in MW-1 the last time they visited the site. He also indicated that the WT has dropped and the screens in MW-2/3 were no longer submerged, however, the screen was still submerged in MW-1.

7/6/04 S&H: DO report received for soil samples done at this property for future sale of property. Mini water, development reasons. GW enc at 9' bgs, petro odors. High vapor of 70ppm. Sending to PM for file/action.

01/31/05 John Kaehler

Review of annual report dated Sep 04

Free product collection system has been inoperable since Enviro-Risk began monitoring the site in 2002.

- Manual free product bailing continues on a periodic basis at the site.
- Indications that a new release occurred were refuted. Sampling was conducted on the free product and it was determined by sulfur content that the existing product was from an old release (ie. Texaco gas and not the current Holiday gas).
- Free product has been present in all 3 wells but found consistently only in MW-1
- MW-2 has been free of product except for Oct-Dec of 03, with thickness around 3".
- MW-3 somewhat more often than MW-2, detected Oct 03 - Feb 04 with thickness around 3".
- It is estimated that through bailing and the recovery system approx 2430 gal of product has been removed
- Recent free product removal by bailing has been minimal.

Consultant Recommendations:

- Continue manual free product collection on a monthly basis.
- Continue semi-annual monitoring through June 2005.

My Take

- Agree with recommendations.
- If the amount of free product present in the MWs does not increase significantly this site will be eligible for closure in 2005.
- 2/15/06 Site PM transferred from JME to ACM.

**Preferred Id: 11991**

**Interest Remarks**      Date and Time Printed: 7/27/2006 12:05:41

07/24/06 John Kaehler

Review of closure request dated Apr 06  
 4 monitoring events indicated GW flow to the S, this conflicts with previous data indicating a more NE flow. Flow direction always difficult to ascertain because of the presence of free product and the highly variable WT, fluctuations from 3-5 ft over the past year.

Sampling has occurred twice, 06/05 and 02/06, since the last report.

Not much change in results, somewhat lower but this can be attributed to the WT above the screen.

Thickness of product found in MW-1 remained around an inch. This is down from a high of over a foot.

Given the lack of increase in product thickness, stability of the plume, and the absence of vapor receptors within 100 ft, this site should be closed.

Consultant is recommending closure, I agree.

BACKGROUND:

---

Leaksite No: 11991 Date: 07/24/06

Site name: Yocum Oil, Jordan

Hydro: John Kaehter  
Proj.Mgr: Jelil Abdella, Jessie Ebertz after reorg in 2001. Amy Miller

Leak report date:  
Leak discovered date:

Consultants: Enviro-Risk, Brad Burke

Emergency : No, but free product is present

Site Info:

Business/light industrial  
At the intersection of Hwy's 169 (to the north) and 282.  
Minnesota River is approx 1 ½ mi to the NW  
Across 282 to the SW lies a wetland (approx 1/8 mi away)

Tank Info:

4 gas USTs in use. All installed in 95 and conform to 98 standards.

Release Info:

Leak in a pipe connection. Leaked from the sump because of torn rubber seal.  
Best guess is about 4000 gallons was lost

Excavation:

No soil has been removed.

Soil Borings (location, #, etc.):

Groundwater investigation (wells, screens, locations, etc.):		
MW-1 located along North edge of tank basin		
Ground	750	
TOS	742.8	
BOS	727.8	
WT	740 (approx 10' bg)	

MW-2 located approx 40' NW(downgradient) of tank basin  
Ground 750

TOS	746.4
BOS	731.4
WT	fp

MW-3 located along W edge of tank basin

Ground	750
TOS	746.0
BOS	731.0
WT	fp

Hydrology:

Depth to GW;  
Hyd. Conductivity (K);  
Thickness:  
Effective Porosity;  
Est. Flow Velocity;  
GW Flow Direction;  
Aquifer Type:

General geology/stratigraphy:

0-8' peat  
6-20+ coarse sand  
WT @ approx 6-10' bg

Natural Attenuation Info:

Well Receptor Info:

Muni water supplied to the area.

The 3 City of Jordan muni wells are located to the SW to SE from the site with the closest approx 800 ft to the SE. They are all cased at least to 220 ft bg.

The closest well is 300 ft to the south and used by the Ford Motor dealer. This well is cased to 220 ft.

Surface Water Info:

Vapor Risk Info:

No sewers or basements of concern.  
Buried electrical lines along Hwy 169 do come in contact with contaminated GW but they don't appear to be in contact with free product.

Listing of Reports:

Dates of Major Events:  
Soil Treatment;

GW Recovery;

CAD Implemented:

Petro Fund Comments:

Justification for closure:

Hydro Comments :

01/28/2000

Review of CAD dated 09/99

A free product recovery system consisting of pumps in two wells was installed in Dec 98.

To date approx 2650 gal of free product has been removed.

Geoprobe were advanced to delineate the plume. It's quite evident that the plume has migrated towards the NW. GP-4 was the furthest downgradient approx 120' NW of the tanks. A water sample collected from this point had 7300 ppb benzene and 32000 GRO. This point was advanced at the edge of Hwy 169.

Currently there are 3 MW's installed at the site.

MW-1 located at the north edge of the tank basin

Highly contaminated

MW-2 located approx 40' NW(downgradient) of the release area (tank basin)

Has free product

MW-3 located along the NW edge of the tank basin

Has free product

Free product is being removed with controllerless pneumatic free product collection pumps.

These pumps separate gas from the water in the monitoring well, pumping "pure" product to a collection tank.

Consultant recommendations:

- 1) additional free product removal until free product no longer present
- 2) when free product no longer is present monitoring would begin on a  $\frac{1}{4}$ 'ly basis for at least 2 quarters

My Take

Free product should continue to be removed.

Downgradient definition still unclear, should either install a well or do periodic geoprobing as well as some investigation across Hwy 169 to be sure plume isn't having continuous migration of

high levels downgradient. The furthest downgradient boring, GP-4, had 7300 ppb benzene and 32000 ppb GRO.

According to our guidance it's pretty clear that additional investigation downgradient needs to be conducted. I'm guessing that the best spot would probably be across Hwy 169.

Also there is a creek that runs on the north side of 169 and a well should be placed between the creek and the release. However, considering the site constraints in may only be feasible to advance periodic geoprosbes instead of borings between 169 and the creek.

02/16/2000;

Contacted John Mills, Arden Environmental, to discuss my concerns. John said they no longer are working on the project and the project is currently being handled by Strusinski & Associates. Donna Strusinski's phone # 651/487-1208.

Spoke with Donna. She said that they called Commerce and Commerce recommended that they get 2 bids from environmental consultants to address finishing the project. She expects to be awarding the project in the next day or so and that she would have the consultant give me a call. We also discussed the additional investigation needed but I explained to her that that wouldn't affect the bidding process.

02/22/2000;

Spoke with the new consultants, Eric Ealy and Brad Birke, IT Corp and discussed the site. We discussed the need for additional work in the downgradient (NNW) direction.

03/15/2000;

Spoke with Eric Ealy. He said that they had discussed the site with the RP and MNDOT. The RP needs a letter specifically requesting the need for geoprobining on the other side of 169 and if possible a geoprobe in the median between the northbound and southbound lanes of 169.

03/31/00:

In review of the September 21, 1999 Remedial Investigation Report submitted by Arden Environmental Engineering, Inc., pertaining to the Yocom Oil Company leaksite, MPCA I.F.A.K #11991. MPCA has determined that additional work is necessary. Specifically further investigation is needed to delineate the downgradient extent of the contaminant plume. A minimum of two geoprosbes should be advanced across Highway 169 near the creek and lowland area. If possible a third geoprobe should be advanced in the median between the north and southbound lanes of Highway 169.

04/30/01

Spoke with Tom Hudrik, IT Corp. It looks as though they finally have access from DOT. Should be able to advance the geoprosbes shortly. High water and snow has pushed back the date.

12/07/01

Review of Additional Site assessment report dated Jul 2001.  
Additional work was performed on May 30, 2001.

3 geoproses advanced, 2 on the north side of 169 and another was advanced in the median.

No detectable vapors were observed in the 3 borings.

GW was encountered approx 10 ft bg at the median and 3 ft bg at the probes across Hwy 169. Water samples were collected from all 3 borings. Analyses indicated no detectable amounts of GRO and VOC's.

It doesn't appear that the plume is migrating to the surface water located across Hwy 169.

#### Consultant Recommendation

No further investigation. I agree

Continue operation of the product removal system until no measurable product is observed. I agree

Once no product present, idle system for at least 3 more visits. If product does not return will request closure. I agree

12/14/2001

Sent letter indicating our agreement with their recommendations.

08/14/03

Review of Annual/CAD system report dated Apr 03

Free product system is off and free product has not been detected in the 2 RWs 2/3 over the past 5 months.

However, free product has been detected in MW-1 for the 1<sup>st</sup> time. First detected July 23, 2002.

MW-1 is located immediately adjacent to the existing UST basin. Some thoughts that it might be from a new release.

GW flow direction is still anticipated to be towards the WSW. The MWs were resurveyed and it was determined that with the increase in WT, water levels in MW-1 were above the TOS for all 8 monitoring events, were above TOS in MW-2 for 6 out of 8, and above TOS in MW-3 for 4 out of 8.

Grade (est)	TOR (est)	TOS	BOS
MW-1 752	751.5	741.6	731.6
MW-2 752	751.5	744.2	734.2
MW-3 752	751.5	744.2	734.2

The 2 pneumatic submersible pumps installed in MW-2 and MW-3 haven't removed product since Enviro-Risk began monitoring in June of 02 (Arden Env previously had the site). The pumps were removed in late 2002.

#### Recovery system

Consists of 2 pneumatic submersible pumps installed in MW-2 and MW-3 with product discharge to an AST receiving tank.

Past reports indicated that approx 2300 gallons of free product, was removed from the wells during the period from Nov 1998 through Jan 1999. Sometimes in excess of 100 gallons/day. There are also indications that approx 500 gallons of product was removed in 1999.

Currently there appears to be approx 200 additional gallons of product in the receiving tank.  
Current total of free product removed is 3000 gallons.

Consultant recommendations;

- Leave the free product recovery system off
- Collect monthly free product measurements from the 3 MWs
- Collect a free product sample from MW-1 for fingerprinting
- Begin collection of free product via the system if sufficient quantities are found in the MWs.

My take

Agree with recommendations except that GW elevations should be collected during the monthly visits. Begin monitoring once it's determined whether we have a new release or not and/or

- Also need to check previous reports to determine whether the MWs have been surveyed. If not, wells need to be resurveyed.

08/14/03

Review of update info letter dated May 2003

Monthly free product checks indicated that the amount of free product in MW-1 has dropped from 0.99 ft to 0.01 ft.

Free product began to show up again in MW-3 in Mar.  
0.16 ft Mar 26, 0.04 ft Apr 24.

The MWs have recently been sampled for Benz/MTBE/GRO

	MW-1	MW-2	MW-3
09/02	fp	28,000/<40/110,00	9200/ <40 / 46,000
12/02	fp	23,000/<400/80,000	9100/ <400/ 51,000
03/03	19,000/250/270,000	17,000/<200/120,000	23,000/<200/130,000
06/03	fp	19,000/<100/ 74,000	6900/ <50 / 42,000
09/03	fp	17,000/<120/ 58,000	8800/<120/ 44,000
06/04	fp	25,000/<100/120,000	18,000/<100/100,000

There appears to be some evidence that a new release has occurred.

Consultant indicates that monthly free product measurements and recovery will continue. Also quarterly sampling of MWs.

08/18/03

Spoke with Brad Burke. We discuss the need to resurvey the MWs and it was decided that it would add some value. The WT has dropped so now the screens in MWs 2 & 3 are exposed. The screen in MW-1 is still submerged. Free product continues to accumulate in MW-1, over a foot the last time out. They are still checking the wells on a monthly basis.

01/31/05

#### Review of Annual dated Sep 04

Free product collection system has been inoperable since Enviro-Risk began monitoring the site in 2002.

Manual free product bailing continues on a periodic basis at the site.

Indications that a new release occurred were refuted. Sampling was conducted on the free product and it was determined by sulfur content that the existing product was from an old release (ie. Texaco gas and not the current Holiday gas).

The MWs have recently been sampled for Benz/MTBE/GRO

	MW-1	MW-2	MW-3
09/02	fp	28,000/<40/110,00	9200/<40 / 46,000
12/02	fp	23,000/<400/80,000	9100/<400/ 51,000
03/03	19,000/250/270,000	17,000/<200/120,000	23,000/<200/130,000
06/03	fp (0.6')	19,000/<100/ 74,000	6900/<50 / 42,000
09/03	fp (0.8')	17,000/<120/ 58,000	8800/<120/ 44,000
06/04	fp (0.1')	25,000/<100/120,000	18,000/<100/100,000

Free product has been present in all 3 wells but found consistently only in MW-1

MW-2 has been free of product except for Oct-Dec of 03, with thickness around 3". MW-3 somewhat more often than MW-2, detected Oct 03 – Feb 04 with thickness around 3".

It is estimated that through bailing and the recovery system approx 2430 gal of product has been removed.

Recent free product removal by bailing has been minimal.

Consultant Recommendations:

- Continue manual free product collection on a monthly basis.
- Continue semi-annual monitoring through June 2005.

My Take

Agree with recommendations.

If the amount of free product present in the MWs does not increase significantly this site will be eligible for closure in 2005.

07/24/06

Review of closure request dated Apr 06

4 monitoring events indicated GW flow to the S, this conflicts with previous data indicating a more NE flow. Flow direction always difficult to ascertain because of the presence of free product and the highly variable WT, fluctuations from 3-5 ft over the past year.

Sampling has occurred twice, 06/05 and 02/06, since the last report.

Not much change in results, somewhat lower but this can be attributed to the WT above the screen.

Thickness of product found in MW-1 remained around 1 inch. This is down from a high of over a foot.

Given the lack of increase in product thickness, stability of the plume, and the absence of vapor receptors within 100 ft, this site should be closed.

Consultant is recommending closure, I agree.

BACKGROUND:

---

Leaksite No: 11991      Date: 08/14/03  
1/21/05

Site name: Yocum Oil, Jordan

Hydro: John Kaebler  
Proj.Mgr: Jelil Abdella, Jessie Ebertz after reorg in 2001.

Leak report date:

Leak discovered date:

Consultants: Enviro-Risk, Brad Burke

Emergency : No, but free product is present

Site Info:

Business/light industrial

At the intersection of Hwy's 169 (to the north) and 282.

Minnesota River is approx 1 1/2 mi to the NW

Across 282 to the SW lies a wetland (approx 1/8 mi away)

Tank Info:

4 gas USTs in use. All installed in 95 and conform to 98 standards.

Release Info:

Leak in a pipe connection. Leaked from the sump because of torn rubber seal.  
Best guess is about 4000 gallons was lost

Excavation:

No soil has been removed.

Soil Borings (location, #, etc.):

Groundwater investigation (wells, screens, locations, etc.):  
MW-1 located along North edge of tank basin

Ground 750

TOS 742.8

BOS 727.8

WT 740 (approx 10' bg)

MW-2 located approx 40' NW(downgradient) of tank basin  
Ground 750

TOS	746.4
BOS	731.4
WT	fp

MW-3 located along W edge of tank basin

Ground	750
TOS	746.0
BOS	731.0
WT	fp

Hydrology:

Depth to GW;

Hyd. Conductivity (K);

Thickness:

Effective Porosity;

Est. Flow Velocity;

GW Flow Direction;

Aquifer Type:

General geology/stratigraphy:

0-8' peat

6-20+ coarse sand

WT @ approx 6-10' bg

Natural Attenuation Info:

Well Receptor Info:

Muni water supplied to the area.

The 3 City of Jordan muni wells are located to the SW to SE from the site with thw closest approx 800 ft to the SE. They are all cased at least to 220 ft bg.

The closest well is 300 ft to the south and used by the Ford Motor dealer. This well is cased to 220 ft.

Surface Water Info:

Vapor Risk Info:

No sewers or basements of concern.

Buried electrical lines along Hwy 169 do come in contact with contaminated GW but they don't appear to be in contact with free product.

Listing of Reports:

Dates of Major Events:  
Soil Treatment;

GW Recovery;

CAD Implemented:

Petro Fund Comments:

Justification for closure:

Hydro Comments :

01/28/2000

Review of CAD dated 09/99

A free product recovery system consisting of pumps in two wells was installed in Dec 98.

To date approx 2650 gal of free product has been removed.

Geoprobe were advanced to delineate the plume. It's quite evident that the plume has migrated towards the NW. GP-4 was the furthest downgradient approx 120' NW of the tanks. A water sample collected from this point had 7300 ppb benzene and 32000 GRO. This point was advanced at the edge of Hwy 169.

Currently there are 3 MW's installed at the site.

MW-1 located at the north edge of the tank basin

Highly contaminated

MW-2 located approx 40' NW(downgradient) of the release area (tank basin)

Has free product

MW-3 located along the NW edge of the tank basin

Has free product

Free product is being removed with controllerless pneumatic free product collection pumps.

These pumps separate gas from the water in the monitoring well, pumping "pure" product to a collection tank.

Consultant recommendations:

- 1) additional free product removal until free product no longer present
- 2) when free product no longer is present monitoring would begin on a 1/4'ly basis for at least 2 quarters

My Take

Free product should continue to be removed.

Downgradient definition still unclear, should either install a well or do periodic geoprobing as well as some investigation across Hwy 169 to be sure plume isn't having continuous migration of

high levels downgradient. The furthest downgradient boring, GP-4, had 7300 ppb benzene and 32000 ppb GRO.

According to our guidance it's pretty clear that additional investigation downgradient needs to be conducted. I'm guessing that the best spot would probably be across Hwy 169.

Also there is a creek that runs on the north side of 169 and a well should be placed between the creek and the release.

However, considering the site constraints in may only be feasible to advance periodic geoprosbes instead of borings between 169 and the creek.

02/16/2000;

Contacted John Mills, Arden Environmental, to discuss my concerns. John said they no longer are working on the project and the project is currently being handled by Strusinski & Associates. Donna Strusinski's phone # 651/487-1208.

Spoke with Donna. She said that they called Commerce and Commerce recommended that they get 2 bids from environmental consultants to address finishing the project. She expects to be awarding the project in the next day or so and that she would have the consultant give me a call. We also discussed the additional investigation needed but I explained to her that that wouldn't affect the bidding process.

02/22/2000;

Spoke with the new consultants, Eric Ealy and Brad Birke, IT Corp and discussed the site. We discussed the need for additional work in the downgradient (NNW) direction.

03/15/2000;

Spoke with Eric Ealy. He said that they had discussed the site with the RP and MNDOT. The RP needs a letter specifically requesting the need for geoprobing on the other side of 169 and if possible a geoprobe in the median between the northbound and southbound lanes of 169.

03/31/00:

In review of the September 21, 1999 Remedial Investigation Report submitted by Arden Environmental Engineering, Inc., pertaining to the Yocum Oil Company leaksite, MPCA LEAK #11991, MPCA has determined that additional work is necessary . Specifically further investigation is needed to delineate the downgradient extent of the contaminant plume. A minimum of two geoprosbes should be advanced across Highway 169 near the creek and lowland area. If possible a third geoprobe should be advanced in the median between the north and southbound lanes of Highway 169.

04/30/01

Spoke with Tom Hudrik, IT Corp. It looks as though they finally have access from DOT. Should be able to advance the geoprosbes shortly. High water and snow has pushed back the date.

12/07/01

Review of Additional Site assessment report dated Jul 2001.  
Additional work was performed on May 30, 2001.

3 geoprobe advanced, 2 on the north side of 169 and another was advanced in the median.

No detectable vapors were observed in the 3 borings.

GW was encountered approx 10 ft bg at the median and 3 ft bg at the probes across Hwy 169. Water samples were collected from all 3 borings. Analyses indicated no detectable amounts of GRO and VOC's.

It doesn't appear that the plume is migrating to the surface water located across Hwy 169.

#### Consultant Recommendation

No further investigation. **I agree**

Continue operation of the product removal system until no measurable product is observed. **I agree**

Once no product present, idle system for at least 3 more visits. If product does not return will request closure. **I agree**

12/14/2001

Sent letter indicating our agreement with their recommendations.

08/14/03

Review of Annual/CAD system report dated Apr 03

Free product system is off and free product has not been detected in the 2 RWs 2/3 over the past 5 months.

However, free product has been detected in MW-1 for the 1<sup>st</sup> time. First detected July 23, 2002.

MW-1 is located immediately adjacent to the existing UST basin. Some thoughts that it might be from a new release.

GW flow direction is still anticipated to be towards the WSW

The MWs were resurveyed and it was determined that with the increase in WT, water levels in MW-1 were above the TOS for all 8 monitoring events, were above TOS in MW-2 for 6 out of 8, and above TOS in MW-3 for 4 out of 8.

Grade (est)	TOR (est)	TOS	BOS
MW-1 752	751.5	741.6	731.6
MW-2 752	751.5	744.2	734.2
MW-3 752	751.5	744.2	734.2

The 2 pneumatic submersible pumps installed in MW-2 and MW-3 haven't removed product since Enviro-Risk began monitoring in June of 02 (Arden Env previously had the site). The pumps were removed in late 2002.

#### Recovery system

Consists of 2 pneumatic submersible pumps installed in MW-2 and MW-3 with product discharge to an AST receiving tank.

Past reports indicated that approx 2300 gallons of free product, was removed from the wells during the period from Nov 1998 through Jan 1999. Sometimes in excess of 100 gallons/day. There are also indications that approx 500 gallons of product was removed in 1999.

Currently there appears to be approx 200 additional gallons of product in the receiving tank.

Current total of free product removed is 3000 gallons.

Consultant recommendations;

Leave the free product recovery system off

Collect monthly free product measurements from the 3 MWs

Collect a free product sample from MW-1 for fingerprinting

Begin collection of free product via the system if sufficient quantities are found in the MWs.

My take

Agree with recommendations except that GW elevations should be collected during the monthly visits. Begin monitoring once it's determined whether we have a new release or not and/or

Also need to check previous reports to determine whether the MWs have been surveyed.  
If not, wells need to be resurveyed.

08/14/03

Review of update info letter dated May 2003

Monthly free product checks indicated that the amount of free product in MW-1 has dropped from 0.99 ft to 0.01 ft.

Free product began to show up again in MW-3 in Mar.  
0.16 ft Mar 26, 0.04 ft Apr 24.

The MWs have recently been sampled for Benz/MTBE/GRO

	MW-1	MW-2	MW-3
09/02	fp	28,000/<40/110,00	92000/<40 / 46,000
12/02	fp	23,000/<400/80,000	9100/<400/ 51,000
03/03	19,000/250/270,000	17,000/<200/120,000	23,000/<200/130,000
06/03	fp	19,000/<100/ 74,000	69000/<50 / 42,000
09/03	fp	17,000/<120/ 58,000	88000/<120/ 44,000
06/04	fp	25,000/<100/120,000	18,0000/<100/100,000

There appears to be some evidence that a new release has occurred.

Consultant indicates that monthly free product measurements and recovery will continue.  
Also quarterly sampling of MWs.

08/18/03

Spoke with Brad Burke. We discuss the need to resurvey the MWs and it was decided that it would add some value. The WT has dropped so now the screens in MWs 2 & 3 are exposed. The screen in MW-1 is still submerged. Free product continues to accumulate in MW-1, over a foot the last time out. They are still checking the wells on a monthly basis.

01/31/05

#### Review of Annual dated Sep 04

Free product collection system has been inoperable since Enviro-Risk began monitoring the site in 2002.

Manual free product bailing continues on a periodic basis at the site.

Indications that a new release occurred were refuted. Sampling was conducted on the free product and it was determined by sulfur content that the existing product was from an old release (ie. Texaco gas and not the current Holiday gas).

The MWs have recently been sampled for Benz/MTBE/GRO

	MW-1	MW-2	MW-3
09/02	fp	28,000/<40/110,00	9200/<40 / 46,000
12/02	fp	23,000/<400/80,000	9100/<400/ 51,000
03/03	19,000/250/270,000	17,000/<200/120,000	23,000/<200/130,000
06/03	fp (0.6')	19,000/<100/ 74,000	6900/<50 / 42,000
09/03	fp (0.8')	17,000/<120/ 58,000	8800/<120/ 44,000
06/04	fp (0.1")	25,000/<100/120,000	18,000/<100/100,000

Free product has been present in all 3 wells but found consistently only in MW-1  
MW-2 has been free of product except for Oct-Dec of 03, with thickness around 3".  
MW-3 somewhat more often than MW-2, detected Oct 03 – Feb 04 with thickness around 3".  
It is estimated that through bailing and the recovery system approx 2430 gal of product has been removed.

Recent free product removal by bailing has been minimal.

Consultant Recommendations:

- Continue manual free product collection on a monthly basis.
- Continue semi-annual monitoring through June 2005.

My Take

Agree with recommendations.

If the amount of free product present in the MWs does not increase significantly this site will be eligible for closure in 2005.

# Office Memorandum

DATE : February 18, 1999

TO : John Mills  
Arden Environmental Engineering, Inc.  
3550 Lexington Ave., Suite 102'  
Shoreview, MN. 55126

FROM : John Kaehler  
MPCA - Metro District Site Remediation  
520 Lafayette Rd  
St. Paul, MN. 55155

SUBJECT : February 18, 1999 Meeting

Dear John,

Thanks again for the opportunity to meet with you to discuss the petroleum release investigation at the Yocom Jordan Site, MPCA leak # 11991.

Please proceed with the geoprobe borings and the installation of additional monitoring wells as per our discussion. Also, please continue using the existing system to recover the free product that is in existence at this site.

If you have any questions please contact me at 651/297-8575.

Sincerely,

John Kaehler  
Hydrologist  
Minnesota Pollution Control Agency

Leaksite ID# 11991  
JORDAN TEXACO  
Site Name

Tank Facility ID 19190  
YOCUM OIL CO  
Responsible Party

#### LEAKSITE REMARKS

Inventory records indicate a loss of more than .2gph. After speaking with the inspector, this is considered a release and investigation is warranted. d. John Mills of Arden Environmental wishes to install recovery wells and would like a bid waiver for this. he says there is more than 1000 gals missing since September. I spoke with Joe Radermacher with Pump and Meter and he thought it was only 100gls missing. Will speak with Dan Han non in spills to see if bid waiver is needed. (SHV)

10/28/98 RHN: I returned call from John Mills, Arden Env.; Tanks were installed in 1995 and they have been using SIR leak detection. They reviewed their records and appear to be "off" since early September. Native soil is sand and ground water is 7 feet below grade. There was a release from a fitting at the dispensor which released into the spill bucket. There was a cracked fitting in the spill bucket which released to the soil. Buildings in the area are presumedly slab on grade. A road and Field are in the presumedly down gradient location. There is a McDonalds restaurant and a car parts store in the other location. Arden sampled tow storm water drains near the tanks. They run to a river 3/4 mile from the site. The drains are 2 to 3 feet below grade and might not be at risk. Arden took readings in both drains with a PID with results of 0 and 4 ppm. John explained that the reading of 4 ppm could be organics. John suggested that they install 3 wells in the area of the tanks to recover free product and would like an emergency bid waiver to perform that work. When we discussed the amount released, he suggested I contact the owner of the company Tim Yokum.

10/28/98 RHN: I called Tim Yokum. There estimate at this time is 100 gallons a day have been lost over the last 30 to 40 days. I explained the bid waiver process and told him I would fax the waiver this morning and suggested that his consultant begin work asap to recovery product. They would need to bid the remaining full investigation and corrective action. I suggested he bid that portion asap and that work would follow a fast timeline.

10/28/98 RHN: I called John Mills @ Arden. I asked that they begin work asap - within a day or two. John will call me back when they have scheduled the work. I explained that the waiver is only for free product recovery and that they will need to bid on the full RI and CAD portion of the work.

10/28/98 RHN: Emergency Bid Waiver sent to Tim Yokum and John Mills

Page: 1

TSR040 Remarks Listing For Leaksite = 11991  
Report Date: November 10, 1998  
for recovery and control of petroleum: 1- on surface or  
ground waters. 2- infiltrating a sanitary or storm sewer.

11991

3- infiltrating a building or structure. 4- vapors in a building, structure or sewer.

11/03/98 RHN: Phone call from John Mills, Arden Env.; Yesterday they installed 3 wells and one boring. The worst case well did not encounter free product. The installed a well 65 feet from the tank in a downgradient direction and encountered 1.5 feet of free product. They encountered 1.8 feet of free product in another well (not sure of location). They placed a boring another 50 feet downgradient and did not find contamination. They can either install a dedicated free product pump which they can trench to a tank or install passive collectors. It would take approximately 2 weeks to install the dedicated system. In the mean time they will perform passive bailing or use vac trucks. I asked that he speak with SGG to discuss free product recovery at the site. I asked that he contact me on a regular basis until things are under control and the bidding has been completed.

11/06/98 RHN: Phone call from John Mills @ Arden Env.; They will be installing an active free product recovery system in approx. 2 weeks. They will be performing passive recovery today at the site. John will submit the free product worksheet after the system is installed. He had performed a walking survey and there are no receptors. John also spoke with SGG on above issues.

End of Remarks

MINNESOTA DUTY OFFICER

## **HAZARDOUS MATERIALS INCIDENT REPORT: TANKS**

REPORT DATE:	10-26-98	TIME:	1557	DUTY OFFICER:	9
REPORTED BY:	NAME: Jim Rademacher CO: Pump & Meter ADDRESS: 11303 Excelsior Blvd. CITY: Hopkins PHONE: 612-4800				
CONTACT:	Todd Steffen c/o: Yocom Oil Co. ADDRESS: 2714 Shillwater Rd. CITY: Maplewood STATE: MN ZIP: 55114 PHONE: 739-9141 ALT. PHONE:				
RESPONSIBLE PARTY/PROPERTY OWNER:					
DISCOVERY DATE:	10-26-98	TIME:	1530	PREVIOUSLY REPORTED SITE?	<input checked="" type="checkbox"/> UNK - LEAK# _____
SITE NAME & ADDRESS:	255 triangle Lane	COUNTY:	Scott	ZIP:	55352
CITY:	Jordan	TANK CONTENTS:	Steel/Fibre Glass	TYPE:	U.S.T./A.S.T.
NUMBER/SIZE OF TANK(S):	2 @ 10,000	AGE OF TANK(S):	20 years	U.S.T./A.S.T.	Steel/Fibre Glass
	2 @ 5,000		gasoline	U.S.T./A.S.T.	Steel/Fibre Glass
	2 @ 5,000		gasoline	U.S.T./A.S.T.	Steel/Fibre Glass
NATIVE SOIL TYPE:	Unknown	SURFACE WATER NEARBY?	<input checked="" type="checkbox"/> UNK	DEPTH TO GROUND WATER?	_____
ARE THERE ANY MONITORING WELLS ON SITE?	<input checked="" type="checkbox"/> UNK	WHAT IS THE SITE WATER SOURCE?	Municipal/Private Well/UNK	CONTAMINATED SOIL EXCAVATED?	<input checked="" type="checkbox"/> UNK
ABLE TO DIG OUT OF CONTAMINATION?	<input checked="" type="checkbox"/> UNK	STAINED SOILS?	<input checked="" type="checkbox"/> UNK	PETROLEUM ODORS?	<input checked="" type="checkbox"/> UNK
GROUND WATER ENCOUNTERED?	<input checked="" type="checkbox"/> UNK	HIGHEST VAPOR READING:	1000 ppm	ANALYTICAL RESULTS:	to be started
FREE PRODUCT FOUND?	<input checked="" type="checkbox"/> UNK	NARRATIVE:	more than 1000 ppm lost since September 98	DUTY OFFICER NOTIFICATIONS MADE: (AGENCY, NAME, TIME)	
MPCA TANKS, ATTN.: STACEY VAN PATTON - FAX	<i>Rahn</i>				
ANY QUESTIONS? CONTACT THE MINNESOTA DUTY OFFICER AT 649-5451 OR 1-800-472-0798	LEAK NUMBER: 11991				

Who Took: \_\_\_\_\_

PM: \_\_\_\_\_

Priority: \_\_\_\_\_ High  
Action: \_\_\_\_\_ Advise

Auto: \_\_\_\_\_ No action

Priority: \_\_\_\_\_ Action  
Action: \_\_\_\_\_ Visit by \_\_\_\_\_  
No action: \_\_\_\_\_ State money spent  
File: \_\_\_\_\_ File  
No File: \_\_\_\_\_ No File

## REMARKS:

Copy To? \_\_\_\_\_

Send Packet?

- Disposal Packet
- Reporting Packet
- Spill Bill Packet
- VIC Packet
- VPIC Packet
- Other \_\_\_\_\_

Quickie Closure:(circle one)

Why Closed:

- 1--Referred to LEAKS
- 2--Referred to RCRA
- 3--Referred to AQ
- 4--Referred to WQ
- 5--Referred to VIC

- 6--Referred to local/county
- 7--Referred to Region
- 8--Referred to GWSW
- 9--Response Completed

- 10--No Response  
Necessary
- 11--Closed for other  
reasons (see remarks) \_\_\_\_\_
- 12--AG Lead

Quickie  
SPILL # \_\_\_\_\_

WQ  
1  
CWSW



# Minnesota Pollution Control Agency

---

July 27, 2006

Mr. Tony Yokum  
Yocum Oil Company  
2719 Stillwater Road  
St. Paul, MN 55119

RE: Petroleum Tank Release Site File Closure  
Site: Jordan Texaco, 255 Triangle Lane, Jordan, 55352  
Site ID#: LEAK00011991

Dear Mr. Yokum:

We are pleased to let you know that the Minnesota Pollution Control Agency (MPCA) staff has determined that your investigation has adequately addressed the petroleum tank release at the site listed above. Based on the information provided, the MPCA staff has closed the release site file.

Closure of the file means that the MPCA staff does not require any additional investigation and/or cleanup work at this time or in the foreseeable future. Please be aware that file closure does not necessarily mean that all petroleum contamination has been removed from this site. However, the MPCA staff has concluded that any remaining contamination, if present, does not appear to pose a threat to public health or the environment under current conditions.

The MPCA reserves the right to reopen this file and to require additional investigation and/or cleanup work if new information, changing regulatory requirements or changed land use make additional work necessary. If you or other parties discover additional contamination (either petroleum or nonpetroleum) that was not previously reported to the MPCA, Minnesota law requires that the MPCA be immediately notified.

You should understand that this letter does not release any party from liability for the petroleum contamination under Minn. Stat. ch. 115C (2002) or any other applicable state or federal law. In addition, this letter does not release any party from liability for nonpetroleum contamination, if present, under Minn. Stat. ch. 115B (2002), the Minnesota Superfund Law.

The monitoring wells for this site should be abandoned in accordance with the Minnesota Department of Health Well Code, Chapter 4725. If you choose to keep the monitoring wells, the Minnesota Department of Health will continue to assess a maintenance fee for each well.

Please note that as a result of performing the requested work you may be eligible to apply to the Petroleum Tank Release Compensation Fund (Petrofund) for partial reimbursement of the costs you have incurred in investigating and cleaning up this petroleum tank release. The Petrofund is administered by the Petroleum Tank Release Compensation Board (Petro Board) and the Minnesota

520 Lafayette Rd. N.; Saint Paul, MN 55155-4194; (651) 296-6300 (Voice); (651) 282-5332 (TTY); [www.pca.state.mn.us](http://www.pca.state.mn.us)  
St. Paul • Brainerd • Detroit Lakes • Duluth • Mankato • Marshall • Rochester • Willmar

Equal Opportunity Employer • Printed on recycled paper containing at least 20 percent fibers from paper recycled by consumers.

Department of Commerce. To learn more about who is eligible for reimbursement, the type of work that is eligible for reimbursement, and the amount of reimbursement available, please contact Petrofund staff at 651-297-1119 or 1-800-638-0418.

If future development of this property or the surrounding area is planned, it should be assumed that petroleum contamination may still be present. If petroleum contamination is encountered during future development work, the MPCA staff should be notified immediately.

For specific information regarding petroleum contamination that may remain at this leak site, please call the Petroleum Remediation Program File Request Program at 651/297-8499. The MPCA fact sheet *Request to Bill for Services Performed* must be completed prior to arranging a time for file review.

Thank you for your response to this petroleum tank release and for your cooperation with the MPCA to protect public health and the environment. If you have any questions regarding this letter, please call me at 651-296-7717 or the site hydrogeologist, John Kaelher at 651-297-8575.

Sincerely,



Abby Miller

Project Manager  
Petroleum Remediation  
Remediation Division



John Kaelher

Hydrogeologist  
Petroleum Remediation  
Remediation Division

AM/JK:ais

cc: Edward Shukle, Administrative City Clerk, Jordan  
Steve Kochlin, Fire Chief, Jordan  
Steve Steuber, Scott County Solid Waste Officer  
Brad M. Burke, Enviro-Risk Consulting Group, Inc  
Mark Hoffman, Minnesota Department of Health  
Minnesota Department of Commerce Petrofund Staff

## Ebertz, Jessica

**From:** Boissonneault, Eric  
**Sent:** Wednesday, June 09, 2004 11:07 AM  
**To:** Henderson, Sarah; Ebertz, Jessica  
**Subject:** RE: Holiday station in Jordan

I just spoke to Wes at Yokum Oil. He said Pump and Meter has been to the site and cleaned the fuel out of the sump, and that no more fuel is entering the sump. They are not sure where the fuel came from. I told him to notify the Duty officer that they have a potential leak so you should be getting that report soon.

-----Original Message-----

**From:** Henderson, Sarah  
**Sent:** Monday, June 07, 2004 3:31 PM  
**To:** Boissonneault, Eric  
**Subject:** FW: Holiday station in Jordan

So... we know nothing up here. Can you call them again and ask them to report it???

-----Original Message-----

**From:** Ebertz, Jessieca  
**Sent:** Monday, June 07, 2004 3:30 PM  
**To:** Henderson, Sarah  
**Cc:** Boissonneault, Eric  
**Subject:** FW: Holiday station in Jordan

I haven't heard anything from anyone about this site, and I do not know if there is a new owner. Is that helpful?

-----Original Message-----

**From:** Henderson, Sarah  
**Sent:** Monday, June 07, 2004 1:55 PM  
**To:** Ebertz, Jessieca  
**Cc:** Boissonneault, Eric  
**Subject:** FW: Holiday station in Jordan

Hi Jessie - read below. Have you heard from the RP for this site about this or is this a new owner??

Sarah

-----Original Message-----

**From:** Boissonneault, Eric  
**Sent:** Monday, June 07, 2004 1:54 PM  
**To:** Henderson, Sarah  
**Subject:** RE: Holiday station in Jordan

Yeah it's the same site and I don't think the owner has changed, but it is definitely a Holiday station now. I was there on the 27th and found about 4-5 inches of fuel in the pump sump, and the sensor for that sump was in the alarm mode with the alarm sound/ light turned off. I was not able to determine how long ago the alarm activated but I told them to call the duty officer to report a leak, which it appears they did not do.

-----Original Message-----

**From:** Henderson, Sarah  
**Sent:** Monday, June 07, 2004 1:45 PM  
**To:** Boissonneault, Eric  
**Subject:** RE: Holiday station in Jordan

On another note, this is the same property as existing L#11991 that Jessie Ebertz has? It's still open... but its listed as a Texaco. Does that seem right?

-----Original Message-----

**From:** Boissonneault, Eric  
**Sent:** Monday, June 07, 2004 1:13 PM  
**To:** Henderson, Sarah

**Subject:** Holiday station in Jordan

Did you every receive a Duty Officer report for a leak at a Holiday gas station located at 255 Triangle Lane in Jordan?



# Minnesota Pollution Control Agency

---

February 3, 2005

Mr. Tony Yocum  
Yocum Oil Company  
2719 Stillwater Road  
Maplewood, MN 55119

RE: Annual Monitoring Report & CAD System Monitoring Worksheet dated September 23, 2004.  
Site: Jordan Texaco, 255 Triangle Lane, Jordan  
Site ID#: LEAK00011991

Dear Mr. Yocum:

The Minnesota Pollution Control Agency (MPCA) Petroleum Remediation Program (PRP) staff has reviewed the Annual Monitoring Report and CAD System Monitoring Worksheet report dated September 23, 2004. The PRP staff agrees with your consultant recommendations as discussed in Section 3 on page 4 of the report.

If subsequently obtained information indicates that the agreed upon recommendations are inappropriate or inadequate, the MPCA may require additional work or modifications in the approved work.

If you have questions regarding the investigation of ground water at this site, please contact MPCA staff hydrogeologist John Kaehler at 651/297-8575. If you have any other questions, please call me at 651/297-8594.

Sincerely,

Jessica Ebertz  
Project Leader  
Petroleum Remediation Program  
Remediation Division

JE:ais

cc: Brad Burke, Enviro-Risk Consulting Group, St. Paul

# Minnesota Pollution Control Agency

---



August 21, 2003

Mr. Tony Yocum  
Yocum Oil Company  
2719 Stillwater Road  
Maplewood, MN 55119

RE: Annual Monitoring Report & CAD System Monitoring Worksheet dated April 24, 2003  
Site: Jordan Texaco, 255 Triangle Lane, Jordan, MN  
Site ID#: LEAK00011991

Dear Mr. Yocum:

The Minnesota Pollution Control Agency (MPCA) Leaking Underground Storage Tank Program staff has reviewed the above referenced report outlining additional investigation at the above-referenced site. The MPCA staff agrees with your consultant recommendations as discussed in Section 3 on pages 3 and 4 of the report. In addition, MPCA staff also request that the three monitoring wells be surveyed and water table elevations be collected on a monthly basis.

If subsequently obtained information indicates that the agreed upon recommendations are inappropriate or inadequate, the MPCA may require additional work or modifications in the approved work.

If you have questions regarding the investigation of ground water at this site, please contact MPCA staff hydrogeologist John Kaehler at 651/297-8575. If you have any other questions, please call me at 651/297-8594.

Sincerely,

Jessica Ebertz  
Project Leader  
Petroleum Remediation Unit  
Petroleum and Landfill Remediation Section  
Majors and Remediation Division

JME:tf

cc: Brad Burke, Enviro-Risk Consulting Group, St. Paul



**ENVIRO-RISK**  
CONSULTING GROUP, INC.

Enviro-Risk Consulting Group, Inc.  
1176 Silverwood Bay  
St. Paul, Minnesota 55125  
Phone: 651.735.7001  
Toll Free: 866.311.7475  
Fax: 651.738.3039  
[www.enviro-risk.com](http://www.enviro-risk.com)

**RECEIVED**

May 9, 2003

MAY 12 2003  
MPCA, MAR Division  
PLR / SS Section

Mr. Tony Yocum  
Yocum Oil Company  
2719 Stillwater Road  
Maplewood, MN 55119

**Re: Update Information - Groundwater & Free Product Monitoring;  
Yocum Oil – Jordan Texaco; Jordan, MN (LEAK#11991)**

Dear Mr. Yocum:

This brief update is being submitted to you for your review regarding on-going monitoring at the Yocum Oil (Jordan Texaco) site. This information is also being forwarded to the MPCA for their review.

**Free Product Monitoring & Recovery**

As you recall, the free product collection system consisted of two pneumatic submersible pumps installed in MW-2 and MW-3, which automatically removed free product from the wells and discharges into an aboveground storage tank located on site. A site map from a previous report is attached for your reference. The free product pumps were removed in late 2002, however free product monitoring and manual collection has continued since then. The following free product levels have been recorded since Enviro-Risk has been assigned to this site:

**YOCUM OIL – JORDAN TEXACO**

**Free Product Levels**

Date	MW-1	MW-2	MW-3
6/13/02	0	0	0.11
6/29/02	0	0	0.02
7/10/02	0	0	0.01
7/23/02	0.15	0	0
9/30/02	0.25	0	0
10/30/02	0.38	0	0
11/20/02	0.63	0	0
12/06/02	0.80	0	0
02/26/03	0.99	0	0
03/26/03	0.01	0	0.16
04/24/03	0.01	0	0.04

Note: All values expressed in feet

Based on the most recent free product measurements, minimal amounts of free product have been detected in the three monitoring wells on site.

#### Quarterly Groundwater Monitoring / Analysis

Per MPCA requirements, quarterly groundwater samples were collected from MW-2 and MW-3 in September and December 2002. A sample was not collected from MW-1 due to the presence of free product. In March 2003, groundwater samples were collected from each monitoring well following purging. The analytical results are summarized as follows:

#### **YOCUM OIL – JORDAN TEXACO** **Quarterly Groundwater Analytical Results**

WELL	Benzene	Toluene	Ethyl Benzene	Xylyne	MTBE	GRO
<b>MW-1</b>						
- 09/30/02	NA	NA	NA	NA	NA	NA
- 12/06/02	NA	NA	NA	NA	NA	NA
- 03/26/03	19,000	49,000	6500	44,000	250	270,000
<b>MW-2</b>						
- 09/30/02	28,000	27,000	1700	8900	<40	110,000
- 12/06/02	23,000	19,000	1800	9700	<400	80,000
- 03/26/03	17,000	31,000	2500	15,500	<200	120,000
<b>MW-3</b>						
- 09/30/02	9200	16,000	870	5100	<40	46,000
- 12/06/02	9100	17,000	1200	7400	<400	51,000
- 03/26/03	23,000	30,000	2800	17,400	<200	130,000

Note: All values expressed in micrograms per liter (ug/L)

NA = Not Analyzed

It is interesting to note that MW-1 contained the highest values for all compounds analyzed, with the exception of benzene. In addition, MTBE was detected in MW-1 for the first time at the site since Enviro-Risk has been sampling, possibly supporting our previous assumption that a new release has occurred from the existing underground storage tanks at the site.

Upcoming Tasks

During this quarter, additional free product measurement and manual recovery will be conducted on a monthly basis. In June 2003, quarterly groundwater samples will again be collected for laboratory analysis per MPCA requirements. Following the receipt of the groundwater analytical results, an update letter summarizing the information collected to date will be submitted to you for review. Depending upon the MPCA's review and response of the Annual report and these most recent results, Enviro-Risk will prepare a proposal and submit it to Yocum Oil to cover any additional work required at the site.

Thank you for the opportunity to work with Yocum Oil Company. If you have any questions, please contact me at 651-735-7001.


Sincerely,

Enviro-Risk Consulting Group, Inc.



Brad M. Burke, PE  
Senior Consultant / Principal

c/att: Ms. Donna Strusinski, Strusinski & Associates  
Ms. Jessica Eberz, MPCA





## Minnesota Pollution Control Agency

December 14, 2001

Mr. Tony Yocum  
c/o Ms. Donna L. Strusinski  
Strusinski & Associates, P.A.  
Western Bank Building  
1740 Rice Street, Suite 280  
St. Paul, MN 55113

RE: Additional Site Assessment Report dated July 18, 2001  
Site: Yocom Oil, 255 Triangle Lane, Jordan, MN  
Site ID#: LEAK00011991

Dear Ms. Strusinski:

The Minnesota pollution Control Agency (MPCA) staff has reviewed the above referenced report prepared by IT Corporation. Please proceed with the recommendations as proposed on page 2 of the report. The recommendations are listed below:

- Continue to operate free product removal system until there is no measurable free product observed in the wells.
- Once it appears that all of the free product has been recovered, shut off system and monitor to see if free product returns.
- Closure will be considered if free product does not return to the wells after system shut-off.

Please submit a *Corrective Action Design System Monitoring Worksheet*, summarizing the free product removal, on an annual basis.

If you have any questions regarding this letter, please contact John Kaehler at 651/297-8575 or myself at 651/297-8594.

Sincerely,

A handwritten signature in black ink, appearing to read "Jessica Ebertz".

Jessica Ebertz  
Project Leader  
Petroleum Remediation Unit  
Petroleum and Landfill Remediation Section  
Majors and Remediation Division

JME:tf

cc: Eric Ealy, IT Corporation, New Brighton



# Minnesota Pollution Control Agency

November 2, 1998

Mr. Todd Steffen  
Yocum Oil Company  
2719 Stillwater Road  
Maplewood, Minnesota 55119

**RE: Petroleum Storage Tank Release Investigation and Corrective Action**

Site: Yocum Oil Company, 255 Triangle Lane, Jordan  
Site ID#: LEAK00011991

Dear Mr. Steffen:

**Notice of Release**

The Minnesota Pollution Control Agency (MPCA) has been informed that a release of petroleum has occurred from storage tank facilities which you own and/or operate. We appreciate your timely notification so this site can be handled in an efficient manner.

**Legal Obligations**

Federal and state laws require that persons legally responsible for storage tank releases notify the MPCA of the release, investigate the release and, if necessary, clean up the release. A person is considered legally responsible for a tank release if the person owned or operated the tank either during or after the release, unless specifically exempted under the law. If you believe that you are not legally responsible for this storage tank release, please contact the project manager listed below.

If you are not legally responsible for the release, but hold legal or equitable title to the property where the release occurred, you may volunteer to take corrective action. Responsible persons and volunteers who take corrective action may be eligible for reimbursement for a major portion of the costs of corrective action. The legislature has established the Petroleum Tank Release Cleanup Account to reimburse responsible persons and volunteers. The account is administered by the Petro Board which is part of the Minnesota Department of Commerce. Final decisions regarding the amount of reimbursement are made by the Petro Board. All questions about eligibility and reimbursement should be directed to the Petrofund staff at 651/297-1119 or 651/297-4203.

**Request to Take Corrective Action**

The MPCA staff requests that you take steps to investigate and, if necessary, clean up the release in accordance with the enclosed MPCA fact sheets. The site investigation must fully define the extent and magnitude of the soil and/or ground water contamination caused by the release. A report (excavation report and/or remedial investigation/corrective action design (RI/CAD) which details the results of the investigation or concludes that excavation was sufficient to clean up the release must be submitted to this office within 10 months of the date of this letter. Please refer to MPCA fact sheets for information pertaining to the amount of work needed at the petroleum release site(s).

Mr. Todd Steffen  
Page 2  
November 2, 1998

Sites with free product (free-floating petroleum), drinking water supply impacts, surface water impacts, indoor vapor impacts, fire or explosion hazards, or ground water impacts which pose a significant threat to public health or the environment, are considered high priority for staff review. If one or more of these situations apply to your site, an RI/CAD report must be submitted within 90 days. In addition, if you know or discover that there is free-product from a well, excavation, or borehole, you must notify the MPCA within 24 hours and IMMEDIATELY begin interim free product recovery.

If you have not already done so, the MPCA recommends that you hire a qualified consulting firm registered with the Petrofund staff that has experience in conducting petroleum release site investigations and in proposing and implementing appropriate corrective actions. A list of registered contractors and consultants is available from the Petrofund staff. The MPCA reserves the right to reject proposed corrective actions if the requirements of the site investigation have not been fulfilled. Please note that, under Minn. R. 2890 (Supp. 1997), you must solicit a minimum of two competitive proposals on a form prescribed by the Petro Board to ensure that the consulting costs are reasonable. Questions about bidding requirements should be directed to Petrofund staff.

**Required Response**

MPCA staff requests a response to this letter within 30 days. Please tell us whether you intend to proceed with the requested work. If you do not respond within this time frame, the MPCA staff will assume that you do not intend to comply, in which case the MPCA Commissioner may order you to take corrective action. Failure to cooperate with the MPCA in a timely manner may result in reduced reimbursement from the Petro Board. See Minn. R. 2890 (Supp. 1997). The enclosed fact sheets will provide you with the information necessary to complete a successful investigation and cleanup.

If you have any questions concerning this letter or need additional information, please contact me at 218/828-6116. Please reference the above LEAK # in all correspondence.

Sincerely,  
*R. Hedenreich*  
Richard Newquist  
Project Manager  
Site Remediation Section  
Metro District

RHN:kh

Enclosures

cc: Kay Kuhlmann, Administrator, Jordan  
William Busch, Fire Chief, Jordan  
Al Frechette, Scott County Solid Waste Office  
Joe Radermacher, Pump & Meter, Hopkins



**Minnesota Pollution Control  
Agency**

*Tanks and Emergency Response Section, 520 Lafayette Road, St. Paul, MN 55155*

## Emergency Response Bid Waiver

To: Responsible Party: **Yokum Oil Company**  
 Street Address: **2719 Stillwater Road**  
 City, State, Zip Code: **Maplewood, Minnesota 55119**

RE: Site Name: **Jordan Texaco**  
 Address: **255 Triangle Lane, Jordan**

LEAK #: 11991  
 Date of Report: 10/28/98

The following actions should be taken to remediate the emergency conditions at the above-referenced site. Only these specified tasks are exempt from the two bid requirements. Unless approved by the assigned project manager, other phases of investigation and remediation at this site will need two bids.

- Recovery and control of pooled petroleum on land.
- Recovery and control of petroleum on surface or ground waters.
- Recovery and control of petroleum infiltrating a sanitary or storm sewer.
- Recovery and control of petroleum infiltrating a building or structure.
- Removal and control of petroleum vapors in a building, structure or sewer.
- Relocation of affected residents.
- Excavation of petroleum contaminated soil to eliminate emergency conditions.
- Product removal from a tank.
- Soil borings/monitoring well installation to assess the emergency conditions.
- Collecting and analyzing surface water, ground water, soil or air samples to assess or monitor the emergency situation.
- Providing an alternate water supply to an affected well owner.
- Other, specify:

Post-it® Fax Note	Date to	7671	# of pages ▲	1
To <b>Lynn Mills</b>	From <b>Rick Newquist</b>			
Co./Dept. <b>Arden Env.</b>	Co. <b>MPCA</b>			
Phone #	Phone #			
Fax # <b>651 484 5568</b>	Fax # <b>651 296 9707</b>			

Authorization:  
Rick Newquist 10-88-98  
sign and date

**Richard Newquist** 651-297-8583  
 print name and telephone #  
 Tanks and Emergency Response Section  
 Hazardous Waste Division

Post-it® Fax Note	Date	10/28	# of pages ▲	1
To <b>Tim Yokum</b>	From <b>Rick Newquist</b>			
Co./Dept. <b>Levee Oil</b>	Co. <b>MPCA</b>			
Phone #	Phone #			
Fax # <b>651 739-6400</b>	Fax # <b>651-296-9707</b>			

*This document can be made available in other audio formats.  
 774 users call 612/282-5332*

John Mills, Arbutus & uv.  
481 - 545  
651 - 484 - 5568 FATT  
General Information

**Site Name/AKA/Address**

JORDAN TEXACO

1

፩፻፲፮ መልካም ጥንቃቤ

— 8 —

- - - - -

ט נדפסה דרכו על דבר:

Release date: 10/26/98

I Standard Letter Date:

Emergency Actions (Y/N) : N

## † Conditional Closure:

File Closure:

Agency Staff Born This Site

**†BBPT:** SHV    **BM: BHN**    **Hydro:**    **Sinill S:** DTH    **Bac:**

End (Find) Clear (PF3) End (PF4) Emerg (F20)

RT(F11) S1(F12) ST(F13) Pm(F14) FB(F17) LT(F19) TR(F20)

† MPCA Leaksite Remarks Screen † Leak ID: 11991

十一

Inventory records indicate a loss of more than .2gph. After speaking with  
the manager this is considered a malaise and immediate action is recommended.

John Mills of Arden Environmental wishes to install recovery wells at

Find would like a bid waiver for this: he says there is more than 1000 qrt

He was last seen in September. I spoke with Joe Radermacher with Pump and Mfg.

Peter and he thought it was only 100gls missing. Will speak with Dan Han

tion in spills to see if bid waiver is needed. (SHV)

十一

卷之三

卷之三

THE JOURNAL OF CLIMATE

◀->◀->

Rpt Trkng (E11) Restore (E12) Save (F10) Print (PFE3) >

MINNESOTA POLLUTION CONTROL AGENCY  
COMMISSIONER'S SITE REPORT  
TO THE PETROLEUM TANK RELEASE  
COMPENSATION BOARD

SITE ID#	RELEASE SITE	APPLICANT	REGION
LEAK00011880	Cenex Convenience Store	High Plains Cooperative	V
LEAK00011991	Jordan Texaco	Vacuum Oil Company, Inc.	Metro
LEAK00012103	Georges 66	Rita Deutsch	Metro

**1. Eligibility Determination**

I hereby determine that the corrective action described in the application was appropriate in terms of protecting public health, welfare, and the environment and that the applicant is eligible for Petrofund reimbursement, pursuant to Minn. Stat. § 115C.09, subd. 2, items (a) and (c) (Supp. 1997).

**2. Compliance with Applicable Requirements: ADEQUATE**

Information readily available to the Minnesota Pollution Control Agency staff shows that the applicant has complied with the applicable requirements of Minn. Stat. § 115C.09, subd. 3(I) (Supp. 1997).

The determinations in this report are made solely for the purpose of determining eligibility for reimbursement under Minn. Stat. § 115C.09, subds. 2 and 3 (Supp. 1997). Nothing in this site report releases any person from liability, and the Minnesota Pollution Control Agency does not waive any of its authority to require additional corrective action at the above-referenced site or to enforce other provisions of state law.

Dated: 2/3/99

*Mark Schmitt*)

Mark Schmitt  
Supervisor  
Regular Facilities, Policy and Planning

# Petroleum Tank Release Compliance Checklist

SITE NAME Jordan Texaco

LEAK0000 //99/  
USE THE FOLLOWING GUIDELINES TO DETERMINE IF THE LEAKING TANK IS IN COMPLIANCE

UNREGULATED TANKS.....are ASTs/USTS 110 gallons or less, OR heating oil ASTs/USTS 1,100 gallons or less with product consumed on the premises, OR farm/residential ASTs/USTS 1,100 gallons or less containing motor fuel not for resale.

STATE REGULATED TANKS.....are heating oil USTS with a capacity more than 1,100 gallons or all ASTs not specified above.

FEDERALLY REGULATED TANKS.....are all USTS not specified above.  
**STATUS OF RESPONSIBLE PARTY:** Regular Applicant f Limited Use Applicant \_\_\_\_\_

## UNREGULATED TANKS, STATE TANKS, FEDERAL TANKS

Release Notification: Date release discovered: MPC A 10-26-98 Petro App 11-2-98  
Date release reported: MPC A 10-26-98 Petro App 11-3-98  
When/how was release discovered? Weekly inventory  
Was there environmental damage due to delay? Yes ✓ No ✗  
Adequate Inadequate Recommend Reduction? Yes ✓ No ✗  
Comments: Leak determined 10-26-98  
Cooperation Issues: Yes ✓ No ✗  
If Yes, please prepare a narrative to be appended to the Commissioner's Site Report.

## STATE TANKS, FEDERAL TANKS

Corrosion Protection: Tanks: Yes ✗ No ✓ N/A Piping: Yes ✗ No ✓ N/A  
Applicable for steel piping/steel USTS installed after 12/22/88. Steel piping/steel USTS installed before 8/1/85 require corrosion protection no later than 12/22/98. Heating oil USTS installed before 8/1/85 don't ever require corrosion protection. Steel piping/steel USTS installed between 8/1/85 and 12/22/88 should be cited as inadequate, but not recommended for reduction. ASTs do not require corrosion protection.

Adequate Inadequate Recommend Reduction? Yes ✓ No ✗

## STATE TANKS, FEDERAL : NKS (cont.)

### FEDERAL TANKS

AST Secondary Containment: Yes  No  N/A  Recommend Reduction? Yes  No

Spill Prevention: Yes  No  N/A  Applicable for USTs installed after 12/22/88. USTs installed before 12/22/88 require spill prevention by 12/22/98.

Overfill Protection: Yes  No  N/A  Adequate  Inadequate  Recommend Reduction? Yes  No  Applicable for USTs installed after 12/22/88. USTs installed before 12/22/88 require spill protection by 12/22/98.

Adequate  Inadequate  Recommend Reduction? Yes  No

Leak Detection: Tanks: Tank Leak Detection:

Yes  No  N/A

Tank Tightness Testing

Yes  No  N/A

If tank was installed

before 1965 or unknown

1965-1969

1970-1974

1975-1979

1980-12/22/88

12/22/89

12/22/90

12/22/91

12/22/92

12/22/93

Tanks installed after 12/22/88 should have leak detection at installation.

Piping: Pipe leak detection: Yes  No  N/A

Pipe tightness testing: Yes  No  N/A

Applicable for pressurized piping installed after 12/22/88. Pressurized piping installed before 12/22/88 must have leak detection by 12/22/90.

Adequate  Inadequate  Recommend Reduction? Yes  No

Comments \_\_\_\_\_

Tanks Properly Closed: Yes  No  Tanks must be removed or properly closed in place within one year of the date they are taken out of service.

Applicable for USTs only.

Adequate  Inadequate  Recommend Reduction? Yes  No

*W/K*

Completed by: *M. Miller*

Date: 2-1-99

10/2/96

OFFICE USE ONLY:  
 LEAK # 1191 PHASE 2  
 ENTERED 1/11/99 BY JGC

State of Minnesota  
 JAN 06 1999  
 Dept. of Commerce

**MINNESOTA PETROLEUM TANK RELEASE COMPENSATION BOARD**  
**APPLICATION FOR REIMBURSEMENT**

**I. APPLICANT INFORMATION**

Name Yocum Oil Co., Inc.  
 Mailing Address 2719 Stillwater Avenue  
 City Maplewood State MN Zip 55119  
 Contact Person (if different from above "Name") Tony Yocum  
 Day Phone (651) 739-9141 Ext:  Fax 739-6400  
**Check One:**  
 Responsible Person  
 Volunteer  
 Non-Responsible Person  
*(see Application Guide)*  
08 / 95 to PRESENT/ Dates applicant owned or operated tank(s) [complete if "Responsible Person" box is checked]  
/ / to / / Dates applicant owned property [complete if "Volunteer" box is checked]

**II. LEAK SITE INFORMATION**

11991 Petrofund Leak Number Richard Newquist MPCA Project Manager  
 Tank Facility Name Yocum Oil Company  
 Address 255 Triangle Lane  
 City Jordan MN 55352  
 Day Phone (651) 739-9141 County of Leak Site: Scott  
11 / 2 / 98 Date petroleum leak detected  
11 / 3 / 98 Date petroleum leak reported to MPCA  
 Yes  No  
0 cubic yards Total amount of contaminated soil excavated at this site  
72000 ppm Range of soil contamination concentration (total hydrocarbons)  
1.8 ft of ppb Range of groundwater contamination concentration (total hydrocarbons)  
Free Product

**III. ASSIGNMENT CERTIFICATION / TERMINATION**

- CHECK ALL THAT APPLY:
- Petrofund Assignment Agreement for this application has been executed (attach original of new assignment form)  
 Assignment form is already on file with the Department of Commerce  
 List Assignees:  
 Not applicable

#### IV. APPLICATION PHASE

Check appropriate box and complete the information requested for the box checked (*see Application Guide for further information*)

- Prerenovation site assessment  
 \_\_\_\_\_ / \_\_\_\_\_ Date of assessment report  
 \_\_\_\_\_ / \_\_\_\_\_ Date of property sale, if applicable

- Phase 1      **Soil** Corrective Action Costs or Remedial Investigation Costs  
 \_\_\_\_\_ / \_\_\_\_\_ Date of MPCA soil treatment letter (*attach copy*)

- Phase 2      Installation Costs of MPCA-approved Soil or Groundwater Monitoring and System Maintenance Costs  
 \_\_\_\_\_ / \_\_\_\_\_ Date of CCAP/CAD approval letter (*attach copy*)  
 \_\_\_\_\_ / \_\_\_\_\_ Date of MPCA site closure letter (*attach copy*)  
 Installation of recovery wells and a Free Product Recovery System was approved 11/3/98.

#### V. SOURCE AND CAUSE

What was the source and cause of the petroleum release at this site? (*see Application Guide*) Likely shift in ground causing a break in a connection.

How was the release discovered? Via weekly inventory control testing

If the release was not reported to the MPCA within 24 hours of discovery, state the reason why:

To the best of your knowledge, list all persons other than the applicant who were owners or operators of the tank during or after the petroleum release: none

- Yes  No Did any of the persons listed above incur corrective action costs related to this petroleum release?  
 If yes, list name(s) and address(es) if known:

#### VI. TYPE OF REMEDIATION SYSTEM

Please check the type of soil or groundwater remediation system used at this site or projected for it.

- | Soil Remediation Technologies  | Groundwater Remediation Technologies   |
|--|--|
| <input type="checkbox"/> Biopiles <input type="checkbox"/> Bioventing <input type="checkbox"/> Incineration <input type="checkbox"/> Landfarming | <input type="checkbox"/> Air sparging <input type="checkbox"/> Biosparging <input type="checkbox"/> Dual phase extraction  |
| <input type="checkbox"/> Low-temperature thermal desorption <input type="checkbox"/> Soil vapor extraction                                       | <input type="checkbox"/> In-situ groundwater bioremediation <input type="checkbox"/> Natural attenuation   |
| <input type="checkbox"/> Soil washing <input type="checkbox"/> Natural attenuation   | <input checked="" type="checkbox"/> Pneumatic Dedicated Free Product Recovery Pump<br><input checked="" type="checkbox"/> Vacuum extraction of free product from monitoring wells. |

#### VII. COMPETITIVE BIDDING

List all written bids/proposals obtained to perform corrective action at this site (*attach additional sheets if necessary*).

Attach copies of all signed and dated bids/proposals.

	Bidder Selected*	Name	Amount of Bid	Date of Bid	Task
Consultants	<input type="checkbox"/>	Arden Environmental	n/a		
Contractors	<input type="checkbox"/>	WORK DONE PURSUANT TO BID WAIVERS - SEE ATTACHED			
	<input type="checkbox"/>				
	<input type="checkbox"/>				
	<input type="checkbox"/>				

\*If lowest bid/proposal was not selected, explain that decision on a separate sheet.

## VIII. ' MPC A TANK INFORMATION AND COMPLIANCE

Yes  No Have you submitted an underground storage tank audit?

- A. Underground Storage Tanks. Complete the following information to reflect the status of your underground storage tanks at the time the release was discovered. Refer to the documents "**Do Underground Storage Tank and Piping Requirements Apply to Your Petroleum Tank?**" and "**What Do You Have to Do?"/"When Do You Have to Act?"** to determine the applicability of registration, leak detection, corrosion protection, and spill/overfill protection requirements.

If you are unsure how tank rules apply to your tanks, please call the UST Compliance and Assistance Unit at (612) 297-8679.  
Please tell the receptionist you have questions about this form.

(List all tanks at the site. Please attach additional sheets if necessary.)

Tank #	Petroleum Product	Capacity	Tank Material	Date Installed	Date Registered	Date Removed (if applicable)
1	Unleaded Regular	10,000	Fiberglass	8/95	8/95	n/a
2	Unleaded Regular	10,000	Fiberglass	8/95	8/95	n/a
3	Unleaded Mid	6,000	Fiberglass	8/95	8/95	n/a
4	Unleaded Prem.	6,000	Fiberglass	8/95	8/95	n/a
5						

### TANKS

Tank #	Leak Detection (select method below)	Corrosion Protection (select method below)	Spill Bucket (Yes/No)	Overfill Protection (select method below)
1	#8	#2 – Fiberglass	Yes	#3 and #4
2	#8	#2 – Fiberglass	Yes	#3 and #4
3	#8	#2 – Fiberglass	Yes	#3 and #4
4	#8	#2 – Fiberglass	Yes	#3 and #4
5				

**Leak detection method**  
(select all that apply):

1. None
2. Inventory control plus annual tightness testing
3. Inventory control plus tightness testing every 5 years
4. Manual tank gauging
5. Manual tank gauging plus annual tightness testing
6. Manual tank gauging plus tightness testing every 5 years
7. Statistical inventory reconciliation (SIR)  
 Automatic tank gauging
8. Interstitial monitoring
9. Vapor monitoring
10. Ground water monitoring
11. Other (specify): \_\_\_\_\_
12. Other (specify): \_\_\_\_\_

**Corrosion protection method:**

1. None
2. Fiberglass, jacketed steel or composite tank
3. STI-P 3 tank
4. Anodes installed
5. Impressed current system
6. Lined tank
7. Other (specify): \_\_\_\_\_

**Overfill protection method:**

1. None
2. Ball float valve
3. Automatic shutoff  
 Audible alarm
4. Other (specify): \_\_\_\_\_

If tank tightness tests were performed, indicate dates of all tests: 8/95 – New Installation \_\_\_\_\_  
\_\_\_\_\_ \_\_\_\_\_ \_\_\_\_\_

## PIPING

	Pressurized Piping Leak Detection	Suction Piping Leak Detection
Tank #	Continuous Leak Detection <i>(select method below)</i>	Periodic Leak Detection <i>(select method below)</i>
1	#4	#5
2	#4	#5
3	#4	#5
4	#4	#5
5		

Continuous method:		Periodic method:	Suction leak detection method:	Corrosion protection method:
1.	None	1.	None	1. None
2.	Automatic flow restrictor	2.	Annual tightness test	2. Steel with anodes
3.	Automatic shutoff device	3.	Statistical inventory reconciliation (SIR)	3. Coated steel with anodes
4.	Continuous alarm	4.	Electronic line leak detector	4. Impressed current piping
		5.	Interstitial monitoring	5. Fiberglass or flexible piping
		6.	Groundwater monitoring	6. Groundwater monitoring

If piping tightness tests were performed, indicate dates of all tests: \_\_\_\_\_

n/a

Identify MPCA-certified tank removal contractor who performed tank excavation

# \_\_\_\_\_ Tank removal contractor's MPCA certification number

B. Aboveground Storage Tanks. Complete the following information to reflect the status of all aboveground tanks at this site at the time the release was discovered.

In describing your secondary containment, specify:

- ◆ materials used to construct both the base and the walls, including type and thickness of materials (e.g., 6" compacted clay; 30 mil HDPE; reinforced concrete slab floor/concrete block walls; none)
- ◆ how material specifications are known (e.g., permeability tests/dates, installation specifications)
- ◆ whether the volume of the secondary containment area is adequate for the contents of the largest tank (Yes/No)

Tank #	Contents	Capacity	Date Installed	Registered (Yes/No/Unk)	Description of Secondary Containment Walls <i>(Yes/No)</i>	Base <i>(Yes/No)</i>	Verification	Volume
1								
2								
3								

## IX. ELIGIBLE COSTS

10 / 1 / 98 to 10 / 31 / 98 Dates of work covered by invoices submitted with this application

- Yes  No Does this application contain costs listed as ineligible under Minn. Rule 2890.0071? (*see Application Guide*)  
 Yes  No Are any of the costs included in this application in dispute? If so, describe the disputed issue(s) on a separate sheet.

- Yes  No Are any of the costs included with this application subject to bankruptcy proceedings? If so, please describe the nature of the proceedings on a separate sheet.

- Yes  No Are ongoing corrective action costs expected at this site? If so, explain briefly below.

Type of Work	Approximate Cost
Remedial Investigation	\$ 20,000.00
	\$ _____
	\$ _____

Please provide a chronological description (including dates) of the clean-up activities covered on this application, including any special circumstances (*attach additional sheets if necessary*):  
\_\_\_\_\_  
\_\_\_\_\_

- Yes  No Has the applicant made a claim against any third party for costs for which the applicant is seeking reimbursement or for any costs associated with this release? If so, attach a separate sheet identifying all third parties and provide a copy of all correspondence between the applicant and third parties.

- Yes  No Is the applicant aware of any action the applicant committed or of any action committed by a consultant or contractor which may have caused or aggravated the contamination at this site? If so, please explain:  
\_\_\_\_\_  
\_\_\_\_\_

## X. INSURANCE

- A.  Yes  No Did the applicant have in effect one or more insurance policies at the time of the release?  
*If "No," skip to question D. If "Yes," proceed to the next question.*
- B.  Yes  No Was a claim filed for coverage of any of the costs for which the applicant is seeking reimbursement in this application? *If "Yes," skip to question C.*  
If "No," please explain why no claim was filed:  
\_\_\_\_\_
- (Skip to question D.)
- C.  Yes  No Did the insurer agree to cover your claim?  
If "Yes":  
■ State the amount of benefits received (or to be received) \$ \_\_\_\_\_  
■ Provide a copy of the insurance policy and the insurer's explanation of benefits.  
If "No":  
■ Provide a copy of the insurance policy and the insurer's letter explaining the reasons for denying your claim.
- D.  Yes  No Is the applicant aware of any other insurance policy, whether held by the applicant or another person, that could cover any of the eligible costs in this application? If so, please explain: \_\_\_\_\_

## XI. CONSULTANTS/CONTRACTORS

Complete the following for ALL contractors, subcontractors, consultants, engineering firms or others who performed corrective actions at this site and whose work is covered by invoices included in this application. (See Application Guide.)

Describe any relationship, financial or otherwise, between the applicant and anyone who performed work at this site:  
none

### Land Farmer/Compost Site or Thermal Treatment Facility

# \_\_\_\_\_ Petrofund Registration Number

County \_\_\_\_\_

Name of individual or firm: \_\_\_\_\_

Mailing Address: \_\_\_\_\_

(City) \_\_\_\_\_

(State) \_\_\_\_\_

(Zip) \_\_\_\_\_

Contact Person: \_\_\_\_\_

# \_\_\_\_\_ Petrofund Registration Number

Name of individual or firm: Arden Environmental Engineering, Inc.

Mailing Address: 3550 Lexington Avenue North, Suite 102, Shoreview, MN 55126

(City) \_\_\_\_\_

(State) \_\_\_\_\_

(Zip) \_\_\_\_\_

Contact Person: John Mills Day phone #: ( 651 ) 484-5415

### Consultants/Contractors (ATTACH ADDITIONAL PAGES IF NECESSARY)

# 2098 Petrofund Registration Number

Name of individual or firm: Arden Environmental Engineering, Inc.

Mailing Address: 3550 Lexington Avenue North, Suite 102, Shoreview, MN 55126

(City) \_\_\_\_\_

(State) \_\_\_\_\_

(Zip) \_\_\_\_\_

# \_\_\_\_\_ Petrofund Registration Number

Name of individual or firm: \_\_\_\_\_

Mailing Address: \_\_\_\_\_

(City) \_\_\_\_\_

(State) \_\_\_\_\_

(Zip) \_\_\_\_\_

# \_\_\_\_\_ Petrofund Registration Number

Name of individual or firm: \_\_\_\_\_

Mailing Address: \_\_\_\_\_

(City) \_\_\_\_\_

(State) \_\_\_\_\_

(Zip) \_\_\_\_\_

# \_\_\_\_\_ Petrofund Registration Number

Name of individual or firm: \_\_\_\_\_

Mailing Address: \_\_\_\_\_

(City) \_\_\_\_\_

(State) \_\_\_\_\_

(Zip) \_\_\_\_\_

## XII. ATTACHMENTS

The following attachments are included with this application (see Application Guide):

*Either A or B must be included:*

Attachment A Standardized Invoice Summary

Attachment C Small Business Owner Form

Contact Person: \_\_\_\_\_

Day phone #: ( ) \_\_\_\_\_

(State) \_\_\_\_\_

(Zip) \_\_\_\_\_

Attachment D Small Gasoline Retailer Form

Attachment E Combined Leaksite Costs Over \$250,000

### XIII. CERTIFICATION PAGE\* *(See Application Guide)*

#### APPLICANT SIGNATURE and NOTARIZATION (SIGNATURE AND NOTARIZATION REQUIRED)

If information contained in this application changes in any material way after this application is submitted to the Petrofund, I will immediately notify the Petrofund in writing of those changes.

I understand that the information used to support this application is subject to audit by the Minnesota Pollution Control Agency and the Minnesota Department of Commerce.

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate and complete.

I certify that if I have submitted invoices for costs that I have incurred but that remain unpaid, I will pay these invoices within 30 days of receipt of reimbursement from the Board. I understand that if I fail to do so, the Board may demand return of all or any portion of reimbursement paid to me and that if I fail to comply with the Board's demand, then the Board may recover the reimbursement, plus administrative and legal expenses in a civil action in District Court. I understand that I may also be subject to a civil penalty.

I further certify that I am authorized to sign and submit this application on behalf of YOCUM OIL CO., INC.

Corporation / ~~PETROFUND~~ Minnesota Petroleum Agency

Signature Tony Yocum  
Name (print/type) Tony Yocum  
Title CEO/President  
Date Signed 12/16/98

#### NOTARIZATION

Subscribed and sworn to before me this 16 day  
of December, 1998.  
Notary Public Soula A. Olson  
My commission expires 1/31/00

#### CONSULTANT SIGNATURE (SIGNATURE REQUIRED)†

I, John Mills, confirm that all costs claimed by Arden Environmental as a part of this  
(Individual name) (Consultant company)  
application are a true and accurate account of services performed. I further confirm that no costs submitted for inclusion on this application by my consulting company are ineligible as listed in Minn. Rule 2890.0071.

Consultant Signature \_\_\_\_\_ / \_\_\_\_\_ Title \_\_\_\_\_ / \_\_\_\_\_ Date \_\_\_\_\_

†Duplicate this section if more than one consultant signature is required.

#### APPLICATION PREPARER'S SIGNATURE (SIGNATURE REQUIRED)

Strusinski & Associates, P.A.

(Preparer's name) Denise D. Cavanaugh / Legal Assistant \_\_\_\_\_  
Preparer's Signature \_\_\_\_\_ / \_\_\_\_\_ Cavanaugh Title \_\_\_\_\_  
Date 1/5/99

\* NOTE: SUBMIT CERTIFICATION PAGE CONTAINING ORIGINAL SIGNATURES.

Please send this application and accompanying documents to:

MINNESOTA DEPARTMENT OF COMMERCE - PETROFUND  
133 EAST SEVENTH STREET  
ST. PAUL, MN 55101-2333  
(651) 297-1119 / (651) 297-4203

THIS APPLICATION IS EFFECTIVE JULY 1, 1998 - JUNE 30, 1999

**XIII. CERTIFICATION PAGE\* (See Application Guide)**

**APPENDIX SIGNATURE AND NOTARIZATION / SIGNATURE AND NOTARIZATION REQUIRED**

If information contained in this application changes in any material way after this application is submitted to the Petrofund, I will immediately notify the Petrofund in writing of those changes.

I understand that the information used to support this application is subject to audit by the Minnesota Pollution Control Agency and the Minnesota Department of Commerce.

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate and complete.

I certify that if I have submitted invoices for costs that I have incurred but that remain unpaid, I will pay these invoices within 30 days of receipt of reimbursement from the Board. I understand that if I fail to do so, the Board may demand return of all or any portion of reimbursement paid to me and that if I fail to comply with the Board's demand, then the Board may recover the reimbursement, plus administrative and legal expenses in a civil action in District Court. I understand that I may also be subject to a civil penalty.

I further certify that I am authorized to sign and submit this application on behalf of YOCUM OIL CO., INC.

NOTARIZATION

卷之三

Dare Signed  
My commission expires

**CONSULTANT SIGNATURE (SIGNATURE REQUIRED)†**

I, John Mills (Individual name), confirm that all costs claimed by Arden Environmental (Consultant company) as a part of this application are a true and accurate account of services performed. I further confirm that no costs submitted for inclusion on this application by my consulting company are ineligible as listed in Minn. Rule 2890.0071.

Consultant Signature

<sup>†</sup>Duplicate this section if more than one consultant signature is required

APPLICATION PREPARER'S SIGNATURE (SIGNATURE REQUIRED)

**Strusinski & Associates, P.A.**

By: \_\_\_\_\_ / Legal Assistant

\* NOTE: SUBMIT CERTIFICATION PAGE CONTAINING ORIGINAL SIGNATURES

*Please send this application and accompanying documents to:*

MINNESOTA DEPARTMENT OF COMMERCE - PETROFUND

ST. PAUL, MN 55101-2333  
(651) 297-1119 / (651) 297-4203

THIS APPLICATION IS EFFECTIVE JULY 1, 1998 - JUNE 30, 1999

## **ATTACHMENT A** **STANDARDIZED INVOICE SUMMARY**

Please use this form if the costs you are submitting for reimbursement have been invoiced to you on the standardized invoice forms prescribed by the Petrofund Board. **This attachment must accompany your application if you entered into a contract on or after October 6, 1995.**

For each standardized invoice form you are submitting with this application, enter the Grand Total from the Actual Invoice Amount column on the corresponding line in the box below. Add these numbers together, subtract the amount of insurance reimbursement you have received, and multiply the resulting total by the appropriate reimbursement rate.

### **STANDARDIZED INVOICE SUMMARY**

Preremoval Site Assessment .....	\$ _____
Underground Storage Tank Removal Assessment .....	\$ _____
Initial Site Assessment.....	\$ <u>2,425.00</u>
Additional Site Assessment.....	\$ _____
Remedial Investigation / Corrective Action Design Report.....	\$ _____
Remedial Design / Maintenance .....	\$ _____
Contractor Services .....	\$ _____
Tank Removal .....	\$ _____
Interest.....	\$ _____
<b>TOTAL.....</b>	<b>\$ <u>2,425.00</u></b>
Insurance Reimbursement (subtract) - \$( <u>0.00</u> )	= \$ <u>2,425.00</u>
	x 90%*
	<b>\$ <u>2,182.50</u></b>

\* If a different reimbursement rate applies, calculate at that rate. See Application Guide.

☞ Please attach a copy of a site map that shows the former tank basin, the excavation area, and any on-site structures. If new tanks were installed, the map also should show their sizes and location(s). The site map should also identify the location of any soil borings and monitoring wells on the property.

- Tank removal costs are eligible only to those applicants that are small gasoline retailers or small business owners as defined in Minn. Stat. §115C.09, Subd. 3f and 3g.



*Arden Environmental Engineering, Inc.*

3550 Lexington Ave. North, Suite 102, Shoreview, MN 55126  
(651) 484-5415, Fax (651) 484-5568

RECEIVED

January 13, 1999

JAN 15 1998

Richard Newquist  
Project Manager  
Tanks and Emergency Response Section  
Minnesota Pollution Control Agency  
520 Lafayette Road N  
St. Paul, MN 55155-4194

MPCA, Metro District  
Site Remediation

**RE: Jordan Texaco - Leak 11991**

Dear Richard:

Enclosed is MPCA fact sheet 3.4, the "Free Product Recovery Report" Worksheet.

If you have any questions, please call me at (651) 484-5415


Sincerely,

A handwritten signature in black ink that appears to read "John Mills".

John Mills, P.E.  
Arden Environmental Engineering, Inc.

cc: Donna Strusinski - Strusinski and Associates

Tom Greene, P.E. - Applied Engineering



## FREE PRODUCT RECOVERY REPORT WORKSHEET

Fact Sheet 3.4  
April 1996

The completion and submittal of this worksheet fulfills the federal (U.S. Environmental Protection Agency) requirement to report to the Minnesota Pollution Control Agency (MPCA) regarding interim product recovery actions within 45 days of free product discovery. For further information on your obligations regarding free product, consult fact sheet 3.3 "Free Product: Evaluation and Recovery."

LEAK # 11991

Site name: Jordan Texaco  
Location: 255 Triangle Lane, Jordan MN

1. Free product discovery date: 11/2/98  
discovery time: 11:15 AM
2. You are required to report free product within 24 hours of discovery by calling the State Duty Officer at 612/649-5451 or 1-800/422-4798.

Call date: 11/3/98  
Call time: 9:00 AM  
Contact person: Richard Newquist

3. Circumstances of free product discovery (e.g., underground storage tank removal, during routine monitoring well sampling, etc.).

Discovered during placement of monitoring well MW-2. Wells were placed at the site for the express purpose of locating free product which we expected to see on site. Investigation was pursued at the direction of Richard Newquist at the MPCA.

4. Product type: Gasoline
5. Free product thickness: MW-2 - 1.5 ft., MW-3 1.8 ft.

If the thickness is greater than 0.1 foot, you are required to recover it and submit the worksheet for MPCA review as part of the "Remedial Investigation Report Form" fact sheet 3.24 within 90 days of product discovery date.

Free Product Recovery Report Worksheet  
Page 2  
April 1996

6. If product thickness is less than 0.1 foot or if an automated free product recovery system is required but not yet installed, describe the method of interim free product recovery.

A free product system, employing pneumatic free product recovery pumps, was installed 12/1/98. During the interim, a vacuum truck was used to evacuate both wells containing free product, approximately twice per week.

Details of volume recovered via the vacuum truck are:

Date	MW-2 Water Product	MW-2 Water Product	MW-3 Water Product	MW-3 Water Product
11/11/98	330	61	391	12
11/13/98	144	31	86	1
11/17/98	106	24	69	0
11/20/98	115	14	53	17
<b>Total</b>	<b>695 gal</b>	<b>130 gal</b>	<b>599 gal</b>	<b>30 gal</b>

Details of volume recovered via the free product recovery system are:

Date	Product
12/14/98	505
12/18/98	475
<b>Total</b>	<b>980 gal</b>

7. Volume recovered: 1,140 gallons  
date: (see above)

Free product recovery system continues to operate in site

8. Relevant observations concerning recharge rate of free product or expected volume present:

During each of the vacuum truck withdrawals of product, free product thickness was measured in the wells. Results are:

Date	MW-2 Before After	MW-3 Before After	MW-3 Before After	
11/11/98	1.65 ft	0.1 ft	1.80 ft	0.25 ft
11/13/98	1.30	0.7	1.55	0.40
11/17/98	1.40	0.40	1.50	0.40
11/20/98	1.20	0.35	1.55	0.35

Wells did not go dry during vacuum pump-out.

On 12/11/98 Free Product thickness was measured in the wells.

MW-2 1.30 feet  
MW-3 1.40 feet

9. Obvious nearby receptors, including basements, utilities, water wells, etc.

A 500 foot walking tour was conducted around the site. No obvious receptors are present.

10. Person preparing this report: John Mills  
date: 12/21/98

Send this Free Product Recovery Report to:

(Project Manager)  
Minnesota Pollution Control Agency  
Tanks and Emergency Response Section  
520 Lafayette Road North  
St. Paul, Minnesota 55155

Upon request, this document can be made available in other formats, including Braille, large print and audio tape.  
TTY users call 612/282-5332 or Greater Minnesota 1-800/657-3864 (voice/TTY).

Printed on recycled paper containing at least 10 percent fibers from paper recycled by consumers.