

**WETLAND DETERMINATION DATA FORM - North Central and Northeast Region**

Project/Site: SPP City/County: Wadena Sampling Date: 2016-07-25  
 Applicant/Owner: Enbridge State: Minnesota Sampling Point: u-138n33w1-aa1  
 Investigator(s): DPT, MGH Section, Township, Range: S1, T138N, R33W  
 Landform (hillslope, terrace, etc.): Rise Local Relief (concave, convex, none): VL Slope (%): 0-2%  
 Subregion (LRR or MLRA): \_\_\_\_\_ Latitude: 46.7930752085... Longitude: -94.78910095... Datum: NAD83  
 Soil Map Unit Name: 564 NWI Classification: N/A  
 Are climatic/hydrologic conditions on the site typical for this time of year? (if no, explain in Remarks): No  
 Are Vegetation No, Soil No, or Hydrology No significantly disturbed? Are "Normal Circumstances" present? Yes  
 Are Vegetation No, Soil No, or Hydrology No naturally problematic? (If needed, explain any answers in Remarks)

**SUMMARY OF FINDINGS - Attach site map showing sampling point locations, transects, important features, etc.**

Hydrophytic Vegetation Present?	<u>No</u>	<b>Is the Sampled Area</b>
Hydric Soil Present?	<u>No</u>	<b>within a Wetland?</b> <span style="float:right;"><u>No</u></span>
Wetland Hydrology Present?	<u>No</u>	If yes, optional Wetland Site ID: _____
Remarks: (Explain alternative procedures here or in a separate report.) No digging, existing forest road, potential buried utilities. Precipitation above normal based on WETS analysis.		

**HYDROLOGY**

<b>Wetland Hydrology Indicators:</b>	<u>Secondary Indicators (minimum of two required)</u>
<u>Primary Indicators (minimum of one is required; check all that apply)</u>	
<input type="checkbox"/> Surface Water (A1)	<input type="checkbox"/> Surface Soil Cracks (B6)
<input type="checkbox"/> High Water Table (A2)	<input type="checkbox"/> Drainage Patterns (B10)
<input type="checkbox"/> Saturation (A3)	<input type="checkbox"/> Moss Trim Lines (B16)
<input type="checkbox"/> Water Marks (B1)	<input type="checkbox"/> Dry-Season Water Table (C2)
<input type="checkbox"/> Sediment Deposits (B2)	<input type="checkbox"/> Crayfish Burrows (C8)
<input type="checkbox"/> Drift Deposits (B3)	<input type="checkbox"/> Saturation Visible on Aerial Imagery (C9)
<input type="checkbox"/> Algal Mat or Crust (B4)	<input type="checkbox"/> Stunted/Stressed Plants (D1)
<input type="checkbox"/> Iron Deposits (B5)	<input type="checkbox"/> Geomorphic Position (D2)
<input type="checkbox"/> Inundation Visible on Aerial Imagery (B7)	<input type="checkbox"/> Shallow Aquitard (D3)
<input type="checkbox"/> Sparsely Vegetated Concave Surface (B8)	<input type="checkbox"/> Microtopographic Relief (D4)
<input type="checkbox"/> Water-Stained Leaves (B9)	<input type="checkbox"/> FAC-Neutral Test (D5)
<input type="checkbox"/> Aquatic Fauna (B13)	
<input type="checkbox"/> Marl Deposits (B15)	
<input type="checkbox"/> Hydrogen Sulfide Odor (C1)	
<input type="checkbox"/> Oxidized Rhizospheres on Living Roots (C3)	
<input type="checkbox"/> Presence of Reduced Iron (C4)	
<input type="checkbox"/> Recent Iron Reduction in Tilled Soils (C6)	
<input type="checkbox"/> Thin Muck Surface (C7)	
<input type="checkbox"/> Other (Explain in Remarks)	

<b>Field Observations:</b>	
Surface Water Present? <u>No</u> Depth (inches) _____	<b>Wetland Hydrology Present?</b> <u>No</u>
Water Table Present? _____ Depth (inches) _____	
Saturation Present? <u>No</u> Depth (inches) _____ (includes capillary fringe)	

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:  
 No digging, could not confirm/deny water table.





Site Photograph 1

Sampling Point: u-138n33w1-aa1



Latitude: 46.7930764239717

Cowardin Classification: \_\_\_\_\_

Longitude: -94.789097439586

Circular 39: \_\_\_\_\_

Direction: west

Eggers & Reed: \_\_\_\_\_

Remarks:  
upland

Site Photograph 2

Sampling Point: u-138n33w1-aa1



Latitude: 46.7930773878906

Cowardin Classification: \_\_\_\_\_

Longitude: -94.7890945897389

Circular 39: \_\_\_\_\_

Direction: east

Eggers & Reed: \_\_\_\_\_

Remarks:  
upland