

WETLAND DETERMINATION DATA FORM - North Central and Northeast Region

Project/Site: SPP City/County: Carlton Sampling Date: 2016-09-06
 Applicant/Owner: Enbridge State: Minnesota Sampling Point: w-47n21w09-aa1
 Investigator(s): DPT, ZCW Section, Township, Range: T9, S47N, R21W
 Landform (hillslope, terrace, etc.): Depression Local Relief (concave, convex, none): CC Slope (%): 0-2%
 Subregion (LRR or MLRA): _____ Latitude: 46.5783507982... Longitude: -92.99555095... Datum: NAD83
 Soil Map Unit Name: 21C NWI Classification: N/A
 Are climatic/hydrologic conditions on the site typical for this time of year? (if no, explain in Remarks): No
 Are Vegetation No, Soil No, or Hydrology No significantly disturbed? Are "Normal Circumstances" present? Yes
 Are Vegetation No, Soil No, or Hydrology No naturally problematic? (If needed, explain any answers in Remarks)

SUMMARY OF FINDINGS - Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	<u>Yes</u>	Is the Sampled Area within a Wetland?	
Hydric Soil Present?	<u>Yes</u>		<u>Yes</u>
Wetland Hydrology Present?	<u>Yes</u>		If yes, optional Wetland Site ID: <u>w-47n21w09-aa</u>
Remarks: (Explain alternative procedures here or in a separate report.) Existing forest road, no digging, potential buried utilities. Precipitation above normal based on WETS analysis.			

HYDROLOGY

Wetland Hydrology Indicators:		Secondary Indicators (minimum of two required)
Primary Indicators (minimum of one is required; check all that apply)		
<input type="checkbox"/> Surface Water (A1)	<input type="checkbox"/> Water-Stained Leaves (B9)	<input type="checkbox"/> Surface Soil Cracks (B6)
<input type="checkbox"/> High Water Table (A2)	<input type="checkbox"/> Aquatic Fauna (B13)	<input type="checkbox"/> Drainage Patterns (B10)
<input type="checkbox"/> Saturation (A3)	<input type="checkbox"/> Marl Deposits (B15)	<input type="checkbox"/> Moss Trim Lines (B16)
<input type="checkbox"/> Water Marks (B1)	<input type="checkbox"/> Hydrogen Sulfide Odor (C1)	<input type="checkbox"/> Dry-Season Water Table (C2)
<input type="checkbox"/> Sediment Deposits (B2)	<input type="checkbox"/> Oxidized Rhizospheres on Living Roots (C3)	<input type="checkbox"/> Crayfish Burrows (C8)
<input type="checkbox"/> Drift Deposits (B3)	<input type="checkbox"/> Presence of Reduced Iron (C4)	<input type="checkbox"/> Saturation Visible on Aerial Imagery (C9)
<input type="checkbox"/> Algal Mat or Crust (B4)	<input type="checkbox"/> Recent Iron Reduction in Tilled Soils (C6)	<input type="checkbox"/> Stunted/Stressed Plants (D1)
<input type="checkbox"/> Iron Deposits (B5)	<input type="checkbox"/> Thin Muck Surface (C7)	<input checked="" type="checkbox"/> Geomorphic Position (D2)
<input type="checkbox"/> Inundation Visible on Aerial Imagery (B7)	<input type="checkbox"/> Other (Explain in Remarks)	<input type="checkbox"/> Shallow Aquitard (D3)
<input type="checkbox"/> Sparsely Vegetated Concave Surface (B8)		<input type="checkbox"/> Microtopographic Relief (D4)
		<input checked="" type="checkbox"/> FAC-Neutral Test (D5)

Field Observations:		Wetland Hydrology Present?	<u>Yes</u>
Surface Water Present?	<u>No</u>	Depth (inches)	_____
Water Table Present?	_____	Depth (inches)	_____
Saturation Present?	<u>No</u>	Depth (inches)	_____
(includes capillary fringe)			

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:
No digging, could not verify water table.

Site Photograph 1

Sampling Point: w-47n21w09-aa1



Latitude: 46.5783323580833

Cowardin Classification: PEM

Longitude: -92.9955419898899

Circular 39: 1

Direction: west

Eggers & Reed: Seasonally Flooded Basin

Remarks:

Site Photograph 2

Sampling Point: w-47n21w09-aa1



Latitude: 46.5783310169788

Cowardin Classification: PEM

Longitude: -92.9955259804549

Circular 39: 1

Direction: east

Eggers & Reed: Seasonally Flooded Basin

Remarks:

Empty rectangular box for remarks.