## TSR040 Remark. Listing For Leaksite = Report Date: May 27, 1998

Leaksite ID# 3388
CINEMA PROFESSIONAL BUILDING
Site Name

Tank Facility ID 14229
ROBIN VANVALKENBURG
Responsible Party

### LEAKSITE REMARKS

closed once Find out if 12/17/92: (JME) I spoke w/MJC about records) e we have r f tank has if so, sit site can be rec'd information regarding the unus closed. this site He feels unused that (abandonment fuel site 011 can TSU pg e

2/9/93:(JME)Called Rob VanValkenberg (4 29 letter - Rob was out - left message (441-8260) to see ge for him to call me. ı. É Q rec'd 12

need documentation/response of the letter to Rob at the 3/16/93:(JME) who said that the lette 3/96 JTC: (JME) Called Н the am UST was going to send out first and info they can offer. called (828-8400). Will Rob V. abandoned in place - filled w/foam. Ise to 12/29 letter. She said I should he Cinema Professional Building. requesting any fax copy woman said W (P

7/17/96 7/22/96 JTC: JTC: response g tank Recv'd Rob called abandonment in place. for this and mentioned lled (828-8400). fax of info I w I was looking . Since once look this for. for tank was previous corresp. Fax closure contained info. site info SPA

could be this looking site for closed, <u>ը</u> sed, I am going to considered closed CLOSE this site. recv'd the Therefore,

05/27/98 sent to archives kl

End of Remarks

Page: 1

CINEMA PROFESSIONAL Site Name Leaksite HQI 3388 BUILDING

Responsible ROBIN VANVALKENBURG Tank Facility Party N

#### LEAKSITE REMARKS

closed once we have rec'd information Find out if tank has been removed or records) - if so, site can be closed. 12/17/92: (JME) I spoke w/MJC about information regarding the unused fuel oil removed or properly abandoned (abandonment this site. Не feels that site can be UST

2/9/93:(JME)Called Rob VanValkenberg 29 letter - Rob was out - left messaç left message (441-8260) to see ye for him to call me. if he'd rec'd 12

of the 7/3/963/16/93: (JME) Called Rob V. a who said that the UST was ak need documentation/response letter to Rob at the abandoned in place -se to 12/29 letter. again to 12/29 letter. She said I should fax copy Cinema Professional Building. send out first wakeup letter requesting any out for the day - spoke ... filled w/foam. മ  $\vdash$ woman said

JTC: response I am goiing to and info t

7/22/96 7/17/96 JIC: could be closed, this site is cons looking tank onse and info they can offer.
Rob called (828-8400). Will
Recv'd fax of info I was loo for this abandonment in place. sed, I am going to considered closed. and mentioned of am actioned of am actioned of a mentioned of a me closed. was looking for. lace. Since all once close look this this for tank previous corresp. w was recv'd the site site. Fax contained info closure Therefore, info. was

Remarks

Page  $\mathbb{E} \vdash$ 

LEAK REMARKS

Leak ID: 3388

Site Name: CINEMA PROFESSIONAL BUILDING Site City: ELK RIVER

12/17/92:(JME)I spoke w/MJC about this site. He feels that site can be closed once we have rec'd information regarding the unused fuel oil UST. Find out if tank has been removed or properly abandoned (abandonment records) - if so, site can be closed.

2/9/93:(JME)Called Rob VanValkenberg (441-8260) 29 letter - Rob was out - left message for him t left message to call to see if he'd rec'd 12/ me.

3/16/93:(JME)Called Rob V. again - out for the day - spoke to a woman who said that the UST was abandoned in place - filled w/foam. I said we need documentation/response to 12/29 letter. She said I should fax copy of the letter to Rob at the Cinema Professional Building.

6/3/2) De Luc Se	Stage of the discussion of the stage of the	201.121	Talto De John Diche	PROJECT LOG SHEET  DATE STAFF WF: ACTED  MEMBER COLLACTED  ACTED  1/8/4 JR  539-1423 16
yh sels our reasons in withing what when was usequate - asking on a know of she had questions as weller additional written info.	Soith & John Colley Sue it surther wint. Sugh & John we feel amended side upont see he many added 98/91) is not meessay. asked he bet me know of	ours save by from a consider that the sail of the sail the sail of	Me Lancing	ACTIVITY (phone number, letter, meeting, etc.)  ACTIVITY (phone number, letter, meeting, etc.)  Refer called to ask when result will be  persual - they want to sell the property  I will him I will the year on (0/31 from  Part he should contact mital re hura-  rand hime.



# Minnesota Pollution Control Agency

520 Lafayette Road, Saint Paul, Minnesota 55155-3898
Telephone (612) 296-6300



December 14, 1990

MC. Robin VanValkenberg 12400 Ridgewood Drive Northwest Elk River, Minnesota 55330

Dear Ms. VanValkenberg:

Site Petroleum Tank Release Remedial Investigation ID#: Cinema Professional Building, 657 Main Street, Elk River LEAK00003388

summarizing the results of the soil boring investigation at the above-referenced site. An MPCA hydrologist has reviewed the report. The following comments are The Minnesota Pollution Control Agency (MPCA) staff has received the Liesch Associates (Liesch) report dated October 1990, documenting and The Minnesota Pollution Control Agency based on this review: The following comments are received the Bruce A.

- At this time, emanating from the investigation has been conducted. the source of the contamination does not appear to be former hardware store site where most of the remedial
- 2. The MPCA staff agrees with the Liesch recommendation to abandon the unused fuel oil tank in place if removal is not possible. soon as possible. This should take place
- ω site. However, if additional investigation of off-site sources shows that problem persists at this site, additional corrective action may be required in the future. The MPCA will the area of contamination as well as the drilling constraints at the require no additional investigation due to the limited extent shows that a

hydrologist If you have any questions or require additional information, please contact MPCA Mitch Chiodi at 612/643-3460 or me at 612/643-3589.

Sincerely,

Deques Comans

Dagmar Romano Project Leader Tanks and Spills Section Hazardous Waste Division

DR: kra

John Lichter, Bruce Al Liesch Associates, Inc., Plymouth

Site Review

VAX FILE: cinema.txt

Date: 11/30/90

Hydrogeologist: M. Chiodi

Site Name: Cinema Professional Building

Address: 657 Main Street, Elk River, MN

Leak Number: 00003388

Name of Report: Remedial Investigation

unused fuel oil tank inplace tive action may be off site sources nation found and drilling constraints. require no additional investigation due Αt The source of the contamination does not appear to be emanating hardware store site were most of the remedial investigation has Liesch Associates, The MPCA staff has this time, the MPCA agrees with the show that a problem persists required Inc. (Liesch) reviewed the in if removal the future. remedial investigation report by Bruce A associated with the above referenced site. Liesch recommendation is not to the However, at this possible, limited areal extent of contamiif additional investigation of site, additional and the MPCA will to abandon the been conducted. from the former correc-



# BRUCE A. LIESCH ASSOCIATES, INC.

HYDROGEOLOGISTS . ENGINEERS . ENVIRONMENTAL SCIENTISTS

13400 15th Avenue No. • Plymouth, MN 55441 • 612-559-1423 • FAX No: 559-2202

ECEIVE

November 16, 1990

MPCA, HAZARDOUS WASTE DIVISION

Ms. Dagmar Romano, Project Manager Tanks and Spills Unit Minnesota Pollution Control Agency 520 Lafayette Road St. Paul, MN 55155

RE: LEAK #3388 - 657 Main Street, Elk River, Minnesota

Dear Ms. Romano:

petroleum release. We intend to conduct and complete necessary work on-site to comply completion of your review. Please contact me if you have any questions. Thank you. efforts to cooperate with the City and Mr. VanValkenberg and look forward to the corrective action plan have been submitted to MPCA for this site. We appreciate MPCAs with the MPCA request of October 25, 1990. I am writing on behalf of Mr. Robin VanValkenberg concerning the investigation of this The remedial investigation and proposed

Sincerely,

cc: Mr. Robin VanValkenberg

Mr. Steve Rohlf

maw:erltr11-16

5/20/90 Off.

C88-304 PRELIMINARY FOUNDATION
INVESTIGATION
Jenne Square Shopping
Mall
65 Main Street
Elk River, MN

WINKELMAN BUILDING CORPORATION

December 9, 1988

10



CONSULTING ENGINEERS/
GEOTECHNICAL AND MATERIALS

Reply to address/phone #:

St Cloud, (612) P.O. . Box 189 MN 56302 253-9940

MINNESOTA Minneapolis

Hibbing St. Cloud Rochester. St. Paul

NORTH DAKOTA Bismarck Williston Minot

AFFILIATED OFFICES

MONTANA Billings Bozeman

ILLINOIS Chicago

J.S. Braun, P.E.
Cameron G. Kruse, P.E.
Geo. D. Kluempke, P.E.
Paul H. Anderson
David R. Hausler, P.E.
Roger V. Blomquist, Ph.D.
James J. Craig, Jr., P.E.
Dale R. Allen, P.E.
Wm. M. Weyrauch, P.E.
Thomas R. Blumberg
Michael M. Heuer, P.E.
Kurt E. Dvorak
Norman, E. Hall

AFFILIATED COMPANIES
Braun Environmental Braun Pavement Technologies, Inc.

Ray A. Huber, P.E. William K. Cody, P.E.

December φ ` 198

P.O. Winkelman Box 1144 Building Corporation

St. Cloud, MN 56302

Attn: Mr. Terry Duffy

RE: C88-.304 PRELIMINARY FOUNDATION

Jenne Square Mall INVESTIGATION Shopping

65 Main Str Elk River, Main Street

Dear Mr. Duffy:

you consisted of s groundwater investig Shopping Mall in Elk recently 9 November completed the investigation seven 7, even standard penetration proposed building area. 1988. River, for preliminary 0 date, the This proposed our work was authorized subsurface investigation ion test bori Jenne soils borings Square i by has

locations extending from two to possibly eight feet the concrete surface. The fill soils were genunderlain by poorly graded sands which were very loose to medium dense. underlain concrete slab was encountered at the building generally generally ig site, le boring e boring beneath

are encountered,
observations; Log also of t Boring included in penetration along with sheets with our engineering the attached report. indicating resistances the various and recommendations water soil strata level

₩e evaluate the preliminary # the have our sands pleasure to be of service to you in ry subsurface soils and groundwater scheduled additional field tests bearing capacity at this site. / and settlement more detailed characteristics to report providing this investigation. more fully

December 9, 1988

issued when the regarding the Jeff Elliott a e services conducted to date, at 253-9940. you please have questions ase contact Mr.

Very truly yours,

BRAUN ENGINEERING TESTING, INC.

Project Engineer

George D. Williamoke

George D. Wluempke, Vice President

보.

RJE/GDK/bjb

. 00:

Braun

Mpls.



E: C88-304 PRELIMINARY FOUNDATION
INVESTIGATION

Jenne Square Shopping

Mall

65 Main Street

Elk River, Mn

## A. INTRODUCTION:

- conditions evaluating Purpose: in the the The purpose proposed building current of our investigation was subsurface area soils and to assist groundwater Ín
- recommendations. penetration 20 1/2 feet. report Scope: test with the The addressing borings investigation results of which were our these borings consisted engineering taken to depths Of. we have seven analysis of 15 prepared standard 1/2 and ţο
- boring were taken locations Bore in the building area Hole Locations and Surface Elevations: are shown on the attached sketch. S requested by your firm. The borings The

elevation of 100.0 was assumed for this north of assumed surface bench mark, the elevation at project the site, at top of a the bore the sanitary sewer manhole Main Street holes were bench mark. intersection. referenced located ф an

The November sampling was Split Field 10, Barrel 1988, Investigation: in Sampling of accordance with a truck-mounted with ASTM D1586 Soils". The borings Using core were "Penetration Test and this auger conducted method, drill.



the need for jetting water. of the hollow-stem auger eliminated the driving of casing and increments soil strength characteristics. standard, 2-inch OD, split barrel advanced the feet 2½-foot below foot t 0 increments bore hole with the hollow-stem auger the Then a of the penetration were termination depth dot 140-pound hammer falling 0 fi to the 10-foot the hollow-stem auger. Soil samples were sampler recorded of each depth ω of the and are total 30 and generally taken penetration of inches drove to the desired The borings. an index at blows 5-foot of f

Visual and Manual Description of Soils." A copy of ASTM D2487 Classification System" visually 9 chief Soil Classifications: the field All in and manually samples were accordance classifications and ASTM D2488 classified in the field then returned to the laboratory with ASTM D2487 Soils encountered in the by a soils engineer "Recommended "Unified Practice by the borings Soils the S T

then auger, groundwater. probed immediately sample the bore with presence the Ín Level Measurements: H holes were 9 the backfilled hollow-stem addition, absence bottom of again probed of water was immediately auger the borings, Immediately after ĺn the and the depth to cave-in after withdrawal of noted. ground to the bore The borings taking holes check were the

#### B. RESULTS:

resistances identification and Log of, water the of level Boring various information sheets soil indicating strata, are attached. the the penetration depth Ηt should



transition and noted that the depths approximate. the depth of change likely varies horizontally. The shown as boundaries actual change may between the strata be more

- observed a extending to the termination original topsoil layer which extended to depth. at extending fill and poorly graded sand with silt fill beneath the concrete possible fill, void space and Soils Encountered: ST-7 sand surface fill The petroleum odor in the poorly graded sands to borings, depth. was encountered encountered possible beneath the two foot depth. and four ST-1 extending Αt foot the concrete extending fill was the The borings encountered a concrete slab and a void space depth. extending ST-4, encountered silty clayey sand 14 foot to depths ranging from 0.1 to 0.6 underlain In all the borings beneath the under the depth in boring to the Boring beneath the concrete the 8% foot depth. by what to the ST-5 15% to concrete; may encountered eight foot 20½ foot ST-3 bе Arrood
- eight resistances soils recorded t o BPF to be Penetration 3 6 Ín the in a very blows recorded poorly per Resistances: in the possible fill ranged from two loose to dense condition. foot (BPF) indicating these graded sands The ranged penetration from weight The cohesionless penetration resistances of hammer
- auger the hollow-stem auger. encountered to 17-foot probing Water Based depth Level the 9 bore Observations: when cave-in depths ranging In the remaining bore the holes probing probings, immediately the Groundwater was bore the moisture hole from five to ten after holes ST-6 removal of groundwater encountered content feet Was and



-4-

groundwater locations. coloration Of. level is the various likely near elevation 67± soils encountered, at the the current boring

and SPA groundwater may occur due variations construction report. Water level readings have other factors not relatively short under reported However, it must reviewed and the conditions planning herein. and evident at the time interpretations should Design to variations in rainfall, temperature, be noted that that fluctuations stated on the boring logs. been made drawings recognize in the borings at the the made and measurements the period of observation in the text of in the specifications possibilities level of were This times made this data and the

## C. ANALYSIS AND RECOMMENDATIONS:

Column loadings supported kips per column. outside four-story, pre-cast Available Design Criteria: nominal primarily are dimensions anticipated to be on the Λq concrete structure. interior of f The proposed building 71 by columns 140 and The structure order of feet exterior and 92 to 435 footings. will have will be a will be CR40#

elevation 78±. interior Ground floor column grade footings 18 anticipated will ç e be be at elevation 80±. situated at approximate The

fill, the project proposed possible fill, Suitability of site building area. S Ø an existing Existing Soils: void space In building addition, and very loose native sands The and directly adjacent borings þ primary encountered street ĺ'n



of limiting total settlement to less structural fill could result in adequate soil conditions capable footing grade pressure of at least 4,000 pounds per square foot, support for the proposed structure. stabilization Our initial calculations indicate existing soils to a O.f supporting column pads sized so as to exert program would would be required. depth of at least eight feet below be required to that a soil correction than 2 inches. In order Placement provide adequate to provide of subcutting of compacted soil

1937

information regarding: bearing pressuremeter steel-frame structure would reduce the loads. example, initiate bracing building you requested that stabilize these soils O.F. capacity and settlement characteristics are discussions changing foundations which would correction would require excavation below the existing The costs the developing other construction alternatives. tests to obtain more detailed information as to the excavation. tests the we conduct additional for those services appears to be high with structure will allow firms You subsequently requested that 9 from a precast provide temporary sheeting providing require เร 6 additional borings provide soil In addition, of f concrete to stabilization and perform the additional costs natural such you and

- the extent of soil correction required

.

1 50

- structural fill placement and compaction criteria
- bearing capacity of the various soils
- foundation, slabs and surrounding structures potential for settlement of the building

scheduled detailed for Wednesday, will then evaluation of the be provided. December 14, foundation criteria This 1988. additional testing for this

- groundwater construction encountered Groundwater Conditions: could likely be controlled utilizing sump ļ which one may boring bе location at elevation As encountered previously indicated, water during 67±. -sdwnd foundation
- approximately exception of 10, odors by chemical analysis is outside the present noted at the photoionization detector on November 11, 1988. transported sample appear Contaminated Soils: strong the sample mentioned above, all H-Nu readings to were 14 to 200 parts interval be those of petroleum. to our petroleum odors and visible at normal background levels. 15 1/2 foot per million. Ħ chemical laboratory During the boring of boring depth. ST-3 Although characterization All yielded and examined scope of work, split spoon dark staining The 14 to 15 ST-3 readings on November With the with samples o f these were 1/2 the an

which the contamination was noted, indicates that consistent The occurrence such tanks. This, coupled with the depth and property storage property owner, the surface of the water table from an off-site tanks there for contamination is likely coming with 40 on the premises. had been any above ground or underground of the years, the contamination Ms. concept and during Erma Jenne, of migration She that stated that Sea at the from an off-site asked by Mr. time of the water restricted there had she has in our opinion, table contaminants source Terry owned the gasoline r S source. area been 9

discussion Control Agency (MPCA) when contamination is (BRAUN) between requires on November Terry Duffy, notification 11, 1988, Doug o H Kr. Bergstrom (BRAUN), and the Duffy encountered. Minnesota Pollution instructed After BRAUN



643.8455-HAZOVE WOOD TO December 9. AFTA 16

Winkelman Building Corp. December 9, 1988

643 - 540 643. W 460 いまらられ ANN BIDWELL 517189

THURS: SPILLS - 643.3464

recommend Lafayette Road, opinion contamination that was observed by Mr. Bergstrom, and also of our Minnesota to notify that that you forward the MPCA. Pollution it was likely . S Paul, On November 14, 1988, Ms. Pat Chabot of the Control MN 55155. a copy of this report to her at coming Agency from an was notified of off-site source. the

しいのスクしっているのみなられた

#### D. GENERAL REMARKS:

construction and noting Such variations may result in additional foundation costs and necessary to make the construction. submitted D.1.Basis suggested attached sketch. Variations may occur between these borings nature and extent after soil borings performed at the locations indicated in this of that a contingency be provided for this Recommendation: performing on-site Ħ a re-evaluation of report variations are of which may the are based upon characteristics of The analysis the recommendations of this not observations encountered, the become and recommendations data any variations evident obtained it will purpose during until be on

foundation phases of the project. necessary observation and testing program for contemplated conformance To actual S permit correlation of the soil data obtained to date with recommended that we soil conditions continuing o E in this report and to the plans the construction professional encountered be retained to develop and perform the ф ф during responsibility the construction and concepts and specifications, the excavation originally for the to

construction, perform the professional recommended responsibility observations becomes and/or testing divided since o f



would those in doing conditions throughout the construction areas require encountered so, they assume responsibility for evaluating that a change in recommendations. in the borings or recognizing variations which are similar the to

- design specifications. recommendations. review, their recommendations recommendations changes report. proposed **D.2** final design and specifications to determine Plan Review: changes, æ intent in design may have had It is recommended that we be retained to structure will have been correctly communicated to has contained or misinterpretation or misapplication of not If we are not permitted to make this recommended as submitted to us This report Эď been liable for losses in this implemented any effect on the validity of the ıs 1 based report, and for preparation of this in the on the arising briefly review whether design of whether out you so 0 f those that and any
- exercised material engineers this area Level of Care: consistent or implied, under similar budget by members with that for of the is made. Services performed by the geotechnical and this level profession project and time restraints. O.H care and skill have currently been conducted in practicing No warranty, ordinarily



December 9, 1988

State of Minnesota. am a duly Registered Professional Engineer under the laws of the report was Professional prepared by me or under Certification: direct supervision and that I I hereby certify that this

R. Weff Elliott, P.E.

Registration Number: 19174

Date: December 9, 1988

MINNESOTA: Minneapolis, Hibbing, St. Cloud, Rochester, St. Paul

≱ply to:

LABORATORY TEST OF AGGREGATES

P.O. Box 189 St. Cloud, MN 56302

Project: C88-304

Bismarck, Williston & Minot, ND Billings & Bozeman, MT Chicago, IL Affiliated Offices:

Date: December 1, 1988

Reported To: Winkelman Building Corporation P.O. Box 1144 St. Cloud, MN 56302 Attn: Mr. Terry Duffy

FOUNDATION INVESTIGATION
Jenne Square Shopping Mail
65 Main Street
Elk River, MN

Copies To:

FIELD DATA

TW.

Sample #:

11-10-88

 $\triangleright$ 

Date Received:

Date

Sampled:

11-10-88

Date Tested:

11-30-88

Sample Location: Classification:

SP - POORLY GRADED SAND, fine to medium grained, with a trace of GRAVEL, brown.

Composite from boring ST-1, ST-6, & ST-7, at the 0 to 10 foot depth

LABORATORY DATA GRADATION

Sieve Size

#10

34 Passing 100 97 60 10 3.8

Specifications

#40 #100 #200

REMARKS:

. /

1.5 2.3

BRAUN ENGINEERING TESTING, INC.

R. Jeff Project Elliott, Engineer

MINNESOTA: Minneapolis, Hibbing, St. Cloud, Rochester, St. Paul

∍ply to:

LABORATORY TEST OF AGGREGATES

P.O. Box 189 St. Cloud, MN 56302

December 1, 1988

Date:

Project: C88-304 FOUNDATION INVESTIGATION
Jenne Square Shopping Mail
65 Main Street
Elk River, MN

Bismarck, Williston & Minot, ND Billings & Bozeman, MT Chicago, IL

Affiliated Offices:

Reported To: Winkelman Building Corporation P.O. Box 1144 St. Cloud, MN 56302 Attn: Mr. Terry Duffy

Copies To:

FIELD DATA

X

Sample #:

 $\boldsymbol{\omega}$ 

11-10-88

Date Received:

Date Sampled:

11-10-88

Date Tested:

11-29-88

Classification:

Sample Location:

SP - POORLY GRADED SAND, fine to medium grained, with a trace of GRAVEL, brown.

Composite from boring ST-2, ST-4, & ST-5, at the 0 to 10 foot depth

LABORATORY DATA GRADATION

Sieve Size

35 Passing

Specifications

#10 #40 #100 #200

.

100 95 49 5 2.4

REMARKS:

BRAUN ENGINEERING TESTING,

R. Jeff Project Elliott, Engineer

Bismarck, Williston & Minot, ND Billings & Bozeman, MT Chicago, IL

Affiliated Offices:

MINNESOTA: Minneapolis, Hibbing, St. Cloud, Rochester, St. Paul

∍ply to:

LABORATORY TEST OF AGGREGATES

P.O. Box 189

t. Cloud, MN 56302

Date: December 1, 1988

Project: C88-304

FOUNDATION INVESTIGATION
Jenne Square Shopping Mall
65 Main Street
Elk River, MN

Reported To: Winkelman Building Corporation P.O. Box 1144 St. Cloud, MN 56302 Attn: Mr. Terry Duffy

5.21

Copies To:

FIELD DATA

0

Sample

\*

Date

Sampled:

11-10-88

Date Received:

11-10-88

Date Tested:

11-30-88

Sample Classification: Location:

SP - POORLY GRADED SAND, medium to coarse GRAVEL, brown.
Boring ST-3, at the 0 to 10 foot depth sand,

with

10 foot depth

LABORATORY DATA GRADATION

Specifications


Sieve Size 1 1/2" 3/4" 3/8" #10 #100 #200 3-8 100 95 91 82 70 57 Passing

. ...


REMARKS:

BRAUN ENGINEERING TESTING, INC.

R. Jeff Project Elliott, Engineer P.E.



75.



....



37

11/29/88 C88-304 FOUNDATION Jenne Square ア 65 Main Street RIVET 32 INVESTIGATION shopping mall

RJE

Date:

Sante: 1"= 30'

(See Report and Standard	o Pia	tes foi	evai	uatio	n and d	1esci	riptive	e term	inolo	ogy.)							
	64.7											78.2	19.1	Elev. 80.2		9	PROJECT:
	15.5											2.0	0.0	Depth 0.0		E - K	OT: FOIN
											ď	]		ASTM D2487 Symbol		e Squar Main Si River,	DATION
Water level not encountered to cave—in depth of 10' immediately after withdrawal of auger.  Boring immediately backfilled.									(Outwash)	waterbearing, very loose to	to medium grained, with a tr	mostly fine to medium grained, 1	Concrete.	Description of Materials (ASTM D2488)		Jenne Square Shopping Mail 665 Main Street Elk River, MN	INVESTIGATION
to to		·									trace	. 1	2		DATE:	See Attached	BORING:
	4		စ		7		ω		0		4			BPF		Atta	<u> </u>
														Ę	11-1	ichec.	Î
								assume mark.	at the Inters	manhol of the	refere	Surfac	1 4 5 - 1	Tests	11-10-88	Sketch	ST-1
æ								d for t	Main S	e locat	nced to	prown,		٩	SCALE:	<b>.</b>	
*								his bench	intersection. An	ed North	the top	moist.	)	Notes	1"-4"		



(See Report and Standard	d Pla	ites for evalua	ition and de	escriptive to	erminology.	)					
	64.7						79.6	Elev. 80.2			PROJECT:
	15.5						0.6	Depth 0.0		K 00 01	CT: 04 FOUN
		*:				ds		ASTM D2487 Symbol		Main S River,	IDAT ION
Water level not encountered to cave-in depth of 10' immediate after withdrawal of auger.  Boring immediately backfilled.				.2		POORLY GRADED SAND, mostly fine to medium grained, light brown to brown, moist to waterbearing, very loose to loose.  (Coarse Alluvium)	Concrete.			Jenne Square Shopping Mail 665 Main Street Elk River, MN	INVESTIGATION
ed.	4	CI	Ch	σ	ω	ring,		BPF WL Tests or Notes	DATE: 11-10-88 SCALE: 1"-4'	Attached Sketch	BORING: ST-2



 $\mathcal{N}^{\mathcal{N}}$ 

200

(See Report and Standard	d Plate	s for evaluation and descriptive terminology.)				
	64.2	79.6	Elev. 79.7		C88-304	PROJECT:
1 1	15.5	14.0	Depth 0.0		ME OF THE PROPERTY OF THE PROP	CT:
	SP		ASTM D2487 Symbol		Main St River,	
Water level not encountered to cave—in depth of 5' immediately after withdrawal of auger.  Boring immediately backfilled.	POORLY GRADED SAND, mostly fine to medium grained, gray, with heavy petroleum odor, i	Concrete. Concrete. POURLY GRADED SAND, mostly fine to medium grained, with GRAVEL, dark brown to brown, moist, loose to medium dense. (Outwash)	Description of Materials (ASTM D2488)		FOUNDATION INVESTIGATION  Jenne Square Shopping Mail  665 Main Street  EIK River, MN	
- <del>-</del>	6	EL, 6	BPF	DATE:	LOCATION: See Attached	BORING:
			<u>ڄ</u>	7	сће	
72	'waterbearing, loose. (Coarse Alluvium)		Tests or Notes	11-10-88   SCALE: 1"-4'	d Sketch	ST-3



 $\mathcal{W}$ 

(See Report and Standard	rd Plates for evaluation and desc	criptive terminology.)					
	σ 4	71.8	77.8	Elev. 79.8		C88-3	PROJECT:
	15.5	1. 1	2.0	Depth 0.0		04 F00 F00 F00 K	<b>1</b>
	ğ			ASTM D2487 Symbol		NDATION Ne Squar Main St River,	
Water level not encountered to cave—in depth of 7' immediately after withdrawal of auger.  Boring immediately backfilled.	medium grained, wtih a li VEL, dark brown, moist to erbearing, loose to dense utwash)	Y GRADED SAND, mostly dium grained, with a AVEL, dark brown to , moist, very loose the wash)		Description of Materials (ASTM D2488)		FOUNDATION INVESTIGATION Jenne Square Shopping Mall 665 Main Street EIK River, MN	
d. edy	15 36 8	trace 4		8PF	DATE:	LOCATION: See Atta	BORING:
				ř K	=======================================	TION: Attached	
			1gral dark	Tests	11-10-88	ed Sketch	ST-4
	3		ned, with GRAVEL brown, moist.	or Notes	SCALE: 1"_4'	ነ <del>ነ</del>	



\*\* \* 5

\*\*\*\*\*

(See Report and Standar	d Plates for eva	luation and desi	criptive terminolog	y.)				
	64.2	67.7	71.7		Elev. 79.7		C88-3	PROJECT:
	15. 5	1.	π ω		Depth 0.0		500 E E E E E E E E E E E E E E E E E E	OT:
	ų		g G		ASTM D2487 Symbol		NDATION Ne Squar Main St River,	
Water level not encountered to cave—in depth of 9' immediately after withdrawal of auger.  Boring immediately backfilled.	GRADED SAND, mostly filum grained, with GRAVE wet to waterbearing, dense.  ash)	0 1		POSSIBLE FILL: consisting primarily of POORLY GRADED SAND with SILT (SP-SM) and POORLY GRADED SAND (SP), mostly fine to medium grained, dark brown to brown, moist.	Description of Materials (ASTM D2488)	D	FOUNDATION INVESTIGATION  Jenne Square Shopping Mail  665 Main Street  Elk River, MN	
* 1	19 11	\$ t + 0	N O	8 8	BPF		LOCATION: See Attached	BORING:
					¥ F		chec	
		loose, mo loose, mo (Possib			Tests	11-10-88 SCA	Sketch	ST-5
	e.	moist, very			or Notes	CALE: 1"=4'		



(See	Report and	Standard Plates for evaluation and descriptive terminole	ogy.)		
	ა ა ა	73.5 62.5	79.5	Elev. 80.0	PROJECT: C88-304
	ი ი ი	6.5 6.5	0.5	Depth 0.0	OT: 04 FOUN Jenr 665 EIK
	, v	SA	SP	ASTM D2487 Symbol	NDATION Ne Squar Main St River,
Water level down 17' with 20' hollow-stem auger in the grou Water level not encountered t cave-in depth of 10' immediat after withdrawal of auger.  Boring immediately backfilled	roorly GRADED SAND, mostly for medium grained, with a trof GRAVEL, brown, waterbeard medium dense.  (Outwash)	brown,	CONCRETE.  CONCRETE GRADED SAND, mostly for grained, brown, moist, loose (Coarse Alluvium)	Description of Materials (ASTM D2488)	FOUNDATION INVESTIGATION Jenne Square Shopping Mail 665 Main Street EIK River, MN
ground.  ed to diately  led.	race Ing,	8 7 5 5	rine Se. 8	BPF WL Tests or Notes	BORING: ST-6 LOCATION: See Attached Sketch  DATE: 11-10-88 SCALE: 1"-4'



100

(See Report and Standard	d Plates for eva	luation and descriptive terminology.)	)		
	64.6	76.1 68.1	79.6	Elev. 80.1	PROJECT: C88-304
1	15.5	12.0	9	Depth 0.0	CT: 04 FOUN Jenr 665 Elk
	ų	Sp		ASTM D2487 Symbol	NDATION Ne Squar Main St River,
water level not encountered to cave—in depth of 10' immediate after withdrawal of auger.  Boring immediately backfilled.	to medium grained, brown, we waterbearing, loose. (Coarse Alluvium)	POURLY GRADED SAND, mostly grained, brown, moist, very loose. (Coarse Alluvium)	VOID Space Under Concrete.	Description of Materials (ASTM D2488)	FOUNDATION INVESTIGATION Jenne Square Shopping Mail 665 Main Street EIK River, MN
lately led.	wet to 10	1 1 W.H.		BPF WL Tests or Notes	BORING: ST-7  LOCATION: See Attached Sketch  DATE: 11-10-88 SCALE: 1"-4'



## Scriptive Termino. Jgy

Designation D 2487 ಜ


## Standard Test Method for CLASSIFICATION OF SOILS FOR ENGINEERING PURPOSES

Highly organic soils	50		-GRAI	ed the	Liquid limit	SILTS AND CLAYS		ore	N	504	20	ret	e	on		
c soils		imit more	O CLAYS		quid limit less than 50%	D CLAYS		Sieve	Coarse fraction	SANDS		GRAVELS More than 50% of coarse fraction retained on No. 4 sieve			- 1	
Primarily organ	organic	inorganic		organic		Inorganic	More than 12% fines d	SANDS WITH FINES		CLEAN SANDS	More than 12% fines C	GRAVELS WITH FINES		CLEAN GRAVELS	GROUP NAMES U	
ganic matt lor	Liquid II	Pl plats	PI plots	Liquid II	PI < 4 or	PI > 7 and p	2% fines d	TH FINES		SANDS	ZE fines C	TH FINES		RAVELS	SIGNING GRO	
Primarily organic matter, dark in color, and organic odor	Liquid limit - oven dried < 0.75	PI plats below "A" line	PI plots on or above "A" line	Liquid limit - oven dried < 0.75	PI < 4 or plots below "A" line J	PI > 7 and plots on or above			$C_{\rm U}$ < 6 and/or 1 > $C_{\rm C}$ > 3 e	Cu ≥ 6 and 1 ≤ Cc ≤ 3 e	Fines classify as CL or CH	Fines classify as ML or MH	$C_U < 4$ and/or $1 > C_C > 3$ e	$C_U \geq 4 \text{ and } 1 \leq C_C \leq 1^{-6}$	CRITERIA FOR ASSIGNING GROUP SYMBOLS AND GROUP NAMES USING LABORATORY TESTS 4	
3	와	Ŧ	2	٩	7	Ъ	SC	HS	Ş	Æ	ន	G#	8	e	SYMBOL	
Peat	Organic clay k, 1, m, p Organic silt k, 1, m, q	Elastic silt k.i,m	Fat clay k, 1,m	Organic clay k, i, m, n Organic silt k, i, m, o	Sile k.l.m	Lean clay k,1,m	Clayey sand 9,h,1	Silty sand 9,h,1	Poorly graded sand 1	Hell-graded sand i	Clayey gravel 1.9.0	Silty gravel f.g.h	Poorly graded gravel f	Well-graded gravel f	GROUP NAME D	The state of the s

	?	•	۵.	
GA-GH well graded grave) with silt GA-GC well graded gravel with clay GA-GH nonchiv notation moves with clay	c. Gravels with 5 to 12% fines require dual symbols	b. If field sample contained cobbles and/or boulders, add "with cobbles and/or boulders" to group name.	a. Based on the material passing the 3-in $(75-mm)$ sieve.	
		<pre>id "with cobbles and/or boulders" to group name.</pre>		

GP-GM poorly graded gravel with clay GP-GC poorly graded gravel with clay symbols with 5 to 12% fines require dual symbols SP-SM poorly graded sand with clay SP-SM poorly graded sand with clay sp-SM poorly graded sand with clay sp-SM poorly graded sand with clay sp-SM poorly graded sand with clay graded san

= 0<sub>60</sub>/0<sub>10</sub> C<sub>c</sub> T<sub>0.8</sub> T<sub>0.6</sub> T<sub>0.8</sub> T<sub>0.6</sub> T<sub>0.8</sub> T<sub>0.6</sub> T<sub>0.8</sub> T<sub>0.6</sub> T<sub>0.8</sub> T<sub>0.6</sub> T<sub>0.</sub>



. .

#### LABORATORY TESTS

<u>9</u>	P	F	M O	Ö	0
Plasticity Index. %	Plastic Limit, %	Liquid Limit, %	Natural Moisture Content, %	Wet Density, pcf	Dry Density, pcf

၁၈၈၈၈ Organic Content, %
Percent of Saturation, 9
Specific Gravity
Cohesion

%

Angle of Internal Friction
Unconfined Compressive Strength

## PARTICLE SIZE IDENTIFICATION

Clay less than .005 mm	Silt No. 200 — .005 mm	Fine No. 40 — No. 200	Medium No. 10 — No. 40	Coarse No. 4 - No. 10	Sand	Fine	Coarse 34" — 3"	Gravel	Cobbles 3" to 12"	Boulders over 12"
÷		i		:		:	÷		:	÷
less than .005 mm	No. 200 — .005 mr	No. 40 — No. 200	No. 10 - No. 40	No. 4 — No. 10		No. 4 — ¾"	%" — 3"		3" to 12"	over 12"

### RELATIVE DENSITY OF COHESIONLESS SOILS

very dense	dense 31 — 50 E	medium dense	loose	very loose0 — 4 E
			31	÷
		200	30	2
		•		
			9	
				·
*				
				(A)
*				
			*	× .
•				*
*		•	*	
•	· :	•	*	
•	<b>*</b>	•	•	
7			*	
27	•		•	•
1		•	*	
7.0	•	•	80	2
2.5	Š :	•	2	8
100	8 :	200	80	0
20	8	100	8	
			90	10
		20		(S)
			33	
•				
				•
	ų			_
•	_	_	UI	0
	1	-1	1	1
/ D	- 1	- (	1	- 1
×.	(D	63		
7	×	$\approx$	=	
T.	_	_	J	+-
m	m	m	m	ш
		,		,

## CONSISTENCY OF COHESIVE SOILS

hard 30+ B	very stiff	stiff 13 — 16 E	rather stiff	medium 6- 8E	rather soft 4 - 5 E	soft 2-	very soft 0 - 18
200	-	-	•	•		•	
:	7	ω	9	6	4	N	0
٠.	1	1	1	1	1	1	1
8	Ġ	_	÷	•	•		•
Ŧ	õ	6	$\overline{\sim}$	$^{\circ}$	Ċī	သ (၁	_
Œ	Œ	m	m	m	m	ന	m
							2.60

#### **DRILLING NOTES**

I.D. hollow-stem augers unless noted otherwise. Jetting water vused to clean out auger prior to sampling only where indicated logs. Standard penetration test borings are designated by: prefix "ST" (Split Tube). Standard penetration test borings were advanced by 31/4" or 6

and are therefore somewhat approximate. Power auger borinare designated by the prefix "B". Power auger borings were advanced by 4" or 6" diamet continuous-flite, solid stem augers. Soil classification and stradepths are inferred from disturbed samples augered to the surface that the surface continuous strategies are inferred from disturbed samples augered to the surface.

Hand probings were advanced manually with a 1½" diame probe and are limited to the depth from which the probe can manually withdrawn. Hand probings are indicated by the pre

**SAMPLING** — All samples are taken with the standard 2" O split tube sampler, except where noted. TW indicates thin-v. (undisturbed) sample.

into undisturbed soil below the hollow-stem auger. Driving resistances are then counted for second and third 6" increment and added to get BPF. Where they differ significantly, they a reported in the following form — 2/12 for the second and third BPF — Numbers indicate blows per foot recorded in standa penetration test, also known as "N" value. The sampler is set penetration test, also known as he hollow-stem auger. Driving increments respectively.

hammer and rods alone, driving not required. WH — WH indicates that sampler penetrated soil under weight

standards. All tests run in accordance ¥<u>:</u> applicable AST



#### REMEDIAL

17

INVESTIGATION AT

**65 MAIN STREET** 

ELK RIVER, MINNESOTA

PREPARED FOR:

CITY OF ELK RIVER

7420 DODGE AVENUE NW

ELK RIVER, MINNESOTA

**OCTOBER 8, 1990** 

PREPARED BY:

BRUCE A. LIESCH ASSOCIATES, INC.

13400 15TH AVENUE NORTH

PLYMOUTH, MINNESOTA 55441

(612) 559-1423

This report was prepared by me or under my direct supervision.

James E. Graham Hydrogeologist

mes E. Graham

DECEIVED

OCT 1 0 1990

MPCA, HAZARDOUS
WASTE DIVISION

### TABLE OF CONTENTS

		PACH	4
1.0	1.0 INTRODUCTION		¥
2.0	2.0 SCOPE OF INVESTIGATION		
3.0	3.0 SITE HISTORY		
4.0	SOIL B		
	4.1 Geology		A. A.
5.0	ANAL		
	5.1 Soil lest Results		C71 C1
6.0	6.0 SUMMARY		•
7.0	7.0 RECOMMENDATIONS		00
	FIGURES (Following Text)	g Text)	
Figur Figur Figur Figur Figur Figur Figur	Figure 1  Site Location Map  Figure 2  Braun Soil Boring Locations  Figure 3  Soil Boring/Tank Locations  Figure 4  Geologic Cross-Section Locations  Figure 5  Figure 6  Geologic Cross-Section B-B'  Figure 7  Geologic Cross-Section B-B'  Figure 8  City of Elk River Map	lons	
	TABLES (Following Figures)	Figures)	
Table Table	Table 1  Headspace Analysis Results for Callected Table 3  Analytical Results for Callected	Analysis Results for Collected Soil Samples er Elevations Results for Collected Soil Samples	
Table	4	ed Water Samples	

## APPENDICES (Following Tables)

₽. C

MPCA Letter
Soil Boring Logs
MPCA Jar Headspace Analytical Screening Procedures

Appendix A
Appendix B
Appendix C
Appendix D
Appendix E Laboratory Test Results MPCA UST Notification Form

### 1.0 INTRODUCTION

general site location. remedial investigation at 65 Main Street in Elk River, Minnesota. Figure 1 illustrates the The City of Elk-River retained Bruce A. Liesch Associates, Inc. (Liesch) to conduct a

## 2.0 SCOPE OF INVESTIGATION

breathing zone conditions during drilling operations using an organic vapor monitor (OVM); This report is to document and summarize the results of the soil boring investigation and headspace analyses of collected soil samples utilizing the OVM. collection of soil and groundwater samples for laboratory analyses; monitoring of remedial investigation included: the observation of soil boring installations; The purpose of this

### 3.0 SITE HISTORY

Minnesota Pollution Control Agency (MPCA) was notified of the petroleum impacted soil  $\bigvee_{K_{So}^{poll}} V_{So}^{poll}$  at the site. In addition, the "Preliminary Foundation Investigation" report prepared by in soil boring ST-3 (see Figure 2). On November 14, 1988, Ms. Pat Chabot of the identified "strong petroleum odors and visible dark staining at the 14 to 15 1/2 foot depth" Braun, dated December 9, 1988, was submitted to the MPCA for review and comment. foundation investigation at the site which consisted of seven standard penetration test Engineering Testing, Inc. (Braun) located in St. Cloud, Minnesota conducted a preliminary fire in June, 1987. This site currently consists of a concrete building foundation and retaining walls on three The site was previously the location of a hardware store which was destroyed by During the installation of these soil borings on November 10, 1988, Braun In response to proposed new construction at the Braun

dated June 14, 1990 and indicated that MPCA would require reimbursement for technical Jane Boerboom of the MPCA acknowledged receipt of the Braun report in a letter Did Not bed Shere born possible

review of the report. the project is contained in Appendix A. A copy of the MPCA letter to Mr. James Trucker, a consultant for

 $\mathbb{F}_{\overline{J}}$ 

underground storage tank (UST) was discovered in the garage. portion of the site (see Figure 2). approximately eight apartment petroleum release On made to pump the tank approximately ten years ago. used since 1976 and no product could be recovered from the tank when an attempt adjacent to adjacent to 13, at the request of Mr. the location of the tank and associated structures. building 1990, Liesch representative ij which included an attached garage and east of soil boring the feet in length and three to four the vicinity of soil boring ST-3 which is western edge Pat Klaers, During a walk-over survey of an of. Mr. John Lichter the garage, City Administrator, to investigate ST-3. An apparent fill and vent near feet in diameter. in the conducted a site visit soil boring ST-3. The tank reportedly has not rear of the building, located The tank appeared to be existing at The the three ø pipe garage Figure 3 potential of an S.

geology and stratigraphy of the site. water; determine the levels of benzene, toluene, ethyl benzene, xylene (BTEX) in the soil at the site to: ground water; confirm groundwater City of Elk River subsequently retained Liesch to conduct a soil boring investigation characterize the apparent extent of petroleum impacted soil and ground flow direction; and to further investigate the

### 4.0 SOIL BORING INVESTIGATION

logs of Twin City Testing Corporation, Inc. (TCT) located in St. Paul, Minnesota was retained to completed on September 19, 1990. borings are contained in Appendix B. soil borings. The installation of soil borings began on September 17, 1990 and Soil boring locations are shown on Figure 3 and

at five foot intervals and at major changes in lithology. Classification System (USCS) using visual-manual procedures. Soil samples were collected (ASTM) D1586. Soil samples were classified in the field following the Unified Soil by the split barrel method in accordance with American Society for Testing Materials diameter (I.D.) hollow stem augers (HSA). respectively. of the site is 93 degrees, 34 minutes, 1 second and 45 degrees, 18 minutes, 9 seconds, Section 34, Township 33 North, Range 26 West. A total of ten soil borings were installed at the site. The site is located in the northeast of the northeast quarter of the southwest quarter of the southwest quarter of Soil borings were installed by a CME Soil samples were obtained in each borehole The approximate longitude and latitude 55 drill rig using 4 1/4-inch inside

drilling operations. Background OVM readings during drilling were less than 1.0 ppm monitored using the OVM both in the breathing zone and at the top of the auger during Headspace Analytical Screening Procedures (see Appendix C). Air quality was periodically gasoline, diesel fuel and fuel oil. Headspace analyses were conducted following MPCA detectable compounds include volatile organic compounds and constituents associated with presence Environmental Instruments OVM (10.0 e.V. Photoionization Detector) to identify Liesch conducted headspace analyses on collected soil samples in the field using a Thermo of organic vapors down to 0.1 parts per million (ppm). The potentially Jar

of the next sample. at each borehole, the split spoon sampler was rinsed with clean water prior to collection cleaned prior to arriving at the site and between boreholes. submitted for laboratory analyses. removed samples with temporarily installed flush threaded PVC well screen and riser. After collecting the water groundwater level. water samples All boreholes and the borehole abandoned with neat cement grout. ы were advanced to a point approximately three feet Voss disposable teflon bailer, the PVC A separate disposable bailer was utilized at each borehole to collect Water samples The PVC casing, well screen and HSA were collected from casing and During sampling procedures the boreholes Water samples below well screen were the apparent were steam utilizing were

#### 4.1 Geology

during the advancement of HSA at these locations. of detectable organic vapors. In addition, stained soils and odors were not encountered on collected soil samples from B-3, B-4, B-8, B-9 and B-10 did not indicate the presence headspace analyses conducted on collected soil samples. cross-sections A-A' and B-B' (Figures 5 and 6). Headspace analyses conducted in the field The site stratigraphy consists primarily of fine to coarse grained sands as illustrated by Table 1 presents the results of

concentration of organic vapors in soil samples collected near the groundwater level at B-1 (12.0 to 14.0 feet), B-2 (13.0 to 15.0 feet), B-5 (13.0 to 15.0 feet) and B-7 (13.0 to B-2 and B-5. Headspace analyses did indicate the presence of organic vapors in soil samples from B-15.0 feet). B-2, B-5, In addition, stained soils and odors were observed in the soil samples from B-6 and B-7 (see Table 1). Headspace analyses indicated the highest

#### 4.2 Hydrogeology

collected from B-1, B-2, B-5, B-6 and B-7. water samples collected from the boreholes, slight odors were apparent in the samples for laboratory analyses. of Borings, Appendix B). Water samples were subsequently collected from each borehole recharge, Liesch personnel measured and recorded the depths to ground water (see ground water to recharge the boreholes prior to abandonment. After allowing groundwater The boreholes were left open below grade and covered at the ground surface to allow Although petroleum sheens or product were not observed on

elevations were then used to determine groundwater elevations for the soil borings as feet on top of the fire hydrant located northeast of the site (see Figure 4). borehole were determined by survey assuming a temporary benchmark elevation of 100.00 completion of the borings, elevations of the ground surface adjacent to These ground

groundwater contour map (see Figure 7). shown in Table interpreted !2 g Based on these groundwater elevations, groundwater flow at be southeast towards the Mississippi River as illustrated the bу site the

### 5.0 ANALYTICAL TEST RESULTS

samples were analyzed for volatile organic hydrocarbons (465C List). soil samples were A total of ten soil and ten water samples were submitted to Minnesota Valley Testing copies of analytical test results and chain of custody forms Laboratories, Inc. analyzed for BTEX and total petroleum hydrocarbons (TPH). (MVTL) located in New Ulm, Minnesota for laboratory analyses. Appendix D contains The water The

### 5.1 Soil Test Results

presents analytical test results for collected soil samples. 56.0 ppb, 110 ppb and 12 ppm as gas or 24 ppm as fuel oil, respectively. 5 (3.0 to 15.0 feet), ethyl benzene, toluene, xylene, and TPH were detected at 38.7 ppb, at 3700 ppb and TPH at 330 ppm as gas or 600 ppm as fuel oil in the soil sample collected detected at 1200 parts per billion (ppb), benzene at 1100 ppb, toluene at 2300 ppb, xylene BTEX and TPH were not detected above laboratory method detection limits (MDL) in soil from B-2 (13.0 to 15.0 feet). Although benzene was not detected in the sample from Bbenzene, collected from B-1, B-3, B-4, B-6, B-8, B-9 and B-10. and xylene were detected at low levels in the sample from B-7 (13.0 to 15.0 toluene and TPH were not detected above laboratory MDL. Ethyl benzene was Although ethyl Table 3

#### 5.2 Water Quality

collected from B-1. BTEX were also detected in the sample from B-2 at 600 ppb, 34.0 detected at 4.4 ppb, ethyl benzene at 13.9 ppb and xylene at 12 ppb in the water sample Table 4 presents analytical test results for collected water samples. Benzene was

detected in the sample from B-7 at 43.6 ppb, 12.6 ppb and 27.6 ppb, respectively. cumene at 2.0 ppb in the sample from B-6. Benzene, ethyl benzene and xylene were 59.1 ppb, cumene at 2.5 ppb and ethyl ether at 1.9 ppb in the water sample from presence of benzene at 110 ppb, toluene at 4.7 ppb, ethyl benzene at 39.6 ppb, xylene at ppb, 470 ppb and 448 ppb, respectively. was detected at 29.1ppb, ethyl benzene at 16.9 Laboratory test results ppb, xylene at also indicated 3.6 ppb B-5 and

Volatile organic hydrocarbons (465C List) were not detected above laboratory which was detected near the laboratory MDL at 3.1 ppb in the sample from B-10. water samples from B-3, B-4, B-8, B-9 and B-10 with the exception of methylene chloride MDL in

concentrations of the other compounds detected in the water samples did not exceed MDH .7 Minnesota Department in drinking water MDH RALfor was exceeded in the water samples xylene of Health (MDH) recommended allowable was also exceeded ij the from sample B-2, from B-5, limit (RAL) for B-6 and B-The

concentration of these compounds was low Although the source of the cumene, ethyl ether and methylene chloride is are likely associated with the petroleum product release (at the laboratory MDL). Cumene and ethyl unknown,

#### 6.0 SUMMARY

During for benzene was exceeded in several of the water samples. observations with BTEX and TPH being detected above laboratory MDL. indicated the and the water installation of soil borings, presence of detectable organic vapors. samples collected from B-1, B-2, B-5, headspace, analyses Subsequent laboratory B-6 and B-7 confirmed the above Xylene also exceeded the on collected The MDH RAL soil samples analyses on

MDH RAL in the water sample collected from collected water not observed on the water samples collected from the boreholes samples did not exceed MDH RALs. B-2. Petroleum sheens Other compounds detected in  $^{\circ}$ free product

bituminous area (see Figure 3) south of the site. In addition, a flowing well of unknown feet south of the site. Other potential target receptors in the immediate vicinity include potential target receptor is apparently the Mississippi River due to its close proximal discharges to the Mississippi River. which supplies distance to the site. groundwater quality has been impacted by a petroleum release. underground gas, and construction is located in the wooded area south of the apartment building field observations, headspace analyses and laboratory test results, it appears water The north bank of the Mississippi River is located approximately 40 to a fountain (located in the grassy area south of the site) that electric and sanitary Should be sampled. sewer utilities which are The primary downgradient located in the

of migration along the building footing since the BTEX levels decrease from B-2 towards levels observed in the water samples from B-5 and B-7 (upgradient of B-2) may be a result BTEX being detected in the samples from B-1 and B-6 (downgradient of B-2). adjacent to the former boiler location in the apartment building) with lower levels of highest levels of BTEX in the ground water were detected in the sample from B-2 (located extent of petroleum impacted soil appears to be limited to the eastern edge of hardware store along the existing apartment building footing. In addition, The BTEX the

petroleum impacts appears to be the fuel oil tank or associated piping to the former boiler Based on field observations and laboratory test results, the most likely source located in the garage and apartment building adjacent to the site (see Figure 3). of the

### 7.0 RECOMMENDATIONS

impacts were observed directly above the water table associated with fluctuating impacted soils at B-2, apartment building). This area is south and west by an alley. the north by Main Street, the east by an existing three story apartment building and the soil are present is in the area along the east side of the site are retaining wall (remnants of the former hardware store). presently overlain by unimpacted soil (no apparent petroleum impacts) consists of B-5, B-6 and B-7 are apparently at a depth of approximately 13 The only area identified where appreciable petroleum impacts water table and/or capillary fringe effects since the a concrete foundation surrounded on three presently covered by concrete. The site is bounded on (adjacent In addition, and may sides to soil the be

treated through soil venting. would be amenable to soil venting, the type of anticipated release (fuel oil) is not ideally recommend excavation or remediation of on-site soils. Owing to the depth of the impacted soil, the fact that the area is covered with concrete the fact that the apartment building footing is exposed in this area, Although the soil is we sandy do and not

to City of Elk River personnel. Due to the depth of ground water, it is not anticipated proximal distance to the site. The sanitary sewer located south of the site trends eastoverriding that the sanitary sewer would be impacted by the apparent release west, flows to the east and is at a depth of approximately three to four feet according groundwater flow is apparently to the southeast towards the Mississippi River, the concern for potential off-site impacts would be the River due to its close Report New )

apartment building footing (see Figure 3), it is recommended that the state fire marshall the MPCA (see Appendix E). Since the tank is located in the garage and adjacent to the contacted and approval obtained to close the tank in place fuel oil tank located in the garage behind the apartment building was registered with

Additional investigation at the site is not recommended for the following reasons:

- :endanger existing structures on and adjacent to the site overlain petroleum impacted soil is table bу apparently and/or capillary unimpacted soil and fringe apparently at a depth of approximately 13 feet, effects. may Excavation be associated of these with fluctuating soils would is
- 3 fuel oil tank and associated piping in place, if approved by the fire marshall. most likely source of the apparent release will be remediated by closing
- ယ steep slopes towards the Mississippi River (see Figure 7), downgradient groundwater monitoring wells are not feasible at the site. Groundwater flow and access limitations Š to the southeast based on groundwater flow direction and at the site including existing structures, woods and
- 4 site migration due to the shallow depth of the utilities and the deeper depth to ground water. The utilities located south of the site would most likely not be impacted by offdowngradient target receptor of petroleum impacts would apparently be the River. Due ಕ the close proximal distance of the Mississippi River, the most likely
- ប River anticipated that drinking water will be affected by the release The businesses and residences adjacent to the site are located in downtown (see Figure 8 which is supplied by municipal water, therefore it S. not EIK


be scheduled to discuss whether additional corrective actions, if any, are necessary at the Ιt S. recommended for review. Following MPCA review of the report, a meeting with MPCA should that a copy of this remedial investigation report be submitted to


reimbursement. site and to determine if site closure is considered complete for subsequent PetroBoard


mas:elkhardware


FIGURES


11











ABLES

## TABLE 1 HEADSPACE ANALYSIS RESULTS FOR COLLECTED SOIL SAMPLES

В-9	B-8	в-7	B-6	B-5	B-4	B-3	B-2	B-1	Soil Boring
								,	<b>∳</b>
9.5 - 6.5 9.5 - 11.5 13.0 - 15.0	4.5 - 6.5 9.5 - 11.5 13.0 - 15.0	4.5 - 6.5 9.5 - 11.5 13.0 - 15.0	4.5 - 6.5 9.5 - 11.5 13.0 - 15.0 18.0 - 20.0	4.5 - 6.5 9.5 - 11.5 13.0 - 15.0	4.5 - 6.5 9.5 - 11.5 13.0 - 15.0	4.5 - 6.5 9.5 - 11.5 12.0 - 14.0 14.5 - 16.5	4.5 - 6.5 9.5 - 11.5 13.0 - 15.0	4.5 - 6.5 9.5 - 11.5 12.0 - 14.0 14.5 - 16.5	Depth (feet)
0 0	0 0 0	0 0 47.1	0 8.6 5.2	0 0 574	0 0 0	0000	0 0 860	20.2 9.2 14.2	OVM Results (ppm)

## TABLE 1 (Cont.) HEADSPACE ANALYSIS RESULTS FOR COLLECTED SOIL SAMPLES

fi

Depth (feet 4.5 ~ 6.5 9.5 - 11.5 13.0 - 15.0
---

Notes: 1) the field from split spoon samples using an organic vapor monitor (OVM). Headspace analyses were conducted following MPCA procedures. Headspace analysis results were obtained at the time of sampling in

2) million (ppm). Background OVM readings during sampling were less than 1.0 parts per

ljs:elktbl104.wp

TABLE 2
GROUNDWATER ELEVATIONS

	1				
Soil Boring	Ground Elevation (ft)	T.O.C. Elevation (ft)	Depth to Ground Water (ft)	Date Measured	Groundwater Elevation (ft)
B-1	76.00	79.99	17.41 (T.O.C.)	9-18-90	62.58
B-2	76.65	79.61	16.39 (T.O.C.)	9-18-90	63.22
B-3	75.81	78.09	15.18 (Grnd)	9-18-90	60.63
B-4	76.53	79.74	13.74 (Grnd)	9-18-90	62.79
B-5	76.81	79.82	16.15 (T.O.C.)	9-18-90	63.67
В-6	75.67	80.17	21.00 (T.O.C.)	9-18-90	59.17
B-7	77.02	77.62	13.72 (T.O.C.)	9-18-90	63.90
B-8	76.53	77.33	14.70 (T.O.C.)	9-18-90	62.63
В-9	76.97	79.72	15.50 (T.O.C.)	9-19-90	64.22
B-10	76.78	79.73	15.89 (T.O.C.)	9-19-90	63.84
MISSISSIPPI RIVER					* 57.37
スロンビス					

### \* Surface water elevation

Notes: 1) feet located on top of the fire hydrant (see Figure 3). All elevations are based on an assumed temporary benchmark elevation of 100.00

2) temporary PVC well casing. and measured from either the ground surface (Grnd) or top of casing (T.O.C.) in the Depths to ground water at the soil borings were determined by taped measurement

ljs:elktbl2104.wp

TABLE 3
ANALYTICAL RESULTS FOR COLLECTED
SOIL SAMPLES

Notes:	B-7 B-8 B-9 B-10	B-1 B-2 B-3 B-4 B-6	Soil Boring
4) 3) 2)	13.0 - 15.0 13.0 - 15.0 13.0 - 15.0 13.0 - 15.0	4.5 - 6.5 13.0 - 15.0 12.0 - 14.0 9.5 - 11.5 13.0 - 15.0	Depth (ft)
BDL = Total Total ppm - pph - Soil s	15.0 15.0 15.0 15.0	15.0 15.0 14.0 15.0 15.0	(ft)
BDL = Below Detection Limi Total Hydrocarbons Minimum As Gasoline - 2.0 ppm As Fuel Oil/Diesel - 5 ppm - parts per million ppb - parts per billion Soil samples were analyzed 9	24.4 <15.0 <15.0 <15.0	<15.0 1200 <15.0 <15.0 38.7	Ethyl Benzene /ppb
BDL = Below Detection Limits Total Hydrocarbons Minimum Detec As Gasoline - 2.0 ppm As Fuel Oil/Diesel - 5.0 ppm ppm - parts per million ppb - parts per billion Soil samples were analyzed 9/27/90	<20.0 <20.0 <20.0 <20.0	<20.0 1100 <20.0 <20.0 <20.0	Benzene /ppb
BDL = Below Detection Limits  Total Hydrocarbons Minimum Detection Limits: As Gasoline - 2.0 ppm As Fuel Oil/Diesel - 5.0 ppm ppm - parts per million ppb - parts per billion Soil samples were analyzed 9/27/90 by MVTL	<20.0 <20.0 <20.0 <20.0	<20.0 2300 <20.0 <20.0 56.0	Toluene /ppb
ឌ	40.0 <15.0 <15.0 <15.0	<15.0 3700 <15.0 <15.0	Xylene /ppb
	BDL BDL BDL BDL	BDL 330 As Gas or 600 As Fuel Oil BDL BDL 12 As Gas or 24 As Fuel Oil BDL	Total Hydrocarbons /ppm

ljs:elktbl3104.wp

TABLE 4
AWALYTICAL TEST RESULTS FOR COLLECTED
WATER SAMPLES

	B-1	B-2	B-3	B-4	B-5	B-6	B-7	B-8	B-9	B-10	MDH RAL
Laboratory Name	NVTL	NVTL	HVTL	NVTL	HVIL	HVTL .	KVTL	MAAT	. HVIL	KVTL	
Sampling Date Date Analyzed	9/17/90 9/27/90	9/17/90 9/27/90	9/17/90 9/27/90	9/17/90 9/27/90	9/18/90 9/27/90	9/18/90 9/27/90	9/18/90 9/27/90	9/18/90 9/27/90	9/19/90 9/27/90	9/19/9 <b>0</b> 9/27/90	
Benzene (ppb) Toluene (ppb) Ethyl Benzene (ppb) Xylene (ppb)	4.4 BDL 13.9 12.0	600 34.0 470 448	BDL BDL BDL BDL	BDL BDL BDL	110 4.7 39.6 59.1	29.1 BDL 16.9 3.6	43.6 BDL 12.6 27.6	BDL BDL BDL BDL	BDL BDL BDL	BDL BDL BDL BDL	7.0 2420.0 680.0 400.0
Cumene (ppb) Ethyl Ether (ppb) Methylene Chloride (ppb)	BDL BDL	BDL BDL BDL	BDL BDL BDL	BDL BDL BDL	2.5 1.9 BDL	2.0 BDL BDL	BDL BDL BDL	BDL BDL BDL	BDL BDL BDL	BDL BDL 3.1	  48.0

MVTL - Minnesota Valley Testing Laboratories, Inc.

BDL - Below Detection Limits

ppb - parts per billion -

NDL RAL - Minnesota Department of Health (MDB) Recommended Allowable Limit (RAL) for Drinking Water

mawith14





P.O BOX 249 NEW ULM, MN 56073-0249

PHONE (507) 354-8517 WATS (800) 782-3557 FAX (507) 359-2890

# WE ARE AN EQUAL OPPORTUNITY EMPLOYER

Report To: Bruce A. Li 13400 15th Plymouth, Attn: Joh John Liesch Associates MN Avenue Lichter 55441 North

> Work Date Date: Order Received: September 21-1500 28, 9-21 - 901990

ч roject Name: Elk River Hardware

Project No. 6 1102

Date Analyzed 9/27/90

#### RENZENE ETHYL BENZENE TOI.UENE XYL 80 TOTAL HYDROCARBONS:

12-14' (Soil)	20.0	9.5-11.5' (Soil)
		< 20.0 < 15.0
30L	8DL	708 708

BDL Below Detection Limit ល

SOIL Total Hydrocarbons Minimum Detection Limits

\* WATER Total Hydrocarbons Minimum Detection Limits

As As Gasoline Fuel Oil ine - 2.0 Oil/Diesel mdd σı 0 шďď

As As Fuel Oil/Diesel Gasoline 0 ហ mdd <u>.</u> 0 mdd

Ву Report and approved for Chemist L /SH Minnesota Wade Valley Pullman Testing labs. Inc





P.O BOX 249 NEW ULM, MN 56073-0249 PHONE (507) 354-8517

WATS (800) 782-3557 FAX (507) 359-2890

# WE ARE AN EQUAL OPPORTUNITY EMPLOYER

Report To: Bruce Attn: 13400 15th Avenue North Plymouth, MN 55441 ₽ John Lichter Liesch Associates

> Date Work Date: September 28, Order: 21-1500 Received: 21 - 901990

Project Name: E1k River Hardware

ч roject No. δ 1102

Date Analyzed 13 9/27/90

#### ANALYZED FOR BENZENE, TYHTE BENZENE, TOLUENE, XYLENE |S TOTAL HYDROCARBONS:

Sample I.D.	Lab #	Ethyl Benzene /ppb	Benzene /ppb	Toluene /ppb	Xylene /ppb	* Total Hydrocarbons /ppm
B-6, S3 13-15' (Soil)	5139	< 15.0	< 20.0	< 20.0	< 15.0	BDL
B-7, S3 13-15' (Soil)	5141	24.4	< 20.0	< 20.0	40.0	BDL
B-8, S3 13-15' (Soil)	5143	< 15.0	< 20.0	< 20.0	< 15.0	BDL
B-9 13-15' (Soil)	5145	< 15.0	< 20.0	<b>^</b> 20.0	< 15.0	BDL
B-10 13-15' (Soil)	5147	< 15.0	< 20.0	<b>&lt;</b> 20.0	< 15.0	BDL
Trip Blank (Water)	5149	^ 1.5	^ 2.0	2.0	^ 1.5	BDL

BDL Below Detection Limits

As As

Gasoline

2.0

mdd

Fuel Oil/Dies

e1

ហ

0

mdd

As As

Gasoline

0.5

mdd

 $\vdash$ 

0

mďď

Fuel Oil/Diesel

	*
	SOIL
	1
Minimum Detection Limits	SOIL - Total Hydrocarbons
	*
	WATER
	1
Minimu	* WATER - Total Hydrocarbons
m Det	iydro
ection	carbons

Report approved by Wade Chemist Pullman,

 $\square$ К and Ħ or Minnesota HS/ Valley Testing labs Inc





P.O BOX 249 NEW ULM, MN 56073-0249 PHONE (507) 354-8517 WATS (800) 782-3557 FAX (507) 359-2890

# WE ARE AN EQUAL OPPORTUNITY EMPLOYER

WATER ANALYZED FOR VOLATILE ORGANIC HYDROCARBONS

Report To: 13400 Plymouth, Bruce Attn: 15th Avenue John Liesch MN Lichter 55441 Associate North Ø

Д roject Name: H k River Hardware

Д roject Number: 61102

Submitted by: New 1126 Minnesota Ulm, Z Front ĭ Valley Testing 56073 Street Labs., Inc.

Κim Lab

**D** Sjogren Manager

Wade

团

Pullman,

Chemist

Jobs#:

5130, 5138,

5132, 5140, 5148,

5134, 5142, 5149

5136, 5144,

146

Dat Date Date Ò Received: Sampled: Reported: 9-18-90 9-28-90 9-21-90 ģ 9-19-

Work

Order

1-1500

Present, qualitative only

MDL Tag UND PQ QN Ħ 11 Not Present, Not Method Below Detection Determined Detection qualitative Limits Limits only

Appendix I Detection Aromatics Test A, Limit methods: Method 602. "Definition = 602. Method Detection Limits determined ition and Procedure for the Determination EPA-600/4-82-057, July 1982. Purgeable Halocarbons Method 601 according of the Met and Purgeable Method t 0





P.O. BOX 249 NEW ULM, MN 56073-0249 PHONE (507) 354-8517 WATS (800) 782-3557 FAX (507) 359-2890

WE ARE AN EQUAL OPPORTUNITY EMPLOYER

Sample

Identification:

Job #:

Purgeable Aromatics:		Purgeable Halocarbons:	Date Analyze
Chlorobenzene		Chloroethane	ed: 9-27-90
BDL 4.4 BDL 13.9 BDL BDL BDL BDL	000 000 000 000 000 000 000 000 000 00	BDL BDL BDL	ug/L
0.4 0.4 0.4	2001 2011 2011 2011 2011 2011 2011 2011		MDL ug/L



P.O BOX 249 NEW ULM, MN 56073-0249 PHONE (507) 354-8517 WATS (800) 782-3557

FAX (507) 359-2890

WE ARE AN EQUAL OPPORTUNITY EMPLOYER

Sample

Identification:

5130

																			Non-Priority		
																			Pollutants:	Date Analyzed	
Dibromomethane	Acetone	К	1,1,2-Trichlorotrifluoroethane.	Dichlorofluoromethane	2,3-Dichloro-1-propene	1,1-Dichloro-1-propene	1,1,1,2-Tetrachloroethane	Cumene	0-Xylene	M-Xylene & P-Xylene	Tetrahydrofuran	ш	Methyl Ethyl Ketone	1,2-Dibromoethane (EDB)	(3-Chloro-1-propene)	Allyl Chloride	1,2,3-Trichloropropane	1,3-Dichloropropane	Cis-1,2-Dichloroethylene	ed: 9-27-90	
BDL	BDL	BDL	BDL	ON	BDL	BDL			1.5	10.5	BDL	BDL					BDL	BDL		ug/L	
1.0	10.4	1.6	0.9	ND	0.8	1.0	0.5	1.5	0.5	1.0	6.0	1.5	3.5	1.0	0.5		0.7	0.6	0.8	MDL ug/L	





P.O BOX 249 NEW ULM, MN 56073-0249 PHONE (507) 354-8517 WATS (800) 782-3557 FAX (507) 359-2890

WE ARE AN EQUAL OPPORTUNITY EMPLOYER

Purgeable Purgeable Sample Halocarbons Aromatic Identification: te Analyzed: Trans-1,2-Dichi Chloroform.... 1,2-Dichloroeth Ch Ω Trans-1,3-Dichloropropene... Trichlorofluoromethane....
1,1-Dichloroethylene.... Vinyl Dichlorodifluoromethane Ethyl Chlorobenzene Bromoform.... 2-Chlo 1,1,2-1,2-Dichloropropane.... Bromodichloromethane..... Carbon 1,1,1-Trichloroethane..... 1,1-Dichloroethane. Methylene Bromomethane.. is-1, hloromethane..... hloroe 3-Dichlorobenzene. 2-Dichlorobenzene. 1,2-Trichloroethylene....lorodibromomethane..... Dichlorobenzene 9-Chloride..... 3-Dichloropropene... roethylvinyl Ether.. Benzene.. 2-Tetrachloroethane.. 2-Tetrachloroethylene roethylvinyl Trichloroethane..... 1,2-Dichloroethylene. Tetrachloride.... thane 90 Chloride. oethane..... N •••••••• 34. BDL 470 BDL BDL 600 NQ BDL 1/bn Job 0 TOM 102 20. 20. 7. 4. ( 9 13 14 20 20 20 20 H 6 5132  $\sigma$   $\omega$ 424 ഗ  $\omega$  4 ω 000000 000 000000000000000 0000 T/bn 0

MDL - Adjusted due to sample matrix.





P.O BOX 249 NEW ULM, MN 56073-0249 PHONE (507) 354-8517 WATS (800) 782-3557 FAX (507) 359-2890

WE ARE AN EQUAL OPPORTUNITY EMPLOYER

Sample Identification: Job #:

5132

																			Non-Priority Pollutant	מכני הוומד	
Dibr	Acetone	Ethyl	1,1,2	Dich	2,3-1	1,1-	1,1,	Cumene	0-Xylene	M-Xylene	Tetr	Methyl	Methyl	1,2-	(3-C)	Allyl	1,2,3	1,3-	s: Cis-	unatyceu:	
ibromomethane	one	1 Ether	2-Trichlorotrifluoroethane.	hlorofluoromethane	Dichloro-1-propene	-Dichloro-1-propene	,1,1,2-Tetrachloroethane	ne	:	lene & P-Xylene	ydrof	Isobu	yl Ethyl Ketone	2-Dibromoethane (EDB)	Chloro-1-propene)	1 Chloride	3-Trichloropropane	Dichloropropane	1,2-Dichloroethylene	3-21-30	9-27-90
BDL	BDL	BDL	BDL	ΟN	BDL	BDL	BDL	BDL	8.0	440	BDL	BDL	BDL	BDL	BDL		BDL	TOB	BDL	ug/L	
10.0	104.0	16.0	9.0	ND	8.0	10.0	5.0	15.0	5.0	10.0	60.0	15.0	35.0	10.0	5.0		7.0	6.0	8.0	MDL ug/L	

MDL - Adjusted due to sample matrix.





P.O BOX 249 NEW ULM, MN 56073-0249 PHONE (507) 354-8517 WATS (800) 782-3557 FAX (507) 359-2890

# WE ARE AN EQUAL OPPORTUNITY EMPLOYER

Sample

Identification:

Job #:

5134

Purgeable Aromatics:		Purgeable Halocarbons:	Date Analyz
Chlorobenzene  Benzene  Toluene  Ethyl Benzene  1,2-Dichlorobenzene  1,3-Dichlorobenzene  1,4-Dichlorobenzene	Dichlorodifluoromethane  Winyl Chloride	hloroethan hlorometha	ed: 9-27-90
301 301 301 301 301 301	8011 8011 8011 8011 8011 8011 8011 8011	סס	ug/L
0 0 0 1 2 2 0 0 ω	7 C C C C C C C C C C C C C C C C C C C		MDL_ug/L





P.O BOX 249 NEW ULM, MN 56073-0249 PHONE (507) 354-8517 WATS (800) 782-3557 FAX (507) 359-2890

# WE ARE AN EQUAL OPPORTUNITY EMPLOYER

Sample

Identification:

Job

#

Non-Priority	
Pollutants:	Date Analyze
Cis-1,2-Dichloroethylene	ed: 9-27-90
BDL	ug/L
0.8 0.6 0.6 1.0 0.5 0.5 0.5 0.5 0.5 0.6 0.6 0.6 0.6 0.6 0.6 0.6 0.6 0.6 0.6	MDL ug/L





P.O. BOX 249 NEW ULM, MN 56073-0249 PHONE (507) 354-8517 WATS (800) 782-3557 FAX (507) 359-2890

# WE ARE AN EQUAL OPPORTUNITY EMPLOYER

Sample

Identification:

Job

#

5136

Purgeable Aromatics:		Purgeable Halocarbons:	Date Analyze
Chlorobenzene  Benzene  Toluene  Ethyl Benzene  1,2-Dichlorobenzene  1,3-Dichlorobenzene  1,4-Dichlorobenzene	romomethane ichlorodifluoro inyl Chloride ethylene Chlori richlorofluorom ,1-Dichloroetha rans-1,2-Dichlo hloroform ,2-Dichloroetha ,1,1-Trichloroetha ,1,1-Trichloromet ,2-Dichloromet ,2-Dichloromet ,2-Dichloromet ,2-Dichloromet ,2-Trichloroe hlorodibromomet ,1,2-Trichloroe hlorodibromomet ,1,2-Trichloroe hlorodibromomet ,1,2-Trichloroe hlorodibromomet ,1,2-Trichloroe hlorodibromomet ,1,2-Trichloroe hlorodibromomet ,1,2-Trichloroe	Chloroethane	ed: 9-27-90
301 308 301 801 801 801 801	1088	BDL	ug/L
0.0.000	00 10 40 40 40 80 80 80 80 80 80 80 80 80 80 80 80 80		MDL ug/L





P.O BOX 249 NEW ULM, MN 56073-0249 PHONE (507) 354-8517 WATS (800) 782-3557

FAX (507) 359-2890

# WE ARE AN EQUAL OPPORTUNITY EMPLOYER

Dibromomethane	ne	臣thyl 臣ther	1,1,2-Trichlorotrifluoroethane	Dichlorofluoromethane	, 3-D	, 1	1,1,1,2-Tetrachloroethane	Cumene		M-Xylene & P-Xylene	Tetrahydrofuran	Methyl Isobutyl Ketone	Methyl Ethyl Ketone	1,2-Dibromoethane (EDB)	loro-1-prope	Allyl Chloride	,2,3	1,3-Dichl	Non-Priority Pollutants: Cis-1,2-Dichloroethylene		Date Analyzed: 9-27-90	Sample Identification: B-4	
:	•	•	ane.	•	•	•	•		•	•	•	•	:	•	•		:	•	:				
BDL	BDL	BDL	BDL	δN	BDL	BDL	BDL	BDL	BDL	BDL	BDL	BDL	BDL	BDL	BDL		BDL	BDL	BDL	ug/L		Job	i
1.0	10.4												ω				٠	0.6	•	MDL ug/L		b #: 5136	



S TOOLAGOT

P.O. BOX 249 NEW ULM, MN 56073-0249 PHONE (507) 354-8517 WATS (800) 782-3557 FAX (507) 359-2890

# WE ARE AN EQUAL OPPORTUNITY EMPLOYER

Sample

Identification:

B-5

Job

	chloroethane	Date Analyzed: 9-27-90
3 4 1 1		ug/L
0 0 1 2 2 0 . 2 6 5 0 0 &		MDL ug/L





P.O BOX 249 NEW ULM, MN 56073-0249 PHONE (507) 354-8517 WATS (800) 782-3557

FAX (507) 359-2890

WE ARE AN EQUAL OPPORTUNITY EMPLOYER

Sample

Identification:

Job

#

																			Non-Priority			
																			Pollutants:		Date Analyze	
Dibrom	Acetone		1,1,2-T	Dichlo	2,3-Di	1,1-Di	1,1,1,	Cumene	0-Xylen	M-Xylene	Tetrah	Methyl	Methyl	1,2-Di	(3-Chl		1,2,3-	1,3-Dic	Cis-1,		ე	
ibromomethane	· · · · · · · · · · · · · · · · · · ·	Ether	Trichlorotrifluoroethane.	orofluoromethane	ichloro-1-propene	ichloro-1-propene	2-Tetrachloroethane		:	ne & P-Xylene	Tetrahydrofuran	Isobutyl Ketor	Ethyl Ketone	Dibromoethane (EDB)	loro-1-propene)	Chloride	-Trichloropropane	chloropropane	2-Dichloroethylene		9-27-90	
BDL	BDL	1.9	BDL	QN	BDL	BDL	BDL	2.5	2.5	56.6	BDL	BDL	BDL	BDL	BDL		BDL	BDL	BDL	ng/L		
1.0	10.4	1.6	0.9	ND	0.8	1.0	0.5	1.5	0.5	1.0	6.0	1.5	3. 5	1.0	0.5		0.7	0.6	0.8	MDL ug/L		



P.O BOX 249 NEW ULM, MN 56073-0249 PHONE (507) 354-8517 WATS (800) 782-3557 FAX (507) 359-2890

WE ARE AN EQUAL OPPORTUNITY EMPLOYER

Sample

Identification:

Job #:

Purgeable Aromatics:		Purgeable Halocarbons:	Date Analyzed
Chlorobenzene  Benzene  Toluene  Ethyl Benzene  1,2-Dichlorobenzene  1,3-Dichlorobenzene  1,4-Dichlorobenzene	ethylene Chrichloroflu ,1-Dichloro ,1-Dichloro rans-1,2-Di hloroform. ,2-Dichloro ,1,1-Trichl arbon Tetra romodichloro rans-1,3-Di ,1,2-Trichl hlorodibrom ,1,2-Trichl hlorodibrom ,1,2-Trichl hlorodibrom ,1,2-Trichl hlorodibrom ,1,2-Trichl hlorodibrom ,1,2-Trichl hlorodibrom ,1,2-Trichl	oroethane oromethane momethane hlorodifluorometh	ed: 9-27-90
BDL 29.1 BDL 16.9 BDL BDL BDL BDL	108 108 108 108 108 108 108 108 108 108	BDL BDL BDL BDL	ug/L
0 0 0 1 2 2 0 0 0 0 0 0 0 0 0 0 0 0 0 0			MDL ug/L





PHONE (507) 354-8517 P.O BOX 249 NEW ULM, MN 56073-0249 WATS (800) 782-3557 FAX (507) 359-2890

## WE ARE AN EQUAL OPPORTUNITY EMPLOYER

Identification:

B-6

Job

#

Non-Priority Sample Pollutant Date Analyzed: Ø Ethyl Cumene.....1,1,2-Tetrachloroethane. Dichlorofluoromethane. O-Xylene..... Allyl 1,1,2-Tetrahydrofuran.. Methyl Methyl (3-Chloro-1-propene). 2-Dibromoethane S 3-Dichloro-1-2,3-Xylene Dichloropropane.. Ether.... Trichlorotrifluoroethane Chloride 9-Trichloropropane.... Isobutyl Ketone.. Ethyl Ketone.... Dichloroethylene. 27-90 ይን P-Xylene..... propene.... (EDB BDL 3.6 BDL 2.0 BDL BDL BDL NQ BDL BDL BDL BDL BDL BDL BDL BDL MDL ND O 0.8 0. 1.0.0 6. 00 6 9 

Dibromomethane Acetone...

BDL BDL

10.



P.O. BOX 249 NEW ULM, MN 56073-0249 PHONE (507) 354-8517 WATS (800) 782-3557 FAX (507) 359-2890

WE ARE AN EQUAL OPPORTUNITY EMPLOYER

Sample

Identification:

Purgeable Aromatics:		Purgeable Halocarbons:	Date Analyz
Chlorobenzene  Benzene  Toluene  Ethyl Benzene  1,2-Dichlorobenzene  1,3-Dichlorobenzene  1,4-Dichlorobenzene	Vinyl Chloride	hloroethanehloromethane	ed: 9-27-90
BDL 43.6 BDL 12.6 BDL BDL BDL BDL BDL	807 1 1 0 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8	108 108 108	<u>ug/L</u>
0.1.2.0.3 0.5.003	20 10 10 10 00 0 20 0 0 0 0 0 0 0 0 0 0		MDL ug/L





P.O BOX 249 NEW ULM, MN 56073-0249 PHONE (507) 354-8517 WATS (800) 782-3557

FAX (507) 359-2890

## WE ARE AN EQUAL OPPORTUNITY EMPLOYER

Sample Identification: Job # 5142

84	Date Analyzed:
1,3-Dich 1,2,3-Tr Allyl Ch (3-Chlor 1,2-Dibr Methyl I Methyl I Tetrahyd M-Xylene Cumene. 1,1-Dich 2,3-Dich Dichloro 1,1,2-Tr Ethyl Ethyl Ethyl	מ
Chloropropane	9-27-90
BDL BDL BDL BDL BDL BDL BDL BDL BDL BDL	T/bn
0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.0	MDL ug/L



P.O BOX 249 NEW ULM, MN 56073-0249 PHONE (507) 354-8517 WATS (800) 782-3557

FAX (507) 359-2890

WE ARE AN EQUAL OPPORTUNITY EMPLOYER

Sample

Identification:

Job

#

Purgeable Aromatics:		Purgeable Halocarbons:	Date Analyze
Chlorobenzene	Vinyl Chloride	hloroethanehloromethane	ed: 9-27-90
108 108 108 108 108 108	1108 1108 1108 1108 1108 1108 1108 1108	BDL	ug/L
0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	7 0 1 0 1 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0		MDL ug/L





P.O. BOX 249 NEW ULM, MN 56073-0249 PHONE (507) 354-8517 WATS (800) 782-3557 FAX (507) 359-2890

## WE ARE AN EQUAL OPPORTUNITY EMPLOYER

Sample

Identification:

Job #:

Non-Priority	
Pollutants:	Date Analyzed
Cis-1,2- 1,3-Dich 1,2,3-Tr Allyl Ch (3-Chlor 1,2-Dibr Methyl E Methyl I Tetrahyd M-Xylene O-Xylene Cumene 1,1,1,2- 1,1-Dich 2,3-Dich Dichloro 1,1,2-Tr Ethyl Et Acetone.	••
Cis-1,2-Dichloroethylene	9-27-90
108 108 108 108 108 108 108 108 108 108	ug/L
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	MDL ug/L





P.O. BOX 249 NEW ULM, MN 56073-0249 PHONE (507) 354-8517 WATS (800) 782-3557 FAX (507) 359-2890

WE ARE AN EQUAL OPPORTUNITY EMPLOYER

Sample

Identification:

Job

#

Purgeable Aromatics:		Purgeable Halocarbons:	Date Analyz
Chlorobenzene	ichlorodifluorometinyl Chloride ethylene Chloride. richlorofluorometh ,1-Dichloroethane. rans-1,2-Dichloroethane. ,2-Dichloroethane. ,1,1-Trichloromethan arbon Tetrachlorid romodichloropropane rans-1,3-Dichloroethy hlorodibromomethan ,1,2-Trichloroethan ,1,2-Trichloroethy hlorodibromomethan ,1,2-Trichloroethy hlorodibromomethan ,1,2-Trichloroethy hlorodibromomethan ,1,2-Trichloroethy hlorodibromomethan ,1,2-Trichloroethy hlorodibromomethan ,1,2-Trichloroethy	Chloroethane	ed: 9-27-90
108 108 108 108 108		708 708 708	1/bn
0.1 0.5 0.6 2	20000000000000000000000000000000000000		MDL ug/L





P.O BOX 249
NEW ULM, MN 56073-0249
PHONE (507) 354-8517 WATS (800) 782-3557 FAX (507) 359-2890

## WE ARE AN EQUAL OPPORTUNITY EMPLOYER

Non-Priority Sample Identification: Pollutants D at Œ Analyzed: 1,1,2-7 Ethyl 1 Cumene.... 0-Xylene..... Tetrahydrofuran..... Dichlorofluoromethane.... M-Xylene Methyl Methyl 1,2-Dibromoethane (3-Chloro-1-propene). Allyl 1,1,2-Tetrachloroethane... s-1,2-Dichloroethylene. 3-Dichloropropane..... 3-Dichloro-1-Dichloro-1-Ether. Chloride Trichlorotrifluoroethane Trichloropropane... 9-2-Dichloroethylene. Isobutyl Ethyl Ketone .... gr 27-90 P-Xylene.... B-9 propene.... propene.... • Ketone (EDB). 1/bn BDL NQ BDL BDL BUL EDT TOB BDL BDL BDL BDL BDL BDL BDL BDL BDL Job MDL # 0.9 0.5 0 ND 0 0 0 6 T/bn 768

Dibromomethane.

BDL

10.

1.0

Acetone...



P.O BOX 249 NEW ULM, MN 56073-0249 PHONE (507) 354-8517 WATS (800) 782-3557

FAX (507) 359-2890

WE ARE AN EQUAL OPPORTUNITY EMPLOYER

Sample

Identification:

Job

a.					Purgeable Aromatics:																									Purgeable Halocarbons:		Date Analyzed
1,4-Dichlorobenzene	-Dichloroben	thyl Be	olu	æ	Chlorobenzene	, 2, 2-	1,1,2,2-Tetrachloroethane	romoform	-Chloroethylvin	is-1,3-Dichloropro	,1,2-Trichloroethan	<b>hlorodibromomet</b>	,1,2-Trichloroe	rans-1,3-Dichlo	,2-Dichlorop	ĺС	arbo	, 1,	,2-Dichloroethan	hloroform	Trans-1,2-Dichloroethylene	,1-Dichloroeth	,1-Dich	Trichlorofluoromethane	ene	Vinyl Chloride	Dichlorodifluoromethane	Bromomethane	Chloromethane	Chloroethane		d: 9-27-90
BDL	BDL	BDL	BDL	BDL	BDL	BDL	TDE	BDL	ÔN	BDL	BDL	BDL	BDL	BDL	BDL	BDL	BDL	BDL	BDL	BDL	BDL	BDL	TUB	BDL	ω. μ	BDL	TOB	BDL	BDL	BDL	ug/L	
0.4	•	•	•	•	•	•	•	•	ND	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•		•		MDL ug/L	





P.O BOX 249 NEW ULM, MN 56073-0249 PHONE (507) 354-8517 WATS (800) 782-3557 FAX (507) 359-2890

WE ARE AN EQUAL OPPORTUNITY EMPLOYER

Sample Identification: # 5148

Non-Priority Pollutants:	Date Ar
ints:	Analyzed:
Cis-1,2- 1,3-Dich 1,2,3-Tr Allyl Ch (3-Chlor 1,2-Dibr Methyl E Methyl I Tetrahyd M-Xylene O-Xylene Cumene 1,1,1,2- 1,1-Dich Dichloro 1,1,2-Tr Ethyl Et Acetone.	d:
Cis-1,2-Dichloroethylene	9-27-90
BD11 BD11 BD11 BD11 BD11 BD11 BD11 BD11	ug/L
0.8 0.6 0.7 0.5 1.0 1.0 0.5 1.5 0.5 0.5 0.5 0.5 1.6 0.9	MDL ug/L





P.O BOX 249 NEW ULM, MN 56073-0249 PHONE (507) 354-8517 WATS (800) 782-3557 FAX (507) 359-2890

WE ARE AN EQUAL OPPORTUNITY EMPLOYER

Sample

Identification:

Trip Blank

Job

#

Purgeable Aromatics:		Purgeable Halocarbons:	Date Analyze
Chlorobenzene  Benzene  Toluene  Ethyl Benzene  1,2-Dichlorobenzene  1,3-Dichlorobenzene  1,4-Dichlorobenzene	ichlorodifluorometh inyl Chloride ethylene Chloride. richlorofluorometha ,1-Dichloroethylene ,1-Dichloroethane. rans-1,2-Dichloroeth hloroform ,2-Dichloroethane ,1,1-Trichloromethane romodichloromethane ,2-Dichloropropane. rans-1,3-Dichloroethyl hlorodibromomethane ,1,2-Trichloroethane ,1,2-Trichloroethane ,1,2-Trichloroethane ,1,2-Trichloroethane ,1,2-Trichloroethane ,1,2-Trichloroethane ,1,2-Trichloroethane ,1,2-Trichloroethane	Chloroethane	ed: 9-27-90
BDL BDL BDL BDL BDL BDL BDL	801 801 801 801 801 801 801 801 801 801	EDL 108	T/bn
0.5 0.5 0.4	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0		MDL ug/L





P.O BOX 249 NEW ULM, MN 56073-0249 PHONE (507) 354-8517 WATS (800) 782-3557 FAX (507) 359-2890

# WE ARE AN EQUAL OPPORTUNITY EMPLOYER

Sample

Identification:

Trip Blank

Job

#

Non-Priority	N
Pollutants:	Date Analyzed:
Cis-1,2-Dichloroethylene	ed: 9-27-90
BDL BDL BDL BDL BDL 4.7 BDL BDL BDL BDL BDL BDL BDL BDL BDL BDL	<u>I/bn</u>
0.8 0.6 0.7 0.5 1.0 0.5 0.5 0.5 0.5 0.5 0.5 0.6 0.6 0.6 0.6 0.7	MDL ug/L