


8650

GME CONSULTANTS, INC.

CONSULTING ENGINEERS

Lake Shore Drive / P.O. Box 250
Crosby, MN 56441 / (218) 546-6371



FAX COVER SHEET

DATE 9-8-97 TIME PM

TO: NAME Steve Thompson
COMPANY MPCA
PHONE NUMBER _____
LOCATION _____

FROM: NAME Mark Millsop
COMPANY GME CONSULTANTS, INC.
PHONE NUMBER (218) 546-6371
LOCATION CROSBY, MINNESOTA 56441

.....

WE ARE SUBMITTING 4 PAGES (INCLUDING THIS COVER SHEET);

OUR FAX NUMBER IS (218) 546-6196.

Hi Steve,

Bob D. called me + said Mark k. mentioned that you or he hadn't seen the attached I FAX'd awhile back - sorry about the mix-up. *Mark*

.....
The information contained in this facsimile message is privileged and confidential information intended for the use of the individual or entity name above. If the reader of this message is not the intended recipient or the employee or agent responsible to deliver it to the recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this fax in error, please immediately notify us by telephone, and return the original message to us at the above address via the U.S. Postal Service.
.....

WILLIAM C. KWASNY, P.E.
GREGORY R. REUTER, P.E.
MARK D. MILLSOP

THOMAS PAUL VENEMA, P.E.
WYATT A. GUTZKE, P.E.
SANDRA J. FORREST

WILLIAM E. BLOEMENDAL, P.E.
MERYYN MINDESS, P.E.
STEVEN J. RUEBINK, P.E.

An Equal Opportunity Employer


GME CONSULTANTS, INC.

Geotechnical • Materials • Environmental
 P.O. Box 250, Lakeshore Drive
 Crosby, Minnesota 56441
 (218) 546-6371
 Fax (218) 546-6186

 JOB NO. C2373D SHEET 1 OF

 JOB NAME Dittmer Oil

 BY MDM DATE 7-9-97

 CHECKED BY DATE

Leak 1940

Dear Steve,

On April 4, you requested more info regarding the Dittmer Oil project, which is explained below:

- A) The well abandonment log for the old Co-op well is attached - it also was in the Appendix of our 2-25-97 report.
- B) The sampling results for the old + new Co-op wells are shown in Table 2 of the 2-25-97 report; only the January 9, 1997 results are for the new well and all other results are for the old well.
- C) No map of the drain tile lines exists, according to our files (and no "locals" know the exact layout). Figure 5 in our 2-25-97 report and Figure 11 in our 5-3-96 UST Report show as much as we know about the system at this time.

Our last report on 2-25-97 recommended site closure as the plume is 300 - 600 feet from the new Co-op well and the Bemnells

**GME CONSULTANTS, INC.**

Geotechnical • Materials • Environmental
P.O. Box 250, Lakeshore Drive
Crosby, Minnesota 56441
(218) 548-8371
Fax (218) 548-8188

JOB NO. _____ SHEET 2 OF 2JOB NAME Dittmer OilBY _____ DATE 7-9-97

CHECKED BY _____ DATE _____

Well, and there apparently is a significant thickness of clay vertically separating the petroleum impacts residing in a non-resource aquifer from ^{lower} sand layers used as aquifers. Again, we request site closure, based on the results to date. Please let me know if you have any more questions.

Sincerely,
Mark Millrop

WELL OR BORING LOCATION

County Name **Renville**

MINNESOTA DEPARTMENT OF HEALTH

WELL AND BORING SEALING RECORD

Minnesota Well and Boring Sealing No.

Minnesota Unique No. or W-series No.

H 56279

Township Name **Cairo** Township No. **112** Range No. **32** Section No. **8** Fraction (con. - 1/4)

Date Sealed **7/18/96**


Approximate Date Well or Boring Constructed **4/20/84**

Numerical Street Address or Plot Number and City of Well or Boring Location

Highway 17 Fairfax MN

Depth Before Sealing **92** ft. Original Depth _____ ft.

Static Water Level Accurate Approximate **89** ft. below _____ above (top) surface



Single Aquifer Multi-aquifer

CASING TYPE Steel Plastic Tile Other

Screen from **180** to **192** ft. Open Hole from _____ to _____ ft.

OBSTRUCTION/DEBRIS/FILL Obstruction Debris Fill

Type of debris/obstruction **Pitless**

Obstruction/Debris/Fill removed? Yes No

PUMP Removed Not Present Other

CASING Diameter _____ Depth _____ Set in concrete hole? Yes No Annular space initially grouted? Yes No Unknown

METHOD USED TO SEAL ANNULAR SPACE BETWEEN 2 CASINGS, OR CASING AND BORE HOLE. No Annular Space Exists Annular space grouted with tremie pipe Casing Perforation/Removal

_____ in. from _____ to _____ ft. Perforated Removed

_____ in. from _____ to _____ ft. Perforated Removed

Type of perforator _____

Other _____

GROUTING MATERIAL **Bentonite** from **192** to top ft. _____ yards _____ bags

_____ from _____ to _____ ft. _____ yards _____ bags

_____ from _____ to _____ ft. _____ yards _____ bags

_____ from _____ to _____ ft. _____ yards _____ bags

UNSEALED WELLS AND BOREHOLES Other unsealed well or boring on property? Yes No

LICENSED OR REGISTERED CONTRACTOR CERTIFICATION This well or boring was sealed in accordance with Minnesota Rules, Chapter 4725. The information contained in this report is true to the best of my knowledge.

Peterson Well Drilling CE338 Contractor Business Name License or Registration No.

_____ 7/27/96 Authorized Representative Signature Date

Shawn Peterson Name of Person Sealing Well or Boring

PROPERTY OWNER'S NAME **Old Co-op**

Mailing Address if different than property address indicated above.

600 East Lincoln Ave

55332 Fairfax, MN

GEOLOGICAL MATERIAL COLOR HARDNESS OF FORMATION FROM TO

GEOLOGICAL MATERIAL	COLOR	HARDNESS OF FORMATION	FROM	TO
Top Soil	Black	Soft	0	2
Clay	Yellow	Soft	2	29
Clay	Blue	Hard	29	61
Rock	Grey	Hard	61	62
Clay	Blue	Hard	62	170
Sand	Yellow	Soft	170	192

REMARKS, SOURCE OF DATA, DIFFICULTIES IN SEALING

AKA "Old Co-op Well"

LOCAL COPY H 56279