520 Lafayette Road North | St. Paul, MN 55155-4194 | 651-296-6300 | 800-657-3864 | 651-282-5332 TTY | www.pca.state.mn.us

January 16, 2009

Ms. Nancy Radle Minnesota Department of Transportation Transportation Building 395 John Ireland Boulevard St. Paul, MN 55155-1899

RE: Petroleum Tank Release Site File Closure

Site: Former Clark Station, Highway 55 and Lake Street, Minneapolis

Site ID#: LEAK00008324

Dear Ms. Radle:

We are pleased to let you know that the Minnesota Pollution Control Agency (MPCA) Petroleum Remediation Program (PRP) staff has determined that your investigation and/or cleanup has adequately addressed the petroleum tank release at the site listed above. Based on the information provided, the PRP staff has closed the release site file.

Closure of the file means that the PRP staff does not require any additional investigation and/or cleanup work at this time or in the foreseeable future. Please be aware that file closure does not necessarily mean that all petroleum contamination has been removed from this site. However, the PRP staff has concluded that any remaining contamination, if present, does not appear to pose a threat to public health or the environment.

The MPCA reserves the right to reopen this file and to require additional investigation and/or cleanup work if new information or changing regulatory requirements make additional work necessary. If you or other parties discover additional contamination (either petroleum or non-petroleum) that was not previously reported to the MPCA, Minnesota law requires that the MPCA be immediately notified.

You should understand that this letter does not release any party from liability for the petroleum contamination under Minn. Stat. ch. 115C (2008) or any other applicable state or federal law. In addition, this letter does not release any party from liability for non-petroleum contamination, if present, under Minn. Stat. ch. 115B (2008), the Minnesota Superfund Law.

If future development of the site or the surrounding area is planned, it should be assumed that petroleum contamination may be present. State law requires that persons properly manage contaminated soil and water they uncover or disturb - even if they are not the party responsible for the contamination. For some properties, special construction may also be needed to prevent the further spreading of the contamination and/or to prevent petroleum vapors from entering buildings or utility corridors. The MPCA Petroleum Brownfields Program can assist with reviews and approvals of Development Response Action Plans required to address environmental risk from petroleum contamination. If contamination is encountered during development work, contact the MPCA immediately.



Ms. Nancy Radle Page 2 January 16, 2009

For specific information regarding petrcleum contamination that may remain at this leak site, please call the Petroleum Remediation File Request Program at 651-757-2799. Thank you for your response to this petroleum tank release and for your cooperation with the MPCA to protect public health and the environment. If you have any questions regarding this letter, please call Mark Koplitz at 651-757-2502 or site hydrogeologist Bassou Oulgout at 651-757-2632.

Sincerely,

Mark Koplitz
Project Leader

Petroleum and Closed Landfill Section

Remediation Division

Bassou Oulgout

Hydrogeologist

Petroleum and Closed Landfill Section

Remediation Division

MK:tf

Josh Goplin, City of Minneapolis, Environmental Bonnie Bleskachek, Fire Chief, Minneapolis

Dave Jaeger, Hennepin County Solid Waste Officer Minnesota Department of Commerce Petrofund Staff



Transportation Building 395 John Ireland Boulevard St. Paul, Minnesota 55155-1899

RECEIVED

FEB 22 2000

February 16, 2000

MPCA, Metro District Site Remediation

Mr. Mark Koplitz Minnesota Pollution Control Agency Metro Site Remediation Section 520 Lafayette Road North Saint Paul, MN 55155-4194

RE:

UPDATE – Petroleum Release Investigation and Corrective Action Former Clark Oil Station – T.H. 55/Lake Street Intersection, Minneapolis

MPCA Leak Number 8324

Dear Mr. Koplitz:

The Minnesota Department of Transportation (Mn/DOT) has received your letter dated February 4, 2000 regarding the referenced site. In the November 19, 1996 memorandum from Mn/DOT to the MPCA, it was stated that "Once the construction project [for Hiawatha Avenue] is complete, Mn/DOT will evaluate the potential for replacing monitoring wells and recovering free product." At this point, construction activities are anticipated to be complete in the spring or summer of 2000. However, it is possible at this point to consider possible additional investigation/free product recovery activities.

As of the last site visit, only two monitoring wells remained from the initial monitoring network of nine wells that had been installed for the investigation of the referenced site and for Leaksite 360. Construction activities required the removal of the majority of the monitoring network. Because of the reconstruction, site conditions are vastly different from when the remedial investigation work was conducted. Much of the free product area may be inaccessible via traditional investigation methods.

Mn/DOT recommends that MPCA and Mn/DOT staff meet at the site to review existing conditions, compare current transportation infrastructure locations to figures depicting site conditions prior to reconstruction, and consider possible additional investigation/remediation measures if necessary.

Please contact me at (651) 284-3782 or via e-mail at scott.reed@dot.state.mn.us with any questions regarding information in this letter or to schedule the recommended site visit.

Sincerely

Scott M. Reed, P.G.

Project Manager/Hydrogeologist

Environmental Compliance and Investigation Unit

cc:

File

Kania, Lauralin [HWTSS]

From:

Kelly, James [GWSRS]

To: Cc: Kania, Lauralin [HWTSS] Haas, Jennifer [GWSRS]

Subject:

Hiawatha Corridor Project

Date:

Wednesday, May 01, 1996 2:29PM

Jennifer and I have been invited to attend a meeting of the People of Phillips neighborhood group on Thursday evening, May 9th. We were invited after sending out a letter to their group in early April describing the environmental issues associated with the Hiawatha Corridor project. The letter basically summed up the issues related to contaminated soil handling (both petroleum and non-petroleum), air monitoring, and groundwater. We're not aware of any major concerns out there, so we're just planning on providing the basics and answering any questions they may have. The letter is also going to another neighborhood council on the other side of Hiawatha. We're doing all this mostly as a result of MnDOT's recalcitrance on this issue, and at the urging of a Minneapolis City Council member.

Anyway, we just wanted to let you know about the meeting. If there is any information that you think is especially important for the group to have regarding petroleum issues, or that we don't have, please let us know. Of course you could attend the meeting with us if you'd like - it's totally up to you. As I mentioned though, we're not aware of any major issues so it's more of an informational trip for us.

Lemme know if you have any questions, or info we're missing. Thanks -

Jim

PAGE 1 INVOICE **Customer Name** MINN ST TRANSPORTATION DEPT 0 Invoice Date Invoice Number Remit to: Customer Number MN POLLUTION CONTROL AGENCY R32-34300000600 04/29/96 0000001353-L FISCAL SERVICES 520 LAFAYETTE ROAD NORTH **Amount Enclosed Amount Due** Due Date 600.00 05/29/96 ST. PAUL MN 55155-4194

Bill to:

MINN ST TRANSPORTATION DEPT 3485 HADLEY AVE N

DAKDALE

3.5			100		
	2 1	0.00	~ ~	200	8
- 1	NΝ	Estable.	ゝっ		/ X
92.0	30.00	100	-	-	
1000	1000		1000		

Method of Payment: (Check Appropriate Box) ☐ Check ☐ Money Order

Please write INVOICE No. on front of check or Money Order. DO NOT MAIL CASH

\neg	Please check if address has changed
_	Write correct address on back of stub
	and enclose with payment.

Please detach the above stub and return with your remittance payable to: MN POLLUTION CONTROL AGENCY

The State of Minnesota

INVOICE

PAGE 1

Customer Number	Billing Code	Orig. Inv. Date
0000001353-L	32PA	

Federal Tax ID: 41-6007162

Due Date Customer Name Invoice Number Invoice Date

MIN	N ST TRANSPORTATION DEPT O	R32-3	4300000600		04/29/96	05/29/96
Ref Line No.	DESCRIPTION	Date of Service	No. of Units	Unit of Measure	Unit Price	CHARGES/CREDIT
01	TECHNICAL ASSISTANCE	03/01/96	10.00	HRS	60.000	600.00
	ATTN: SCOTT REED RE: LEAK00008324, FORMER CLARK OIL S REVIEW OF RI/CAD. QUARTERLY MONITORIN			:: IICAL		

REPORTS ON MARCH 12-13, 1996. ALL WORK WAS DONE BY BASSOU OULGOUT. HE CAN BE REACHED AT 612/297-8597

INVOICE TOTAL:

600.00

KEY INV# EXACTLY AS SHOWN. V#200019012-00, SELL ACT TYPE 02. PV TYPE 6.IF YOU NEED MORE INFO CONTACT PERSON ON INVOICE



Minnesota Pollution Control Agency

April 29, 1996

Mr. Scott M. Reed Minnesota Department of Transportation Environmental Compliance and Investigation Unit 3485 Hadley Avenue North Oakdale, Minnesota 55128

RE: Hiawatha Corridor Construction, 28th Street to 32nd Avenue, Minneapolis Project Number 6020

Dear Mr. Reed:

The Minnesota Pollution Control Agency (MPCA) staff in the Voluntary Investigation and Cleanup (VIC) Unit has reviewed reports submitted for the Hiawatha Corridor construction project, from 28th Street to 32nd Avenue, Minneapolis (the Site). The reports reviewed (Site Documents) include the following:

- 1. "Environmental Profile Hiawatha Avenue Reconstruction from I-94 to Lake Street," dated November 25, 1991, prepared by EnPro Assessment Corp;
- "Drilling Investigation Trunk Highway 55, Hiawatha Corridor Southern Portion," dated December 29, 1994, prepared by Braun Intertec Corporation (Braun);
- 3. "Drilling Investigation Report CMC Heartland Partners Property, Trunk Highway 55 and 28th Street, Minneapolis, Minnesota," dated January 17, 1995, prepared by Nova Environmental Services:
- 4. "Soil Response Action Plan, Southern Portion of Hiawatha Avenue Corridor, Lake Street to East 24th Street, Minneapolis, Minnesota," dated July 24, 1995, prepared by Braun;
- 5. "Hiawatha Corridor Site Assessment Review and Surface Soil Sampling Plan, Hiawatha Corridor (Trunk Highway 55), Minneapolis, Minnesota," dated November 6, 1995, prepared by Braun;
- 6. "Surface Soil Sampling Investigation Results and Soil Response Action Plan Implementation Addendum, Hiawatha Corridor (Trunk Highway 55), 28th Street to 32nd Avenue, Minneapolis, Minnesota," dated February 5, 1996, prepared by Braun;
- 7. "Response Action Plan Addendum, Hiawatha Corridor (Trunk Highway 55), 28th Street to 32nd Avenue, Minneapolis, Minnesota," dated March 12, 1996, prepared by Braun;

- "Final Changes to Response Action Plan Addendum, Hiawatha Corridor (Trunk Highway 55), 28th Street to 32nd Avenue, Minneapolis, Minnesota," dated April 10, 1996, prepared by Braun; and
- 9. Various correspondence contained in MPCA files.

Based on MPCA staff's review of the Site Documents, the Response Action Plan with addenda (Site Documents numbered six through eight above) is hereby approved subject to the modifications listed in Attachment B. Please note that it is the MPCA staff's understanding that a deed notification will be placed on the property deed(s) indicating the location(s) of contaminated soil that is placed or remains on the Site.

Additionally, as you are aware, the MPCA staff strongly recommends (and has requested repeatedly during meetings and conference calls beginning in August 1995) that the Minnesota Department of Transportation (MnDOT) notify the public about the environmental problems that will be encountered during the construction project. The MPCA staff has sent a letter summarizing the contamination issues to local neighborhood groups and plans to attend a public meeting, due to MnDOT's failure to inform the public on this issue to date.

Please be advised that this letter is subject to the disclaimers listed in Attachment A.

If you have any questions concerning this letter, please contact Jim Kelly at (612) 296-7744 or Jennifer Haas at (612) 297-1802 of the VIC Unit staff.

Sincerely,

Deborah B. DeLuca

Unit Supervisor

Voluntary Investigation and Cleanup Unit

D. Inch B. a Duce

Site Response Section

Ground Water and Solid Waste Division

DBD:ilm

cc: Christine M. McCarthy, Braun Intertec Corp.
R. Kannankutty, City of Minneapolis
Cathy Thurber, Minneapolis City Councilperson, 9th Ward
Joel Williams, MnDOT Metro Construction

Laurie Kania, MPCA - HW/TERS

Annie Young, The Green Institute

Matt Williams, People of Phillips

ATTACHMENT A DISCLAIMERS Hiawatha Corridor Construction 28th Street to 32nd Avenue

1. Reservation of Authorities

The MPCA Commissioner reserves the authority to take any appropriate actions with respect to any release, threatened release, or other conditions at the Site. The MPCA Commissioner also reserves the authority to take such actions if the voluntary party does not proceed in the manner described in this letter or if actions taken or omitted by the voluntary party with respect to the Site contribute to any release or threatened release, or create an imminent and substantial danger to public health and welfare.

2. No MPCA Assumption of Liability

The MPCA, its Commissioner and staff do not assume any liability for any release, threatened release or other conditions at the Site or for any actions taken or omitted by the voluntary party with regard to the release, threatened release, or other conditions at the Site, whether the actions taken or omitted are in accordance with this letter or otherwise.

3. Letter Based on Current Information

All statements, conclusions and representations in this letter are based upon information known to the MPCA Commissioner and staff at the time this letter was issued. The MPCA Commissioner and staff reserve the authority to modify or rescind any such statement, conclusion or representation and to take any appropriate action under his authority if the MPCA Commissioner or staff acquires information after issuance of this letter that provides a basis for such modification or action

4. Disclaimer Regarding Use or Development of the Property

The MPCA, its Commissioner and staff do not warrant that the Site is suitable or appropriate for any particular use.

5. Disclaimer Regarding Investigative or Response Action at the Property

Nothing in this letter is intended to authorize any response action under Minn. Stat. § 115B.17, subd. 12.

ATTACHMENT B MODIFICATIONS

Hiawatha Corridor Construction 28th Street to 32nd Avenue

- 1. If significant volumes of ground water are encountered in excavations the MPCA shall be contacted to discuss options for handling the ground water.
- 2. Copies of air monitoring logs shall be provided to the MPCA staff on a weekly basis.
- 3. MnDOT shall make every effort to ensure that contaminated soil is not carried or spread off the Site by construction vehicles or through airborne dust.
- 4. A copy of the Site Health and Safety Plan shall be submitted to the MPCA staff for review.

BRAUN MINTERTEC

Ground Water & Solid Waste Divisions Northland Drive Mendota Heights, Minnesota 55120-1141 612-683-8700 Fax: 683-8888

Category Engineers and Scientists Serving the Built and Natural Environments

Subcategory

Initials

Project No. CMXX-95-0125

April 10, 1996

Ms. Jennifer Haas
Voluntary Investigation and Cleanup Program
Minnesota Pollution Control Agency
520 Lafayette Road North
St. Paul, MN 55155-4194

Dear Ms. Haas:

Re: Final Changes to Response Action Plan Addendum, Hiawatha Corridor (Trunk Highway 55), 28th Street to 32nd Avenue, Minneapolis, Minnesota

On behalf of the City of Minneapolis and the Minnesota Department of Transportation (MnDOT), Braun Intertec Corporation (Braun Intertec) has made the following final changes to the Response Action Plan (RAP) Addendum presented to the Minnesota Pollution Control Agency (MPCA) on March 12, 1996:

Soil Stockpiles and Associated Sampling

- * To evaluate the potential hazard of excavated non-petroleum contaminated soil, up to four composite soil samples will be collected from each stockpile generated from Site cc, Site ee, Site ff, Site j, and Site 1. Each stockpile sample will be analyzed for polycyclic aromatic hydrocarbons (PAHs), total lead, and/or Resource Conservation and Recovery Act (RCRA) metals as stated in the March 12, 1996 RAP Addendum.
- * To document the concentrations of petroleum contaminated fill placed in the northern and southern portions of the Lake Street Bridge structure, soil samples will be collected from locations petroleum contaminated soil has been placed. Grab soil samples will be collected from what appear representative portions of the fill based on the number of soil samples required in accordance with MPCA Tanks and Spills Fact Sheet #13.
- * All petroleum and non-petroleum contaminated soil excavated and stockpiled during the Hiawatha reconstruction project will be placed within designated construction limits.

APR : 2 1996

MP Project No. CMXX-95-0125 April 10, 1996 Page 2

Groundwater Sampling at Site M

- Groundwater likely encountered during the storm water utility excavations at the northwestern corner of Lake Street and Hiawatha Avenue (Site M), will be sampled and analyzed for parameters required by the Metropolitan Council Office of Wastewater Services for sanitary sewer disposal. In addition, the groundwater from this site will be sampled for parameters likely associated with past site use including; petroleum related constituents (diesel range organics and gasoline range organics), total lead, and volatile organic compounds.
- * If groundwater is encountered in any of the other excavations during construction activities, groundwater samples will be collected and analyzed for parameters likely associated with past site use.

Air Monitoring

Air monitoring utilizing the MiniRam® (realtime aerosolization monitoring device) will be conducted in areas where construction activities involve non-petroleum (PAHs and RCRA metals) contaminated soils. On-site organic vapor monitoring will be conducted according to procedures outlined in the site specific Health and Safety Plan during construction activities in the petroleum contaminated areas.

MiniRam® air monitoring activities will be conducted as follows:

- Measurements of total particulate concentrations will be obtained in the upwind (background), breathing zone (immediate work area), and downwind (at construction limit or edge of exclusion zone) locations twice daily. If weather conditions or construction activities cause for increases in dust suspension, the air monitoring frequency will be increased accordingly.
- * Weather conditions, construction activities, and MiniRam® readings will be documented in the designated project field daily log.
- Based on the maximum concentrations of PAHs and RCRA metals identified in the soils at Sites cc, ee, ff, j, and l and the Occupational Safety and Health Administration's (OSHA) permissible exposure limits (PELs), the maximum allowable particulate suspension within the breathing zone and downwind locations will be 1 milligram per cubic meter (mg/m³) and 5 mg/m³, respectively. If these levels are exceeded in either the breathing zone or downwind locations, dust suppression methods will be implemented. Since impact from dust associated with construction activities is anticipated to be less in areas further downwind than immediately downwind from the construction zone, air monitoring at the construction limit or edge of the exclusion zone should be sufficient to identify the potential for exposure to the surrounding community.
- * To evaluate particulate suspension conditions upwind in relation to conditions onsite, background MiniRam® readings will be obtained on-site at a location immediately upwind of the excavation activity.

MPCA Project No. CMXX-95-0125 April 10, 1996 Page 3

Following your review and agreement to these final RAP Addendum changes, please provide us with the appropriate written approval so that construction activities within the contaminated areas may begin as soon as possible. Should you have any questions regarding the above, please call Christine at (612) 683-8721 or Richard at (612) 683-8752.

Sincerely,

Christine M. McCarthy

Project Manager/Geologist

Richard M. Johnston

Project Coordinator, Principal

₹ c:

Mr. Darnell Blume, City of Minneapolis

Ms. Laurie Kania, MPCA

Mr. Ramman Kannankutty, City of Minneapolis

Mr. Leonard Krumm, City of Minneapolis

Mr. Scott Reed, MnDOT

f:*wpfiles\cmxx\95\0125\0125.L02

DEPARTMENT OF TRANSPORTATION - Office of Environmental Services

invoice 2hr + fike

DATE: Nove

November 19, 1996

TO:

Laurie Kania, Project Manager

Voluntary Petroleum Investigation and Cleanup Program

Minnesota Pollution Control Agency

FROM:

Scott M. Reed, Hydrogeologist

Environmental Compliance and Investigation Unit

PHONE:

779-5103

SUBJECT:

S.P. 2724-103, T.H. 55 (Hiawatha Avenue)

Former Clark Oil Service Station, 2308 East Lake Street, Minneapolis

MPCA Leak Number 8324

Enclosed for your review is a copy of the "Petroleum Release Remedial Investigation Addendum" prepared by Barr Engineering Company for the referenced site. This report summarizes the results of additional field investigation work requested in your letter dated April 18, 1996. Specifically, the report provides additional groundwater analytical results and vapor risk survey results.

The vapor risk survey did not detect any evidence of petroleum vapors in the sewer systems near the site. The additional round of groundwater sampling indicated that free product is still present in MW-102. No petroleum compounds were detected in MW-101 or MW-103, with the exception of 0.36 mg/L of diesel range organics (DRO) detected in MW-103. However, the chromatogram of the DRO analysis indicated that the result was likely caused by laboratory contamination or naturally occurring organic compounds. Since the groundwater sampling event, all monitoring wells except MW-3 from the Miller & Holmes remedial investigation and MW-103 have been abandoned during the reconstruction Hiawatha Avenue.

Once the construction project is complete, Mn/DOT will evaluate the potential for replacing monitoring wells and recovering free product. Please call if you have any questions or require additional information.

enclosure

cc (w/out encl):

S. Kordosky

E. Ruhland

cc (w/ encl.):

File

DEPARTMENT OF TRANSPORTATION - Office of Environmental Services - Oakdale

STATE OF MINNESOTA

Office Memorandum

DATE:

May 6, 1996

TO:

Lauralin Kania, Project Manager

Voluntary Petroleum Investigation and Cleanup Unit/

Minnesota Pollution Control Agency

FROM:

Scott M. Reed, Hydrogeologist

Environmental Compliance and Investigation Unit

PHONE:

779-5103

SUBJECT:

S.P. 2724-103, Trunk Highway 55 (Hiawatha Avenue)

Former Clark Oil Station MPCA Leak Number 8324

RECEIVED

MAY 08 1996

MPCA, HAZARDOUS WASTE DIVISION

As part of the Hiawatha Avenue reconstruction project, Mn/DOT has abandoned several of the monitoring wells at the former Clark Oil site. Among these wells are MW-4 and MW-102, both of which have shown evidence of free product. Construction activities have necessitated the removal of these monitoring wells. Groundwater elevation measurements and analytical samples (from wells without free product) were taken at the site prior to well abandonment. Following completion of construction activities, Mn/DCT will work with the MPCA to determine which monitoring wells should be replaced to continue assessment of the contamination plume at the site.

One of the requests from the MPCA for continued monitoring of the Clark Oil site was to complete a vapor risk survey in the Lake Street utilities to the south. Traffic volumes on Lake Street and Hiawatha Avenue make this survey difficult to complete. However, at various times during this construction project, traffic will be diverted around the Hiawatha/Lake intersection. This will allow the vapor risk survey to be completed with minimal traffic hazards. Data should be available later this summer.

Please call if you have any questions or require additional information regarding this project.

3485 Hordler Oak Dale
35138

cc:

J. Williams

B. Johnson/File



Minnesota Pollution Control Agency

April 18, 1996

Mr. Scott Reed Minnesota Department of Transportation 3485 Hadley Avenue North Oakdale, Minnesota 55128

RE: Petroleum Tanks Release Site Corrective Action Design Approval

Site: Former Clark Oil Service Station, 2308 East Lake Street, Minneapolis

Site ID#: LEAK00008324

Dear: Mr. Reed

Minnesota Pollution Control Agency (MPCA) Tanks and Emergency Response Section staff has reviewed your "Petroleum Release Remedial Investigation Report" dated February 1996 outlining a plan of response to the petroleum tank release(s) at the above-referenced site. The MPCA staff hereby approves the implementation of the proposed recommendations which consist of the following:

- A.- Leaving contaminated soils in place and addressing them as needed during road construction and utility installation,
- B.- Perform a vapor risk assessment on the Lake Street sewer line east of the Lake Street/Hiawatha Avenue intersection,
- C.- Continue the recovery of free product using passive product recovery at the existing monitoring wells where free product has been detected,
- D- Continue ground water monitoring using the existing monitoring network and analyse for benzene, toluene, xylene, gasoline range organics and diesel range organics.

If subsequently obtained information indicates that the approved corrective actions are inappropriate or inadequate, the MPCA may require additional work or modifications in the approved work.

Approval of this CAD is based on its environmental merits for addressing the petroleum contamination only. This letter does not apply to other types of contamination that may be present on the subject property. You are responsible for insuring that this remedial system complies with all applicable building, electrical and fire codes and health department rules, and that all necessary state and local approvals are obtained.

This approval qualifies you under Minn. Stat. § 115C.09, subd. 2(a)(3) (1994) to be eligible for Petrofund reimbursement of eligible cleanup costs. Applications for reimbursement must be made directly to the Petrofund. Decisions regarding Petrofund reimbursement are made by the Petro Board. Reimbursement decisions are based on factors such as the adequacy of cleanup, reasonableness of cost, compliance with notification laws, and cooperation with the MPCA.

If you have questions regarding the investigation of ground water at this site, please contact MPCA staff hydrogeologist Bassou Oulgout at 612/297-8597. If you have any other questions, please call me at 612/297-8600.

Sincerely,

Laurie Kania Voluntary Petroleum Investigation and Cleanup Tanks and Emergency Response Section

LK:bah

cc: Gary Remple, Barr Engineering, Minnespolis
Minnesota Department of Commerce Petrofund Staff



Program Application Request for Assistance Form

Complete this form to request assistance from the Minnesota Pollution Control Agency (MPCA) staff in the Voluntary Petroleum Investigation and Cleanup (VPIC) Program pursuant to Minn. Stat. § 115C.03, subd. 9 (as amended by Minn. Laws, 1994). Answer all applicable questions.

If you have any questions about the services offered by the MPCA VPIC Program or this application, please contact Laurie Kania at 612/297-8600 or Bassou Olgout at 612/297-8597. The MPCA can also be reached at 1-800-657-3864.

Please mail the completed form to:

Laurie Kania
Tanks and Spills Section
Voluntary Petroleum Investigation and Cleanup
Minnesota Pollution Control Agency
520 Lafayette Road
St. Paul, Minnesota 55155

Subject Property Name Former Clark Oil Service Station 2308 East Lake Street Address Zip Code _55406 City (or Township) County Hennesin Applicant* Organization Hadlen Avenue Zip Code _53728 City Oakdale State Phone (612) 779-5103 Federal Employer ID Minnesota Taxpayer ID _____NA Social Security Number (if individual)

* The applicant is the individual seeking review of a petroleum release site and/or issuance of a General Liability, Determination, Verification or Confirmation letter by the MPCA VPIC Program. The applicant is responsible for payment of MPCA costs to provide services as requested by application.

Description of Applicant's Request Expedited review of a petroleum storage tank release site (e.g., MPCA Leak Site). Will provide expedited review of Remedial Investigation/Corrective Action Design (RI/CAD) and other reports required for these sites by the MPCA Tanks and Spills Section, Leaking Underground Storage Tank (LUST) Program.
MPCA ID# LEAK0000 8324 and LEAK00000360
Review of a petroleum release site for which the contamination did not originate from a tank (e.g., petroleum non-tank release site). Will provide review of Phase I and II Environmental Site Assessment and other reports.
MPCA ID# SPILL0000 (if applicable)
Review of site development plan for a petroleum impacted property. MPCA ID# LEAK0000(if applicable)
General Liability letter.
Off-site Tank Release Determination letter. Suspected source MPCA ID# LEAK0000
Leak Site Tank Removal Verification letter. MPCA ID# LEAK0000
Leak Site File Closure Confirmation letter. MPCA ID# LEAK0000
Other technical assistance not specified above (Please attach separate sheet describing request).
Applicant's Interest Currently owns property Considering purchasing property Responsible party (as defined under Minn. Stat. 115C) Mortgagee interest in property Renting or leasing property Other (explain) Property development
Current Property Owner (If Different from the Applicant) Name Title
OrganizationPhone
Address
City State Zip Code

General Information Has the subject property been entered into the MPCA Voluntary Investigation and Cleanup (VIC) Program which offers services pertaining to properties with non-petroleum contamination? Yes X No > Surrounding TH 55 corridor, not leakentes specifically. If yes, please attach a separate sheet describing VIC's involvement.
Please list the names of MPCA staff that you have spoken with regarding the subject property. Mitch Chicali, Barb Hearley - Tunks a Emergency Response Section
Contact Persons Please list the name(s) of your current environmental consultant and legal counsel, if applicable.
Attorney Sherry Enzler - Office of the Attorney Phone (612) 832-2734 Consultant Garry Remple - Barr Engineering Phone (612) 832-2734 Phone (612) 282-5705
Authorization and Agreement to Pay for Services I hereby request the MPCA VPIC staff to provide services to me and the company/organization I represent, as requested by this application. I understand that if an expedited review of a Leak Site is the requested service, VPIC staff will retain review authority until the site file is closed or until the date they receive a written request from me to cease VPIC review of the site. I understand that I will be billed for these services at the rate of \$60.00 per hour and that I am required by Minn. Stat § 115C.03, subd. 9 (as amended by Minn. Laws, 1994) to reimburse the MPCA for the Agency's costs, as determined by the MPCA Commissioner. I further understand that legal or administrative action may be initiated against me by the State of Minnesota if I do not reimburse the MPCA.
I hereby agree to pay the costs of the MPCA to provide services to the applicant as requested in this application. Furthermore, I hereby certify that I have the authority to submit this application on behalf of the applicant named herein.
Name (type or print) Seath M. Reed Signature Date 2-21-46 Title Hydrogeologist

DEPARTMENT OF TRANSPORTATION - Office of Environmental Services - Oakdale

STATE OF MINNESOTA Office Memorandum

May 22, 1995 DATE:

Jean Hanson, Project Leader TO:

Tanks and Spills Section

Minnesota Pollution Control Agency

Scott M. Reed, Hydrogeologist FROM:

3 MReed Environmental Compliance and Investigation Unit

779-5103 PHONE:

Former Clark Oil Service Station, T.H. 55 and Lake Street SUBJECT:

> Mn/DOT S.P. 2724-103 MPCA Leak Number 8324

This memorandum is in response to your letter dated May 9, 1995. The Minnesota Department of Transportation (Mn/DOT) has initiated free product recovery at the monitoring well (MW-4) located at the above referenced leak site. Approximately 0.5 gallons of product has been recovered since the initiation of recovery operations on April 10, 1995.

Free product was initially discovered during an investigation at the former Miller & Holmes (M&H) station (MPCA Leak Number 360) to the west of the former Clark Oil site. On July 18, 1991, Leggette, Brashears & Graham, Inc. (LBG), M&H's consultant, installed monitoring well MW-4 at the Clark Oil site to provide additional groundwater information for the investigation of leak 360. Free product was discovered in August 1991.

The investigation work completed by LBG and later by Geraghty & Miller, Inc. (M&H's second consultant) subsequently indicated that the free product found in MW-4 is likely associated with a release from the former Clark Oil site. In a telephone conversation with Michael Chiodi, MPCA hydrogeologist, on February 14, 1995, Mn/DOT was informed that the Clark Oil site was being considered a separate release and the MPCA requested Mn/DOT to initiate free product recovery. Mn/DOT agreed to install a passive free product recovery system in MW-4 and indicated that a remedial investigation would likely be completed at the site when funding is available.

Based on information from our files, Mn/DOT purchased the site on April 11, 1969. underground storage tanks (a 6,000 gallon tank, a 3,000 gallon tank, and a 1,000 gallon tank) were removed from the site sometime after September 10, 1970. The tanks reportedly contained gasoline.

Attached for your review is a copy of the "Free Product Recovery Worksheet" for leak 8324. Also included is the data from a Geraghty & Miller report showing the date of free product discovery. Mn/DOT will initiate a remedial investigation of the Clark Oil site in mid-1995, with work expected to be completed by fall 1995.

Page 2 May 22, 1995

Please call if you have any questions or require additional information.

Enclosure

cc (w/ encl.):

File

cc (w/out encl.):

S. Enzler

K. Rasmussen

M. Spielmann

B. Johnson

FREE PRODUCT RECOVERY REPORT WORKSHEET Fact Sheet #5 Minnesota Pollution Control Agency LUST Cleanup Program April 1993

The completion and submittal of this worksheet fulfills the federal (U.S. Environmental Protection Agency) requirement to report to the Minnesota Pollution Control Agency (MPCA) regarding interim product recovery actions within 45 days of free product discovery. For further information on your obligations regarding free product, consult fact sheet \$18 "Free Product: Evaluation and Recovery."

	Site name: Former Clark Oil Station Location: NE Corner of the TH 55/Lake Street Intersection
1,	Free product discovery date: August 23, 1991 NA NA
2.	You are required to report free product within 24 hours of discovery by calling the State Duty Officer at 612-649-5451, 612-296-8100, or 1-800-422-4798.
	Call date: N/A Call time: N/A Contact person: N/A
	Circumstances of free product discovery (e.g., UST removal, during routine monitoring well sampling, etc.). Tree product discovered during RI muestigation of adjacent leak site #
4.	Product type: gasoline Free product thickness: at time of discovery - 0.05', latest reading 0.4'
	If the thickness is greater than 0.1 foot, you are required to recover it and submit the worksheet for MPCA review as part of the remedial investigation/corrective action design (RI/CAD) within 90 days of product discovery date.
6.	If product thickness is less than 0.1 foot or if an automated free product recovery system is required but not yet installed, describe the method of interim free product recovery.

Passive free product collector using a wicking action installed in MW-4.

(see reverse side)

7. Volume recovered: ~ 0.5 gallons date: 4-10-95 to 5-12-95

Pree Product Recovery Report Worksheet Page 2
April 1993

- 8. Relevant observations concerning recharge rate of free product or expected volume present:

 The passive collection system is recovering product quite slowly.
- 9. Obvious nearby receptors, including basements, utilities, water wells, etc.

Nearest buildings are slab on grade construction. Groundwater flow is generally to the north a northwest. No structures or wells are in the munediate vicinity of the site in this direction.

NOTE: A full risk assessment ("Petroleum Vapor Risk Assessment and Survey," "Hydrogeologic Setting and Ground Water Characterization," and "Ground Water Receptor Survey") will be required in the RI/CAD report.

10. Person preparing this report:

date:

Scott M. Reed - MnlDot

5-15-95

Send this Free Product Recovery Report to:

(Project Manager)
Minnesota Pollution Control Agency
Tanks and Spills Section
520 Lafayette Road North
St. Paul, Minnesota 55155

Upon request, this document can be made available in other formats, including Braille, large print and audio tape. TDD users, call the Minnesota State Relay Service, 612/297-5353 or Greater Minnesota TDD 1-800-627-3529.

Printed on recycled paper containing at least 10 percent fibers from paper recycled by consumers.

SITE CLOSURE REPORT

MILLER & HOLMES, INC. 2300 LAKE STREET MINNEAPOLIS, MINNESOTA LEAK SITE NO. 360

Prepared for:

Miller & Holmes, Inc.

Prepared by:

GERAGHTY & MILLER, INC. 105 Fifth Avenue South, Suite 350 Minneapolis, Minnesota 55401




TABLE 1
MILLER & HOLMES, INC.
STATION NO. 27
MINNEAPOLIS, MINNESOTA

FLUID-LEVEL DATA

WELL		DEPTH TO HYDROCARBON	WATER	ELEVATION TOC	GRAVITY	ELEVATION HYDROCARBON	ELEVATION WATER	THICKNESS	CORRECTED ELEVATION	WELL NO.
MW-1	07-Aug-89	21.40	21.65	845.76	0.76	824.36				
MW-1	10-Jan-90	22.34	23.47		0.76	823.42	824.11 822.29	0.25	824.30	MW-1
MW-1	06-Apr-90	23.14	24.84	845.76	0.76	822.62	820.92	1.13	823.15	MW-1
MW-1	09-Aug-90	20.23	20.39		0.76	825.53	825.37	1.70	822.21	MW-1
MW-1	15-Aug-90	20.06	20.11	845.76	0.76	825.70	825.65	0.16	825.49	MW-1
MW-1	23-Aug-90	19.81	19.98	845.76	0.76	825.95	825.78	0.05	825.69	MW-1
MW-1	07-Sep-90	19.69	19.90	845.76	0.76	826.07	825.86	0.17	825.91	MW-1
MW-1	12-Nov-90	20.35	20.87	845.76	0.76	825.41	824.89	0.21	826.02	MW-1
MW-1	30-Nov-90	20.44	21.10	845.76	0.76	825.32	824.66	0.52 0.66	825.29	MW-1
MW-1	14-Dec-90	20.66	21.34	845.76	0.76	825.10	824.42	0.68	825.16	MW-1
MW-1	27-Dec-90	20.85	21.49	845.76	0.76	824.91	824.27	0.64	824.94	MW-1
MW-1	04-Jan-91	20.97	21.65	845.76	0.76	824.79	824.11	0.68	824.76 824.63	MW-1
MW-1	11-Jan-91	21.06	21.81	845.76	0.76	824.70	823.95	0.75	824.52	MW-1
MW-1	01-Feb-91	21.37	22.09	845.76	0.76	824.39	823.67	0.72	824.22	MW-1
MW-1	08-Feb-91	21.43	22.18	845.76	0.76	824.33	823.58	0.75	824.15	MW-1 MW-1
MW-1	22-Feb-91	21.64	22.36	845.76	0.76	824.12	823.40	0.72	823.95	MW-1 MW-1
MW-1	01-Mar-91	21.70	22.51	845.76	0.76	824.06	823.25	0.81	823.87	M₩-1
MW-1	15-Mar-91	21.88	22.75	845.76	0.76	823.88	823.01	0.87	823.67	MW-1
MW-1	26-Mar-91	21.85	22.84	845.76	0.76	823.81	822.92	0.64	823.60	MW-1
MW-1	29-Mar-91	22.04	22.88	845.76	0.76	823.72	822.88	0.84	823.52	MW-1
MW-1	05-Apr-91	22.05	22.92	845.76	0.76	823.71	822.84	0.87	823.50	MW-1
MW-1	12-Apr-91	22.10	22.94	845.76	0.76	823.66	822.82	0.84	823.46	MW-1
MW-1	18-Apr-91	22.13	22.97	845.76	0.76	823.63	822.79	0.84	823.43	MW-1
MW-1	01-May-91	22.15	22.93	845.76	0.76	823.61	822.83	0.78	823.42	MW-1
MW-1	09-May-91	22.15	22.93	845.76	0.76	823.61	822.83	0.78	823.42	MW-1
MW-1 MW-1	17-May-91		21.82	845.76	0.76	Ü	823.94		823.94	MW-1
MW-1	31-May-91		21.03	845.76	0.76		824.73		824.73	MW-1
MW-1	14-Jun-91		20.42	845.76	0.76		825.34		825.34	MW-1
MW-1	11-Jul-91	4	19.49	845.76	0.76		826.27		826.27	MW-1
MW-1	19-Jul-91	• • •	19.40	845.76	0.76	***	826.36		826.36	MW-1
MW-1	12-Aug-91 23-Aug-91		19.29	845.76	0.76	***	826.47		826.47	MW-1
MW-1	13-Sep-91		19.36	845.76	0.76	•••	826.40		826.40	MW-1
MW-1	04-0ct-91	•	19.44	845.76	0.76		826.32		826.32	MW-1
MW-1	12-Nov-91		18.80	845.76	0.76	***	826.96		826.96	MW-1
MW-1	09-Dec-91	•	19.31	845.76	0.76	***	826.45		826.45	MW- 1
MW-1	10-Jan-92		18.82	845.76	0.76		826.94		826.94	MW-1
MW-1	30-Jan-92	•••	18.99	845.76	0.76	826.77	826.77		826.77	MW-1
	30-3811-92		19.30	845.76	0.76	826.46	826.46		826.46	MW-1
MW-2	07-Aug-89	Z210115	24.00							
MW-2	10-Jan-90		21.90	845.55	0.76	***	823.65		823.65	MW-2
MW-2	06-Apr-90	***	21.55	845.55	0.76	***	824.00	•••	824.00	MW-2
MW-2	09-Aug-90		22.24	845.55	0.76	***	823.31		823.31	MW-2
MW-2	15-Aug-90		40.74	845.55	0.76) ****	***	1656165	MW-2
MW-2	23-Aug-90	***	18.71	845.55	0.76	S ÷ ÷) ¥	826.84	253	826.84	MW-2
MW-2	07-Sep-90		18.65	845.55	0.76		826.90		826.90	MW-2
MW-2	12-Nov-90	***	18.94	845.55	0.76	• •	826.61	***	826.61	MW-2
MW-2	30-Nov-90	•••	19.58	845.55	0.76	#0###	825.97	2.55	825.97	MW-2
MW-2	14-Dec-90			845.55	0.76		826.05	•••	826.05	MW-2
MW-2	27-Dec-90		19.87	845.55	0.76		825.68	***	825.68	MW-2
MW-2	04-Jan-91	•••		845.55	0.76		825.53		825.53	MW-2
HW-2	11-Jan-91			845.55	0.76		825.33	1975E	825.33	MW-2
	- 1 VOII-71		20.28	845.55	0.76	***	825.27		825.27	MW-2
										2

TABLE 1 MILLER & HOLMES, INC. STATION NO. 27 MINNEAPOLIS, MINNESOTA

FLUID-LEVEL DATA

							w			
WELL	NO. DATE	DEPTH TO HYDROCARBON		ELEVATION		ELEVATION	ELEVATION	PRODUCT	CORRECTED	
	========	######################################	_ WATER	TOC	GRAVITY		WATER	THICKNESS	FLEVATION	WELL NO.
4W-2	01-Feb-91		20.73	845.55	0.76		8 24. 82	***		
1W-2	08-Feb-91		20.71	845.55	0.76		824.84		824.82	1177 4
1W-2	22-Feb-91		21.13	845.55	0.76		824.42	200	824.84	MW-2
1W-2	01-Mar-91		20.90	845.55	0.76		824.65		824.42	MW-2
1W-2	15-Mar-91		21.29	845.55	0.76		824.26		824.65	MW-2
W-2	26-Mar-91	• • •	21.02	845.55	0.76		824.53	1555	824.26	MW-2
W-2	29-Mar-91		21.30	845.55	0.76		824.25	***	825.53	MW-2
W-2	05-Apr-91		20.93	845.55	0.76				824.25	MW-2
W-2	12-Apr-91		20.91	845.55	0.76		824.62 824.64	5	824.62	MW-2
W-2	18-Apr-91		20.90	845.55	0.76			•••	824.64	MW-2
W-2	01-May-91		20.95	845.55	0.76		824.65	•••	824.65	MW-2
W-2	09-May-91		20.95	845.55	0.76		824.60	***	824.60	MW-2
W-2	17-May-91		20.08	845.55	0.76		824.60	***	824.60	MW-2
W-2	31-May-91		19.55	845.55	0.76		825.47	•••	825.47	MW-2
W-2	14-Jun-91		19.09	845.55	0.76		826.00		826.00	MW-2
W-2	11-Jul-91		18.75	845.55	0.76		826.46	***	826.46	MW-2
W-2	19-Jul-91	•••	18.85	845.55	0.76		826.80	• • •	826.80	MW-2
W-2	12-Aug-91		18.72	845.55			826.70	***	826.70	MW-2
W-2	23-Aug-91		18.79	845.55	0.76		826.83	• • •	826.83	MW-2
∤- 2	13-Sep-91		18.68	845.55	0.76		826.76	•••	826.76	MW-2
2	04-0ct-91		18.47		0.76		826.87	****	826.87	MW-2
- 2	12-Nov-91	•	19.02	845.55	0.76		827.08	555	827.08	MW-2
-2	09-Dec-91		18.96	845.55	0.76		826.53		826.53	MW-2
1-2	10-Jan-92		19.11	845.55	0.76		826.59		826.59	MW-2
1-2	30-Jan-92		19.11	845.55	0.76		826.44	***	826.44	MW-2
	***********		19.20	845.55	0.76		826.35	***	826.35	MW-2
1-3	19-Jul-91		21.86	848.98	0.76		827.12			
1-3	12-Aug-91		21.91	848.98	0.76		827.12		827.12	MW-3
1-3	23-Aug-91		22.02	848.98	0.76	***	826.96	700000 1100000	827.07	MW-3
-3	13-Sep-91	•••	22.00	848.98	0.76		_	•••	826.96	MW-3
-3	04-Oct-91		21.50	848.98	0.76		826.98		826.98	MW-3
-3	12-Nov-91	***	22.13	848.98	0.76	•••	827.48	***	827.48	MW-3
-3	09-Dec-91		21.66	848.98	0.76	***	826.85	• • •	826.85	MW-3
-3	10-Jan-92		21.78	848.98	0.76	***	827.32		827.32	MW-3
-3	30-Jan-92	***	22.08	848.98	0.76		827.20	***	827.20	MW-3
	••••••				•••••		826.90		826.90	MW-3
-4	19-Jul-91	•••	18.80	846.61	0.76	¥	827.81	•••	007.04	• • • • • • • •
-4	12-Aug-91	W-20	18.81	846.61	0.76		827.80		827.81	MW-4
-4	23-Aug-91	18.97	19.02	846.61	0.76	827.64			827.80	MW-4
- 4	13-Sep-91	18.65	18.72	846.61	0.76	827.96	827.59	0.05	827.63	MW-4
4	04-Oct-91	18.27	18.37	846.61	0.76	828.34	827.89	0.07	827.94	MW-4
4	12-Nov-91	19.16	19.29	846.61	0.76		828.24	0.10	828.32	MW-4
4	09-Dec-91	18.72	18.86	846.61	0.76	827.45	827.32	0.13	827.42	MW-4
4	10-Jan-92	19.06	19.25	846.61	0.76	827.89	827.75	0.14	827.86	MW-4
4	30-Jan-92	19.15	19.41	846.61		827.55	827.36	0.19	827.50	MW-4
			17.71	0.01	0.76	827.46	827.20	0.26	827.40	MW-4

TOC = Top of casing
--- = No data available

All elevations referenced to sea level



Minnesota Pollution Control Agency

May 9, 1995

CERTIFIED MAIL
RETURN RECEIPT REQUESTED

Mr. Scott Reed
Office of Environmental Services
Minnesota Department of Transportation
Mail Stop 620
3485 Hadley Avenue North
Oakdale, Minnesota 55128-3307

Ms. Maureen Turman Clark Refining & Marketing, Inc. 760 Pasquinelli Drive Suite 352 Westmont, Illinois 60559

RE: Petroleum Storage Tank Release Investigation and Corrective Action

Site: Former Clark Oil Service Station, Hiawatha and Lake Street,

Minneapolis, Minnesota Site ID#: LEAK00008324

Dear Ms. Turman and Mr. Reed:

Notice of Release

The Minnesota Pollution Control Agency (MPCA) has received notification that a release of petroleum has occurred from storage tank facilities at an old Clark Oil Service Station (located at the above-referenced site) that has resulted in contamination of soil and/or ground water. It is MPCA staff understanding that the property was purchased by the Minnesota Department of Transportation (MNDOT).

Legal Obligations

Federal and state laws require that persons legally responsible for storage tank releases notify the MPCA of the release, investigate the extent of the release and take actions needed to ensure that the release is cleaned up. A person is considered legally responsible for a tank release if the person owned or operated the tank either during or after the release, unless specifically exempted under the law. See Minn. Stat. § 115C.021 (1992). If you believe that you are not legally responsible for this storage tank release, please submit a written explanation of your position to the MPCA within 30 days.

CLARK

MAY 15 1995

MPCA, HAZARDOUS
WASTE DIVISION

REFINING & MARKETING, INC.

1307 Butterfield Road, Suite 424 Downers Grove, Illinois 60515

May 11, 1995

Minnesota Pollution Control Agency Ms. Jean Hanson Project Leader, Cleanup Unit II Tanks and Spills Section

RE:

Petroleum Storage Tank Release Investigation and Corrective Action

Site: Former Clark Oil Service Station, Hiawatha and Lake Street,

Minneapolis, Minnesota Site ID#: LEAK00008324

Dear Ms. Hanson:

Please be advised that we are in receipt of the May 9, 1995 correspondence from you (copy attached) concerning the above site. Based on the date of sale of this property, June 24, 1969, this company has no involvement with respect to this site.

This company, Clark Refining & Marketing, Inc. ("Clark") was incorporated in February, 1938. Clark was incorporated to negotiate the purchase of certain assets of a company known at the time as Clark Oil & Refining Corporation, a Wisconsin corporation ("Clark Wisconsin"). Clark Wisconsin, which was owned by a company know as Apex Oil Company, had filed for Chapter 11 Bankruptcy protection along with Apex and other related companies in December, 1987. Clark negotiated with the debtors to purchase several of the assets owned by Clark Wisconsin. The Asset Purchase Agreement entered into between the debtors and Clark specifically provided that Clark would not assume any environmental liabilities,. Particularly pre-existing liabilities, of the debtor companies. That agreement was approved by the United States Bankruptcy Court for the Eastern District of Missouri by Order dated November 7, 1988, and this transaction and transfer of assets took place on November 22, 1988.

The relevant time period indicated for this site, prior to June 24, 1969, demonstrates that the site has not in any way been active for twenty years prior to Clark's existence. Moreover, the Bankruptcy Court's Order in connection with Clark Wisconsin's Bankruptcy makes clear that this company has not inherited any liability of that company for involvement it may have had with this site.

If we can be of further assistance with respect to this matter please do not hesitate to contact me.

Sincerely,

Clark Refining & Marketing, Inc.

Maureen Turman

Environmental Projects Manager

Enclosure

CC: Mr. Scott Reed, Minnesota Department of Transportation



Ms. Maureen Turman Mr. Scott Reed Page 2 May 9, 1995

If you are not legally responsible for the release, but hold legal or equitable title to the property where the release occurred, you may volunteer to take corrective action. Responsible persons and volunteers who take corrective action may be eligible for reimbursement for a major portion of the costs of corrective action. The legislature has established the Petroleum Tank Release Cleanup Account to reimburse responsible persons and volunteers. The account is administered by the Petro Board which is part of the Minnesota Department of Commerce. Final decisions regarding the amount of reimbursement are made by the Petro Board. All questions about eligibility and reimbursement should be directed to the Petro Board at 612/297-1119 or 612/297-4203.

Request to Take Corrective Action

The MPCA staff is requesting you to take the steps necessary to investigate and clean up the release in accordance with the enclosed MPCA fact sheets. The MPCA requires that you conduct a site investigation to define the full extent and magnitude of the soil and/or ground water contamination caused by the release. A report which details the results of the investigation or concludes that excavation was sufficient to address the release for cleanup (Excavation Report and/or Remedial Investigation/Corrective Action Design (RI/CAD)) must be submitted to this office within 10 months of the date of this letter. Please refer to MPCA fact sheets for information pertaining to the degree of investigative work necessary at petroleum release sites.

MPCA staff has been notified that monitoring well MW-4 has free product. Sites with free product, drinking water supply impacts, fire or explosion hazards, or ground water impacts which pose a significant threat to public health or the environment, are considered high priority for staff review. If one or more of these situations apply to your site, an RI/CAD report must be submitted within 90 days. In addition, if you know or discover that there is free-floating petroleum in a well, excavation, or borehole, you must notify the MPCA within 24 hours and IMMEDIATELY begin interim free product recovery.

If you have not already done so, the MPCA recommends that you hire a qualified consulting firm registered with the Petro Board that has experience in conducting petroleum release site investigations and in proposing and implementing appropriate corrective actions. A list of registered contractors and consultants is available from the Minnesota Department of Commerce. The MPCA reserves the right to reject proposed corrective actions if the requirements of the site investigation have not been fulfilled. Please note that, under Minn. Rules pt. 2890.0075, subp. 2, you must solicit a minimum of two competitive proposals on a form prescribed by the Petro Board to ensure that the consulting costs are reasonable. Questions about bidding requirements should be directed to Petro Board staff.

Ms. Maureen Turman Mr. Scott Reed Page 3 May 9, 1995

Required Response

MPCA staff requests a written or verbal response to this letter within 30 days. In your response, please tell us whether you intend to comply with the above requirements. If you do not respond within this time frame, the MPCA staff will assume that you do not intend to comply, in which case the MPCA Commissioner may order you to take corrective action. If you do not comply with the Commissioner's order, it may be enforced in court or, alternatively, the MPCA could use state funds to clean up the release and then request the Attorney General to recover its costs from you through legal action. Failure to cooperate with the MPCA in a timely manner will also result in reduced reimbursement from the Petro Board. See Minn. Rules pt. 2890.0065, subp. 1, item C.

MPCA staff requests the following information be submitted by MNDOT staff by May 30, 1995:

- 1. Ground water measurements taken on September 8, 1991, which identify this as a separate release (report format).
- 2. Submit the enclosed "Free Product Report Worksheet", to MPCA.
- 3. The date MNDOT purchased the former Clark Oil Station site.
- 4. When were the underground storage tanks removed?

The enclosed fact sheets will provide you with the information necessary to complete a successful investigation and cleanup. If you have any questions concerning this letter or need additional information, please contact me at 612/297-8595. Please reference the above LEAK # in all correspondence.

Sincerely,

Jean Hanson

Project Leader

Cleanup Unit II

Tanks and Spills Section

JH:bah

Enclosures

cc: Karen Nordby, Department of Operations and Regulatory Services
 Merry Keefe, City Clerk, Minneapolis
 Greg Lie, Hennepin County Solid Waste Officer
 Tom Dickinson, Fire Chief, Minneapolis



Minnesota Pollution Control Agency

May 9, 1995

CERTIFIED MAIL
RETURN RECEIPT REQUESTED

Mr. Scott Reed ₹779-5103
Office of Environmental Services
Minnesota Department of Transportation
Mail Stop 620
3485 Hadley Avenue North
Oakdale, Minnesota 55128-3307

Ms. Maureen Turman # 708/434-5360 Ext. 209 Clark Refining & Marketing, Inc. 760 Pasquinelli Drive Suite 352 Westmont, Illinois 60559

RE: Petroleum Storage Tank Release Investigation and Corrective Action Site: Former Clark Oil Service Station, Hiawatha and Lake Street, Minneapolis, Minnesota

Site ID#: LEAK00008324

Dear Ms. Turman and Mr. Reed:

Notice of Release

The Minnesota Pollution Control Agency (MPCA) has received notification that a release of petroleum has occurred from storage tank facilities at an old Clark Oil Service Station (located at the above-referenced site) that has resulted in contamination of soil and/or ground water. It is MPCA staff understanding that the property was purchased by the Minnesota Department of Transportation (MNDOT).

Legal Obligations

Federal and state laws require that persons legally responsible for storage tank releases notify the MPCA of the release, investigate the extent of the release and take actions needed to ensure that the release is cleaned up. A person is considered legally responsible for a tank release if the person owned or operated the tank either during or after the release, unless specifically exempted under the law. See Minn. Stat. § 115C.021 (1992). If you believe that you are not legally responsible for this storage tank release, please submit a written explanation of your position to the MPCA within 30 days.

Ms. Maureen Turman Mr. Scott Reed Page 2 May 9, 1995

If you are not legally responsible for the release, but hold legal or equitable title to the property where the release occurred, you may volunteer to take corrective action. Responsible persons and volunteers who take corrective action may be eligible for reimbursement for a major portion of the costs of corrective action. The legislature has established the Petroleum Tank Release by the Petro Board which is part of the Minnesota Department of Commerce. Final decisions by the Petro Board which is part of the Minnesota Department of Commerce. Final decisions eligibility and reimbursement are made by the Petro Board. All questions about eligibility and reimbursement should be directed to the Petro Board at 612/297-1119 or eligibility and reimbursement should be directed to the Petro Board at 612/297-1119 or

Request to Take Corrective Action

The MPCA staff is requesting you to take the steps necessary to investigate and clean up the release in accordance with the enclosed MPCA fact sheets. The MPCA requires that you conduct a site investigation to define the full extent and magnitude of the soil and/or ground water contamination caused by the release. A report which details the results of the investigation or concludes that excavation was sufficient to address the release for cleanup (Excavation Report and/or Remedial Investigation/Corrective Action Design (RI/CAD)) must be submitted to this office within 10 months of the date of this letter. Please refer to MPCA fact sheets for information pertaining to the degree of investigative work necessary at petroleum release sites.

MPCA staff has been notified that monitoring well MW-4 has free product. Sites with free product, drinking water supply impacts, fire or explosion hazards, or ground water impacts which pose a significant threat to public health or the environment, are considered high priority for staff review. If one or more of these situations apply to your site, an RI/CAD report must be submitted within 90 days. In addition, if you know or discover that there is free-floating petroleum in a well, excavation, or borehole, you must notify the MPCA within 24 hours and IMMEDIATELY begin interim free product recovery.

If you have not already done so, the MPCA recommends that you hire a qualified consulting firm registered with the Petro Board that has experience in conducting petroleum release site investigations and in proposing and implementing appropriate corrective actions. A list of registered contractors and consultants is available from the Minnesota Department of Commerce. The MPCA reserves the right to reject proposed corrective actions if the requirements of the site investigation have not been fulfilled. Please note that, under Minn. Rules pt. 2890.0075, subp. 2, you must solicit a minimum of two competitive proposals on a form prescribed by the Petro Board to ensure that the consulting costs are reasonable. Questions about bidding requirements should be directed to Petro Board staff.

Ms. Maureen Turman Mr. Scott Reed Page 3 May 9, 1995

Required Response

MPCA staff requests a written or verbal response to this letter within 30 days. In your response, please tell us whether you intend to comply with the above requirements. If you do not respond within this time frame, the MPCA staff will assume that you do not intend to comply, in which case the MPCA Commissioner may order you to take corrective action. If you do not comply with the Commissioner's order, it may be enforced in court or, alternatively, the MPCA could use state funds to clean up the release and then request the Attorney General to recover its costs from you through legal action. Failure to cooperate with the MPCA in a timely manner will also result in reduced reimbursement from the Petro Board. See Minn. Rules pt. 2890.0065, subp. 1, item C.

MPCA staff requests the following information be submitted by MNDOT staff by May 30, 1995:

- 1. Ground water measurements taken on September 8, 1991, which identify this as a separate release (report format).
- 2. Submit the enclosed "Free Product Report Worksheet", to MPCA.
- 3. The date MNDOT purchased the former Clark Oil Station site.
- 4. When were the underground storage tanks removed?

The enclosed fact sheets will provide you with the information necessary to complete a successful investigation and cleanup. If you have any questions concerning this letter or need additional information, please contact me at 612/297-8595. Please reference the above LEAK # in all correspondence.

Sincerely,

Jean Hanson

Project Leader

Cleanup Unit II

Tanks and Spills Section

JH:bah

Enclosures

cc: Karen Nordby, Department of Operations and Regulatory Services Merry Keefe, City Clerk, Minneapolis Greg Lie, Hennepin County Solid Waste Officer Tom Dickinson, Fire Chief, Minneapolis DATE: February 15, 1995

то: Michael Chiodi, Project Hydrogeologist

Tanks and Spills Section

Minnesota Pollution Control Agency

FROM: Scott Reed, Hydrogeologist

Environmental Compliance and Investigation Unit

PHONE: 779-5103

SUBJECT: Former M&H Site/Clark Oil Site- Lake Street and T.H. 55

MPCA Leak Number 360

Site History/Update

The following is a summary of the actions taken at the M&H site as understood by the Minnesota Department of Transportation:

- M&H operated a gas station at the site starting in 1949.

- M&H purchased the site from Carleton College in 1956 (it is assumed that M&H must have leased the property from Carleton College from 1949 to 1956).

- M&H sold the property to Mn/DOT in 1968, and continued to lease the property from Mn/DOT until 1987.

- Three underground storage tanks (USTs) were located on the property, two 4,000 gallon tanks installed in 1949 and one 10,000 gallon tank installed in 1956. The tanks reportedly contained gasoline and diesel fuel. The tanks were epoxy lined in 1983.
- The USTs were removed in 1987. Petroleum contamination was encountered and reported to Mn/DOT by the City of Minneapolis, who observed the tank removal. Mn/DOT reported the release to the MPCA on October 5, 1987. Information in MPCA files (correspondence between M&H and Mn/DOT) indicates that at that time, Mn/DOT and M&H had agreed that M&H would be responsible for any contamination found at the site.
- In 1988, M&H first retained Twin City Testing (TCT), then Leggette, Brashears & Graham (LBG) to complete an investigation of the site. Three soil borings were drilled at the site, two of which were completed as monitoring wells. Soil contamination was encountered between 10 and 28 feet below ground surface. Both monitoring wells indicated petroleum contamination had impacted the groundwater, with free product being present in MW-1. A program of free product removal was initiated at this time (free product was removed by bailing).
- Under the supervision of LBG on January 8-9, 1990, the M&H site was excavated to a depth of 18 feet to determine if any USTs remained on site. Soil samples were field screened for volatile petroleum contaminants. No volatile constituents were detected, however, the winter temperatures may have had a significant effect on field screening readings. No samples were collected for chemical analysis. Following removal, the soil was replaced in the excavation.

- LBG performed additional work at the site, summarized in a February 1991 report. Three borings were drilled to the east of the site. Elevated field screening readings were detected from approximately 12 to 20 feet below ground surface. No soil samples were collected for analysis. Water samples were collected from the boreholes. Analysis of these samples indicated that petroleum contamination was present in the groundwater (Mn/DOT is of the opinion that the collection of groundwater samples from soil borings is not a valid method and the contamination detected may have been caused by clean groundwater coming into contact with contaminated soil rather than true groundwater contamination). Free product removal from MW-1 was continued.
- In July 1991, LBG installed two additional monitoring wells, one each to the east and west of the site. MW-3, installed to the west of the site, showed no indication of significant petroleum contamination, however, analysis of groundwater samples revealed the presence of solvent related constituents. MW-4, installed to the east of the site on the former Clark Oil property, showed evidence of both petroleum and non-petroleum groundwater contamination.
- A report prepared by Geraghty & Miller, Inc. (the third consultant hired by M&H) stated that "groundwater appears to flow toward the site from the southeast and southwest as part of a more general northerly flow." The report also indicated that the contamination from the former Clark Oil site may be contributing to contamination to the west of Hiawatha Avenue (it was assumed this meant the M&H site). The Geraghty & Miller report recommended "site closure in terms of M&H's involvement" based on "widespread local ground-water contamination".
- An April 29, 1993 letter from the MPCA to M&H and Mn/DOT indicated that more work needs to be completed at the site, and that the MPCA is not in a position to determine whether M&H should remain involved with the site. The MPCA stated that "Only Mn/DOT and M&H can decide whether M&H remains involved with this project."
- A May 21, 1993 letter from M&H to the MPCA stated that "M&H's investigation and cooperation are not an acknowledgement that . . . M&H is responsible for any contamination found." M&H clearly indicated that they do not wish to have any involvement with the site beyond continued groundwater monitoring.
- A May 26, 1993 letter from Mn/DOT to M&H requested permission to access the monitoring wells to collect groundwater elevation data and possibly groundwater samples for chemical analysis.
- A soil boring completed in August 1994 at the M&H site by Braun Intertec during the T.H. 55 Corridor Drilling Investigation encountered soil contamination above the water table.
- During a September 7, 1994 meeting, Attorney General staff recommended that Mn/DOT measure groundwater elevations and determine groundwater flow direction at the M&H site. If the flow direction did not indicate that the M&H contamination was migrating from an off-site source, then Mn/DOT should request that M&H complete a thorough investigation of the M&H site.
- Mn/DOT measured groundwater elevations on September 8, 1994. The data indicated that the groundwater flow direction was to the north. Based on this data, no evidence of a

Page 3 February 15, 1995

connection between contamination at the Clark Oil site and contamination at the M&H site was observed.

It was recently brought to Mn/DOT's attention that the free product detected in MW-4 may not only be unconnected with the M&H release, but may actually be associated with a possible release from the Clark Oil site. Mn/DOT has contacted Geraghty & Miller and confirmed that they will be measuring water levels and checking for free product. Upon confirmation that MW-4 has collectable free product, Mn/DOT will install a passive free product collector to provide immediate response to and evaluation of the free product at the Clark Oil site.

A complete investigation of these sites is required to determine if there is a connection between the observed contamination plumes. The work completed to date is not sufficient to assess the extent of contamination or determine possible remedial alternatives. Mn/DOT will proceed with an investigation of the former Clark Oil site, while M&H should continue the investigation of their own site. Due to budget and contractual constraints, Mn/DOT will not be able to initiate a remedial investigation of the Clark Oil site until late spring or early summer of 1995.

Please call if you have any questions or require additional information.

cc:


Sherry Enzler - Assistant Attorney General, Office of the Attorney General Karl Rasmussen - Director, Mn/DOT Office of Right of Way and Surveys

Elliott Ruhland - Mn/DOT Metro Division Right of Way

Lawrence Foote - Director, Mn/DOT Office of Environmental Services

John Sampson - Director, Mn/DOT Environmental Analysis and Compliance Section Bruce Johnson - Mn/DOT Environmental Compliance and Investigation Unit Chief

N. Radle/File



Minnesota Department of Transportation



Transportation Building 395 John Ireland Boulevard Saint Paul, Minnesota 55155-1899

December 16, 2008

Mr. Mark Koplitz
Ms. Stacey Hendry Van Patten
Petroleum and Closed Landfill Section
Minnesota Pollution Control Agency
520 Lafayette Road
St. Paul, MN 55155-4194

Site: Former Clark Station-T.H. 55/Lake Street Intersection, Minneapolis Petroleum Storage Tank Release Investigation and Corrective Action Site ID#: LEAK00008324 Request for Site Closure RE:

Dear Mr. Koplitz and Ms. Hendry-Van Patten:

(Landmark), additional research of archived files was required to address the request for a information regarding the above referenced site (Site). As indicated in a follow-up email dated September 9, 2008, from Mn/DOT's consultant, Landmark Environmental, LLC The Minnesota Department of Transportation (Mn/DOT) has received the Minnesota Pollution Control Agency's (MPCA) request, dated August 12, 2008, for additional Site status update.

completed in approximately 2000. A map showing the former monitoring well locations additional meetings, correspondence, investigation, or remedial activities have occurred is included in Attachment A. It is Mn/DOT's opinion that no further investigation or Based on the review of Mn/DOT files and consistent with the MPCA file status, no on the Site since the monitoring wells were abandoned and bridge construction was remedial activities are warranted for the following reasons:

- The Site was purchased by Mn/DOT in 1969 and the underground storage tanks Source of Contamination has been Removed (USTs) were removed in 1970.
- 1997. The MPCA issued the "Completion of Voluntary Response Actions for construction activities conducted during 1996 and the placement of petroleum Corporation (Braun) Response Action Implementation Report and Addendum management of petroleum contaminated soil that was encountered during recontaminated soil in the Hiawatha/Lake Street Bridge approach during April dated June 10, 1997, and August 11, 1997. These documents describe the Soil remediation was conducted in accordance with the MPCA approved Voluntary Response Action Plan, as documented in the Braun Intertec Soil Remediation has been Completed

excavated from the Site met cleanup goals for reuse on-site as fill material for the -LEAK#9127 Petroleum Contamination" letter for the "Hiawatha Corridor" site—LEAK (which included LEAK#8324 and LEAK#360) on October 31, 1997. Soil bridge embankment construction.

Adjacent Site with Free Product and Groundwater Contamination was Closed in 1996

product and petroleum-impacted groundwater from 1991 through 1995, when the MPCA issued the Site Closure letter. Groundwater analytical data and the Site The MPCA issued a Site Closure letter, dated April 19, 1996, for the adjacent M&H Site (LEAK#360). Data from this site documents the presence of free Closure letter are included in Attachments A and B, respectively.

Groundwater-Impacts are Localized and Stable

observed in monitoring wells MW-3 and MW-6, which were located west of these wells MW-101 and MW103, located south and northeast of the Site, respectively, Free product was shown to be decreasing in these wells up through 1995, when addition, free product was also previously identified in monitoring wells MW-1 the MPCA issued a Site Closure letter for the M&H Site. No free product was Addendum), dated November 1996. The RI Addendum indicated free product with the exception of 0.36 milligrams per liter (mg/L) of diesel range organics Prior to sealing the monitoring wells on the Site and in the vicinity of the Site, was detected in one monitoring well (MW-102) located on the Site and in one wells. No free product or petroleum compounds were detected in monitoring summarized in the Petroleum Release Remedial Investigation Addendum (RI and MW-2, which were located at the west adjacent M&H Site (LEAK#360) thickness readings in 1996 measured 0.13- and 0.04 feet, respectively). In monitoring well (MW-4) located east of the Site (the most recent product Barr Engineering Company (Barr) conducted groundwater sampling as (DRO) in MW-103 (reported by Barr to likely be caused by laboratory contamination or naturally occurring organic compounds).

No Groundwater Receptors within 500 Feet of the Site

in the RI Report indicates that the nearest well is located 500 feet northeast of the considered low. Barr indicated that since groundwater occurs within a glacial till source of water and is not a resource aquifer. The 1991 well search summarized ordinance, no new water supply wells (drinking and industrial) would have been located generally downgradient of the Site. According to a City of Minneapolis Report (RI Report), which was prepared by Barr, the potential risk posed by the 0.77 miles west of the Site, are also cased through the Platteville Limestone and unit with a low hydraulic conductivity, the unit is not considered to be a viable unconsolidated sediments and the Decorah Shale, and all but one well located Glenwood Formation. Additionally, none of the identified wells appear to be identified petroleum-impacted groundwater plume to a resource aquifer was According to the February 1996 Petroleum Release Remedial Investigation Site. All identified wells within 1-mile of the Site are cased through the

installed in the vicinity of the Site since the initial well search was conducted in

- monitoring wells (1996). No evidence of vapors was detected in the sewer system Street and Hiawatha Avenue at the same time as free product was detected in the groundwater at the Site does not represent an exposure pathway. Additionally, As discussed in the RI Addendum, a vapor survey was conducted along Lake would likely provide a buffer to the nearby properties from any potential soil No Evidence of Vapors was Detected in the Sewer Systems near the Site the footprint of the bridge, its embankment, and the associated right-of-way near the Site, which indicates that soil vapor from the petroleum-impacted vapors originating from the Site.
- available data from the Site and adjacent sites (Attachment A), and the length of The release from the USTs occurred prior to 1970, at which time the USTs were removed from the Site. Based on the type of contamination detected at the Site, Contamination has likely Attenuated at the Site

time since the release, natural attenuation is likely to be occurring at the Site.

at the Site. Further investigation would not likely be in close enough proximity of The presence of the bridge and embankment limit access for future investigations the Site to accurately define any potential remaining groundwater contamination associated with the Site, especially because free product was also previously The Site is Capped by Bridge and Embankment, Limiting Access identified at adjacent closed leak site locations.

Based on the reasons outlined above, Mn/DOT requests that MPCA issue a Site Closure letter for LEAK#8324. Please call me at 651-366-3621 with any questions.

Sincerely,

Nancy Radle, P.G.

Attachments:

Attachment A: Mc Attachment B: Md

Monitoring Well Locations and Groundwater Data

M&H Site Closure Letter

ATTACHMENTS

ATTACHMENT A

TABLE 3

GROUNDWATER QUALITY DATA LAKE AND HIAWATHA RI

(concentrations in ug/L)

٧	MWIOI			MW103				
	11/02/95	12/04/95	04/19/96	11/02/95	12/04/95	12/04/95	04/19/96	04/19/96
					Sample	Duplicate	Sample	Duplicate
Acetone	<5.0	<5.0	1	<5.0	<5.0	<5.0	:	
Allyl Chloride	<5.0	<5.0	E	<5.0	<5.0	<5.0	1	
Benzene	<1.0	<1.0	<1.0	<1.0	<1.0	<1.0	<1.0	<1.0
Bromodelsene	0.1.0	0.1.0	;	0.1.0	<1.0	0.1.0		18
	0.12	0.1.	1	0.1.0	0.1×	0.1>		**
Bromodicaloromethane	۲۱.0 د در	0.1	1.	. 0.1.	<1.0	<1.0	;	1 -
BIOMODE TO THE STATE OF THE STA		0.17		O.1.	0.1.	<1.0 1.0	V.	i
Brombinetiale	0.T.V	0.1.0	1	0.1.	<1.0 1.0	<1.0	:	1
Butylbenzene	0. T	0.1.	1	0.1.0	<1.0	<1.0	1	
Sec-burylbenzene	0. T	0.1.	6	0.1.	0.1.0	<1.0	£	1
Terc-bucyloensene Carbon Tetrachlorida	VI.0	O.T.	:	0. L	<1.0 .1.0	0,1,0	1 8	
Carton recirculated	7 7	0.5	i i	0.4.	0.17	0.17	:	:
Chloroethane	<1.0 <1.0	41.0		0.7	0.7	7.0	()	1
Chloroform	\$1.0 1.0	41.0	1	×1.0	0:1	0.15		
Chloromethane	<1.0	<1.0		5. 1. 0	<1.0	2: 5		
o-Chlorotoluene	<1.0	<1.0	1	<1.0	\$1.0 \$1.0	61.0		
p-Chlorotoluene	<1.0	<1.0		<1.0	0.12	<1.0	:	
1,2-Dibromo-3-chloropropane	<1.0	<1.0		<1.0	<1.0	<1.0	1	
Chlorodibromomethane	<1.0	<1.0	1	<1.0	<1.0	<1.0	;	:
Dichlorofluoromethane.	<1.0	<1.0	1	<1.0	<1.0	<1.0	1	1
1,2-Dibromoethane	<1.0	<1.0	1	<1.0	<1.0	<1.0	1	
Dibromomethane (Methylene Bromide)	<1.0	<1.0	**	<1.0	<1.0	<1.0	1	1
1,2-Dichlorobenzene	<1.0	<1.0	t	<1.0	<1.0	<1.0	6	1
1,3-Dichlorobenzene	<1.0	<1.0	1	<1.0	<1.0	<1.0	•	
1,4-Dichlorobenzene	<1.0	<1.0	;	<1.0	<1.0	<1.0	1	1
Dichlorodifluoromethane	<1.0	<1.0	:	<1.0	<1.0	<1.0	1	
1,1-Dichloroethane	<1.0	<1.0	i.	<1.0	<1.0	<1.0		**
1,2-Dichloroethane	<1.0	<1.0	1.	0.1.0	<1.0	<1.0	ţ	1 1
	<1.0	<1.0	1	<1.0	<1.0	<1.0	į.	
Ü :	<1.0	<1.0	1	<1.0	<1.0	<1.0		
1,2-bichloroechylene, trans	<1.0	<1.0	1	<1.0	<1.0	<1.0	1	
L, Z - Dichiloropropane	0.1	0,1,0	11	0.15	<1.0	0.1.0	:	
1,3-bicitoropropane	0.5	77.0	1	O. T.	VI.U	0.1.0		
1.1-Dichloro-1-propere	0.1.0	7.50		5.5	27.0	7.0		
is-1,3-Dichloro-1-propene	ν. τ. ο 1. ο	×1.0	;	0.17	×1.0	×1.0		
Trans-1,3-Dichloro-1-propene	<1.0	<1.0	1	<1.0	<1.0	<1.0	;	1
thyl Benzene	<1.0	<1.0	<1.0	<1.0	<1.0	<1.0	<1.0	<1.0
Sthyl Ether	<1.0	<1.0	ì	<1.0	<1.0	<1.0	-	
sexachlorobutadiene	<1.0	<1.0	1	<1.0	<1.0	<1.0	2000	
Junene	<1.0	<1.0	Ē	<1:0	<1.0	<1.0		
o-Cymene (Isopropyltoluene)	<1.0	<1.0	1	<1.0	<1.0	<1.0	1	-
<pre>fethyl Ethyl Ketone</pre>	<5.0	<5.0	;	<5.0	<5.0	<5.0	2000	22.27
<pre>fethyl Isobutyl Ketone</pre>	<5.0	<5.0;	ì	<5.0	<5.0	<5.0	ĭ	•
ert-Butyl Methyl Ether	<1.0	<1.0	ì	<1.0	<1.0	<1.0	1	
ethylene Chloride	<5.0	<5.0	į.	<5.0	<5.0	<5.0	1	1
aphthalene	<1.0	<1.0	1	<1.0	<1.0	<1.0		
ropylbenzene	<1.0	<1.0	į	<1.0	<1.0	<1.0	1	1
tyrene	<1.0	<1.0		<1.0	<1.0	<1,0	*	

⁻⁻ Not analyzed. lake2.prn 09/26/96

TABLE 3 (cont.)

GROUNDWATER QUALITY DATA LAKE AND HIAWATHA RI

(concentrations in ug/L, unless noted otherwise)

	MW101			MW103				
	11/02/95	12/04/95	04/19/96	11/02/95	12/04/95	12/04/95	04/19/96	04/19/96
					Sample	Duplicate	Sample	Duplicate
1 1.1.2-Tetrachloroethane	<1.0	<1.0	1	<1.0	<1.0	<1.0	1	1
1.1.2.2-Tetrachloroethane	<1.0	<1.0	ŧ	<1.0	<1.0	<1.0	1	1
retrachloroethylene	<1.0	<1.0	;	<1.0	<1.0	<1.0	1	1
Tetrahydrofuran	<5.0	<5.0	ŧ,	<5.0	<5.0	<5.0		500
Toluene	<1.0	<1.0	<1.0	<1.0	<1.0	<1.0	<1.0	<1.0
1,2,3-Trichlorobenzene	<1.0	<1.0		<1.0	<1.0	<1.0		
1,2,4-Trichlorobenzene	<1.0	<1.0	ľ	<1.0	<1.0	<1.0	1	
1,1,1-Trichloroethane	<1.0	<1.0	į	<1.0	<1,0	<1.0	漢	*
1,1,2-Trichloroethane	<1.0	<1.0	7	<1.0	<1.0	<1.0	1	1000
Trichloroethylene	<1.0	<1.0	()	<1.0	<1.0	<1.0	ı	i.
Trichlorofluoromethane	<1.0	<1.0	•	<1.0	<1.0	<1.0	;	J
1,2,3-Trichloropropane	<1.0	<1.0	10.0	<1.0	<1.0	<1.0	1	
Trichlorotrifluoroethane	<1.0	<1.0	()	<1.0	<1.0	<1.0		1
1,2,4-Trimethylbenzene	<1.0	<1.0	:	<1.0	<1.0	<1.0		1
1,3,5-Trimethylbenzene	<1.0	<1.0	1	<1.0	<1.0	<1.0	1	
Vinyl Chloride	<1.0	<1.0	i.	<1.0	<1.0-	<1.0	1	Į.
m & p Xylene	<2.0	<2.0	Ä	<2.0	<2.0	<2.0		1
o-Xylene	<1.0	<1.0	:	<1.0	<1.0	<1.0	1	1
Xylenes (total)	i	į.	<1.0	;	1	:	<1.0	<1.0
			85					
Gasoline Range Organics, mg/L	<0.050	<0.050	<0.050	<0.050	<0.050	<0.050	<0.050	<0.050
Diesel Range Organics, mg/L	<0.10	<0.10	<0.1	<0.10	<0.10	<0.10	0.36 (1)	0.21 (1)
Lead, mg/L	0.0013	0.0010	1	<0.0006	>0.0006	<0.0006	1	1

⁻⁻ Not analyzed. (1) Peak pattern atypical of diesel, single peak present. lake2.prn 09/26/96

Groundwater Elevation and Product Thickness Data Miller & Holmes, Inc., Station No. 27, 2300 Lake Street, Minneapolis, Minnesota TABLE 3.

ا ہے۔																									1420															
Corrected Elevation (ft. MSL)	824.30	823.15	822.21	825.49	825.69	825.91	826.02	825.29	825.16	824.94	824.76	824.63	824.52	824.22	824.15	823.95	823.87	823.67	823.67	823.52	823.50	823.46	823.43	823.42	823.42	823.94	824.73	825.34	826.27	826.36	826.47	826.40	826.32	826.96	826.45	826.94	826.77	826.46	824.92	827.47
Specific Gravity	0.76	0.76	0.76	0.76	0.76	0.76	0.76	92.0	92.0	0.76	92.0	92.0	92.0	0.76	0.76	0.76	0.76	92.0	0.76	0.76	92.0	0.76	0.76	0.76	0.76	92.0	0.76	0.76	0.76	92.0	0.76	0.76	92.0	92.0	92.0	0.76	92.0	0.76	0.76	0.76
Product Thickness (feet)	0.25	1.13	1.70	0.16	0.05	0.17	0.21	0.52	99.0	89.0	0.64	89.0	0.75	0.72	0.75	0.72	0.81	0.87	0.99	0.84	0.87	0.84	0.84	0.78	0.78	1	1	- 1	J	ı	I	1	1	ı	1	ı	1	ı	1	I
Elevation Water (ft. MSL)	824.11	822.29	820.92	825.37	825.65	825.78	825.86	824.89	824.66	824.42	824.27	824.11	823.95	823.67	823.58	823.40	823.25	823.01	822.92	822.88	822.84	822.82	822.79	822.83	822.83	823.94	824.73	825.34	826.27	826.36	826.47	826.40	826.32	826.96	826.45	826.94	826.77	826.46	824.92	827.47
Elevation Hydrocarbon (ft. MSL)	824.36	823.42	822.62	825.53	825.70	825.95	826.07	825.41	825.32	825.10	824.91	824.79	824.70	824.39	824.33	824.12	824.06	823.88	823.91	823.72	823.71	823.66	823.63	823.61	823.61	1	ı	1	I	1	ı	1	ı	ı	ı	ı	I	I	ı	ł
Elevation TOC (ft. MSL)	845.76	845.76	845.76	845.76	845.76	845.76	845.76	845.76	845.76	845.76	845.76	845.76	845.76	845.76	845.76	845.76	845.76	845.76	845.76	845.76	845.76	845.76	845.76	845.76	845.76	845.76	845.76	845.76	845.76	845.76	845.76	845.76	845.76	845.76	845.76	845.76	845.76	845.76	845.76	845.76
Depth to Water (feet)	21.65	23.47	24.84	20.39	20.11	19.98	19.90	20.87	21.10	21.34	21.49	21.65	21.81	22.09	22.18	22.36	22.51	22.75	22.84	22.88	22.92	22.94	22.97	22.93	22.93	21.82	21.03	20.42	19.49	19.40	19.29	19.36	19.44	18.80	19.31	18.82	18.99	19.30	20.84	18.29
Depth to Hydrocarbon (feet)	21.40	22.34	23.14	20.23	20.06	19.81	19.69	20.35	20.44	20.66	20.85	20.97	21.06	21.37	21.43	21.64	21.70	21.88	21.85	22.04	22.05	22.10	22.13	22.15	22.15	1	I	1	1	1	I	1	!	ı	!	ı	ſ	1	!	i
Date	07-Aug-89	10-Jan-90	06-Apr-90	09-Aug-90	15-Aug-90	23-Aug-90	07-Sep-90	12-Nov-90	30-Nov-90	14-Dec-90	27-Dec-90	04-Jan-91	11-Jan-91	01-Feb-91	08-Feb-91	22-Feb-91	01-Mar-91	15-Mar-91	26-Mar-91	29-Mar-91	05-Apr-91	12-Apr-91	18-Apr-91	01-May-91	09-May-91	17-May-91	31-May-91	14-Jun-91	11-Jul-91	19-Jul-91	12-Aug-91	23-Aug-91	13-Sep-91	04-Oct-91	12-Nov-91	09-Dec-91	10-Jan-92	30-Jan-92	25-May-93	13-Oct-93
Well No.	MW-1																																							

Page 1 of 4

Miller & Holmes, Inc., Station No. 27, 2300 Lake Street, Minneapolis, Minnesota Groundwater Elevation and Product Thickness Data CABLE 3.

cted tion ISL)
Corrected Elevation (ft. MSL)
Specific Gravity
Product Thickness (feet)
Elevation Water (ft. MSL)
Elevation Hydrocarbon (ft. MSL)
Elevation TOC (ft. MSL)
Depth to Water (feet)
Depth to Hydrocarbon (feet)
Date
Well No.

Miller & Holmes, Inc., Station No. 27, 2300 Lake Street, Minneapolis, Minnesota Groundwater Elevation and Product Thickness Data ABLE 3.

	Denth to	Denth to	Flevation	Flevation	Flevation	Product	Specific	Corrected
Hydrocarbon (feet)	ou	Water (feet)	TOC (ft. MSL)	Hydrocarbon (ft. MSL)	Water (ft. MSL)	Thickness (feet)	Gravity	Elevation (ft. MSL)
	1							
Ī		18.96	845.55	i	826.59	I	92.0	826.59
1		19.11	845.55	l	826.44	I	92.0	826.44
ı		19.20	845.55	1	826.35	ı	0.76	826.35
ı		19.62	845.55	1	825.93	l	0.76	825.93
1		17.87	845.55	1	827.68	I	0.76	827.68
1		18.82	845.55	1	826.73	1	92.0	826.73
19.95		19.97	845.55	825.60	825.58	0.02	0.76	825.60
19.71		19.72	845.41*	825.70	825.69	0.01	0.76	825.70
19.55		19.56	845.41*	825.86	825.85	0.01	0.76	825.86
1		21.86	848.98	ì	827.12	I	92.0	827.12
1		21.91	848.98	1	827.07	١	0.76	827.07
ſ		22.02	848.98	i	826.96	I	0.76	826.96
1		22.00	848.98	1	856.98	ı	0.76	826.98
I		21.50	848.98	1	827.48	1	92.0	827.48
1		22.13	848.98	1	826.85	ı	0.76	826.85
L		21.66	848.98	1	827.32	1	0.76	827.32
1		21.78	848.98	ĵ	827.20	I	0.76	827.20
4		22.08	848.98	1	826.90	I	0.76	826.90
1		22.93	848.98	1	826.05	I	0.76	826.05
1		21.28	848.98	I	827.70	1	0.76	827.70
1		22.80	848.98	I	826.18	I	92.0	826.18
1		22.18	848.98	1	826.80	I	0.76	826.80
22.82		22.825	848.82*	826.00	825.995	0.005	0.76	826.00
1		22.78	848.82*	1	826.04	1	0.76	826.04
		19.80	846.61		877 81	. 1	92.0	827.81
ı		18.81	846.61	1	827.80	i	0.76	827.80
18.97		19.02	846.61	827.64	827.59	0.05	0.76	827.63
18.65		18.72	846.61	827.96	827.89	0.07	92.0	827.94
18.27		18.37	846.61	828.34	828.24	0.10	0.76	828.32
19.16		19.29	846.61	827.45	827.32	0.13	0.76	827.42
18.72		18.86	846.61	827.89	827.75	0.14	0.76	827.86
19.06		19.25	846.61	827.55	827.36	0.19	0.76	827.50
19.15		19.41	846.61	827.46	827.20	0.26	92.0	827.40
19.47		20.37	846.61	827.14	826.24	0.90	0.76	826.92
18.64		18.72	846.61	827.97	827.89	0.08	0.76	827.95
19.50		19.55	846.61	827.11	827.06	0.05	0.76	827.10
20.44		20.80	846.61	826.17	825.81	0.36	0.76	826.08
MM		20.43	846.46*	*	826.03	*	0.76	826.03
							E	

Groundwater Elevation and Product Thickness Data Miller & Holmes, Inc., Station No. 27, 2300 Lake Street, Minneapolis, Minnesota ABLE 3.

Corrected Elevation (ft. MSL)	826.41	827.78 829.46	823.94 823.70
Specific Gravity	92.0	0.76	0.76 0.76
Product Thickness (feet)	*	11	II.
Elevation Water (ft. MSL)	826.41	827.78 829.46	823.94 823.70
bepth to Elevation Elevation Elevation Water TOC Hydrocarbon Water (feet) (ft. MSL) (ft. MSL)	- #	1 1	11
Depth to Elevation Water TOC E (feet) (ft. MSL)	846.46*	845.55* 845.55*	847.82*
Depth to Water (feet)	20.05	17.77	23.88
Depth to Hydrocarbon (feet)	NIM	1.1	1 1
Date	03-May-95	12-Apr-95 03-May-95	12-Apr-95 03-May-95
Well No.	MW-4	MW-5 MW-5	MW-6 MW-6

Feet above Mean Sea Level as referenced to the National Geodetic Vertical Datum of 1929 . MSL

feet

Top of casing.

8

No measurable free product present.

New survey data, collected by R.E. Stransky Land Surveyors on April 12, 1995.

Well fitted with a passive CT-collector.

Il elevations referenced to sea level.

OPROJECTSVAMO136/001/TABLES/WTRLEVEL.XLS

Monitoring Wells MW-1 Through MW-6 Miller & Holmes, Inc., Station Mo.27, 2300 Lake Street, Minneapolis, Minnesota

<100	-	224	000'91	048,4	7,700	087	06 <i>L</i>	072	18-8uA-21	t-WM
	0.2>	(400)	<100	AN	0.1>	0 [.] I>	0.1>	0.1>	03-May-95	E-WM
82410			<100	٧N	0.I>	0.1>	0.I>	0.I>	46-nsl-90	E-WM
		·	<100	AN	0.1>	0.I>	0.I>	0.1>	13-Oct-93	E-WM
-	0.2>	0\$>	<100	ΨN	0.I>	0.I>	0.I>	0.1>	25-May-93	E-WM
	01>		005>	AN	0.2>	0.2>	0.8>	0.2>	30-Jan-92	E-WM
	<10		00\$>	AN	0.2>	0.8>	0.8>	0.5>	21-0ct-91	E-WM
<100			00\$>	H	<10	11	01>	01>	19-8uA-21	KW-3
0012	4.7		0032		012					-0
			000'91	0\$1'6	1,400	720	001'1	007'9	46-nst-80	MW-2
			18,000	8,820	J°200	220	1,300	5,800	13-Oct-93	7-MM
(- 1 - 1	7,300	7 -10- 3	000'LI	060'9	059	220	079	009'₺	30-Jan-92	Z-WM
	006'I		008'6	091'\$	- 0 <i>LL</i>	0.2>	069	3°,700	71 - 0¢1-91	MW-2
0,000)	(1 0000)	73,000	14,110	001'1	= 005°L	017	001'\$	18-3uA-21	Z-WW
100		- 222	-	089'9	009'I	081	300	009'₺	16-1qA-20	Z-WM
<100			78,000	8,420	1,300	450	300	00†'9	09-SuA-90	C-WIM
	0.2>		000't†	007'97	000'\$	000°L	1,200	13,000	28-yalm-50	I-WM
		3***	000'19	001'97	001'6	13,000	2,000	22,000	46-nsl-90	I-WM
			-000'IL	007'15	0016	000,21	1,800	25,000	13-Oct-93	I-WM
	3,300	00ε'λ	43,000	22,700	005'†	000'9	1,200	11,000	25-May-93	I-WM
	005,1		000'\$1	3,900	1,200	009'I	760	048	30-Jan-92	I-WM
· v	000'\$		34,000	25,400	002'9	8,000	1,300	004'6	71-Oct-91	I-WM
			3,700	1,128	330	320	38	410	12-Aug-91	I-WM
			τ, τη							
			_	22	10,000	1,000	002	10		MDH HRLS
Lead	MTBE	DKO	СВО	Total BTEX	Xylenes	Toluene	Ethyl Benzene	Benzene	Sampling Date	Well I.D.
						790.5				

CERAGHTY & MILLER, INC.

FIGURES

Page 1 of 2

TABLE 4. Summary of Analytical Results for Hydrocarbon Constituents Detected in Groundwater Samples Collected from Monitoring Wells MW-1 Through MW-6 Miller & Holmes, Inc., Station No.27, 2300 Lake Street, Minnespolis, Minnesota

bead 	MTBE	ОЯО 	СВО	Total BTEX 	Xylenes	Toluene 1,000	J00 Benzene Ethyl	I0 Benzene	Sanipling Safe	Well I.D.
0\$00.0>	0.1>	A lbert	<100	AN	06.0>	<0.20	05.0>	0.30	12-Apr-95	S-WM
	0.2>		<100	ΨN	<1.0	0.1>	0.1>	0.1.>	69-yaM-50	S-WM
0\$00.0>	0.1>		017	\$89	8.72	78	ŞŞ	250	28-1qA-21	9-WM
0200.0>	<i.0< td=""><td>S4448</td><td>054</td><td>SOL</td><td>9.92</td><td>LL</td><td>15</td><td>920</td><td>24-14A-21</td><td>(qub)2-WM</td></i.0<>	S 444 8	054	SOL	9.92	LL	15	920	24-1 4A- 21	(qub)2-WM
	0.2>	S anz :	067	L9 E	LI	0.7	23	370	69-yaM-50	9-MW
	<17		250	326	€6	9. č	17	350	29-ybM-80	(qub) 9-WM
-	0.2>	0\$>	<100	ΨN	<1.0	0.1>	<1.0	<i.0< td=""><td>25-May-93</td><td>Trip Blank</td></i.0<>	25-May-93	Trip Blank
-	45	(1)	<100	AN	0.I>	0.1>	0.I>	0.1>	46-nsl-90	Trip Blank
0200.0>	0.1>	2)	<100	ΑN	06.0>	<0.20	05.0>	<0.30	24-14A-21	Trip Blank
	0.2>		<100	ΑN	<1.0	<i.0< td=""><td><i.0< td=""><td><1.0</td><td>03-May-95</td><td>Trip Blank</td></i.0<></td></i.0<>	<i.0< td=""><td><1.0</td><td>03-May-95</td><td>Trip Blank</td></i.0<>	<1.0	03-May-95	Trip Blank

All results are in micrograms per liter (ug/L). GRO data prior to 1993 were determined using a gas chromatograph-flame ionization detector (GC-FID). < Not detected at or above detection limit specified.

Not analyzed

NA Not applicable

MDH HRLs Minnesota Department of Health Health Risk Limits (in ug/L)

No MDH Health Risk Limit for this compound.

G:/bBO1ECTS/MN0136/001/TABLES/WTRQUAL.XLS

GERAGHTY & MILLER, INC.

FIGURES

Page 2 of 2

TABLE 5. Summary of Analytical Results for Other Volatile Organic Compounds
Groundwater Samples Collected from Monitoring Wells MW-5 and MW-6
Miller & Holmes, Inc., Station No. 27, 2300 Lake Street, Minnespolis, Minnesota

- II	8.1	- 07	81	£.6	£.4	4.5	0.1	70		(qub) 2-WM
13	7.7	77	61	10	9.4	č .£	1.0	17		9-MW
05.0>	05.0>	07.0>	<0.20	06.30	05.0>	0.1>	0£.0>	05.0>	3	s-ww
300			-) (1) (1) (1) (1) (1) (1) (1) (1) (1) (1	ç	t	χī	MDH HRLs
Naphthalene	peuzeue	penzene	penzene	peuzeue	peuzeue	peuzeue	propane	сцувис	2 1	Well ID
9	n-Butyl	sec-Butyl	tert-Butyl	l,3,5 Trimethyl-	n-propyl	Isopropyl	1,2 Dichloro-	1,2 Dichloro-	(6)	

All groundwater samples collected on April 12, 1995. Results are in micrograms per liter (ug/L).

MDH HRLs Minnesota Department of Health Risk Limits (in ug/L)

— No MDH Health Risk Limit for this compound.

G:/PROJECTS/MN0136/001/TABLES/465DDET.XLS

GERACHTY & MILLER, INC.

