From: Katie Hill Brandt
To: Cordes, Richard M (MPCA)
Cc: Bech, Troy - 1520
Subject: Sanimax - Original SV019
Date: Tuesday, July 02, 2013 2:43:39 PM
Attachments: ATT00002.png

Hi Dick,

Troy Bech was able to verify that stack SV019 was built as a room air scrubber stack, but it has never been in operation. It is not a process scrubber and its intended use would be for ventilation purposes only.

Thanks,

Katie Hill Brandt, PE | Environmental Engineer
SEH | 3535 Vadnais Center Drive | St. Paul, MN 55110
651.490.2032 direct | 612.723.6704 cell | 651.490.2150 fax
www.sehinc.com
SEH—Building a Better World for All of Us™

----- Forwarded by Katie Hill Brandt/seh on 07/02/2013 02:24 PM -----

From: "Bech, Troy - 1520" <Troy.Bech@sanimax.com>
To: Katie Hill Brandt <khillbrandt@sehinc.com>,
Date: 07/02/2013 02:04 PM
Subject: Re: Scrubber and Fan Info

The second stack is not in operation. It was put in as a room air scrubber stack. It has never been in operation.

Troy Bech
EHS Specialist
Sanimax
P: 651-451-6858

On Jul 2, 2013, at 1:35 PM, "Katie Hill Brandt" <khillbrandt@sehinc.com> wrote:

Hi Troy,

Dick Cordes at MPCA is asking for verification that the second poultry plant scrubber stack was not built and/or not in operation. Can you confirm? The MPCA shows both stacks SV018 and SV019 in their database and they would like to eliminate any confusion about the second stack (SV019). I can forward your response on to Mr. Cordes.

Thanks!

Katie Hill Brandt, PE | Environmental Engineer
SEH | 3535 Vadnais Center Drive | St. Paul, MN 55110

651.490.2032 direct | 612.723.6704 cell | 651.490.2150 fax
www.sehinc.com
SEH—Building a Better World for All of Us™

From: "Bech, Troy - 1520" <Troy.Bech@sanimax.com>
To: "tpotas@sehinc.com" <tpotas@sehinc.com>, Katie Hill Brandt <khillbrandt@sehinc.com>,
Cc: "Kedrowski, Tim - 1534" <Tim.Kedrowski@sanimax.com>, "Hays, Wayne - 1522" <Wayne.Hays@sanimax.com>
Date: 04/09/2013 09:48 AM
Subject: Scrubber and Fan Info

Good morning,
I have attached the information regarding the poultry plant scrubber stack and fan. The second stack is not in operation. Let me know if you need anything further.

<mime-attachment.gif>

Troy A. Bech, B.Sc.
Environment, Health and Safety

Sanimax
P: 1-651-451-6858 x1520
F:1-651-451-6542
E: troy.bech@sanimax.com
Web: www.sanimax.com

<mime-attachment.png>

[attachment "201304090941.pdf" deleted by Katie Hill Brandt/seh]