From:	Katie Hill Brandt
To:	Cordes, Richard M (MPCA)
Cc:	ben.bertram@sanimax.com
Subject:	Sanimax - Additional Boiler Information
Date:	Thursday, August 13, 2015 9:13:59 AM
Attachments:	NESHAP JJJJJJ - Existing Units_Highlights.pdf

Hello Dick,

I was able to find out more details on the boilers at Sanimax, regarding your question as to whether they all have oxygen trim systems installed.

- Boiler #1 (EU001) has an oxygen trim system. If/when it becomes subject to NESHAP 6J, tune-ups will be required every 5 years.
- Boiler #2 (EU006) does not have an oxygen trim system. If/when it becomes subject to NESHAP 6J, tune-ups will be required every 2 years.
- Boiler #3 (EU023) will have an oxygen trim system. If/when it becomes subject to NESHAP 6J, tune-ups will be required every 5 years.

I have made minor edits to the highlighted NESHAP 6J rule text for the existing boilers to incorporate this information (see attached).

Sanimax is tracking down the startup date for Boiler #2, and we are working on the revisions you had requested to the waste vs. fuel memo.

Thank you,
Katie

Katie Hill Brandt, PE | Environmental Engineer
SEH | 3535 Vadnais Center Drive | St. Paul, MN 55110
651.490.2032 direct | 612.723.6704 cell | 651.490.2150 fax
www.sehinc.com
SEH—Building a Better World for All of Us™