

# Minnesota Pollution Control Agency

April 9, 1997

**CERTIFIED MAIL  
RETURN RECEIPT REQUESTED**

Mr. Jack Curtis  
Curtis Oil Company  
4997 Miller Trunk Highway  
Duluth, MN 55811

RE: Petroleum Storage Tank Release Investigation and Corrective Action  
Site: Junction Food-N-Fuel, 5493 Miller Trunk Highway, Hermantown  
Site ID#: LEAK00003534

Dear Mr. Curtis:

On October 16, 1990, the Minnesota Pollution Control Agency (MPCA) staff was notified that a release of petroleum occurred from storage tank facilities that you own and/or operate at the site referenced above.


A recent review of our files shows that we have not received a Revised Remedial Investigation/Corrective Action Design (RI/CAD) report within the time frame outlined in our June 18, 1993, letter to you. MPCA staff have also had several telephone conversations and meetings with you and your consultants concerning this site. We have yet, however, to receive a completed RI/CAD. MPCA staff requests that you take the steps necessary to investigate and clean up the petroleum release and submit a RI/CAD within 60 days of receipt of this letter. Failure to meet this deadline may result in reduced reimbursement from the Petrofund and/or enforcement action taken against you by the MPCA.

Please refer to MPCA fact sheets for information regarding the scope of investigations required at petroleum release sites. MPCA staff requires that the site investigation fully define the extent and magnitude of soil and ground water contamination caused by the release. We reserve the right to reject proposed corrective actions if the requirements of the site investigation have not been fulfilled.

Mr. Curtis  
Page Two  
April 9, 1997

Please refer to MPCA fact sheets for information regarding the scope of investigations required at petroleum release sites. MPCA staff requires that the site investigation fully define the extent and magnitude of soil and ground water contamination caused by the release. We reserve the right to reject proposed corrective actions if the requirements of the site investigation have not been fulfilled. If you have any questions concerning this letter or need additional information, please call me at 218/723-4897. Please reference the above LEAK # in all correspondence.


Sincerely,



Steven J. Leppälä  
Regional Specialist

cc: Nancy Sirois, City Clerk  
John Klaers, Planning and Zoning  
Mark Darby, Twin Ports Testing, Inc.  
Minnesota Department of Commerce, Petrofund Staff

UNITED STATES POSTAL SERVICE



First-Class  
Postage & Fees Paid  
USPS  
Permit No. G-10

RECEIVED

• Print your name, address, and ZIP Code in this box • 1007

APR 11 1007

MPCA - DULUTH  
DULUTH, MN.

MN Pollution Control Agency  
Government Services Center  
320 West Second Street, Suite 704  
Duluth, MN 55802

ATTN: STEVE LEPPALA



Is your RETURN ADDRESS completed on the reverse side?

**INSTRUCTIONS:**

- Complete items 1 and/or 2 for additional services.
- Complete items 3, 4a, and 4b.
- Print your name and address on the reverse of this form so that we can return this card to you.
- Attach this form to the front of the mailpiece, or on the back if space does not permit.
- Write "Return Receipt Requested" on the mailpiece below the article number.
- The Return Receipt will show to whom the article was delivered and the date delivered.

I also wish to receive the following services (for an extra fee):

- Addressee's Address
- Restricted Delivery

Consult postmaster for fee.

3. Article Addressed to:

MR JACK CURTIS  
 CURTIS OIL COMPANY  
 4997 MILLER TRUNK HIGHWAY  
 DULUTH MN 55811

2-3534

4a. Article Number

P 296 197 170

4b. Service Type

- Registered
- Express Mail
- Return Receipt for Merchandise
- Certified
- Insured
- COD

7. Date of Delivery

4-10

5. Received By: (Print Name)

6. Signature: (Addressee or Agent)

X JASON RISDAK *Jason Risdak*

8. Addressee's Address (Only if requested and fee is paid)

PS Form 3811, December 1994

Domestic Return Receipt

Thank you for using Return Receipt Service.