

**MINNESOTA POLLUTION CONTROL AGENCY  
TANKS AND SPILLS SECTION  
LEAK/SPILL REPORT**

Report taken by: *K7*

Time of report: *2 pm*

Date of report: *7-24-88*

Date spill discovered: *7-24-88*

**SITE LOCATION**  
name:  
street:  
city:                      ↓                      county:

**CALLER**  
name: ~~Bob Erwin~~ *Roe Rabung* *owner*  
phone: *612-878-2614*  
relationship to site:  
*owner*

**DIRECTIONS TO SITE**  
*94 W. Exit 183 Hasty Silver  
Creek Exit  
Texaco Truck Sp.*

**SITE OWNER**  
name: *Hasty Truck Terminal*  
street: *Rt 1 Clearwater*  
city, zip: *55320*  
phone:

**TYPE AND AMOUNT OF SPILLED MATERIAL**  
*2000 gal Diesel fuel*

**SITE OPERATOR**  
name:  
street:  
city, zip:  
phone:

**SITUATION**

*Crossover pipe - repaired - cracked pipe.  
20,000 gal U.G. Diesel tanks  
hole is still open - 2' to 3'  
Soil is on top of ground  
Stow K. is coordinating site visit*

HAZARDS AND POTENTIAL/ACTUAL IMPACTS OF SPILL/LEAK:

(e.g. free product, wells, sewers, contaminated soil, human contact, fire, etc.)

INSTRUCTIONS GIVEN TO RESPONSIBLE PARTY

WHAT

TIMEFRAME


CONTACTS MADE/TO BE MADE (circle contacts made or to be made and describe who talked to, when, by who, and messages passed)

- EPA
- MPCA Region
- Mn/DOT
- Mn/DNR
- Mn/Ag
- MDH
- Local Fire
- Local Police
- Mn Hwy Patrol
- Mn Emer Services
- Coast Guard
- MPCA Contractor

(circle contacts made or to be made and describe who talked to, when, by who, and messages passed)