

Leaksite ID# 8188	Tank Facility ID 52044
UNION COOP OIL CO SOUTH BULK PLANT	UNION COOP OIL CO
Site Name	Responsible Party

LEAKSITE REMARKS

- 2/06/95 Release reported by Gary Hartman, Union Oil. Approximately 30 gallons of product had leaked from an AST. When discovered, the remaining product within the AST had been pumped to another tank. Floor dry was used to absorb some of the product. The spilled material was in a clay diked area. Some excavation may be necessary.
- 2/10/95 GR: MAILED standard letter.
- 8/20/95 MDN: Spoke with Gary Hartman, Union Co-op. He indicated that it was a small release that was cleaned up. They still have a small pile of contaminated soil on site (less than 9 yds). I told Gary that they may be able to thinspread the soil provided certain parameters. Gary indicated that the soil could be spread on site. I also requested that Gary provide a summary of events that occurred and a map that showed the location of the spill and the area where the soil was spread.
- 8/21/95 Thinspread approval letter sent.
- 7/22/96 AH: Reviewed file. Have not rec'd info that MDN requested on 8/21/95. Sent WAKEUP letter with fact sheet 3.5. Requested summary of events and how release was contained.
- 8/28/96 AH: Rec'd Follow-up Checklist from Gary Hartman.
- 8/29/96 AH: Reviewed file. Site can be considered closed based on the following: (1) small release approx. 30 gallons; cleanup began right away with floor dry material; (2) release occurred in clay diked area-contained; (3) remaining contaminated soil removed (approx. 9 yds) and (4) thin spread the soil on-site. Ground water, vapor, and surface water do not appear to be at risk. Site can be considered closed.
- 06/22/98 sent to archives kl

End of Remarks

Leaksite ID#	8188	Tank Facility ID	52044
UNION COOP OIL CO SOUTH BULK PLANT		UNION COOP OIL CO	
Site Name		Responsible Party	

---

LEAKSITE REMARKS

---

- 2/06/95 Release reported by Gary Hartman, Union Oil. Approximately 30 gallons of product had leaked from an AST. When discovered, the remaining product within the AST had been pumped to another tank. Floor dry was used to absorb some of the product. The spilled material was in a clay diked area. Some excavation may be necessary.
- 2/10/95 GR: MAILED standard letter.
- 8/20/95 MDN: Spoke with Gary Hartman, Union Co-op. He indicated that it was a small release that was cleaned up. They still have a small pile of contaminated soil on site (less than 9 yds). I told Gary that they may be able to thinspread the soil provided certain parameters. Gary indicated that the soil could be spread on site. I also requested that Gary provide a summary of events that occurred and a map that showed the location of the spill and the area where the soil was spread.
- 8/21/95 Thinspread approval letter sent.
- 7/22/96 AH: Reviewed file. Have not rec'd info that MDN requested on 8/21/95. Sent WAKEUP letter with fact sheet 3.5. Requested summary of events and how release was contained.
- 8/28/96 AH: Rec'd Follow-up Checklist from Gary Hartman.
- 8/29/96 AH: Reviewed file. Site can be considered closed based on the following: (1) small release approx. 30 gallons; cleanup began right away with floor dry material; (2) release occurred in clay diked area-contained; (3) remaining contaminated soil removed (approx. 9 yds) and (4) thin spread the soil on-site. Ground water, vapor, and surface water do not appear to be at risk. Site can be considered closed.

End of Remarks

**MINNESOTA POLLUTION CONTROL AGENCY  
TANKS AND SPILLS SECTION  
PETROLEUM TANK RELEASE REPORT**

Report Taken By: *DO / MDN / SM*

Date/Time Occurred:

Date/Time Reported: *2/06/95*

Date/Time Discovered: *2/06/95*

LEAK# *8188*

PROJECT MANAGER: *SM*

USTIS # *52044*

**CALLER**

Name: *GARY HARTMAN*  
Phone: *612-848-6288*  
Relationship to site:  
*UNION CO-OP*

**SITE**

Name: *UNION CO-OP OIL SOUTH BULK PLANT*  
Street:  
City: *HECTOR* Zip: *55342*  
County: *RENVILLE* Region: *4*

**TANK OPERATOR**

Name:  
Street:  
City: Zip:  
Contact Person:  
Phone:

**TANK OWNER**

Name: *UNION CO-OP OIL*  
Street: *260 Main St.*  
City: *Hector* St.: *MN* Zip: *55342*  
Contact Person: *Gary Hartman*  
Phone: *(612) 848-6288*

Own tanks/product/property?  
Share in profits?  
Control over inventory, maintenance  
and tank decisions?

**SITUATION**

Material Released/Amount:  
*#2 FUEL OIL / 30 GAL*

Source of Release:

*AST*

Release Discovery:

*AST was leaking*

**TANK INFORMATION**

Contents	Size	Age	Removed	Condition	Registered
_____	_____	_____	_____	_____	_____
_____	_____	_____	_____	_____	_____
_____	_____	_____	_____	_____	_____
_____	_____	_____	_____	_____	_____
_____	_____	_____	_____	_____	_____
_____	_____	_____	_____	_____	_____

State or Federal

Excavation Contractor: \_\_\_\_\_

Notification prior to removal: \_\_\_\_\_

Consultant: \_\_\_\_\_

**SOIL**

Contaminated soil excavated: *no*

Was it a total excavation:

Vapor readings:

Soil samples:

Borings:

Native soil type:

Stockpiled properly/disposal arranged:

Other:

*- used floor-dri*

**CONCLUSIONS AND OTHER RELATED INFORMATION**

**INSTRUCTION GIVEN**

**CONTACTS**  
Local Fire/Police  
Local Officials  
Regional Staff  
Other

Hire consultant  
Submit report  
Staff will call  
Contact staff

**SITE INFORMATION**

Description of area:  
Previous release(s):

**VAPORS**

Sewers/buildings:

**WATER**

Groundwater in excavation:  
Free product present:  
Depth to groundwater:  
City water/wells private/municipal:  
Surface water:

To: MPCA SPILLS

SM

# STATE OF MINNESOTA

DEPARTMENT OF PUBLIC SAFETY - DIVISION OF EMERGENCY MANAGEMENT  
85 STATE CAPITOL SAINT PAUL 55155-1049

## MINNESOTA DUTY OFFICER HAZARDOUS MATERIAL INCIDENT REPORT: SPILL

REPORT DATE: 2-6-95 TIME: 1903 DUTY OFFICER: Judy RECORD#:

<b>REPORTED BY:</b>		<b>SUSPECTED SOURCE/RESPONSIBLE PARTY:</b>	
NAME: <u>Gary Hartman</u>	CONTACT:		
C/O: <u>Union Co. oil</u>	C/O:		
ADDRESS: <u>260 Main St</u>	ADDRESS: <u>same</u>		
CITY: <u>Hector</u> STATE: <u>Mn</u>	CITY:	STATE:	
PHONE: <u>612-848-6288</u> ZIP: <u>55432</u>	PHONE:	ZIP:	
ALT. PHONE:	<u>55342</u>	ALT. PHONE:	

HAVE LOCAL OFFICIALS BEEN NOTIFIED?: YES / NO

\*\* IF EMERGENCY RESPONSE IS NEEDED, HAVE CALLER NOTIFY 911 IMMEDIATELY! \*\*

MATERIAL & QUANTITY: #2 fuel oil (diesel) 30 gallons

INCIDENT DATE: 2-6-95 TIME: 1803 ONGOING?: YES / NO / UNKNOWN

LOCATION: Union Co. oil - Hwy 4 do.  
Hector, Renville

LEGAL: SECTION: TOWNSHIP: RANGE: South Bull Kent

RELEASED TO: SOIL / ASPHALT / CONCRETE / SURFACE WATER / WELL  
TILE LINE / GROUND WATER / STORM SEWER / SANITARY SEWER

DESCRIBE AREA: URBAN / RURAL / RESIDENTIAL / COMMERCIAL / INDUSTRIAL

SPILL AIR RELEASE / COMPLAINT / DUMPING / MALFUNCTION / SHOTDOWNS / PIPELINE LEAK / RAD MATERIAL

NARRATIVE: above ground storage tank was leaking & so we pumped it to another tank. It went to a clay dyke containment area. After we got it pumped over, we may have to remove some soil.

HAS MATERIAL ESCAPED LOCATION PROPERTY?: YES / NO / UNKNOWN

HAS RELEASED MATERIAL BEEN CONTAINED?: YES / NO / UNKNOWN

ANY STATE AGENCY RESPONSE?: YES / NO SPECIFY:

\*\* IS THIS A BUSINESS OR GOVERNMENT FACILITY REPORTING

IN COMPLIANCE WITH SARA TITLE III, SECTION 304?: YES / NO / UNKNOWN

(IF YES, COMPLETE PAGE TWO: SARA SUPPLEMENT)

### DUTY OFFICER NOTIFICATIONS MADE (AGENCY, NAME, TIME)

<u>MPCA - fax</u>	<u>Region 4 &amp; 5 fax</u>
<u>Renville Co. fax</u>	
<u>for c.c.</u>	

QUESTIONS? CONTACT THE MINNESOTA DUTY OFFICER AT 649-5451 OR 1-800-422-0798



# Minnesota Pollution Control Agency

---

August 30, 1996

Mr. Gary Hartman  
Union Co-op Oil  
260 Main Street  
Hector, Minnesota 55342

RE: Petroleum Tank Release Site File Closure  
Site: Union Co-op Bulk Plant, Hector  
Site ID#: LEAK00008188

Dear Mr. Hartman:

We are pleased to let you know that the Minnesota Pollution Control Agency (MPCA) Tanks and Emergency Response Section (TERS) staff has determined that your investigation and/or cleanup has adequately addressed the petroleum tank release at the site listed above. Based on the information provided, the TERS staff has closed the release site file.

Closure of the file means that the TERS staff does not require any additional investigation and/or cleanup work at this time or in the foreseeable future. Please be aware that file closure does not necessarily mean that all petroleum contamination has been removed from this site. However, the TERS staff has concluded that any remaining contamination, if present, does not appear to pose a threat to public health or the environment.

The MPCA reserves the right to reopen this file and to require additional investigation and/or cleanup work if new information or changing regulatory requirements make additional work necessary. If you or other parties discover additional contamination (either petroleum or nonpetroleum) that was not previously reported to the MPCA, Minnesota law requires that the MPCA be immediately notified.

You should understand that this letter does not release any party from liability for the petroleum contamination under Minn. Stat. ch. 115C (1994) or any other applicable state or federal law. In addition, this letter does not release any party from liability for nonpetroleum contamination, if present, under Minn. Stat. ch. 115B (1994), the Minnesota Superfund Law.

If future development of this property or the surrounding area is planned, it should be assumed that petroleum contamination may still be present. If petroleum contamination is encountered during future development work, the MPCA staff should be notified immediately.



August 30, 1996

Mr. Gary Hartman  
Hector, Minnesota 55042

cc: Mathew Hylen, City Administrator, Hector  
Jon Hintze, Fire Chief, Hector  
Doug Knutson, Renville County Solid Waste Officer

AH:dms

Tanks and Emergency Response Section  
Cleanup Unit I  
Project Manager  
Anthony Hill

*for*  
*Anthony Hill*

Sincerely,

Thank you for your response to this petroleum tank release and for your cooperation with the MPCa to protect public health and the environment. If you have any questions regarding this letter, please contact me at 612/297-8577.  
For specific information regarding petroleum contamination that may remain at this leak site, please call the TERS File Request Program at 612/297-8499. The "Leak/Spill and Underground Storage Tank File Request Form" (TERS Fact Sheet #35) must be completed prior to arranging a time for file review.

Page 2  
August 30, 1996  
Mr. Gary Hartman

UNION CO-OP OIL COMPANY



Where the customer is the company

Phone 848-6288  
Box 488  
HECTOR, MINNESOTA 55342

RECEIVED

AUG 28 1996

MPCA, HAZARDOUS  
WASTE DIVISION

August 27, 1996

To: Anthony Hill

This is in response to your letter dated July 24, 1996. I had filled out a report prior to this one and was told to spread the soil that was contaminated thinly on the property adjacent to the spill that is owned by the co-op in August of 1995. I don't recall exactly but I think I was talking with Mike? If you need additional information or if I can be of any help please call me anytime - phone1-320-848-6288.

Thank You

Gary Hartman

A handwritten signature in blue ink that reads "Gary Hartman".

General Manager





# Minnesota Pollution Control Agency

---

July 24, 1996

CERTIFIED MAIL  
RETURN RECEIPT REQUESTED

Mr. Gary Hartman  
Union Co-operative Oil  
260 Main Street  
Hector, Minnesota 55342

RE: Petroleum Storage Tank Release Investigation and Corrective Action  
Site: Union Co-op Bulk Plant, Hector  
Site ID#: LEAK00008188

Dear Mr. Hartman:

On February 6, 1995, the Minnesota Pollution Control Agency (MPCA) staff was notified that a release of petroleum occurred from storage tank facilities that you own and/or operate at the site referenced above. In a telephone conversation on August 8, 1995, MPCA staff requested that you provide a detailed summary explaining the procedures used in remediating the release of petroleum from the aboveground storage tank.

A recent review of our files shows that we have not received the information that was previously requested. MPCA staff requests that you submit fact sheet #3.5, "Surface Release at Tanks Sites" for review within 45 days of receipt of this letter. Failure to comply with this requirement may result in reduced reimbursement from the Petrofund and/or enforcement action taken against you by the MPCA.

If you have any questions concerning this letter or need additional information, please call me at 612/297-8577. Please reference the above LEAK # in all correspondence.

Sincerely,

A handwritten signature in black ink that reads "Anthony Hill".

Anthony Hill  
Project Manager  
Cleanup Unit I  
Tanks and Emergency Response Section

Enclosure



Minnesota Pollution Control Agency

# Surface Petroleum Release Follow-up Checklist

for contained surface releases and surface releases of 100 gallons or less

A member of the Minnesota Pollution Control Agency (MPCA) Leaking Underground Storage Tank (LUST) program has been assigned to your surface petroleum release incident which occurred on the date indicated below. We are sending this request for information as a follow-up to the incident.

Incident name/location: Union Co-op Oil

Date of incident: Feb-6-1995 Leak number: 00008188

Tank owner/operator: Union Coop Oil Contact person: GARY HARTMAN

Mailing Address: P.O. Box 488 Hector, MN 55342

Reply due date: 45 days of the receipt of letter

**Direct questions and reply to:**

ANTHONY HILL  
 Minnesota Pollution Control Agency  
 Tanks and Spills Section  
 520 Lafayette Road  
 St. Paul, Minnesota 55155  
 Phone: (612) 297 - 8577 or 1-800-657-3864  
 Fax: (612) 297-8676

Please fully answer each of the questions which are marked. Use separate paper to respond. The questions must be answered by individuals who are familiar with the incident. The response must be signed by the tank owner/operator. The signature must be preceded by the following statement:

*"I have personally examined and am familiar with the information submitted in this incident report and all attached documents.*

*I believe the submitted information is true, accurate and complete."*

*Gary Hartman*

Your file will remain open until a response is received by this agency.

### INCIDENT RESPONSE AND CHRONOLOGY

- Describe the location of facilities involved in the incident. List contents, capacity, type, and age of involved tanks.  
*South Bullc Plant Hwy 4 South. 50,000 GAL TANK*
- List the type and quantity of released material.  
*#2 Diesel Fuel. Estimate 15-20 GAL*
- What time did the incident occur? When and how was it discovered?  
*Around 6:30 Pm Went to look up Bulk Plant And noticed it -*
- What was the cause of the incident?  
*TANK BOTTOM Spring A LEAK*
- When were these notifications made?  
1. Local public safety response organizations; 2. Company personnel authorized to hire cleanup contractors; 3. Minnesota State Duty Officer; 4. Federal agencies (if applicable). *Immediately*

## INCIDENT RESPONSE AND CHRONOLOGY (continued)

- When did recovery and cleanup equipment and personnel mobilize to and depart from the site?  
(Give a time for each contractor and groups of personnel ordered to the incident.)  
*We Started Cleanup Right Away. We did it Ourselves -*
- Where did recovery and cleanup personnel come from?  
(Give a company name, address, and phone number for each contractor, consultant, and group of personnel used.)  
*Ourselves -*
- Describe the major containment and cleanup tasks completed, including approximate start and finish times.  
*We Pumped up what we could then Spread Floor Dry Absorbent to*
- Other: *Clean up the Rest - All within 1 Hr of Spill*

## INVESTIGATION AND CLEANUP

- Describe the recovery and cleanup operations completed, estimate the volume of each spilled material recovered, and document the amount of soil recovered. *We recovered All Floor Dry material*
- Provide information about excavation of contaminated soil. Include excavation dimensions, soil type, depth to ground water and/or bedrock (if encountered), and any other unique site conditions.  
*Shovel Dig Approx. 2' of Soil from Dike Area where Spill Occurred -*
- Include site location map(s) which show locations of tanks, piping, and dispensers, buildings or structures, roadways, sewers, wells, extent (horizontal and vertical) of soil excavation and spilled product. All maps should have a north arrow, a bar scale, and a map legend.  
*Soil was Spread on our property Approx 1/2" thick to Evaporate -*
- List amounts, location, and method of disposal for petroleum contaminated soil. Also give MPCA approval dates for treatment of contaminated soils. *Aug - 1995*
- Describe remaining contamination by estimating the amount of and depth to contaminated soil. Explain why contamination was left. In the event that contaminated soil remains, soil sampling may be required.
- Other: *None*

## SITE HISTORY

- Are other leak or spill incidents associated with the site? If so, provide incident dates, MPCA leak number(s), spill number(s), and project manager(s). *NO*

## PREVENTION AND PREPAREDNESS

- What steps has or will you/the organization take to prevent a similar incident?  
*We put New Bottoms in Both Tanks*
- How will you/the organization improve its preparedness for response to spills or other incidents (including training, equipment, staffing, contracting, and procedural enhancements)? *We have Employee mtgs*
- Other: *Every month on Accidents and Maintenance plus other prep work*



# Minnesota Pollution Control Agency

---

July 24, 1996

CERTIFIED MAIL  
RETURN RECEIPT REQUESTED

Mr. Gary Hartman  
Union Co-operative Oil  
260 Main Street  
Hector, Minnesota 55342

RE: Petroleum Storage Tank Release Investigation and Corrective Action  
Site: Union Co-op Bulk Plant, Hector  
Site ID#: LEAK00008188

Dear Mr. Hartman:

On February 6, 1995, the Minnesota Pollution Control Agency (MPCA) staff was notified that a release of petroleum occurred from storage tank facilities that you own and/or operate at the site referenced above. In a telephone conversation on August 8, 1995, MPCA staff requested that you provide a detailed summary explaining the procedures used in remediating the release of petroleum from the aboveground storage tank.

A recent review of our files shows that we have not received the information that was previously requested. MPCA staff requests that you submit fact sheet #3.5, "Surface Release at Tanks Sites" for review within 45 days of receipt of this letter. Failure to comply with this requirement may result in reduced reimbursement from the Petrofund and/or enforcement action taken against you by the MPCA.

If you have any questions concerning this letter or need additional information, please call me at 612/297-8577. Please reference the above LEAK # in all correspondence.

Sincerely,

A handwritten signature in black ink that reads "Anthony Hill". The signature is written in a cursive, slightly slanted style.

Anthony Hill  
Project Manager  
Cleanup Unit I  
Tanks and Emergency Response Section

Enclosure

520 Lafayette Rd. N.; St. Paul, MN 55155-4194; (612) 296-6300 (voice); (612) 282-5332 (TTY)

Regional Offices: Duluth • Brainerd • Detroit Lakes • Marshall • Rochester

Equal Opportunity Employer • Printed on recycled paper containing at least 10% fibers from paper recycled by consumers.



# Minnesota Pollution Control Agency

---

September 21, 1995

Mr. Gary Hartman  
Union Co-op Oil  
260 Main Street  
Hector, Minnesota 55342

RE: Approval to Thinspread Less than Ten Cubic Yards of Petroleum Contaminated Soil  
Site: Union Co-op Bulk Plant, Hector  
Site ID#: LEAK00008188

Dear Mr. Hartman:

The Minnesota Pollution Control Agency's Tanks and Emergency Response Section is authorizing the thinspreading of less than ten cubic yards of petroleum contaminated soil. This letter authorizes thinspreading providing the following conditions can be met:

1. Permission has been granted from the owner of the property.
2. Material stored prior to thinspreading is placed in barrels or covered with plastic.
3. Application of the petroleum contaminated soil takes place between April 1 and November 1.
4. The contaminated material is not spread onto residential lawns or in flower or food gardens and the spreading area is not used for food production for one year.
5. The spreading surface does not have a slope greater than six percent.
6. The contaminated material is spread as thin as possible not to exceed two inches in thickness.
7. The spreading is done in a relatively isolated area. In general, set-back distances of 200 feet from houses and property lines and 100 feet from bodies of water, storm sewers, and gardens. A minimum depth of four feet to seasonal high water table should be maintained. All petroleum contaminated soil should be spread on soil with moderate to high fertility.
8. After application, the petroleum contaminated soil worked into the native soil by disking, raking, blading or equivalent methods.

Mr. Gary Hartman

Page 2

September 21, 1995

9. The local government officials are notified and compliance with local and county ordinances is observed for storing and spreading soil.

10. Once the soil is spread, please provide a map of the location (including the address) of the spread soil. Please address the map to the project manager, Mike Nelson, at the address listed on the bottom of the first page.

The application site should be observed for visual contamination for a minimum of one year. After that time the soil should be inspected for petroleum odor, staining or discoloration. If any of these signs are present, notify me and continue treatment.

If the above conditions cannot be met, or you have any further questions, please contact me at 612/297-8577. Thank you for your time and cooperation.

Sincerely,



Mike Nelson

Project Manager

Cleanup Unit I

Tanks and Emergency Response Section

MN:KF

cc: Mathew Hysten, City Administrator, Hector  
Doug Knutson, Renville County Solid Waste Officer  
Minnesota Department of Commerce, Petrofund Staff



# Minnesota Pollution Control Agency

---

February 10, 1995

Mr. Gary Hartman  
Union Co-op Oil  
260 Main Street  
Hector, Minnesota 55342

RE: Petroleum Storage Tank Release Investigation and Corrective Action  
Site: Union Co-op Oil South Bulk Plant, Hector  
Site ID#: LEAK00008188

Dear Mr. Hartman:

## **Notice of Release**

The Minnesota Pollution Control Agency (MPCA) has received notification that a release of petroleum has occurred from storage tank facilities which you own and/or operate that has resulted in contamination of soil and/or ground water.

## **Legal Obligations**

Federal and state laws require that persons legally responsible for storage tank releases notify the MPCA of the release, investigate the extent of the release and take actions needed to ensure that the release is cleaned up. A person is considered legally responsible for a tank release if the person owned or operated the tank either during or after the release, unless specifically exempted under the law. See Minn. Stat. § 115C.021 (1992). If you believe that you are not legally responsible for this storage tank release, please submit a written explanation of your position to the MPCA within 30 days.

If you are not legally responsible for the release, but hold legal or equitable title to the property where the release occurred, you may volunteer to take corrective action. Responsible persons and volunteers who take corrective action may be eligible for reimbursement for a major portion of the costs of corrective action. The legislature has established the Petroleum Tank Release Cleanup Account to reimburse responsible persons and volunteers. The account is administered by the Petro Board which is part of the Minnesota Department of Commerce. Final decisions regarding the amount of reimbursement are made by the Petro Board. All questions about eligibility and reimbursement should be directed to the Petro Board at 612/297-1119 or 612/297-4203.

520 Lafayette Rd. N.; St. Paul, MN 55155-4194; (612) 296-6300 (voice); (612) 282-5332 (TTY)

Regional Offices: Duluth • Brainerd • Detroit Lakes • Marshall • Rochester

Equal Opportunity Employer • Printed on recycled paper containing at least 10% fibers from paper recycled by consumers.

February 10, 1995

Mr. Gary Hartman  
Page 2

**Request to Take Corrective Action**

The MP&A staff is requesting you to take the steps necessary to investigate and clean up the release in accordance with the enclosed MP&A fact sheets. The MP&A requires that you conduct a site investigation to define the full extent and magnitude of the soil and/or ground water contamination caused by the release. A report which details the results of the investigation or concludes that excavation was sufficient to address the release for cleanup (Excavation Report and/or Remedial Investigation/Corrective Action Design (RI/CAD)) must be submitted to this office within 10 months of the date of this letter. Please refer to MP&A fact sheets for information pertaining to the degree of investigative work necessary at petroleum release sites.

Sites with free product, drinking water supply impacts, fire or explosion hazards, or ground water impacts which pose a significant threat to public health or the environment, are considered high priority for staff review. If one or more of these situations apply to your site, an RI/CAD report must be submitted within 90 days. In addition, if you know or discover that there is free-floating petroleum in a well, excavation, or borehole, you must notify the MP&A within 24 hours and IMMEDIATELY begin interim free product recovery.

If you have not already done so, the MP&A recommends that you hire a qualified consulting firm registered with the Petro Board that has experience in conducting petroleum release site investigations and in proposing and implementing appropriate corrective actions. A list of registered contractors and consultants is available from the Minnesota Department of Commerce. The MP&A reserves the right to reject proposed corrective actions if the requirements of the site investigation have not been fulfilled. Please note that, under Minn. Rules pt. 2890.0075, subp. 2, you must solicit a minimum of two competitive proposals on a form prescribed by the Petro Board to ensure that the consulting costs are reasonable. Questions about bidding requirements should be directed to Petro Board staff.

**Required Response**

MP&A staff requests a written or verbal response to this letter within 30 days. In your response, please tell us whether you intend to comply with the above requirements. If you do not respond within this time frame, the MP&A staff will assume that you do not intend to comply, in which case the MP&A Commissioner may order you to take corrective action. If you do not comply with the Commissioner's order, it may be enforced in court or, alternatively, the MP&A could use state funds to clean up the release and then request the Attorney General to recover its costs from you through legal action. Failure to cooperate with the MP&A in a timely manner will also result in reduced reimbursement from the Petro Board. See Minn. Rules pt. 2890.0065, subp. 1, item c.



Mr. Gary Hartman


Page 3

February 10, 1995

The enclosed fact sheets will provide you with the information necessary to complete a successful investigation and cleanup.

If you have any questions concerning this letter or need additional information, please contact me at 612/297-8578. Please reference the above LEAK # in all correspondence.

Sincerely,



Sandy Miller-Moren

Project Manager

Cleanup Unit I

Tanks and Spills Section

SMM:bah

Enclosures

cc: Matthew Hylan, City Clerk, Hector  
Jon Hintze, Fire Chief, Hector  
Doug Knutson, Renville County Official  
Nancy Hennen, MPCA, Marshall Regional Office