# AIRES

#### REMEDIAL INVESTIGATION REPORT FORM


FOR

GTE NORTH, INC.

HALLOCK, MINNESOTA

**AUGUST 1996** 

**PROJECT NO. 96-6176** 



AUG 30 1096

MPCA, HAZARJOUS
MASTE DIVISION

PREPARED BY

AIRES CONSULTING GROUP, INCORPORATED

1550 HUBBARD STREET BATAVIA, ILLINOIS 60510 (630) 879-3006 326 S MAIN STREET, SUITE D MORTON, ILLINOIS 61550 (309) 263-7713



# Rem edial Investigation Report Form Fact Sheet #3 24 April 1996

MPCA with the minimum amount of information be included if deemed important for making a sit	h a remedial investigation (RI) is conducted—this or a full RI Completing this form will provide the innecessary for a full RI Additional information should be cleanup decision. If the consultant has concluded that ite, Section 6 and Section 7 may be deleted from this
Refer to MPCA fact sheet #3.19 "Leaking Underg	ground Storage Tank Investigation and Cleanup Policy"
for guidance for the overall objectives of an RI an	nd other MPCA fact sheets regarding investigations
•	eets #3 6 "Excavtion of Petroleum Contaminated Soil" bleum Release Sites" for reporting requirements
<b>,</b>	1 0 1
If free product is discovered the initial reporting s	should be done in accordance with fact sheet #3 3 "Free #3 4 "Free Product Recovery Report Worksheet "
If free product is discovered the initial reporting s Product Evaluation and Recovery" and fact sheet	should be done in accordance with fact sheet #3 3 "Free
If free product is discovered the initial reporting s Product Evaluation and Recovery" and fact sheet	should be done in accordance with fact sheet #3 3 "Free #3 4 "Free Product Recovery Report Worksheet "
If free product is discovered the initial reporting s Product Evaluation and Recovery" and fact sheet  LeakNumber LEAK0000 8767  Responsible Party GIE North, Incorporated	should be done in accordance with fact sheet #3 3 "Free #3 4 "Free Product Recovery Report Worksheet "  Date August 30, 1996
If free product is discovered the initial reporting s Product Evaluation and Recovery" and fact sheet  LeakNumber LEAK0000 8767	should be done in accordance with fact sheet #3 3 "Free #3 4 "Free Product Recovery Report Worksheet "  Date August 30, 1996

#### TABLE OF CONTENTS

SECTION 1: Emergency and High Priority Sites

SECTION 2: Site and Release Information

SECTION 3: Excavated Soil Information

SECTION 4. Extent and Magnitude of Soil Contamination

SECTION 5: Aquifer Characteristics/Ground Water Contamination Assessment

SECTION 6: Extent and Magnitude of Groundwater Contamination

SECTION 7: Evaluation of Natural Biodegradation

SECTION 8: Well Receptor Information/Assessment

SECTION 9: Surface Water Risk Assessment

SECTION 10: Vapor Risk Assessment/Survey

**SECTION 11: Discussion Section** 

**SECTION 12: Conclusions and Recommendations** 

SECTION 13. Required Figures

SECTION 14. Appendices

SECTION 15: Consultant (or other) information

#### Section 1: Emergency and High Priority Sites

1 Is an existing drinking water well impacted?

YES NO

2 Are there existing vapor impacts?

YES NO

3 Is there an existing surface water impact as indicated by 1) a product
sheen on the surface water or 2) a product sheen or volatile organic
compounds in the part per million range in ground water in a well located
close to the surface water

4 Has the release occurred in the last 30 days?

YES (NO)

5 Has free product been detected at the site?

YES NO

6 Is sand or gravel aquifer impacted which is tapped by water wells within YES NO or potentially within 500 feet from the edge of the plume or does impacted soil overlie a karsted limestone or fractured bedrock? If yes, explain:

Due to restrictions on site posed by overhead lines and underground utilities, a subsurface investigation was not able to be conducted. It is not likely that impacted soil overlies a karsted limestone or fractured bedrock. Regional geology of Hallock indicates that the bedrock consists of dolomitic shale with upper beds of cherty dolostone which are not fractured. All residents within 500 feet of the site obtain their drinking water from municipal sources, and it is unlikely that the municipal water supply has been impacted. See Figures 2d and 2e, and Appendix G

If you answered YES to any of questions I through 6 above describe below the actions taken to date to reduce or eliminate the risk posed by the release

The leaking underground storage tank was removed September 14, 1995. Due to unfavorable conditions at the time of tank removal, overexcavation of the contaminated soils was not feasible. The proximity of the underground utilities to the tank as well as the location of the building immediately to the west rendered overexcavation impossible. See Figure 2. Contaminated soils were returned to the excavation. Plastic sheeting was used to separate the contaminated backfill from the native soil within the excavation as well as the clean fill used to bring the excavation to grade.

#### Section 2: Site and Release Information

2 1 Describe the land use and pertinent geographic features within 1000 feet of the site

The topography in the vicinity of Hallock is relatively flat Land use within 1000 feet of the site is primarily commercial, but minor residential areas do exist. Two Rivers is approximately 1/2 mile northeast of the site. No surface waters or wetland areas exist within 1000 feet of the site. Eight (8) LUST sites are located within 1000 feet of the GTE facility in Hallock. Please refer to Appendix H.

LECEIVED

AUG 30 1096

MPCA, HAZARDOUS

Provide the following for all tanks that have been at the site

			ŀ	
285 gallons	Diesel fuel	18 yrs	removed 9/14/95	Heavy pitting and corrosion of the north end of the tank bottom, especially around the weld seam
				285 gallons Diesel fuel 18 yrs removed 9/14/95  (date), abandoned in place (date), or currently used

2.2 I	escribe the status of the other components of the tank system(s), (i.e.,	piping a	nd
d	spensers) for those tanks listed above.		

Some corrosion was noted in the piping, but it was otherwise in good condition. The tank was used to store fuel for an emergency generator located at the site. No dispenser was present in the UST system.

2 3 Identify and describe the source or suspected source(s) of the release

The suspected source of the release was the weld seam of the tank

2 4 What was the volume of the release? (if known). unknown gallons
2 5 When did the release occur? (if known) unknown

#### Section 3: Excavated Soil Information

3 1 Was soil excavated for off-site treatment?

YES (NO)

If YES then complete the fact sheet #3.7 "Excavation Report Worksheet for Petroleum Release Sites" and include it as an appendix

Date excavated	Not Applicable
Volume removed	cubic yards

Page 5		
3 2 Indicate soil treatment type	land treatment thermal treatment composting/biopiling other ( Name and location of treatment facility	y
Section 4: Extent and Mag	nitude of Soil Contamination	
_	or immediately adjacent to all likely source eas, piping, dispensers, remote fill pipes,	YES NO
be completed at least five feet be deepest measurable (field screen	extent of contamination soil borings should elow the water table or ten feet below the ung and visual observation) contamination, oil borings completed to the required depth?	YES NO
	igraphy at least one boring should be ter table, unless a confining layer is present	YES NO
not conducted in the required "Soil and Ground Water Invergarding exceptions and MP Underground utilities and over investigation at the facility not feasible Please refer to	f the three previous questions, explain why the locations or to the required depths (see fact she estigations Performed During Remedial Investigations Performed During Remedial Investigations Performed During Remedial Investigations Performed During Remedial Investigations (CA approval for depth of drilling) rerhead lines eliminated the possibility of a subsurface Access to the facility by any size drilling equipment was Figure 2a and the photographs attached in Appendix H pon discovery of these site conditions and an alternative was suggested	eet #3 19 gations"
4 4 Indicate the drilling method	hollow-stem augersonic drillingpush probesother (	†

Subsurface drilling activities were not able to be conducted at this facility

Table 2.

Complete the following table indicating jar headspace results (in ppm) for soil samples from soil borings.

ASTM soil	Depth				Soil B	oring				
classification	(ft)	1	2	3	4	5	6	7	8	9
			·							
<u> </u>										
										<del></del>
	ļ									
			<u> </u>							
<del></del>			<u> </u>					-		
		l	1	l						

Notes: (type of PID/FID)

A subsurface investigation was not able to be conducted at this site

Table 3.

Indicate the laboratory analytical results for soil samples in mg/kg.

Well/Boring, Depth(ft)	Date Analyzed	Benzene	Toluene	Ethylbenzene	Xylene	GRO	DRO
<u> </u>							

Notes (use less than symbols to show detection limits)

A subsurface investigation was not able to be conducted at this site

#### Table 4.

Indicate other notable contaminants (either petroleum or non-petroleum derived) detected in soil samples Indicate contaminant and list in reported units mg/kg

Well/Boring, Depth (ft)	Date Analyzed			
		-		
				]

Notes

Soil samples were not collected at the site

4.5 If any non-petroleum compounds were detected list them below and identify possible sources of these compounds

Not Applicable

4 6 Describe the vertical and horizontal extent and magnitude of soil contamination

Soil samples were not able to be collected for laboratory analysis at the time of the Site Investigation The extent of soil contamination is unknown Minor amounts of BTEX were detected in the north tank base sample as well as the center tank base sample collected at the time of tank removal. The south tank base sample did not indicate the presence BTEX compounds The north and south tank base samples collected from native soil at the time of tank removal showed elevated levels of diesel range organics, but the center tank base sample detected no DRO Regional soil conditions are not conducive to extensive migration of the contamination

### Section 5: Aquifer Characteristics/Ground Water Contamination **Assessment**

	111
supporting information for the determination in the Methodologies appendix	

	C 11
$1 \times 10^{-6} < X < 1 \times 10^{-3}$ cm/sec	x estimate from reference
estimate is based on an aquifer media of sandy silt, clayey sands, and silty sands, glacial outwash and alluvial deposits  5.2 Indicate the thickness of the aquifer	slug test permeability test Hazen approximation from grain-size distribution  If the investigation does not provide enough
information to determine the aquifer	thickness, assume the aquifer is greater than 20 feet
thick	less than 10 feet
	between 10 and 20 feet
	x 20 feet or greater
5.3 Describe in detail the geology under	lying the site including confining layers, bedrock
formations and the lateral extent of	hasa farmatiana

formations and the lateral extent of these formations

Native soil conditions noted at the time of tank removal consisted of brown silty clay Quaternary geology in the area consists of alluvium, sand and gravel locally interbedded with silt, clay and organic material, deposited on floodplains of major streams. The bedrock consists of Cretaceous Aquifer deposits, fine- to coarse-graded sandstone and quartzose, generally at the base of a shale-siltstone sequence The bedrock is regionally extensive, and the quaternary deposits are locally extensive

#### Page 8

The impacted aquifer or the aquifer that is likely to be impacted at the site is considered a resource aquifer if one of the following situations exist

- . The aquifer is a current water supply source
- The water bearing unit has a hydraulic conductivity greater than 1 X 10-2 cm/sec and a minimum thickness of 10 feet.
- The water bearing unit has a hydraulic conductivity between I X 10-4 cm/sec and 1 X 10-2 cm/sec and a minimum thickness of 20 feet
- The water bearing unit has a hydraulic conductivity less than 1 X 10-4 cm/sec and no other viable source of water supply is available. (Bedrock may be considered a resource aquifer if it is the only water supply available.)
- 5.4 Based on the aquifer characteristics and water supply availability, is the aquifer at the site a resource aquifer?

YES NO

5 5 If other water supplies are available, explain

Municipal water is available in Hallock Municipal supply wells are not located within 1/2 mile of the site. All residents within 500 feet of the site obtain their drinking water from municipal sources. It is unlikely that the aquifer at the site is a supply aquifer, and it is unlikely that the municipal water supply of Hallock has been impacted by the release

5.6 Are there any other reasons the impacted aquifer should not be considered a resource aquifer?

Table 5.

Indicate the water level measured in all of the soil borings

					Soil E	Boring				
	1	2	3	4	5	6	7	8	9	10
Water level										
depth, ft	1	1	1	1	<b> </b>	1				

Notes:

Soil borings were not able to be advanced at the site

5 7 Is contaminated soil in contact with ground water?

YES NO

If YES or if ground water contamination appears likely then complete tables 6 and 7 below

It is unknown whether contaminated soil is in contact with groundwater at the site

Table 6.

Indicate the laboratory analytical results for water samples collected from the borings, temporary wells or push probes

	lumber	Date Analyzed	Benzene	Toluene	Ethylbenzene	Xylene	GRO	DRO
							,	
		:						
		<u>                                     </u>						
Notes								
<u>Wa</u>	ater samp	les were not able	to be collected a	t the site for	laboratory analy	SIS		
			Ta	ble 7.				
, ,								
					non-petroleum			
water samp	les coll	ected from the			non-petroleum lls or push pro			
water samp	les coll				-			
water samp	les coll	ected from the			-			
water samp and report 1	les coll	ected from the			-			
water samp and report 1 Well/Boring	les coll n units	ected from the			-			
water samp and report 1 Well/Boring	les coll n units	ected from the			-			
water samp and report 1 Well/Boring	les coll n units	ected from the			-			
water samp and report 1 Well/Boring	les coll n units	ected from the			-			
water samp and report 1 Well/Boring	les coll n units	ected from the			-			
water samp and report 1 Well/Boring	les coll n units	ected from the			-			
water samp and report 1 Well/Boring	les coll n units	ected from the			-			
water samp and report i  Well/Boring Number	Date Analyz	ected from the	borings, tem	porary wel	-			

Water samples were not able to be collected at the site

5 9 If contaminated soil is not in contact with ground water, what is the distance separating the deepest contamination from the surface of the water table? Was this distance measured during site activities, referenced from geologic information, or estimated based on professional opinion during a site visit?

e <u>20</u> feet unswerd question 5.7 w/ unchar whether 6w is impacted.

This distance was referenced from geologic information gathered from various sources on the regional hydrogeology of the Hallock area.

5.10 Describe observations of any evidence of a fluctuating water table and a seasonal high water table (e g, mottling). Also, from other sources of information describe the range of natural water table fluctuations in the area

No soil bonngs were advanced at the site, but no hydrogeologic information indicates the possibility of a seasonally high water table at the site

5 11 In your judgment, is there a sufficient distance separating the petroleum contaminated soil (or an impacted non-resource aquifer) from the underlying resource aquifer to prevent petroleum contamination of the resource aquifer? Please explain in detail. In your explanation consider the data and information of this section as well as the nature of the petroleum release (i.e., volume, when it occurred, petroleum product)



The source of the release has been removed Based on all referenced materials concerning the geologic and hydrogeologic characteristics of the Hallock area, it appears that sufficient distance separates the impacted soil from the underlying resource aquifer to prevent petroleum contamination of the resource aquifer. The immediate subsurface material consists of silty clay which would prevent vertical migration of the contaminants through the soil. Quaternary deposits in the area consist of poorly sorted outwash mixed with fines and organic matter which are not condusive to contaminant migration. The bedrock in the Hallock area consists of shale and quartzose. This would also tend to prevent vertical migration of the contamination through the bedrock. The bedrock does not appear to be fractured, and this would greatly reduce the ability of the contamination to migrate horizontally through the bedrock.

#### Additional Ground Water Investigation

Complete Section 6 and Section 7 only if 1) a resource aquifer has been impacted at or above Minnesota Department of Health Health Risk Limits (HRLs), 2) a resource aquifer has been impacted below the HRLs, but the levels are likely to reach the HRLs, or 3) there is an insufficient distance separating the petroleum contaminated soil (or an impacted non-resource aquifer) from the underlying resource aquifer. Regardless of whether you are submitting a Limited Site Investigation or a full RI, all sections following Section 7 must be completed

# Section 6. Extent and Magnitude of Groundwater Contamination

Table 8

Monitoring well construction

Unique Well Number	Date Installed	Relative Surface Elevation	Riser Height Above Grade	Bottom of Well (Elevation)	Screen Interval (Elev Elev.)
	<u> </u>				
	lumber	lumber Installed	lumber Installed Elevation	lumber Installed Elevation Above Grade	lumber Installed Elevation Above Grade (Elevation)

Notes (location and elevation of benchmark)

Table 9.

Water table summary

Well Number	Date	Depth of Water from Top of Casing	Product Thickness	Depth of Water Below Grade	Relative Groundwater Elevation
MW-1					
MW-2					
MW-3					
MW-4					

Notes (GW above/below screen, etc.)

6 1 Were any deep monitoring wells completed at the site?

YES NO

If YES, which are deep wells?

Before a deep well is installed contact the MPCA project hydrologist for guidance on its necessity and placement. A deep monitoring well may be necessary if 1 ) contamination exist more than 10 feet below the water table or 2) the impacted aquifer is a resource aquifer or is hydraulically connected to a resource aquifer presently utilized by a water supply well located within 500 feet of the site

Provide estimates of the following ad	ıddıtıonal aquıfer i	parameters
---------------------------------------	----------------------	------------

Horizontal Gradient (dh/dl)	<u>.</u>
Vertical Gradient (dv/dl).	
Porosity	
Flow direction	
Hydraulic Conductivity (K)	rn/s
Pore velocity:	meters/year

Table 10

All ground water monitoring data should be collected from a minimum of two quarterly sampling events.

Indicate the laboratory analytical results for water samples.

Well #	Date	Benzene	Toluene	Ethylbenzene	Xylene	MTBE	GRO	DRO
MW-1								
MW-2								
MW-3								
MW-4								
							1	

Notes (e g, free product, dry well, units etcJ

#### Table 11.

Indicate other notable contaminants (either petroleum or non-petroleum derived) detected in water samples

Well #	Date Analyzed				
			1		

Notes units

- 6 2 If any non-petroleum compounds were detected list them below and indicate whether they exceed the HRLs Also, identify possible sources of these compounds
- 6 3 Is there a clean or nearly clean (below HRLs) downgradient monitoring well YES NO located along the longitudinal axis of the contaminant plume?

  (approximately 20 degrees plus or minus the axis)
- 6 4 Is there a worst case well completed through the source area of the release? YES NO

  If you have answered NO to any of the above three questions, please explain why a well was not completed in the required location
- 6 5 Provide an estimate of the longitudinal length of the dissolved \_\_\_\_\_\_ feet contaminant plume
- 6 6 Describe the extent and magnitude of the ground water contamination.

# Section 7: Evaluation of natural attenuation

#### Table 12

Complete the bioactivity data in the table below Data should be from two quarterly rounds of sampling. Refer to the fact sheet #3 21 "Assessment of Natural Biodegradation at Petroleum Tank Release Sites" for acceptable methodologies and indicate the chosen method in the Methodologies appendix

Monitoring Well	Temp. °C	pН	Dissolved oxygen (mg/l)	Nitrate (mg/l)	(Fe II) (mg/l)	(H2S, HS) (mg/l)
MW-I						
MW-2						
MW-3						
MW-4						
· · · · · · · · · · · · · · · · · · ·						

Nο	tos	

- 7 1 Discuss the results of the bioactivity evaluation Specifically, compare the concentrations of the inorganic parameters inside and outside the plume
- 7 2 In your judgment, is natural biodegradation occuring at this site? Please YES NO Explain

#### Section 8: Well Receptor Information/Assessment

Include in the appendices of this report 1) a list of addresses within 500 feet from the edge of the plume and confirmation of status of water supply from the city utility billing department, 2) well logs, and 3) map showing 1/2 mile radius, 500 foot radius, water supply wells, other potential petroleum sources, and addresses for properties within 500 feet

Table 13

Complete the following table for all water supply wells located within 500 feet of the edge of the plume and any municipal or industrial wells found within 1/2 mile

Unique Well #	Ground Elevation	Total Depth (ft)	Base of Casing (ft)	Static Elevation	Aquifer	Use	Owner	Distance & Direction from site
215966	815 ft ASL	529	504	102 05		observation	Federal Government	1800 ft SSW

Notes

No water supply or municipal wells exist within the specified radii

8 l Is municipal water available in the
---



) NO

8 2 Were all property owners within 500 feet of the nearest edge of the contaminant plume successfully contacted to determine if water wells are present? If No, please explain



All property owners are provided municipal water service See Appendix G

8 3 Discuss the results of the ground water receptor survey and any analytical results from sampling conducted at nearby water wells. Comment on the risks to water supply wells identified within 500 feet from the edge of the plume as well as the risk posed by or to any municipal or industrial wells found within 1/2 mile. Specifically indicate whether water supply wells identified utilize the impacted aquifer (Note an impacted aquifer separated from another aquifer by a clay lens is not considered a separate aquifer.)

No water supply wells exist within a 500 foot radius of the site. No municipal or industrial wells are located within 1/2 mile of the site. No risk is imposed by the impacted soils to supply wells, municipal or industrial wells, or the surface water in the vicinity of Hallock.

8.4 Are there any plans for groundwater development in the within one half mile of the site, or one mile down gradier aquifer is fractured? Please give the name, title and photoperson that was contacted for this information.	nt of the site if the
Mr Hank Noel, City of Hallock	Phone 218-843-2737
Section 9: Surface Water Risk Assessment	
9 1 Are there any surface waters or wetlands located within 1/	/4 mile of the site? YES NO
If YES, indicate its name	
9.2 If surface water is present downgradient of the site, is the gradient soil boring or monitoring well located between t surface water?	
If NO, we assume that contamination discharges to su the following information.	arface water Therefore, complete
Name of receiving water.	
Plume width, (W)	feet

If YES, identify them and indicate the distance to these features and discuss the contamination risk potential.

# Section 10: Vapor Risk Assessment/Survey

10 1 Is there a history of vapor impacts in the vicinity of the site?

YES (NO

feet

gal/day/ft2

(unitless)

YES (NO



Plume thickness, (H)

Hydraulic conductivity, (K)

Horizontal gradient, (dh/dl)

Discharge, (Q) = H\*W\*K\*(dh/dl)/1440

10 2 Is there any indication that free product or highly contaminated groundwater may be traveling offsite within the utility corridors? If YES, have they been investigated with borings or push probes?



Although several utility conduits are located at the facility, no free product exists at the site. It is not likely that highly contaminated groundwater exists at the site.

10 3 Discuss the potential for vapor migration/accumulation near the site. In your discussion consider soil types, product type, presence and distribution of free product or high concentrations of dissolved product. Also, compare the depth of contamination with the location of underground utility lines, location and depth of storm and sanitary sewers and location of nearby basements.

The potential for vapor migration/accumulation is insignificant. The source of the release has been removed. Utility corridors surround the tank location, but no storm or sanitary sewers are located near the former LUST. Free product does not exist at the site, and it is not likely that highly contaminated groundwater exists at the site. Subsurface soils consist of silty clay as well as poorly sorted outwash and alluvial deposits. The permeability of the soil appears to be extremely low.

If the vapor risk assessment indicated a risk of vapor impacts to buildings or utilities, complete the following table with vapor monitoring data collected Location numbers should be mapped on an accompanying figure of the surveyed area

Table 14

t of the LEL	Percent of	PID reading (ppm)	Date	Location #
	<u> </u>	<del>                                     </del>		
	<u> </u>	<del>                                     </del>		
		+		
-				

Notes

A Vapor Survey was not necessary at the site

10 4 Describe and interpret the results of the vapor survey

A Vapor Survey was not performed at this site

#### Section 11: Discussion

#### 11.1 Discuss the risks associated with the remaining soil contamination?

The remaining soil contamination does not likely present any risk to the environment or to human health. No vapor impacts exist at the site, and no free product exists at the site. Highly contaminated groundwater is not likely to be present at the facility. The subsurface soils and bedrock in the Hallock area are not conducive to the vertical or horizontal migration of contamination.

#### 11 2 Discuss the risks associated with the impacted ground water?

The groundwater is not likely to be impacted Hallock residents obtain their drinking water from municipal sources, none of which exist within 1/2 mile of the site. Surface water shows no evidence of impacts. The subsurface soils would tend to prevent the vertical migration of the contamination to the groundwater.

#### 11.3 Discuss other concerns not mentioned above

Site restrictions such as underground utilities and overhead lines made it impossible to advance soil borings at the site (see Figure 2) Minnesota Department of Health restrictions on boring and monitoring well locations rendered it impossible to drill within approximately 70 feet of the tank Overexcavation of the contaminated soils would undermine the building immediately west of the former tank location, as well as jeopardize the integrity of the utility conduits running throughout the site

#### Section 12: Conclusions and Recommendations

Recommendation for site.	x site closure
	additional vapor monitoring
	additional ground water monitoring
	active cleanup
The recommendation above sho	uld be based on fact sheet #3 1 "Leaking Underground Storage
Tank Investigation and Cleanup	Policy." Describe below how you applied the policy to support
your recommendation.	

The risks posed to surface waters and resource aquifers are low as well as is the risk of vapor impacts. Free product does not exist at the site and the source of the release has been removed. Additional investigation and/or monitoring is not a feasible option at the facility. Since risks to receptors are low, site closure is the most feasible corrective action plan.

If additional monitoring is recommended, indicate the proposed monitoring schedule and frequency

Additional monitoring is not recommended at this site

If active cleanup is proposed then MPCA staff will review this remedial investigation report at a higher than normal priority to determine if active cleanup is required. We will respond with either a request for proposal for additional monitoring or a corrective action design report. Please indicate below what cleanup technology you are considering at this time.

Site closure - no active cleanup recommeded

# Section 13: Required Figures

#### Indicate attached figures

Indica	te attached i	figures
<u>x</u>	Figure 1, la:	Site location map (approximate scale is not acceptable) and a large scale site map show all potential receptors within 300 feet of the site. The large scale site map should show those properties with basements and wells
<u> </u>	Figure 2, 2a, 2b, etc:	One or more site map showing structures; all past and present petroleum storage tanks, piping, and dispensers, extent of soil excavation, boring and well locations (including any drinking water wells on site), horizontal extent of soil contamination, horizontal extent of ground water contamination; and location of end points for all geologic cross sections
<u>NA</u>	Figure 3, 3a:	Ground water gradient contour maps (for sites with monitoring wells)
<u>x</u>	Figure 4	Well receptor survey map showing 1/2 mile radius, 500 foot radius, water supply wells, other potential sources of contamination
_NA_	Figure 5	Vapor survey map showing utilities and buildings with basements and monitoring locations (if a survey was required)
NA	Figure 6	Geologic cross sections

# Section 14: Appendices

Indicate	attached	appendices.
----------	----------	-------------


NA	Appendix A	Excavation Report Worksheet for Petroleum Release Sites
NA_	Appendix B	Laboratory analytical reports for soil and ground water.
<u>x</u>	Appendix C	Methodologies and procedures, including field screening of soil, other field analyses, soil boring, soil sampling, well installation, and water sampling
NA	Appendix D	Geologic logs for each well or boring using attached template
NA	Appendix E	Well construction diagrams and copies of the Minnesota Department of Health Well Record using attached template.
<u>x</u>	Appendix F	Copies of water supply well logs with legible unique numbers.
<u>x</u>	Appendix G	A list of addresses within 500 feet from the edge of the plume and confirmation of status of water supply from the city utility billing department.
<u>x</u>	Appendix H	A list of LUST sites located in the city of Hallock
<u>x</u>	Appendix I	Photographs taken during the Limited Site Investigation

#### Section 15: Consultant (or other) information


By signing this document, I/we acknowledge that we are submitting this document on behalf of and as agents of the responsible person or volunteer for this leaksite. I/we acknowledge that if information in this document is inaccurate or incomplete, it will delay the completion of remediation and may harm the environment and may result in reduction of reimbursement awards. In addition, I/we acknowledge on behalf of the responsible person or volunteer for this leaksite that if this document is determined to contain a false material statement, representation, or certification, or if it omits material information, the responsible person or volunteer may be found to be in violation of Minn. Stat f 115 075 (1994) or Minn Rules 7000 0300 (Duty of Candor), and that the responsible person or volunteer may be liable for civil penalties

Name and Title:	Signature:	Date signed:
EUZABETH RACHMAN HYDROGEOLOGIST	Elizabeth Racliman	8123196
SUPERUSUR-TECHNICAL SCENIES	Melhu	<u>8123196</u> <u>8126196</u>
Company and mailing address	Aires Consulting Group, Inc	REGISTERED PROFESSIONAL ENGINEER NO. 24141 OF MINNESSIONAL
	1550 Hubbard Street	* REGISTERED * PROFESSIONAL PROFESSIONAL
	Batavia, IL 60510	MO. 24141 1.7
		W. W. W. W.
Phone	(630) 879-3006	
Fax	(630) 879-3014	

Upon request, this document can be made available in other formats, including Braille, large print and audio tape. TTY users call 612/282-5332 or Greater Minnesota 1-800-657-3864




SECOND STREET SOUTH





GTE	 HALLOCK,	MINNESOTA	
	FIGURE	1	
	SITE LOCATION	MAP	


SCALE: 1" = 20'


DRAWN BY: BP PROJECT: 96-6176 DATE: 8-19-96















AIRES SITE LOCATION allock 48 -Matts Kennedy Englynd Middle River Scale 1:500,000 1 inch equals approximately 8 miles 40 Miles 30 10 10 0 10 20 30 50 Kilometers BHHHH Cretaceous Aquiter Red River - Winnipeg Aquifer Sandstone, quanticee, fine- to coarse grained: gunerally near the base of a dominantly shale-siltstone sequence; commonly overfies a deeply weathered saprolitic zone in crystalling rooks. Littlestone, culomitto irrestone vuggy thin shalle partings. Sand-stone, fine- to medium-grained quartorse, finable or moderately cemented with caloire (Middle Ornovician age). GTE - HALLOCK, MINNESOTA FIGURE 2d Kanivetsky, 1978, Hydrogeologic Map of Minnesota BEDROCK HYDROGEOLOGIC MAP BY: ER SCALE: 1:500,000 96-6176 DATE: PROJECT: 8/6/96

O Humboldt SITE LOCATION 985 HALLOCK ST 0 STATE Bronch A GAME REMINE Mayoution torre Lake Bronson 1.10 gr Scale 1:250,000 0 15 20 Statute Miles 0 30 Kilometers CONTOUR INTERVAL 50 FEET Cretaceous rocks, undivided
Dominantly light olive-gray to medium- and dark-gray
shale. Bottom of sequence contains beds of white,
calcareous to quartzitic sandstone and scattered thin layers
of lignite. Maximum known thickness 15 meters (50 feet). Hallock red beds Dominantly pale reddish-brown, dolomitic shale with upper beds of yellowish-gray, cherty dolostone. Maximum known thickness 91 meters (300 feet). GTE - HALLOCK, MINNESOTA Green, John C., 1982, Geologic Map of Minnesota, FIGURE 2e Roseau Sheet, Bedrock Geology BEDROCK GEOLOGY SCALE: 1:500,000 BY: ER


PROJECT:

96-6176 DATE:




# APPENDIX A


**EXCAVATION REPORT WORKSHEET FOR PETROLEUM RELEASE SITES** 



# **APPENDIX A - Excavation Report for Petroleum Release Sites**




Soils were not removed from the GTE facility in Hallock Therefore, an Excavation Report Worksheet was not necessary.




# APPENDIX B

LABORATORY ANALYTICAL REPORTS FOR SOIL AND GROUNDWATER




## APPENDIX B - Laboratory Analytical Reports for Soil and Groundwater

A subsurface investigation was not able to be conducted at the facility in Hallock; laboratory analytical reports are not available



#### APPENDIX C

#### METHODOLOGIES AND PROCEDURES



#### **APPENDIX C - Methodologies and Procedures**

The presence of overhead and underground utilities severly restricted the subsurface investigation activities at the GTE facility in Hallock. Minnesota Department of Health restrictions on the location of borings and monitoring wells relative to underground and overhead utilities rendered it impossible to conduct drilling activities. No borings were able to be advanced at the site. In an effort to assess the site as accurately as possible, research was conducted using all available information and maps. All information required in the Remedial Investigation Report Form was collected wherever possible.

#### References

The source used for each figure is listed on the figure itself. Information regarding the water supply wells and nature of the municipal water supply was obtained from Mr. Hank Noel of the City of Hallock LUST sites were obtained from the Leaking Underground Storage Tank Section of the Minnesota Pollution Control Agency.

#### **Hydraulic Conductivity**


The hydraulic conductivity at the subject site is an estimate 
The materials referenced for this information are as follows

Fetter, CW, Applied Hydrogeology, 3rd ed., Macmillian College Publishing Company, New York, 1994.

Heath, Ralph C, <u>Basic Ground-Water Hydrogeology</u>, USGS Water-Supply Paper 2220, US Department of the Interior, 1993


#### APPENDIX D

#### **SOIL BORING LOGS**




### **APPENDIX D - Soil Boring Logs**

Due to the extensive presence of overhead and underground utilities, soil borings were not advanced at the GTE facility in Hallock, Minnesota




### APPENDIX E

MONITORING WELL CONSTRUCTION DIAGRAMS
MINNESOTA DEPARTMENT OF HEALTH WELL RECORDS




## APPENDIX E - Monitoring Well Construction Diagrams & MDPH Well Records

Monitoring wells were not installed at this facility.



#### APPENDIX F

#### WATER SUPPLY WELL LOGS





MINNESOTA

U.S. DEPT OF THE INTERIOR
GEOLOGICAL SURVEY

WELL NO 16/N 49W 13B
----------------------

from Brietkrietz school	SITE SCHEDULE	WELL NO 1011 7 9 10 13 15 CV
tron Bricker i CF school.  GENERAL SITE DATA (0)	Jill Jellebott	Date
Site Ident No 4.8.4.6.0 5.0.9.5.5.6.5.2	0.1 R = 0 + T - A + Ste-Type 2 - W + R	Deta 3 = 1 C U L M 1 e
Project 5 *	District 6 - 2,7   4   State 7 - 2,7   4	COUNTY KITTSON 8- 600
444606	In- INGLETIES Lat-Long	S S T M B Reporting A- U.S.C.S. In
dog min me	deg min 100	Agency 45 U 5 U 5
Number 12 - 1:0:1N 419W 1001CD	14- HALLECK	
Attrude 16- 18/15/ Mee	altimater level map	18- 3 * Scale 15- 24000 *
Hydrologic 20 - 0.9.02.0.3.12 *	Construction 21 = 0.8/	0.1/1.9.72.
Depth of 27 = , 529	Depth of 28 - 5/4 *	Source of Depth Data 29-5+ Topo Setting 19- +
Water 30,1,0,2,0,5 * Messure	Source C	3 - S * Method of Measurement 34 - G = Status 37 - 1 =
Source of 3 6 - 5 * Pump Used 3	Use TIZE Second Use C	1 = 0 = Use of 24 = U +
OWNER IDENTIFICATION (1)	Date of 159 # 0.8/0.1/1.97	721
add dalote modify	month day yeer	<del></del>
Name Last 181 # U.S.G.S.H.A.L.L.D., Hallock Test Hole	C   162 = A.R.T.E.	5; /.E.S.7 * Initial 163-   *
ADDRESS		PHONE
OTHER SITE IDENTIFICATION NUMBERS (1)		
R = 189 * T = A D M * Ident	190 7	91- M,N,U,N,I,Q,U,E,N,O, , , , , , , , , , , , , ,
New Card Same R & T	190 # Assigner 1	91=
WELL CONSTRUCTION DATA (1)		
R = 581 * T = A D M * Entry No 5	month	0.1/1.9.72 * Source of ① 64 • D • Const Data
Name of Contractor/Driller 63 - KEVS	* Method of Construction 5 = H * Finish 66	Type of 67 = 8 C G Z *  bentonce clay, cament other
Seel 68 = 4.0.5 * Me thad of Developm		grout
CASING SCHEDULE (2)  T = A D (M) * Construction Entry No.	Ven # New York East On We	
add delete, medity	S 9 #	
77#	Casing Segment Below LSD Diameter of Casing Segment	t Casing Meternal ®
778 , , -4,	50.4.0. • 79# , 2	• • • • • • • • • • • • • • • • • • •
77# 78-	79# , , , , ,	* 80-11*
OPENINGS SCHEDULE (2)	Type of Openings ®	85-5+
A - 82 * T - A D M * Entry No (Opening	Type of Meterial 17	86-
Top of Section Below LSD 83# 50 Bottom of Section Below LSD 84 = 57	Diameter of Open Sec  Width of Opening	87° 3. •
PRODUCTION DATA (1)		
R = 134 146 0 T = A D M 0	Entry No 147# # Date 148=	month day your
Discharge: 150-	ferthod of 152 = # Draw 209 =	Production 153-
Source 155 - * Pumping Puried 167 -	Specific 272 =	State: 154-
LIFT DATA (1)		
R-42 # T- A D M # Lift 4	3# A B C J P R S	T U Z * Entry 254 #   *

R-320 a T- A D M Begin 321 # 08/0/11/9/72 End 322 a / / / #  Mesearting 323 - H A D M B Remarks 324 b M P I.S. CENITER DF PRESSURE: CARE, I B BOTTOM 92 - MODELINE DESCRIPTIONS (1)  R-90 a T- A D M B Entry 256 # , 1 a Depth to Top 91 - 3.5.7 a Bottom 92 - 5.7.5 a Bottom 93 - 3.6.4 W.N.P.G. a Lithology 98 - S.N.D.S & Modifier 97 - AND. CLAYSTONE, & Contribution 304 P a AQUIFER DATA (2)  R-94 * T- A D M B Geohydrologic Unit Entry No 256 # , 1 a Unit Entry No 256 # , 1 a Water Good Geohydrologic 256 # , 1 a Water 132 - Modifier 95 # 0 1 / 18 / 19 7 \$ a Water 126 - 1 / 15 - 3.3 a Contributed 132 - 4   B Water 132 -	C
GEOMYDROLOGIC UNIT DESCRIPTIONS (1)  R = 90	C
R = 90 0 T - A D M = Entry 256 # , 1 0 Depth to Top 91 - , 3,5,7,    Bottom 92 - , 5,7,5,    Water destributer 93 - 3,6 #, W, N, P, G,    Unit destributer 93 - 3,6 #, W, N, P, G,    Lithology 96 - S, N, D, S + Modifier 97 - A, N, D, C, A, Y, S, T, ONE,    Water Contribution 304 - P = AOUIFER DATA (2)  R = 94   9 T - A D M = Geohydrologic Unit Entry No Unit Entry No Unit Entry No 256 # , 1 +   Date 95 # 0, 1 / 18 / 19,73 + Water Level 126 - , 1, 1, 5, 5, 3 + Contributed 132 - ,    Water Level 126 - , 1, 1, 5, 5, 3 + Contributed 132 - ,    * Water Contributed 132 - ,    * Wa	<b>(</b>
AQUIFER DATA (2)  Geohydrologic Unit Entry No 256 # , 1 #  Date 95 # 0 1 / 18 / 1973 * Water Level 126 - , 1 / 5 - 5 3 * Contributed 132 * ;   #	
AQUIFER DATA (2)  R = 94   # T = A D M = Geohydrologic Unit Entry No	
Unit Entry No 256 # 1 # Water Contributed 132 • 1 # Contributed 132 • 1 #	
Date 95 # 0.1/18/1973 . Water Level 1261.1.5.33 . Contributed 132	
GEOHYDROLOGIC UNIT DESCRIPTIONS (1)  R = 9 0   # T = A D M # Entry 256 # , 2 # Depth 9 1 =	
add delete modify  Unit	
Identifier W Modifier W Contribution 304"	
AQUIFER DATA (2)  R + 94 * T = A D M *  add delete modelty  Geohydrologic 256 # , 2 *	
Date 95 #	
PERTINENT REMARKS	
R=183 # T- A # Entry 311#	
New Card Same R&T  No. 311#	(
FIELD WATER QUALITY MEASUREMENTS (1)  R = 192 + T = A D M * Date 193 # / / /   # Geohydro 195 # / /   #	
add delete modify month day year	
New Card Same R thru 195  Temperature 196# 0,0,0,0 1 0 # Degrees C 197 -	
0 as and	
R thru 195 Temperature 198 # 0 0 0 9 5 # Degrees C 197 -	
Conductance 196 # 0 0 0 9 5 * # Minor 197 -	
Conductance    196 # 0 0 0 0 9 5 *	
R thru 195   Temperature   196 # 0 0 0 0 1 1 0 # Degrees C   197 -	
Conductance 196 # 0 0 0 9 5 * # Mhose 197	
R thru 195   Temperature   196 # 0   0   0   0   9   5   #	
Conductance    198 # 0 0 0 0 9 5 *	
R thru 195  Temperature 198 # 0, 0, 0, 1, 0 # Degrees C 197 - ,	
Temperature 196 # 0 0 0 0 9 5 *	
R thru 195   Temperature   198 #   0   0   0   0   9   5   8	
R thru 195   Temperature   196 #   0 , 0 , 1 , 0   9   5   8   187   9   197   197	
R thru 195   Temperature   198 #   0   0   0   0   9   5   8	

i i

#### WELL SCHEDULE

U. S. DEPT. OF THE INTERIOR

GEOLOGICAL SURVEY

WATER RESOURCES DIVISION

MASTER CARD
Record by Brietkrietz Source USGS, MGS Date 10-26-72 No. Hallock 15min.
State Minnesota 27 County (or town) Kittson 35
Lactitude: 484606Ns Longitude: 0,965652 Sequencial number:
Lat-long [2] + 1619, 496 s. 13, SE. SW. NW.
vell number: 461 49 13BCD 1 number:
Lucal use: KEYS WELL CO OT DATE: Hallock Test
Owner or name: U. S. GEØL. SURVEY Address:
Ownership: County, Federal's, City, Corp or Co, Private, State Agency, Water Dist
(A) (B) (C) (D) (E) (F) (H) (H) (H) (P) (R)  Use of Air cond, Bottling, Comm, Devater, Fower, Fire, Dom, Irr, Hed, Ind, P S, Rec,
water: (S) (T) (W) (W) (X) (Y) (±) Stock, Instit, Unused, Repressure, Recharge, Desai-P S, Desai-other, Other
Use of (A) (D) (G) (H) (P) (R) (T) (U) (W) (X) (S) well. Anoda, Drain, Seismic, Heat Res, Ooi, Oil-gas, Recharge, Test, Unused, Withdraw, Waste, Destroyed,
DATA AVAILABLE: Well data Freq. W/L meas.: Weekly Field equifer char. 72
Ryd. lab. data:
Qual. water data, type:
Freq. sampling: Pumpage inventory: no, period:
Aperture cards:
Log data:
WELL-DESCRIPTION CARD
SAME AS ON MASTER CARD Depth well: 529 fc 529 Head rept accuracy
Depth cased; 504 ft 504 Cype: Stee , Diam. in 2
po(C) (F) (G) (H) (0) (F) (S) (T) (W) (X) (A)  Finish: porous gravel w. gravel w. horiz. open parf., screen, sd. pt., shored, open
Method (A) (B) (C) (D) (H) (J) (P) (R) (T) (V) (W) (B) Other Drilled: air bored, cable, dug, bored, cable, dug, rot., percussion, rotary, wash, other other wash, other
Drilled: 8-/-72 - 9:7:2 Pump intake setting:
Briller: Keys Well Co. ST. Paul
Lift (A) (B) (C) (J) multiple, multiple, multiple, politiple, poli
Power LP Trans. or (type): diesel, elec. gas, gasoline, hand, gas, wind; H.P.
Descrip. HT Center pressure gauge 4.45 (Chove ) sp. Alt. HP
Alt. LSD: 8 1 5 Accuracy: (source)
Lavel +102.05 ft below MP; Ft below LSD + 1 0 2 Accuracy:
Date 10-5-72 53 0 7 2 35 Yield.   Spe   Hethod determined
Drawdown: ft Accuracy: Pumping period hra
OUALITY OF WATER DATA: Iron Sulface Chloride Hard.
Drawdown:ft

# Wall No. 161, 49, 13 bcd1

	Tatitude-los	ngitude			
HYDROGEOLOGIC CARD		di :	• •	4	• •
SAME AS ON MASTEE CARD Physiographic Province:		Ī	2 500010	n:	
- B Prainage		3 0 W	besin:	· ,	
(D) (C) (E)	(B) (B)	(E) (L)		* 1 .	المودا حبيب
Topo of depression, stream channel, dunes,	list, billtop,	sink, swamp,		<b>.</b>	•
offsbore, pediment, hillside, terr	race, padulating	(V) , valley flat			;75
AQUIFER Ordovician Middl	e Ø2	1. Winn	pea		
Lithology: Sandstone		Marino	er, formation	E	_ <del> </del>
Length of	V 0r18		Thicks	<u> </u>	38_ft
35 17 well open to: 10 7	_" <u>[110</u>	Depth to top of:	<u>357</u>	ft [	<u>3 5 7 </u>
AQUIFER: system series	L_i		r, formation,		
Lithology:	Origi		Aquife Thickne		
Length of		Depth to	30	<u></u>	ft
Intervale Screened: 504-514	ft [	top of:		ft	57 59
Screened: 304-314		1	<del></del>		
consolidated rock: 25 ft 60.	215	Source of data:	· · · · · · · · · · · · · · · · · · ·		"C
Depth to basement: 515 ft	5 1 5	Source of data:			"C
Surficial Clay		iltration racteristics:			<i>n</i> 5
Coefficient Trans: gpd/ft		Coefficient			
Coefficient	73 75	Storage:		L,	الدور سلسساني
	: cap:	gpoc/ft; Numb	er of geologi	c cards:	
• • •			<del></del>		-
-					-
e e	•	•.		<del> </del> -	
	· =*		_ ;·:		_
	•		<b></b>	<del> </del>	
			, · [		·
*)			_		
			_ \	<u> </u>	ا لبنا
		<u> </u>		_=\	
	••			1	]
			-		1
` <b>.</b>		Maraja aujori.	77.77	· - · · ·	• -
					_
•	•••	Ţ,			· · · ·
· · ·					
				. • • •	
<del>-</del> · · · · · · · · · · · · · · · · · · ·					
• • • • • • •	· , · . <del></del>	<del>-</del> -			
	* ***			<b></b>	
					1

223 of 5" csq cemented in 20 sacks cemen
504' of 2" galvinized pipe 10' screen #30 slott from 504'-514'
10' screen #30 slott from 504-514'
514' total of 2"
514-529' open hole in greenstone filled with (2) 5 gal buckets of
filled with (2) 5 gal buckets of
gravel
<u> </u>
405'- 514' Gravel packed with #30 filter
405'- 514' Gravel packed with #30 filter Sand ( Eau Claire).
405' - to surface Cemented between 5" & 2"casing
with 35 sacks of cement.
•

. **.** 

HALLOCK TEST HOLE SW1/4 NW 1/4 SEC. 13 T. 161 N., R. 49 W.

The first stratigraphic test hole of the Northwestern Minnesota drilling program was begun July 23, 1972, and was drilled to a total depth of 529 feet. It was completed on August 1, 1972. Two-inch galvanized tubing will be run in this test hole and it will be developed as an observation well for the U.S. Geological Survey.

The lithological log for the well follows:

Pleistocene glacial sediments (0-215 ft., 215 ft. thick)

0-62 ft. Dark gray lacustrine clay

62-215 ft. Gray, clayey glacial till with minor sand and numerous pebbles that are predominantly granite and limestone

Hallock red beds (215-357 ft., 142 ft. thick)

215-223 ft. Soft, light gray claystone grading down into red brown claystone

Five inch casing was set at 223 ft. with 20 sacks of cement
223-247 ft. Soft red brown to light gray claystone with minor
medium to dark gray claystone

Core 247-262 ft. (79% recovery)

3 ft. 4 in. to 3 ft. 5 in. of dark to medium gray, fissile shale 3 ft. 11 in. of interbedded sandstone and shale. Sandstone is dense, fine to medium grained, quartzitic, with dense carbonate cement. Shale is medium gray, sandy and fissile .

4 ft. 7 in. of light gray, chalky, vuggy limestone

Core 262-273 1/2 ft. (17.4% recovery)

4 1/2 in. of white earthy limestone

1 ft. 3 1/2 in. of light red brown to light green gray mottled claystone

4 in. of white earthy limestone

Core 273 1/2-285 1/2 ft. (58.4% recovery)

Material very soft and broke up in the core barrel.

5 ft. 6 in. to 6 ft. of green gray claystone with minor gray cher

1 ft. of red brown claystone with gray chert

Resumed drilling because of poor core recovery

285-291 ft. Medium gray claystone

291-357 ft, Red brown claystone

Winnipeg Formation (357-515 ft., 158 ft. thick)

357-360 ft. Light gray, fine to medium grained, quartz sandston with interbedded green gray claystone

Core 360-377 ft. (35.3% recovery)

5 ft. 8 in. of soft, red brown claystone

4 in. of light gray, fine to medium grained, quartz sandstone Red brown claystone may be material which caved to bottom of hole and squeezed into core barrel.

Core 377-382 ft. (8% recovery)

4-5 in. of light gray, fine to medium grained, quartz sandstone Resumed drilling

382-410 ft. Light gray, very friable, fine to medium grained, quartz sandstone

410-500 ft. Soft gray green and varigated claystone. Varigate glaystone is light green, maroon and yellow brown

in color. Sand stringers in claystone noted in basal part of interval, especially in 470-475 ft. and 490-500 ft. intervals

500-510 ft. Soft gray green claystone with stringers of medium to very coarse sandstone. Sandstone is mostly quar with minor jasper and white quartzitic siltstone grains. Minor amounts of sandstone cemented with dense calcite cement

510-515 ft. Blue gray, very plastic clay. (Possibly weathered zone at top of greenstone)

Precambrian basement rock (515-529 ft., 14 ft. drilled)

515-520 ft.. Greenstone


Core 520-529 ft. (94.4% recovery)


8 ft. 6 in. of greenstone which possesses bedding that is inclined about 50°. Rock is a tuffaceous sandstone. It contains numerous very thin quartz veins. No sulfides were observed.

No gypsum was seen in the Hallock red bed sequence. Paleontologic analysis will indicate whether or not these red beds are the same age as those containing gypsum in Manitoba.

Further petrographic analysis will be made of the cores from the Hallock red bed sequence and the Precambrian greenstone.

Coring was not attempted for much of the Hallock red bed and Winnipeg sandstone and shale sequence because the formations were very soft and sticky and washed away or plugged the core barrel when coring was attempted.





# OBWELL UNIQUE NUMBER RECONCILIATION CWI(p1)

WELL NO.	: 35001				
VI IXFM1:	PRINCIPAL	DATA 1			
215966 1.no.	35 CO	1 FORM			
161 DWNSHIP 215 LEV MET ELEVATION	_		CCTION METHOD LOCATION 5.29 LOCATION 5.14 1972 DEPTH YYYY PED DRILLED COMPL	METH  8 1 <u>OF</u> MM DD USE  ETED	OD STATUS
I					
	PRINCIPAL D 35 CO		DRILLER (OR DATA SOUR	======= CE)	<b></b>
USGS HALLO	CK		LOCAL IDENT.	LOCAL	ID TYPE
NER/CONT	ACT NAME	 			
_	PRINCIPAL D			=========	=======================================
JN.NO.	<b>35</b> CO	3 FORM	2 50 DIAM DEPT CASING INFO	4 GROUT	
ST. DE	IR. TYPE SOURCE	DATE ABANDO	? SEALED CO	DE PROPERTY	
INOWIN QUIFER	DEPTH TO BEDROCK	FIRST BEDROCK	OWIN OWIN TOP BOTTOM OPEN HOLE UNITS	NUMBER PERMIT	TYPE
	ROTECTION AR	EA:	DNR PA-NO.	<b>:</b>	

N MBER STREET NO.	FORM  /NAME ROUTE NAME			ROAD IDENTIFIER	DIRECTION
NMBER STREET NO. OR F	FORM  /NAME ROUTE NAME  ZIP				DIRECTION
NMBER STREET NO. OR F	ZIP				DIRECTION
OR F	ZIP				DIRECTION
USER DEF.1(A/N):	USER D				
USER DEF.1(A/N):	HSER D				
		EF.2(I):			-======================================
CI IXFM7: REMARKS	=======================================	<b></b>			
■ 35	7				
35 U.NO. CO	FORM				
C SED: 5", 0-223' AM	ND 2", 0-504'.	SCREENED:	504-514'.		
REMARKS /xutim SE	nirst fairwound				

BWELL NO.: 35001

WI/WL WLF	M1: PRINC	CIPAL DATA					=====	====	<b>22222</b>
215%6 N.NO.	35	1							
161 OWNSHIP 529									
514 PETH RILLED	BEDROCK ELEVATO	FIRS	OW ST AQ ROCK	UIFER	OWIN TOP OPEN	OWIN BOTTOM HOLE UNIT			
OURCE EOLOGIC IN	NTERPRETA	TION							
WI/WL WLFN				<del>-</del>		<del></del>	- <b></b>		
IN.NO.	<b>35</b> CO	2 FORM	DRILL	ING: M	ETHOD:	M HA FLA	uiD: _		_
ASING: MAT	TERIAL: 8	јоін	ING:	то	P: <u>4/</u>	_ DRIVE SE	HORE:		
ASING 1:	sin.	FROM:	О то	: 223	ft.	OPEN HOLE	1: i	in. 5	ro:
ASING 2:	$\frac{\lambda}{\lambda}$ in.	FROM:	<u>O</u> TO	: 504	ft.	OPEN HOLE 2	2: i	in. 5	ro:
						OPEN HOLE	3: i	in. 7	ro:
	_ : ADDI	TIONAL CAS	ING INFO.		:CASI	NG TYPE			
WI/WL WLFM	3: SCRE	EN.			- <del></del>				
N.NO.	<b>35</b> CO	3 FORM	SCREEN	PRESENT	r: <u>/</u>	FROM: OPEN HOI		TO:	REENED
AKE:				TYPI	S:	_ DIAM:	2		
SLOT/GAU SCREEN 1	ZE: 30	LENGI	н: _/О	TOP:	Soy TING	BOTTOM:	<u>5</u> K <u>y</u>		
SLOT/GAU SCREEN 2		LENGT		SET	TING	BOTTOM:			


CWI/WL(p2) ELL NO.: 35001 WL WLFM4: PUMPAGE TEST STATIC WATER LEVEL: 102.05 (a base quant)
DATE DATE TESTED: 72 /0 5 rist 1: LEVEL: \_\_\_\_ HOURS: \_\_\_\_ GPM: \_\_\_\_ TEST 2: LEVEL: HOURS: GPM: \_\_\_\_ HOURS: GPM: PEST 3: LEVEL: \_\_\_\_ DELLER'S NAME: CWI/WL WLFM5: COMPLETION/GROUT 35 5 UN.NO. CO FORM PTLESS ADAPTOR: MAKE: \_\_\_\_\_ MODEL: \_\_\_\_\_ BASEMENT OFFSET: \_\_\_ >/= 1ft. ABOVE GRND.: \_\_ PLASTIC CASING PROJECT.: \_\_\_ A05 GROUT 1: TYPE: G FROM: O TO: 564 AMOUNT: \_\_\_ UNITS: \_\_\_ GOUT 2: TYPE: \_\_\_ FROM: \_\_\_\_ TO: \_\_\_ AMOUNT: \_\_\_\_ UNITS: TO: \_\_\_\_ GROUT 3: TYPE: \_\_\_ FROM: \_\_\_ AMOUNT: \_\_\_\_\_\_\_\_\_\_\_\_\_ /WL WLFM6: PUMP. TO FORM PUMP INSTALLED?: 1 DATE: NO. MAKE: \_\_\_\_ MODEL:

H.P.: \_\_\_\_\_ VOLTS: \_\_\_\_ LENGTH: \_\_\_\_ MATERIAL: \_\_\_\_\_
DROP PIPE

PUMP TYPE:

#### APPENDIX G

#### LIST OF ADDRESSES





#### ENVIRONMENTAL SERVICES, Limited

1550 HUBBARD

BATAVIA, IL 60510

(708) 879-3006

FAX (708) 879-3014

June 19, 1996

Mr. Hank Noel City of Hallock P.O Box 336 Hallock, MN 56728

RE: List of addresses of city water customers

Dear Mr. Noel:

The purpose of this letter is to follow up the telephone conversation I had with you on June 17, 1996, regarding the city water customers in Hallock.

Our office is in the process of conducting a remedial investigation at a leaking underground storage site in Hallock. The investigation usually entails advancing soil borings and installing monitoring wells in order to collect and analyze soil and groundwater samples to characterize the extent of the release from the tank.

A report on the investigation is then submitted to the Minnesota Pollution Control Agency (MPCA). However, due to the extent of overhead and underground utilities, a subsurface investigation was not able to be conducted at the site. Therefore, it is necessary for our office to gather as much information as possible concerning the nature of the groundwater in the vicinity of Hallock.

Section 8 of the Remedial Investigation Report concerns well receptor information. The purpose of this section is to determine the risk imposed to private drinking water wells, municipal and industrial wells. In this section of the report, the MPCA requests "confirmation of status of water supply from the city utility billing department." I have enclosed a copy of Section 8 and the corresponding Appendix on which I have highlighted the specific request for your reference

96-6176

## AIRES

Mr. Hank Noel June 19, 1996 Page 2

I contacted the MPCA on the afternoon of Friday, June 14, 1996, requesting that they state exactly what is needed to fulfill the requirement of Section 8 in the report. It was explained to me that a list of the addresses of all residences, businesses, etc. that employ city water is required. Therefore, I am requesting from you a list of all addresses where municipal water is in use.

Additionally, pursuant to Section 8.4, enclosed, please indicate if there are any plans for groundwater development in the city of Hallock If so, please indicate the location of the groundwater development.

If you have any further questions, please feel free to contact me. Thank you.

Sincerely,

Elizabeth Rachman Hydrogeologist

EAR<sup>·</sup>ra Enclosures

## Section 8: Well Receptor Information/Assessment

Include in the appendices of this report: 1) a list of addresses within 500 feet from the edge of the plume and confirmation of status of water supply from the city utility billing department; 2) well logs; and 3) map showing ½ mile radius, 500 foot radius, water supply wells, other potential petroleum sources, and addresses for properties within 500 feet.

Table 13.

Complete the following table for all water supply wells located within 500 feet of the edge of the plume and any municipal or industrial wells found within  $\frac{1}{2}$  mile.

Unique Well #	Ground Elevation	Total Depth (ft)	Base of Casing (ft)	Static Elevation	Aquifer	Use	Owner	Distance & Direction from site
· · ·								
						ļ <u> </u>		
			<u> </u>					
		ļ	ļ		ļ			
	ļ <u>.                                    </u>		<u> </u>		<u> </u>	-		<del> </del>
		<del> </del>				<del></del>		
		<u> </u>	<del> </del> -		<del> </del>	<del>                                     </del>		
		-	<del></del>	<del> </del>	<u> </u>	-		
	<del> </del> -					┨		
	<del> </del>		<del>                                     </del>		-	<del>  -</del>		
	<del> </del> -	+	<del>                                     </del>		<del> </del>	<del>                                     </del>	-	
		<del>                                     </del>	1	<del></del>	<del>                                     </del>	1		

Notes:

8.1 Is municipal water available in the area?

YES NO

8.2 Were all property owners within 500 feet of the nearest edge of the contaminant plume successfully contacted to determine if water wells are present? If No, please explain.

YES NO

8.3 Discuss the results of the ground water receptor survey and any analytical results from sampling conducted at nearby water wells. Comment on the risks to water supply wells identified within 500 feet from the edge of the plume as well as the risk posed by or to any municipal or industrial wells found within ½ mile. Specifically indicate whether water supply wells identified utilize the impacted aquifer. (Note: an impacted aquifer separated from another aquifer by a clay lens is not considered a separate aquifer.)

8.4 Are there any plans for groundwater development in the impacted aquifer within one half mile of the site, or one mile down gradient of the site if the aquifer is fractured? Please give the name, title and phone number of the person that was contacted for this information.

NO

	Phone	
Section 9: Surface Water Risk Assessmen	it	
9.1 Are there any surface waters or wetlands located withi	n ¼ mile of the site?	YES NO
If YES, indicate its name:		
9.2 If surface water is present downgradient of the site, is gradient soil boring or monitoring well located between surface water?		YES NO N/A
If NO, we assume that contamination discharges to the following information:	surface water. Therefore	re, complete
	surface water. Therefore	re, complete
the following information:	surface water. Therefore	re, complete
the following information:  Name of receiving water:		re, complete
the following information:  Name of receiving water:  Plume width, (W):	feet	
Name of receiving water:  Plume width, (W):  Plume thickness, (H):	feet feet	ay/ft²

## Section 10: Vapor Risk Assessment/Survey


10.1 Is there a history of vapor impacts in the vicinity of the site?

YES NO

If YES, describe:

## **Section 14: Appendices**

Indicate attached appendices. Excavation Report Worksheet for Petroleum Release Sites. Appendix A Laboratory analytical reports for soil and ground water. Appendix B Methodologies and procedures, including field screening of soil, other field Appendix C analyses, soil boring, soil sampling, well installation, and water sampling. Geologic logs for each well or boring using attached template. Appendix D Well construction diagrams and copies of the Minnesota Department of Appendix E Health Well Record using attached template. Copies of water supply well logs with legible unique numbers. Appendix F A list of addresses within 500 feet from the edge of the plume and Appendix G confirmation of status of water supply from the city utility billing department.



0025 FARMERS DIL COMPANY		PO BOX 198	KENNEDY, MN 56733
0030 PEARSON AUTO	914 S ATLANTIC	PO BOX 425	HALLOCK, MN 56728
CO35 H E. EVERSON	906 S ATLANTIC AVE	PO BOX 820	HALLOCK, MN 56728
0036 JANSEN MACHINE	EILEEN R JANSEN	ROUTE 1 80X 68	HALLOCK, MN_56728
0040 VALLEY VIEW MOTEL	808 S ATLANTIC	PO BOX 787	HALLOCK, MN 56728
0041 VALLEY VIEW MOTEL ISLAN	D UNIT 808 S ATLANTIC	PO BOX 787	HALLOCK, MN 56728
0045 <u>S</u> alon 75	728 S ATLANTIC	PO BOX 25	HALLOCK, MM56728
0050 GATEWAY MOTEL	702 S ATLANTIC	PO BOX 403	HALLOCK, MN 56728
0055 VALLEY VIEW MOTEL TRAILE	ER #1 % BOB CLIMER	PO BOX 787	HALLOCK, MN 56728
0067 VALLEY VIEW MOTEL TRAILE	R \$3 % BOB CLIMER	PO BOX 787	HALLOCK, MN 56728
0070 VALLEY VIEW MOTEL TRAILE	R #5 % BOB CLIMER	PO BCX 787	HALLOCK, MN 56728
0075 VALLEY VIEW MOTEL TRAILE	R #6 % BOB CLIMER	PO 80X 787	HALLOCK, MN 56728
0080 P K.M BUILDING	601 S ATLANTIC		WARREN, MN 56762
0085 OTTER TAIL WAREHOUSE	546 S ATLANTIC	PO 8GX 850	HALLOCK, MN 56728
0090 FAMILY RESTAURANT	% KELLY LAVATY	PO BOX 46	HUMBOLDT, MN 56731
0095 JOHNSON STANDARD	502 S ATLANTIC	PO 80X 907	HALLOCK, MN 56728
0105 NORTHERN PLAINS AGENCY	442 S ATLANTIC	PO BOX 844	HALLOCK, MN 56728

,-	11			
ACCT #	ACCOUNT NAME	ADDRESS #1	ADDRESS #2	CITY, STATE & ZIP C
0110	HALLOCK EAGLES CLUB	418 S ATLANTIC	PO BOX 936	HALLOCK, MN 56728
0116	NORTHERN AIR	406 S ATLANTIC	PO BOX 302	HALLOCK, MN 56728
0120	CAMPBELL'S LIQUOR STORE	350 S ATLANTIC	PO BOX 805	HALLOCK, MN 56728
0125	HALLOCK PLUMBING AND MEATING	25 4TH STREET SE	PO BOX 785	HALLOCK, MN 56728
0130	THOMPSON PERFORMANCE	_ 336_S ATLANTIC AVE	PO BOX 132	HALLOCK, MN 56728
0135			PO BOX 310	HALLOCK, MN 56728
0140	MINI MALL	290 S ATLANTIC	JOE 80UVETTE	HALLOCK, MN 56728
0145	STERLING INC	290 S ATLANTIC	PC BOX 40	HALLOCK, MN 56728
	WIESE, RANDY	234 S ATLANTIC		HALLOCK, MN 56728
0170	GULLANDER HARDWARE	224 S ATLANTIC	PO BOX 937	HALLOCK, MN 56728
0180	JOHNSON DIL	146 S ATLANTIC	20 BOX 907	HALLOCK, MN 56728
0194	EDS ELECTRONICS	130 S ATLANTIC	PG BOX 129	HALLOCK, MN 56728
0200	BAKKEN BOOTS	103 N ATLANTIC	PG BOX 482	HALLOCK, MN 56728
0210	CENEX OF HALLOCK\DRAYTON	16 S ATLANTIC	PO BOX 549	HALLOCK, MN 56728
0215	RYDEN DEVELOPMENT	102 E BROADWAY	PO BOX 11	HALLOCK, MN 56728
0225	FIRE HALL	110 E BROADWAY		HALLOCK, MN 56728
0230	U S. POST OFFICE	105 S BIRCH AVE	PO BOX 9998	HALLOCK, MN 56728
0234	AMERICAN FEDERAL BANK	157 2ND STREET SE	PO BOX 189	HALLOCK, MN 56728
0245	GULLANDER APPLIANCES	121 2ND STREET SE	PC BOX 937	HALLOCK, MN 56728
0250	CARRIERE, DAN RENTAL	131 2ND STREET SE	PO 80X 820	HALLOCK, MN 56728
0255	SUZANNES BY VAL	117 2ND STREET SE	PO 80X 367	HALLOCK, MN 56728
0256	SUZANNES BY VAL-METER #2	117 2ND ST SE	°0 BOX 367	HALLOCK, MN 56728
0260	STATE FARM INSURANCE	% 808 CARLSON	₽0 BOX 157	KARLSTAD, MN 5673
0265	LUTHERAN BROTHERHOOD	23 2ND STREET SE	PO BOX 486	HALLOCK, MN 56728
0270	FARMERS MUTUAL INSURANCE	21 2ND STREET SE	PO BOX 695	HALLOCK, MN 56728
0275	GILLIE JEWELRY	28 2ND STREET SE	PO 80X 490	HALLOCK, MN 56728
0285	LUNDBOHM, JACK D C	112 2ND STREET SE	PD 80X 576	HALLOCK, MN 56728

08/	01/96		A ACCOUNT FIGURE	
ACCT #	ACCOUNT NAME	ADDRESS #1	ADDRESS #2	CITY, STATE & ZIP
0290	MCALLEN AND RUTZ OPT CLINIC		PC 80X 910	HALLOCK, MN 56728
0295	AMERICAN FAMILY INSURANCE	118 2ND STREET SE	90 80X 95	HALLOCK, MN 56728
0300	MARGIE'S CAFE	128 2ND STREET SE	PO BOX 35	HALLOCK, MN 56728
0305	C AND C LAUNDRY	146 2ND STREET SE	PO BOX 434	HALLOCK, MN 56728
0316	GTE	-	PO BOX 152127	IRVING, TX 75015
0325	KITTSON COUNTY ENTERPRISE	109 3RD STREET SE	PG 80X 730	HALLOCK, MN 56728
0330	C AND M FORD BODY SHOP	123 3RD STREET SE	106-630	HALLOCK, MN 56728
0336	ÇIT <u>Y Ha</u> ll	<u>163 3RD STREET</u> SE	PO_BOX_ <u>33</u> 6	HALLOCK, MN 56728
0340	CRANE JOHNSON LUMBER	172 3RD STREET SE	PO BOX 250	HALLOCK, MN 56728
0355	GRACE LUTHERAN RENTAL	107 4TH STREET SE	PO BOX 489	HALLOCK, MN 56728
0360	GRACE LUTHERAN CHURCH	321 Ş_BIRCH AVE	PO BOX 489	HALLOCK, MN 56728
0365	GUSTAFSON, LU	178 4TH STREET SE	209-242	HALLOCK, MN 56728
0375	CHRISTENSEN, VERA Y	136 4TH STREET SE	PC BOX 249	HALLOCK, MN 56728
0380	BEDARD, DWIGHT	120 4TH STREET SE	PO BOX 862	HALLOCK, MN 56729
0384	STEEN, HELMER	110 4TH STREET SE	PO BOX 63	HALLOCK, MN 5672
0394	HARTWIG AIRCRAFT	WINNIPEG ST ANDREWS	512 AIRLINE ROAD	WINNIPEG RIA 3P3,
0400	SWAN, DOROTHY	107 5TH STREET SE	FO BOX 42	HALLOCK, MN 56728
0411	CAMACHO, MACARIO AND TAMAMI	125 5TH STREET SE	GEN DELIVERY	HALLOCK, MN 5672
0415	ST PATRICK'S CHURCH	170 STH STREET SE	PO BOX 519	HALLOCK, MN 56728
0420	SOLI, DALE	108 6TH STREET SE	PO 30X 462	HALLOCK, MN 5672
0426	REESE, DELORES	143 6TH STREET SE	105-531	HALLOCK, MN 5672
0430	NYEGAARD, CURTIS	167 6TH STREET SE	PO BOX 434	HALLOCK, MN 5672
2005	ANDERSON, KATHY	110 6TH STREET SE	PO BOX 213	HALLOCK, MN 5672
2010	BERGMAN, JIM	142 6TH STREET SE	PO BOX 763	HALLOCK, MN 5672
2015	STEEN, MINORA	166 6TH STREET SE	PO BOX 142	HALLOCK, MN 5672
2020	KLEGSTAD, MICHELLS	163 7TH STREET S	PO BOX 475	HALLOCK, MN 5672
2025	ANDERSON, DAVID R.	139 7TH STREET SE	PO 80X 701	HALLOCK, MN 5672

ACCT #	ACCOUNT NAME	ADDRESS #1	4DDRESS #2	CITY, STATE & ZIP (
2030	OLSON, GREG	109 7TH STREET SE	PO BOX 383	HALLOCK, MN 56728
2034	JACKSON, DONNA	110 S 7TH STREET	PO BOX 684	HALLOCK, MN 56728
2035	JANSEN, RANDALL	EILEEN R JANSEN	ROUTE 1 BOX 68	HALLOCK, MN 56728
2040	ENGLUND, LARI-ANN	703 S BIRCH AVE	PO BOX 441	HALLOCK, MN 56728
2045	JOHNSON, MIKE	801 S BIRCH AVE	PO BOX 126	HALLOCK, MM 56728
2050	FERGUSON, BOB	805 S BIRCH AVE	PO BOX 6	HALLOCK, MN 56728
2051	ERYDEN, MARJORIE	711 S BIRCH AVE	PO 80X 711	HALLOCK, MN 56728
2055	COSTIN 8 PLEX	809_BIRCH_AVE	_ PO BOX 658	HALLOCK, MN 56728
2060	JOHNSON, MORRIS	901 S BIRCH AVE	PO 80X 473	HALLOCK, MN 56728
2067	CHAPUT, DAVID	909 S BIRCH AVE	PO BOX 58	HALLOCK, MN 56728
2080	HAMILTON, DONNA	921 S BIRCH AVE	PO BOX 184	HALLOCK, MN 56728
2085	HECKMAN, TODD	925 S BIRCH AVE	PO BOX 656	HALLOCK, MX 56728
2090	WILSON, ORVILLE	1021 S BIRCH AVE	PO BOX 67	HALLOCK, MN 56728
2095	CARLSON, EDWIN	1027 S BIRCH AVE	PO BOX 284	HALLOCK, MN 56728
2100	TRI, JIM	1029 S BIRCH AVE	PO BOX 97	HALLOCK, MR 56728
2105	PEARSON, PERRY	1033 S BIRCH AVE	PO BOX 591	HALLOCK, MN 56728
2110	TURGEON, KELLY	1037 S BIRCH AVE	PO BOX 311	HALLOCK, MN 56728
2121	JOHNSON, ELDEN	1040 SE ELM AVE	PO BOX 804	HALLOCK, MN 56728
2122	FAILING, RICK	1030 S ELM AVE	PO BOX 566	HALLOCK, MN 56728
2123	BERGERON, DEAN	1022 SE EL™ AVE	PO BOX 302	HALLOCK, MN 56728
2124	EUKEL, KEN	1018 S ELM AVE	BOX 501	HALLOCK, MN 56728
2125	BEDARD, WALTER	203 11TH STREET S	PO BOX 281	HALLOCK, MN 56728
2126	OLSONAWSKI, JOHANNA	1032 SE ELM AVE	PO BOX 313	HALLOCK, MN 56728
2127	SDBERASKI, RODNEY	1002 S ELM AVE	PO BOX 744	HALLOCK, MN 56728
2128	INGEMAN, BRUCE	1019 S FOREST AVE	PO 30X 272	HALLOCK, MN 56728
2129	ENGLUND, JEFF	1037 S FOREST AVE	PO BOX 441	HALLOCK, MN 56728
2130	SYLVESTER, KALVIN	201 11TH AVE S	PO BOX 242	HALLOCK, MN 56728

ACCT # A	CCOUNT NAME A	DDRESS #1	ADDRESS #2	CITY, STATE & ZIP
2135 CA	RRIERE, CONNIE	1026 S BIRCH AVE	PO BOX 773	HALLOCK, MN 56728
2140 TU	IRESON, ALFRED	1020 S BIRCH AVE	224-696	HALLOCK, MN 56728
2145 KN	IUDSON, CHRISTI	1022 S BIRCH AVE	PO BOX 204	HALLOCK, MN 56728
2150 KI	TTSON MEMORIAL HOSPITAL	1010 S BIRCH AVE	METER NO 1	HALLOCK, MN 56728
2155 KI	ITTSON MEMORIAL HOSPITAL	1010 S.BIRCH AVE	METER NO 2	HALLOCK, MN 56728
2157 KI	ITTSON MEMORIAL HOSPITAL	1010 S BIRCH AVE	METER NO 3	HALLOCK, MN 56728
2158 KI	ITTSON MEMORIAL NURSING HOME	1010 S BIRCH AVE	PO BOX 700	HALLOCK, MN 56728
2159KI	IIISON_MEMORIAL_NURSING_HOME	_1010_S_BIRCH_AVE	METER_NO 2	HALLOCK, MN _56728
2160 UN	NRAU, JOHN	901 S ELM AVE	PO BOX 172	HALLOCK, MN 56728
2161 HA	- ANSON, MARV	1004 S FOREST AVE	PO BOX 249	HALLOCK, MN 56728
2165 MC	C GOVERN, WILLIS	905 S ELM_AVE	215-626	HALLOCK, MN _ 56728
2170 NE	ELSON, WALLACE	210 11TH STREET S	PO BOX 276	HALLOCK, MN 56728
2175 AS	SSEMBLY OF GOD CHURCH	1106 S BIRCH AVE	PO BOX 507	HALLOCK, MN 56728
2180 B	ERNSTROM, ROGER	202 11TH STREET SE	PO BOX 813	HALLOCK, MN 56728
2181 01	LSON, ROD	1021 S FOREST AVE	PO BOX 182	HALLOCK, MN 56728
2183 A	IPPERSPACH, DERALL	1017 S FOREST AVE	PO BOX 754	HALLOCK, MN 56728
2186 AI	NDERSON, PAM	507 9TH STREET SE	PO BOX 222	4ALLOCK, MN 5672€
2187 W	ARNER, KAREN	808 S BIRCH AVE	PO BOX 321	HALLOCK, MN 5672
2188 C	HARON, HARLAN	1001 S FOREST AVE	PO BOX 835	HALLOCK, MN 5672
2189 M	ORRISON, MIKE	1009 S FOREST AVE	PO BOX 459	HALLOCK, MN 5672
2190 K	OOP, GARY	802 S BIRCH AVE	PO BOX 363	HALLOCK, MN 5672
2195 K	ASPROWICZ, GREG	710 S BIRCH AVE	PO BOX 154	HALLOCK, MN 5672
2205 F	ILTERATION PLANT	211 7TH STREET SE	PO 80X 336	HALLOCK, MN 5672
2210 H	AGEN, TRISHA	218 6TH STREET SE	PO 80X 27	HALLOCK, MN 5672
2215 T	URESON, JIM	214 6TH STREET SE	PO BOX 81	HALLOCK, MN 5672
2220 G	GERSUCH, SCOTT	210 6TH STREET SE	PO BOX 274	HALLOCK, MN 5672
2225 A	ANDERSON, PAUL	204 6TH STREET SE	PO BOX 455	HALLOCK, MN 5672

08/	01/96	COSTUNE	( MCCOOM! LISTING	
ACCT #	ACCOUNT NAME	ADDRESS #1	ADDRESS #2	CITY, STATE & ZIP C
2226	HUNT, RAY	520 S BIRCH AVE		
2230	KEMP, HAROLD	514 S BIRCH AVE	co BOX 668	HALLOCK, MN 56728
2235	WOLLIN, MIKE	209 6TH STREET SE	PO BOX 611	HALLOCK, MN 56728
2240	NELSON, DENNIS	217 6TH STREET SE	277-376	HALLOCK, MN 56728
2245	BERG, TIM	221 5TH STREET SE	PO 80X 654	HALLOCK, MN 56728
2250	WALTERS, KENNETH	220 S CEDAR AVE	261-614	HALLOCK, MN 56728
2255	NORDLING, DONALD	505 S CEDAR AVE	PO BOX 604	HALLOCK, MN 56728
_ 2261_	BAKKEN, VI	214_5_TH _ST_ SE	PO BOX 722	RALLOCK, MN _56728
2265	LINDSTROM, CLARECE	210 5TH STREET SE	112-627	HALLOCK, MN 56728
2270	MC ENELLY, CRAIG	206 5TH STREET SE	PO BOX 702	HALLOCK, MN 56728
2275	GATHERIDGE, RUTH	204 5TH STREET SE	PO BOX 412	HALLOCK, MN 56728
2281	LOER, HERMAN	203 5TH STREET SE	PO BOX 82	HALLOCK, MN 56728
2285	MIKOLAJCZYK, GRACE	205 STH STREET SE	PO BOX 627	HALLOCK, MN 56728
2290	HOMSTAD, CHARLES	209 5TH STREET SE	PO BOX 791	HALLOCK, MN 56728
2295	MASLOSKI, JIM	215 5TH STREET SE	PO BOX 295	HALLOCK, MN 56728
2300	ANDERSON, KEITH	219 5TH STREET SE	PO BOX 880	HALLOCK, MN 56728
2310	_DAHLMAN, CAROL	218 4TH STREET SE	PO 80X 271	HALLOCK, MN 56728
2315	LOCKEN, MARTIN	214 4TH STREET SE	PO 80X 162	HALLOCK, MN 56728
2320	JOHNSON, INEZ	206 4TH STREET SE	PO BOX 446	HALLOCK, MN 56728
2325	LERDAHL, WANDA	202 4TH STREET SE	PO 30X 174	HALLOCK, M™ 56728
2330	LINDEGARD, RICK	410 S BIRCH AVE	PC BOX 353	HALLOCK, MN 56728
2335	FLOWER SHOP	326 S BIRCH AVE	PO 80X 355	HALLOCK, MN 56728
2340	KITTSON LOCKER PLANT	322 S BIRCH AVE	PO BOX 188	HALLOCK, MN 56728
2350	WILSON LANDSCAPING AND GRNHSE	209 4TH STREET SE	PO BOX 442	HALLOCK, MN 56728
2370	ERICKSON, ANNE	212 3RD STREET SE	PO BOX 512	HALLOCK, MN 56728
2375	ST JOHNS EPISCOPAL	218 3RD STREET SE	PO BOX 187	HALLOCK, MN 5672
2385	SORENSON, OREL	202 3RD STREET SE	PO BOX 492	HALLOCK, MN 56729

ACCT #	ACCOUNT NAME	ADDRESS #1	4DDRESS #2	CITY, STATE & ZIP
2390	BRINK, SOBOLIK, SEVERSON, MALM	207 S BIRCH AVE	PO BOX 790	HALLOCK, MN 56728
2393	DAHL HATTON MUIR & REESE LID	720 67H STREET SE	PO BOX 698	HALLOCK, MN 56728
2395	STANISLOSKI, TIM	205 3RD STREET SE	PO BOX 812	HALLOCK, MN 56728
2400	BERGH, JOHN	209 3RD STREET SE	PO BOX 263	HALLOCK, MN 56728
2405	OLSONAWSKI, CINDY	215 3RD STREET SE	PO BOX 194	HALLOCK, MN 56728
2410	HOMSTAD, RUTH	211 S CEDAR AVE	PO BOX 688	HALLOCK, MN 56728
2417	ANDERSON, VERN	207 S CEDAR AVE	PO BOX 64	HALLOCK, MN 56728
2420	ANDERSON, _VERN	222 2ND STREET SE	PO BOX 64	HALLOCK, MN 56728
2425	TAYLOR, SCOTT	218 2ND STREET SE	PO BOX 37	HALLOCK, MN 56728
2435	SJOSTRAND APTS	204 2ND STREET SE	PO BOX 357	HALLOCK, MN 56725
2445	NORTHWESTERN STATE BANK	203 2ND STREET SE	PO BOX 760	HALLOCK, MN 56720
2450	C AND M FORD	209 2ND STREET SE	106-630	HALLOCK, MN 56727
2455	OTTER TAIL POWER COMPANY	215 2ND STREET SE	PO BOX 850	HALLOCK, MN 5672
2460	HUGHES FUNERAL HOME	221 2ND STREET SE	PO BOX 905	HALLOCK, MN 5672
2465	MASONIC LODGE	104 S CEDAR AVE	PO BOX 52	HALLOCK, MN 5672
2470	KITTSON AUTO AND IMPL	15 N ATLANTIC	PO BOX 399	HALLOCK, MN 5672
2475	KITTSON AUTO	15 M ATLANTIC	PO BOX 399	HALLOCK, MN 5672
2480	FARMERS STORE	24 E BROADWAY AVE	PO BOX 69	HALLOCK, MN 5672
2490	HALLOCK AMBULANCE SERVICE	125 E BROADWAY	PO 80X 700	HALLOCK, MN 5672
3006	WHITE, JEFF	115 MAYPLACE	PO BOX 7	HALLOCK, MN 5672
3020	JOHNSON, EDMUND	203 E BROADWAY	PO BOX 777	HALLOCK, MN 5672
3035	SWANSON, MYRON	330 2ND STREET SE	PO BOX 113	HALLOCK, MN 5672
3040	HOWE, JEANINE	318 2ND STREET SE	PO BOX 582	HALLOCK, MN 5672
3045	FERTIG, DAVID	314 2ND STREET SE	PO 80X 341	HALLOCK, MN 5672
3050	KNUTSON, RUBY	310 2ND STREET SE	PO BOX 544	HALLOCK, MN 5672
3051	PEMBERTON, BILL	210 S CEDAR AVE	219-993	HALLOCK, MN 5677
3060	SATTERLUND, DICK	303 3RD STREET SE	PO BOX 343	HALLOCK, MN 5671

4407 B	ADDRINT HAME	ADDRESS #1	ADDRESS #2	CITY, STATE & ZIP C
	ACCOUNT NAME			HALLOCK, MN 56728
3065	BERG, EMMETT	315 3RD STREET SE		
3070	SHOCKLEY, TIM	321 3RD STREET SE		HALLOCK, MN 56728
3075	MALM, ROGER	323 3RD STREET SE	PO BOX 775	HALLOCK, MN 56728
3080	HAUBRICH, HAROLD	372 3RD STREET SE	PO 80X 538	HALLOCK, MN 56728
3085	SWANSON, JILL	415 3RD STREET SE	PO BOX 543	HALLOCK, MN 56728
3090	ANDERSON, JIM	421 3RD STREET SE	PO BOX 451	HALLOCK, MN 56728
3095	OLSON, ANDY	326 3RD STREET SE	PO BOX 161	HALLOCK, M№ 56728
3105	PETERSON, MIKE.	318_3RD_STREET_SE		_ HALLOCK, MN56728
3110	SNARE, KENNETH	314 3RD STREET SE	PO BOX 35	HALLOCK, MN 56728
3121	CRAIGMILE, JANELLE	310 3RD STREET SE	PO BOX 401	HALLOCK, MN 56728
_ 3127	BERGH, JAY	_310 S CEDAR AVE	PO 80X 26	HALLOCK, MN 56728
3130	THORSON, TERRY	305 4TH STREET SE	PO BOX 593	HALLOCK, MN 56728
3135	BOCKWITZ, AUDREY	315 4TH STREET SE	PO BOX 85	HALLOCK, MN 56728
3136	HERITAGE RESIDENCE	410 S CEDAR AVE	PO BOX 906	HALLOCK, MN 56728
3140	KITTSON CENTRAL ELEMENTARY	411 4TH STREET SE	PO BOX 670	HALLOCK, MN 56728
3149	MINSKE, BERNICE	401 4TH STREET SE	PO 80X 725	HALLOCK, MN 56728
3151	NOEL, HENRY	405 S ELM AVE	265-543	HALLOCK, MN 56728
3160	SUNBY, MEL	415 S ELM AVE	223-706	HALLOCK, MN 56728
3165	MISSION COVERANT CHURCH	421 S ELM AVE	PO BOX 417	HALLOCK, MN 56728
3170	KITTSON COUNTY COURTHOUSE	410 STH STREET SE	PO 80X 848	HALLOCK, MN 56728
3180	JOHNSON, TODO	604 S DOUGLAS AVE	PO BOX 294	HALLOCK, MN 56728
3185	JOHNSON, MYLES	610 S DOUGLAS AVE	₽0 BOX 157	HALLOCK, MN 56728
3190	KLEGSTAD, ERNIE	614 S DOUGLAS AVE	PO BOX 733	HALLOCK, MN 56729
3200	CERKOWNIAK, ANNIE	622 S DOUGLAS AVE	PO BOX 505	HALLOCK, MN 5672:
3205	KLEGSTAD, TOM	704 S DOUGLAS AVE	PO BOX 631	HALLOCK, MN 5672
3210	PETERSON, PAUL	714 S DOUGLAS AVE	PO BOX	HALLOCK, MN 5672
3215	HARTWIG AIRCRAFT	720 S DOUGLAS AVE	PO 80X 400	HALLOCK, MN 5672

00	101/70			
ACCT #	ACCOUNT NAME	ADDRESS #1	ADDRESS #2	CITY, STATE & ZIP
3224	KOOP, WILBUR	726 S DOUGLAS AVE	PO BOX 518	HALLOCK, MN 56728
3225	JOHNSON, GARY	412 7TH STREET SE	PO BOX 277	HALLOCK, MN 56728
3230	SOBERASKI, MARY	703 S ELM AVE	PO BOX 422	HALLOCK, MN 56728
3235	PEARSON, KRIS	709 S ELM AVE	PO BOX 444	HALLOCK, MN 56728
3240	BLOMQUIST, DANNY	715 S ELM AVE	PO BOX 124	HALLOCK, MN 56728
3245	HARMSEN, RITA	721 SOUTH ELM AVE		HALLOCK, MN 56728
3250	SWANSON, LEONARD	805 S ELM AVE	PO BOX 69	HALLOCK, MN 56728
3255	EASTON, JANINE	702.S ELM_AVE	PO_BOX 727	
3262	LANCTOT, THOMAS	710 SO ELM AVENUE	PO 80X 156	HALLOCK, MN 56728
3265	JOHNSON, CECIL	714 S ELM AVE	PO BOX 33	HALLOCK, MN 56728
3271	SOBOLIK, BRAD	804 S ELM AVE	PO 80X 233	HALLOCK, MN 56728
3275	REFF, JACK	805 S FOREST AVE	PO BOX 253	HALLOCK, MN 56728
3280	HOLMGREN, VENDELL	721 S FOREST AVE	PO 80X 580	HALLOCK, MN 56728
3285	PANTZER, KENNETH	711 S FOREST AVE	PO BOX 415	HALLOCK, MN 56728
3290	WILSON, DEAN	707 S FOREST AVE	PO 80X 924	HALLOCK, MN 56728
3291	CARLSON, DAVID	520 7TH STREET SE	PO 80X 488	HALLOCK, MN 56728
3295	LUND, JUNE	702 S FOREST AVE	PO BOX 906	HALLOCK, MN 56728
3300	CLOW, RAYMOND	710 S FOREST AVE	PO BOX 532	HALLOCK, MN 56728
3305	STANNAGE, SAM	720 S FOREST AVE	PO 80X 364	FALLOCK, MN 56728
3315	DUCKSTAD, JARED	816 87H STREET SE	PO 80X 143	HALLOCK, MN 5672;
3316	SMOLAK, RAY	618 8TH STREET S	PO 86X 686	HALLOCK, MN 5672
3320	ANDERSON, DORIS	715 S GROVE AVE	PO BCX 4	HALLOCK, MN 5672'
3325	DREWLOW, MARLIN	709 S GROVE AVE	PO 80X 895	HALLOCK, MN 5672
3330	NORDLING, DONNA	618 7TH ST SE	PO 80X 308	HALLOCK, MN 5672
3335	GATHERIDGE, ELIZABETH	702 7TH STREET SE	PO BOX 834	HALLOCK, MN 5672
3340	FORFANG, CURTIS	710 7TH STREET SE	PO BOX 232	HALLOCK, MN 5672
3345	OLSON, TIM	718 S GROVE AVE	PO BOX 310	HALLOCK, MN 5672

ACCT #	ACCOUNT NAME	ADDRESS #1	ADDRESS #2	CITY, STATE & ZIP C
3346	RENVILLE, LEONARD	710 8TH STREET S	PO BOX 2	HALLOCK, MN 56728
3350	GAETZ, DAN	837 8TH STREET S	PO BOX 484	HALLOCK, MN 56728
3355	WILLIAMS, ŁOWELL	716 7TH STREET SE	PO BOX 88	HALLOCK, MN 56728
3360	CARRIERE, DUANE	719 7TH STREET SE	PO BOX 460	HALLOCK, MN 56728
3361	CARRIERE, DUANE	719 7TH STREET SE	PO BOX 460	HALLOCK, MN 56728
3365	DOCKIN, ALFRED	714 6TH STREET SE	PO BOX 155	HALLOCK, MN 56728
3370	DAHL, CONRAD	720 6TH STREET SE	PO BOX 734	HALLOCK, MN 56728
3380	GARCIA, ESTEBAN.	722 6TH STREET SE	GEN DELIVERY	HALLOCK, MK 56728
3385	CLAY, PAUL	604 SOUTH GROVE AVE	PO BOX 595	HALLOCK, MN 56728
3390	NORDINE, KEN	610 S GROVE AVE	PO BOX 273	HALLOCK, MN 56728
3395	RYNNING, GLADYS	614 S GROVE AVE	221-647	HALLOCK, MN 56728
3405	LONG, DELORES	619 S GROVE AVE	PO BOX 158	HALLOCK, MN 56728
3410	GIERSZEWSKI, CHARLES	615 S GROVE AVE	PO 80× 672	HALLOCK, MN 56728
3420	HANSON, JOANN	601 S GROVE AVE	209-736	HALLOCK, MN 56728
3435	VISNESS, RON	614 S FOREST AVE	PO BOX 651	HALLOCK, MN 56728
3441	GUSTAFSON, TIM	624 FOREST AVE	PO BOX 937	HALLOCK, MN 56728
3445	PEARSON, MARK	521 7TH STREET SE	PO 80X 425	HALLOCK, MN 56728
3450	HANSON, CLARICE	517 7TH STREET SE	PO BOX 173	HALLOCK, MN 56728
3455	GLIDDEN, FRED JR	615 S FOREST AVE	PO 8GX 112	HALLOCK, MN 56728
3465	ANDERSON, BOB	607 S FOREST AVE	20 BOX 4	HALLOCK, MN 56728
3475	REESE, JEFF	504 6TH STREET SE	PO BOX 382	HALLOCK, MN 56728
3480	REESE, CHARLES	606 S ELM AVE	PO BOX 413	HALLOCK, MN 56728
3490	SORENSON, RUBY	614 S ELM AVE	230-332	HALLOCK, MN 56728
3500	TURNER, HAROLD	622 S ELM AVE	PO BOX 535	HALLOCK, MN 56728
4005	KLEIN, DAVE	617 S ELM AVE	P O BOX 339	HALLOCK, MN 56728
4010	OVEREND, PAT	615 S ELM AVE	PG BOX 835	HALLOCK, MN 56728
4020	GREENBERG, PAUL	503 ELM AVE	PO 80× 87	HALLOCK, MN 56729

		ADAREGE #1	ADDRESS #3	CITY STATE 9 775
ACCT #	ACCOUNT NAME	ADDRESS #1	ADDRESS #2	CITY, STATE & ZIP
4025	TUSOW, DALE	509 6TH STREET SE	PG BOX 358	HALLOCK, MN 56728
4035	SLUSAR, SCOTT	519 S FOREST AVE	PO 90X 398	HALLOCK, MN 56728
4040	HUNT, EARL	511 S FOREST AVE	PO BOX 542	HALLOCK, MN 56728
4045	TURESON, ELAINE	522 5TH STREET SE	PO 90X 81	HALLOCK, MN 56728
4060	WALLENBERG, WES	522 5TH STREET SE	PO BOX 712	HALLOCK, MN 56728
4065	NIELSEN, HARVEY	531 S ELM AVE	218-042	HALLOCK, MN 56728
4070	CAMPBELL, NEIL	416 S ELM AVE	PO BOX 805	HALLOCK, MN 56728
4075	LARSON, WALTER	410_S_ELM_AVE	PO BOX 244	HALLOCK, MN 56728
4080	DONNER, RICHARD	402 S ELM AVE	PO BOX 875	HALLOCK, MN 56728
4085	STENQUIST, JOHN	505 4TH STREET SE	PO BOX 12	HALLOCK, MN 56728
4090	BEDARD, PAT	320 S ELM AVE	PO BOX 762	HALLOCK, MN 56728
4091	BEDARD, PAT	314 S ELM AVENUE	PO BOX 762	HALLOCK, MN 56728
4100	ANDERSON, DON	514 3RD STREET SE	PO 80X 335	HALLOCK, MN 56728
4105	GUSTAFSON, CEDRIC	511 3RD STREET SE	PO BOX 481	HALLOCK, MN 56728
4115	RYDEN, DAVID	315 S FOREST AVE	22:-508	HALLOCK, MN 56728
4120	DAHLGREN, VERNE	323 S FOREST AVE	PO 80X 301	HALLOCK, MN 5672°
4125	HANSON, KEVIN	327 S FOREST AVE	PO 89X 103	HALLOCK, MN 56728
4130	OLSON, HELEN	516 4TH STREET SE	PO BOX 785	HALLOCK, MN 56728
4135	EGGERLING, KRISTIN	520 4TH ST SE	PO 80X 328	HALLOCK, MN 5672
4137	DUGUAY, KARI	413 S FOREST AVE	ନ୍ତ 80X 494	HALLOCK, MN 5672:
4138	NW MULTI COUNTY HRA 4	413 S FOREST AVE	PO BOX 1522	MENTOR, MN 56736
4145	HOLM, GARY	417 S FOREST AVE	PO BOX 175	HALLOCK, MN 5672
4146	BENGTSON, LEGNARD	521 STH STREET SE	201-793	HALLOCK, MN 5672
4150	YOUNGGREN, JOHN	422 S FOREST AVE	PO 80X 776	HALLOCK, MN 5672
4153	LANG, JERRY	510 S FOREST AVE	PO 60X 74	HALLOCK, MN 5672
4155	KLEGSTAD, ROBERT	514 S FOREST AVE	PO BOX 404	HALLOCK, MN 5672
4160	AHLGREN, HAZEL	515 S GROVE AVE	254-393	HALLOCK, MN 5672

ACCT #	ACCOUNT NAME	ADDRESS #1	ADDRESS #2	CITY, STATE & ZIP C
4165	WINGER, SUE	509 S GROVE AVE	PO BOX 613	HALLOCK, MN 56728
4172	OGOREK, TERRY	505 S GROVE AVE	PO BOX 224	HALLOCK, MN 56728
4175	STANNAGE, SAM	501 S GROVE AVE	PO BOX 364	HALLOCK, MN 56728
4180	TURNER, JOYCE	506 S GROVE AVE	PO BOX 693	HALLOCK, MN 56728
4185	WELESKI, SHANE	_510 S GROVE AVE	PO BOX 653	HALLOCK, MN 56728
4190	DANFORTH, STELLA	514 S GROVE AVE	PO BOX 700	HALLOCK, MN 5628
4195	OLSON, HARLEY	518 S GROVE AVE	PO BOX 214	HALLOCK, MN 56728
4200_	_PETERSON,_RICHARD	_ 514_S_GROVE_PLACE	PO BOX 111	HALLOCK, MN 56728
4205	VAGLE, JOHN	504 S GROVE PLACE	PO BOX 861	HALLOCK, MN 56728
4215	MINSKE, DARRIN	502 S GROVE PLACE	PO BOX 331	HALLOCK, MN 56728
4220	KRASKA, BRIAN	422 S GROVE AVE	PO BOX 394	HALLOCK, MN 56728
4225	YOUNGGREN, LARRY	710 4TH STREET SE	PO BOX 279	HALLOCK, MN 56728
4230	ANDERSON, RICHARD	411 S HOLLY AVE	PO 80X 95	HALLOCK, MN 56728
4235	JOHNSON, HARRIS	410 S HOLLY AVE	212-494	HALLOCK, MN 56728
4240	YOUNGGREN, DIANE	420 S HOLLY AVE	PO BOX 98	HALLOCK, MN 56728
4245	MATTSON, VINCENT	502 S HOLLY AVE	216-311	HALLOCK, MN 55728
4250	NORDINE, JOYCE	508 HOLLY AVE	PG BOX 322	HALLOCK, MN 56728
4255	BALDWIN, MIKE	510 S HOLLY AVE	PO BOX 687	HALLOCK, MN 56728
4259	MATTSON SHOP	VINCENT MATTSON	216-311	HALLOCK, MN 56728
4260	DAVIS, PAT	515 S HOLLY AVE	PO 80X 387	PALLOCK, MN 56728
4265	JOHNSON, JIM	513 S HOLLY AVE	PO 80X 126	HALLOCK, MN 56728
4270	BENGTSON, B MARVIN	509 S HOLLY AVE	PO 80X 351	HALLOCK, MN 56728
4275	BENGTSON, ART	503 S HOLLY AVE	PO BOX 696	HALLOCK, MN 56728
4280	ANDERSON, ROGER	417 S HOLLY AVE	PO BOX 125	HALLOCK, MN 56728
4285	OTTE, TOM	418 S GROVE AVE	PO BOX 104	HALLOCK, MN 56728
4290	KLEGSTAÐ, KEITH	414 S GROVE AVE	PO BOX 733	HALLOCK, MN 56728
4295	ERICKSOM, KELLY	706 4TH STREET SE	PO BOX 877	HALLOCK, MN 56729

08/	01/96	CUSTOMER A	CCOUNT LISTING	
ACCT #	ACCOUNT NAME		ADDRESS #2	CITY, STATE & ZIP
4310	ROSENGREN, KAY		PO 80X 177	HALLOCK, MN 56728
4315	CEDERHOLM, DONALD	405 S GROVE AVE	PO BOX 130	HALLOCK, MN 56728
4320	LINDGREN, WILBUR	603 5TH STREET SE	PO BOX 246	HALLOCK, MN 56728
4325	BACKLUND, FOLKE	420 S FOREST AVE	PO 80X 176	HALLOCK, MN 56728
4326	KEENAN, JASON	414 S FOREST AVE	PO 80X 235	HALLOCK, MN 56728
4330	GARIA, EMILIA	410 S FOREST AVE	PO BOX 922	HALLOCK, MN 56728
4335	HANE, JEFF	602 4TH ST SE	PO BOX 790	HALLOCK, MN 56728
4340	HANSON, DALE	606 4TH_STREET SE	PO 80X 531	HALLOCK, MN 56728
4345	DALZELL, DAN	328 S FOREST AVE	PO BOX 742	HALLOCK, MN 56728
4350	WALLER, TONI	314 S FOREST AVE	PO BOX 3	HALLOCK, MN 56728
4355	PEMBERTON, JEAN	616 2ND STREET SE	266-503	HALLOCK, MN 56728
4356	YASA HUS	640 2ND STREET SE	216-311	HALLOCK, MN 56728
4360	PASTIR, BRIAN	655 2ND STREET SE	PO BOX 771	HALLOCK, MN 56728
4365	KOSKIMIEMI, ERNEST B		1512 GARY AVENUE	DETROIT LAKES, MN
4375	KINKEAD, DENNIS	641 2ND STREET SE	PO BOX 597	HALLOCK, MN 56728
4380	TREUMER, DAVID	631 2ND STREET SE	PO 80X 116	HALLOCK, MN 56728
4390	HENNEN, KEN	619 2ND STREET SE	PO 80X 304	HALLOCK, MN 56728
4395	BRISSON, LIONEL	318 DOWLING AVE EAST	WINNIPEG MANITOBA	CANADA R2C3K7,
4400	HOLMQUIST, CLARICE	609 2ND STREET SE	PG BOX 802	HALLOCK, MN 56728
4405	COSTIN 4-PLEX	601 2ND STREET SE	PO BOX 658	HALLOCK, MN 5672
4406	ANDERSON, LAMAR	511 2ND STREET SE	PO BOX 923	HALLOCK, MN 5672
4410	ANDERSON, MARY ETTA	509 2ND STREET SE	PO BOX 935	HALLOCK, MN 5672
4420	LOSCH, KEN, REVEREND	505 3RD STREET SE	PO BOX 489	HALLOCK, MN 5672
4425	COSTIN, RUTH	521 E BROADWAY	PO BOX 658	HALLOCK, MN 5672
4430	COSTIN, KERRY	505 E BROADWAY	PO BOX 643	MALLOCK, MN 5672
4435	AMANN DAVE	502 2ND STREET SE	PO BOX 674	HALLOCK, MN 5672
4440	ABEL, ERMA	425 3RD STREET SE	PO BOX 814	HALLOCK, MN 5672

08,	/01/96	CUSTOMER	ACCOUNT LISTING	
ACCT #	ACCOUNT NAME	ADDRESS #1	ADDRESS #2	CITY, STATE & ZIP C
4445	C & M FORD	427 3RD STREET SE	106-630	HALLOCK, MN 56728
4450	KASPROWICI, SUSIE	422 E BROADWAY ST	PO 80X 54	HALLOCK, MN 56728
4455	HANSON, EVAN	418 E SROADWAY	PO BOX 14	HALLOCK, MN 56728
4460	HEDMAN, CLAYTON	431 E BRO≏DWAY	PO BOX 327	HALLOCK, MN 56728
4465	ESCHLER, DALE	421 5 BROADWAY	PO 80X 235	HALLOCK, MN 56728
4470	HANSON, HARRY D D S.	417 E BROADWAY	PO BOX 356	HALLOCK, MN 56728
4475	COLE, JOHN	407 E BROADWAY ST	PO BOX 673	HALLOCK, MN 56728
4481	RUTZ,_DUANE	341 E BROADWAY_ST	<u>PO</u> 80X 910	HALLOCK, MN _56728
4491	MELIN, GARY	331 E BROADWAY	PO BOX 520	HALLOCK, MN 56728
4495	SJOSTRAND, JIM	325 E BROADWAY	PC BOX 357	HALLOCK, MN 56728
4500	SJOSTRAND, JIM	319 E BROADWAY ST	PO BOX 357	HALLOCK, MN 56728
4505	OLSON, RON	25 SHORT AVE N	PO BOX 785	HALLOCK, MN 56728
4510	WISE, PAT	315 E BROADWAY ST	PO BOX 545	HALLOCK, MN 56728
4515	CAMERON, BOB	311 E BROADWAY	PO BOX 250	HALLOCK, MN 56728
4521	BENGTSON, NORMA	307 E BROADWAY	PO BOX 395	HALLOCK, MN 56728
4530	CARLSON, EARL T	40 N CEDAR AVE	PO BOX 131	HALLOCK, MN 56728
4535	LOEFFLER, TERRY_	50 N CEDAR AVE	PO BOX 218	HALLOCK, MM 56728
4540	ANDERSON, HAROLD	115 N CEDAR AVE	PO BOX 99	HALLOCK, MN 56728
5005	BLAZE, TONY	300 2ND STREET NE	PO 80X 191	HALLOCK, MN 56728
5006	BROBECK, BARRY	304 2ND STREET NE	PO BOX 547	HALLOCK, MN 56728
5007	WALLER, KEVIN	306 2ND STREET NE	PO BOX 215	HALLOCK, MN 56728
5008	ADAMSON, ANDY	318 2ND STREET NE	PO BOX 433	HALLOCK, MN 56728
5011	PETERSON, EDWIN	314 2ND STREET NE	PO BOX 111	HALLOCK, MN 56728
5015	TRIPP, REVEREND ROBERT	329 2ND STREET NE	PO BOX 507	HALLOCK, MN 56728
5017	BOROSKI, ANTON	330 2ND STREET NE	PO 80X 431	HALLOCK, MN 55728
5020	LINDEP, ROY	340 2ND STREET NE	PO BOX 476	HALLOCK, MN 56728
5025	YOUNGGPEN, LOREN	102 N DOUGLAS AVE	PO BOX 238	HALLOCK, MN 56728

CCT #	ACCOUNT NAME	ADDRESS #1	ADDRESS #2	CITY, STATE & ZIP
5030	QUADE, E.F	202 N DOUGLAS AVE	PO BOX 186	HALLOCK, MN 5672
5035	HUGHES, TOM	302 N DOUGLAS AVE	PO 8CX 874	HALLOCK, MN 5672
5040	OLSON, ARNOLD	402 N DOUGLAS AVE	PO BOX 96	HALLOCK, MM 5672
5045	GUSTAFSON, JIM	405 N DOUGLAS AVE	209-306	HALLOCK, MN 5672
5050	8AHR, EARL	337 2ND STREET ME	PO 80X 833	HALLOCK, MN 5672
5060	LYBERG, ANDY	329 2ND STREET NE	215-343	HALLOCK, MN 5672
5065	GUSTAFSON, DELBERT	325 2ND STREET NE	209-218	HALLOCK, MN 5672
5070	PEARSON, SCOTT	319.2ND STREET NE	PO BOX 94	HALLOCK, MN 5672
5075	SOBERASKI, HAROLD	309 2ND STREET NE	PO BOX 366	HALLOCK, MN 5672
5080	WALLER, KEN	303 2ND STREET NE	PO BOX 202	HALLOCK, MN 5672
5085	NORBY, GREG	216 N CEDAR AVE	PO BOX 35	HALLOCK, MN 5672
5095	HALLOCK ARENA	205 4TH STREET NE		HALLOCK, MN 5677
5103	SEVERSON, ROBERT	226 N BIRCH AVE	PO BOX 220	HALLOCK, MN 5677
5110	GLIDDEN, ETHEL	205 2ND STREET NE	PO BOX 803	HALLOCK, MN 567
5115	STRAND, RITA	209 2ND STREET NE	PO BOX 621	HALLOCK, MN 567
5120	PLAINE, COREY	215 2ND STREET NE	PO 80X 864	HALLOCK, MN 567
5125	SHAFER, JIM	219 2ND STREET NE	PO 80X 752	HALLOCK, MN 567
5135	YOUNGGREN, MAE	121 N CEDAR	PO BOX 776	HALLOCK, MN 567
5140	THOMPSON, PAUL	214 2MD STREET N	PO BOX 171	HALLOCK, MN 567
5145	THOMPSON, PAUL	210 2ND STREET NE	PO 80X 171	HALLOCK, MN 567
5150	MALONEY, DAN	102 N BIRCH AVE	PO 80X 421	HALLOCK, MN 567
5155	CAMPBELL, PAT	116 N BIRCH AVE	PO BOX 146	HALLOCK, MN 567
5160	YOUNGGREN, DEAN	120 N BIRCH AVE	PO 80X 821	HALLOCK, MN 567
5165	BACKOUS, JERRY	118 2ND STREET NE	PO BOX 753	HALLOCK, MN 567
5170	YOUNGGREN, VERLA	102 2ND STREET NE	PO BOX 278	HALLOCK, MN 567
5175	BECKEN, DONALD	100 2ND STREET N	PO BCX 411	HALLOCK, MN 567
5180	ANDERSON, DIANA L	103 2ND STREET NE	PO 80X 521	HALLOCK, MN 567

08/01/96

#### CITY OF HALLOCK CUSTOMER ACCOUNT LISTING

ACCT #		ADDRESS #1	ADDRESS #2	CITY, STATE & ZIP C
5185	WALUKIEVICZ, JOE	111 2ND STREET NE	PO BOX 261	HALLOCK, MN 56728
5190	CZAPIEWSKI, HILARY	115 2ND STREET NE	PO BOX 3i	HALLOCK, MN 56728
5200	LINDEGARD, DAVID	119 2ND STREET NE	PO BOX 778	HALLOCK, MN 56728
5201	SOBOLIK, DENNIS	221 N BIRCH AVE	PO 80X 9	HALLOCK, MN 56728
5205	ENDRISS, DAVID	118 4TH STREET NE	PO BOX 842	HALLOCK, MN 56728
5210	PRESBYTERIAN CHURCH	228 N ASH AVE	PO BOX 429	HALLOCK, MN 56728
5215	FOWLER, DELIA	224 N ASH AVE	PO BOX 746	HALLOCK, MN 56728
5220	INGEMAN, MARK	216 N ASH AVENUE	PO 80X 584	HALLOCK, MN 56728
5225	HATTON, MARK	217 N ASH AVE	PO BOX 293	HALLOCK, MN 56728
5235	HATTON, MARY		PO BOX 432	HALLOCK, MN 56728
5240	WIDERSTRAND, ELMER	% LOUISE HALVERSON	8100 WYNNWOOD RD	GOLDEN VALLEY, MN
5245	MATTSON, CASPER	305 N ASH AVE	PO 80X 115	HALLOCK, MN 56728
5250	NILES, JOHN	312 N ATLANTIC	111-958	HALLOCK, MN 56728
5252	FARM CREDIT SERVICES	HIGHWAY 75 N	PO 80X 878	HALLOCK, MN 56728
5260	SUNDBERG, PHIL	216 N ATLANTIC	PO BOX 850	HALLOCK, MN 56728
5265	MONEY, JOHN	17 2ND STREET NE	PO BOX 724	HALLOCK, MN 56728
5270	EHRENSTROM, MYRTLE	% LEONARD EHRENSTROM	RR 2 BOX 33	LAKE BRONSON, MN 5
5285	VOLD, JOEL	20 2ND STREET NE	PO BOX 781	HALLOCK, MN 56728
5290	YOUNGGREN, DAN	16 2ND STREET NE	PO BOX 201	HALLOCK, MN 56728
5300	PEDE, BOB	12 2ND STREET NE	PO BOX 314	HALLOCK, MN 56728
5305	KITTSON CENTRAL HIGH SCHOOL	444 N ASH AVE	PO BOX 670	HALLOCK, MN 56728

<b>ENVIRONMENTAL</b>	SERVICES,	Limited
----------------------	-----------	---------

1550 HUBBARD


BA1AVIA, 1L 60510

(708) 879 3006

• FAX: (708) 879-3014


#### FAX TRANSMISSION

Date:	
Recipient FAX number:	218-843-2579
Recipient name & address:	MRHANK NOEL CITY OF HALLOCK
	Po.Box 336
	HALLOCK, MN 56728
Sender's name: <u>E17</u>	ZARETH RACHMAN 708-879-3004
Number of pages to follow:	
Special instructions or comme	ents: THE ADDRESS OF THE SITE
IS: GTE NORTH, INC., 150	S. SECOND STREET, HALLCCK, NN.
THE INNER CIRCLE PEPP	ESENTS 500 FEET. IF YOU
NEED ANYTHING ELSE FE	EL PREE TO CALL THANKS
FOR YOUR HELP! -L	-
•	



### APPENDIX H

### LIST OF LUST SITES



#### **APPENDIX H - List of LUST Sites**

Several Leaking Underground Storage Tanks (LUSTs) have been reported in the City of Hallock Please refer to the table below (sites listed in bold are within 1000 feet of the subject site)

SITE ADDRESS	LEAK#
Cooperative Services 16 North Atlantic	6099
Cooperative Services 16 North Atlantic	8567
Hallock Coop 16 North Atlantic	6391
Hallock Elementary School 411 4th Street South	2128
Hallock High School 44 North Ash	1318
John Urau Property 901 South Elm	5746
Johnson Oil (Standard) 146 South Atlantic	2936
Kittson Oil Implement 15 North Atlantic	2870
MNDOT Hallock Truck 307 South Columbus	1752
Northern Air Radiator 406 South Atlantic	2688
Northwestern State Bank 203 2nd Street South	3290
Pantzer Residence Route 1, Box 116	8568
Ryden Development 346 Atlantic	2761
vacant building 102 East Broadway	4529

APPENDIX I **PHOTOGRAPHS** 




Photo #1
View of GTE facility in Hallock, MN (looking north) showing underground utility locations

Photo #2
View of facility (looking north) showing location of overhead electric lines





Photo #3
View of overhead lines at GTE facility as well as property to the west

Photo #4
View of overhead lines at properties west of GTE (looking northwest)





Photo #5
View of overhead lines at properties west of GTE and in the alley (looking west northwest)

Photo #6
View of adjacent property. Photograph taken from between the two GTE buildings looking northeast.





Photo #7
View of overhead lines in the alley running east of the site

Photo #8
View of overhead lines at the property to the east of the GTE facility

