

Leaksite ID#	8767	Tank Facility ID	19378
GTE NORTH INC		GTE NOTH INC	
Site Name		Responsible Party	

LEAKSITE REMARKS

10/16/95: CLM received a message from Ted Foster that they intend to comply with requirements of our standard letter. His number is 309-663-3380.

4/2/97: SCT-Call from Liz Rachman of Aeries Consult. Due to weather conditions (still have lots of snow and expecting a flood), they would like to push back the response date on the required additional work. I agreed and changed the due date from 5/7/97 to 7/1/97.

11/24/97: SCT-Recommend closure. Comments in file.
End of Remarks

Closure Recommended

U.S. # 8767

S. Thompson 11/21/97

GTE - Hallock

Rept: RI
July 1997

- 1 diesel UST - 285 gal removed 9/95 -
- NO soil removed
- Hand augers used for investigation - boring advanced only from 6-8'
- moderate contamin levels (PID) in all borings
analytical showed only 400 mg/kg DRO @ 3-6'
in HA-2A -
- sediments - hard clay
- NO GW was encountered
- Risk to drinking water receptors is very low -
all residents are only muni-supplied water. Those
wells are \approx 1/2 mi from site & separated from
the surface by \approx 90' clay

- low level of volatiles makes vapor impacts unlikely
- no surface H₂O threats