Phase I Environmental Property Assessment Voluntary Investigation and Cleanup

Northeast Quadrant of I-494 and Penn Avenue Richfield, Minnesota

Prepared for Opus Northwest L.L.C.

April 2000



4700 West 77th Street Minneapolis, MN 55435 Phone: (612) 832-2600 Fax: (612) 832-2601



Voluntary Investigation and Cleanup Preliminary Phase I Environmental Property Assessment Northeast Quadrant of I-494 and Penn Avenue Richfield, Minnesota

Table of Contents

Findings. 5	Current Conditions4	Motorwerks BMW Site4	Walser Buick Site4	Leaseback Properties Site	Wally McCarthy Oldsmobile	Regulatory History/Previous Investigations3	Surrounding Land Use History2	Property Land-Use History	Property Setting1
5	4	4	4	4	3	3	2	2	

Tables

Table 1	Well Search Results
Table 2A	West 77th Street, Commercial Property History Summary
Table 2B	West 78th Street, Commercial Property History Summary
Table 2C	Knox Avenue South, Commercial Property History Summary
Table 2D	Logan Avenue South, Commercial Property History Summary
Table 2E	Morgan Avenue South, Commercial Property History Summary
Table 2F	Newton Avenue South, Commercial Property History Summary
Table 2G	Penn Avenue, Commercial Property History Summary
Table 3	UST/AST Summary

Figures

Figure 2	Figure 1
Property I avout Man	Property Location Map
, c	Мар

Appendices

Appendix F	Appendix E	Appendix D	Appendix C	Appendix B	Appendix A
Signatures and Qualifications	Property Inspection Photographs	Previous Investigations	Regulatory Reports	Historical Documentation	Phase I Checklist

				ň
W				

Preliminary Phase I Environmental Property Assessment Northeast Quadrant of I-494 and Penn Avenue Voluntary Investigation and Cleanup Richfield, Minnesota

the Phase I checklist in Appendix A. Historical documentation is in Appendix B. related to previous investigations, interviews, information sources, and data failure, are presented in setting, land-use history, regulatory history, and Property features, as well as detailed information This narrative briefly summarizes the results of the Assessment. Detailed descriptions of Property to each parcel is granted; addenda to this report will be provided following the parcel inspections. was conducted from public access points. Individual parcel inspections will be conducted as access Agreement between Opus and Barr, dated July 30, 1999. The Property inspection for this assessment #8, and the applicable requirements for Assessments included as Exhibit "A" of the Master Services Control Agency (MPCA) Voluntary Investigation and Cleanup (VIC) Program Guidance Document Society for Testing and Materials (ASTM) Practice E 1527-97 (Practice), Minnesota Pollution is shown on Figure 1. Barr performed this Assessment in general conformance with American I 494 and Penn Avenue in Richfield, Hennepin County, Minnesota (Property). The Property location Assessment (Assessment) of mixed residential, commercial, and light industrial parcels located at Barr Engineering Company (Barr) completed a Preliminary Phase I Environmental Property

Property Setting

include the Prairie du Chien-Jordan, Franconia-Ironton-Galesville, and the Mt. Simon Hinckley present at an approximate depth of 180 feet beneath the Property (Reference 3). Regional aquifers sand, and loamy sand, overlain by thin deposits of silt loam or organic sediment, underlie the (Reference 1). Approximately 180 feet of unconsolidated sediments consisting of sand, gravelly (Reference 3). Property (Reference 2, 3). The uppermost bedrock unit consisting of the Prairie du Chien Group is Surface elevations of the Property range from 830 to 850 feet above mean sea level (MSL)

approximately 0.6 miles north/northeast of the Property (Reference 1). nearest likely discharge zone (Reference 3). The nearest surface water bodies are an unnamed wetland located approximately 0.6 mile northwest of the Property and Wood Lake located The anticipated groundwater flow direction is south/southeasterly towards the Minnesota River, the Groundwater is anticipated to be present beneath the Property at a depth of 20 feet (Reference 3).

municipal well is located approximately 2 miles northeast of the Property (Reference 7). located throughout the City of Richfield. The wells range in depth from 400 to 1000 feet; the nearest The Property is supplied with municipal water. Municipal water is obtained from municipal wells

Minnesota Geological Survey well logs and Property building records, was conducted for the many Property buildings have or likely have utilized private wells. A well search, utilizing Based on the dates of Property building construction and municipal water availability to the Property,

buildings and the dates of municipal water connection, the presence of additional, unidentified wells Property. Table 1 summarizes the results of the well search. Based on the age of most Property is likely.

Property Land-Use History

comprises approximately 27 acres of the Property. Current and known historical Property features use comprises approximately 17 acres of the Property; commercial/light industrial land-use are shown on Figure 2. The Property consists of approximately 44 acres of land in Richfield, Minnesota. Residential land-

aerial photographs, possibly indicating filling activities (Reference 4). farmsteads. A wetland area, apparent in 1937 through 1945, was no longer present on subsequent Areas of potential surface debris/disturbances were apparent in the vicinity of many of these Approximately eight farmsteads were located on the Property by the early 1950s (Reference 4). The Property was originally developed for agricultural use prior to 1937 (Reference 4, 5)

containing materials exists. fuel storage. In addition, based on the age of many Property buildings, the potential for asbestos likely utilized above-ground storage tanks (ASTs) or underground storage tanks (USTs) for heating utilized private wells and septic systems, including commercial occupants; many Property occupants Property at the time of early development. Historical documents indicate many Property occupants 1950s. Sanitary sewer, municipal water, and potentially natural gas were not available to the Residential, commercial, and industrial development began on the Property beginning in the early-

development history by address; associated addresses and historical features are shown on Figure 2 and plastic fabricators (Reference 4, 6, 12, 13). Table 2 summarizes the commercial parcel asphalt company; drycleaners (two separate locations); metal refinishing; lithographers; machinists; identified at the Property: auto body repair; auto service and sales; gas station; garbage collection; A summary table of residential parcel development is included in Appendix B. Based on the review of available historical information, the following historic uses of chemicals were

Surrounding Land Use History

use until the early-1950s. Property vicinity has been developed since prior to 1937 and consisted mainly of agricultural landwest/southwest. Interstate I-494 and commercial property are located to the south. This general and commercial property are located east and west of the Property, including a gas station to the family homes and multi-family complexes are located north of the Property. Multi-family complexes The Property is located in an area of mixed residential and commercial use. Residential single-

2

Regulatory History/Previous Investigations

been reported. See Appendix A for details. an active LUST site. Free-phase product has been detected at the site and offsite contamination has therefore, groundwater contamination, exists at the site. Mobile Southtown Service was identified as as a closed leaking UST (LUST) site; however, the potential for residual soil contamination and, Service [Citgo], located adjacent to the southwest corner of the Property. Naegle Sign was identified potential for impacting soil or groundwater beneath the Property: Naegle Sign (Universal Outdoor, Inc.), formerly located adjacent to the southeast corner of the Property; and Mobile Southtown The following adjacent or potentially upgradient sites identified in the regulatory searches have the Adjacent and potentially upgradient sites were identified within search radii defined by the Practice. (EDR) on March 8, 2000 and the MPCA on March 24, 2000. Regulatory reports are in Appendix C. Regulatory records reviews for the Property were obtained from Environmental Data Resources, Inc

available for review at the time of this report; MPCA project managers for the sites were contacted summarized below. Copies of available investigation reports or report excerpts are in Appendix D 2000. The available reports and the results of the interviews and online database reviews are for more information. In addition, MPCA online LUST and VIC databases were accessed April 13, Site are summarized below. No site reports for the other two LUST sites and the VIC site were inactive by the MPCA. Available previous investigation reports for the Wally McCarthy Oldsmobile the third (Walser Buick) is reported as closed by the MPCA. The VIC site is currently reported as LUST sites (Wally McCarthy Oldsmobile and Motorwerks BMW) are currently under investigation; RCRIS-small quantity generators were identified on the Property. See Appendix A for details. Two AST and four UST sites, one MPCA Voluntary Investigation and Cleanup (VIC) site, and nine The Property was identified in regulatory lists searched by EDR and MPCA. Three LUST sites, one

Wally McCarthy Oldsmobile

groundwater were not present, and soil contamination, although observed, did not "appear to extend the building. Conclusions of the investigation indicated that "significant" impacts to shallow shallow geoprobe or hand auger borings near floor drains, a former dispenser island, and adjacent to which have not been formerly summarized into a report. The investigation included placing 10 (ESA) of potential petroleum hydrocarbon impacts. Meisch conduct a limited ESA, the results of McCarthy Oldsmobile site (1900 W. 78th Street and 7725 Morgan Avenue South) in October 1999 of the tanks. Meisch also conducted a Phase I Environmental Site Assessment at the Wally evidence of a release from the actual tanks. Groundwater was not encountered during the excavation evidence of a release under dispensers for two tanks (Tanks 5 and 6); Meisch indicated there was no the Wally McCarthy Oldsmobile site (1900 W. 78th Street) in September 1999. Meisch reported Meisch & Associates (Meisch) completed an "Excavation Worksheet for Petroleum Release Sites" at to great depth." See Appendix A for details. Based on the Phase I assessment, Meisch recommended a Phase II Environmental Site Assessment

Leaseback Properties Site

that involved the use of solvents, including trichloroethylene (TCE). She suspected that TCE may be present in the groundwater, but she did not think it had migrated offsite. Nearby domestic wells were summary information. Ms. Kromar indicated that, at one time, manufacturing took place on the site program on August 26, 1992. The MPCA project manager, Karen Kromar was contacted for sampled, but she did not think they had been impacted. The Leaseback Properties is an inactive site in the MPCA VIC program. The site entered the VIC

Walser Buick Site

approximately 100 yd3 of soil were excavated at the time of tank removal and no residual contamination was left in place. No follow up monitoring was conducted. The file was inactive until the site in 1989, and that a tank assessment report was completed at that time. He stated that Balcos was contacted for summary information. Mr. Balcos indicated that USTs were removed from 1994, when it was closed based on the results of the 1989 tank removal and assessment. Walser Buick is a LUST site that was closed June 14, 1994. The MPCA project manager, Edwin

Motorwerks BMW Site

MPCA LUST database, no contaminated soils remain at the site, and contamination has not migrated located on a parcel that was formerly Walser Imports, a registered UST facility. According to the Motorwerks BMW is a LUST site that is the subject of ongoing investigation. Motorwerks BMW is

Current Conditions

during the Property inspection are in Appendix E. to each parcel is granted; addenda to this report will be provided following the parcel inspections. Existing Property features are shown in the Property layout on Figure 2. Photographs obtained March 9, 2000 from public access points. Individual parcel inspections will be conducted as access The Property inspection for this preliminary assessment was conducted by representatives of Barr on

apartments and Citgo gas station are located to the west. churches are also located to the north. FountainHead apartments and Gallyan's retail store are located east of the Property; I-494 is located south, with retail complexes beyond it. Century Court Residential and multi-family housing (Colony Apartments) is located north of the Property; two The Property is located in an area of mixed commercial, residential, and light industrial use

and associated auto repair facilities, metal finishers, paint store, and plastic fabricators. A list of housing (duplexes and apartment buildings), and commercial businesses, including car dealerships The Property consists of multiple parcels that currently support residential homes, multi-family

outdoor ASTs were observed at either the residential or commercial parcels. Six to seven 55-gallon the exception of the yard behind 7708 Knox Avenue South, which was enclosed by a fence. No drums were observed to be stored on pallets outside 7629 Logan Avenue (Pioneer Plastics). observed on the southwest corner of Knox Avenue South and W. 77th Street. During the Property these parcels and their current occupants are included in Appendix B. A city lift station was also inspection, most outdoor areas of the Property could be observed from the public access points, with

Findings

Company qualifications, special terms, conditions, limitations, and exceptions that apply to the Program Guidance Document #8, and July 1999 Opus Northwest, LLC Master Services Agreement. Assessment are described in Appendix F. Barr performed this Assessment in April 2000 in conformance with the Practice, MPCA VIC

Property, except for the following: The Assessment revealed no evidence of recognized environmental conditions in connection with the

- lithographers. cleaning; metal finishing; garbage collection; metal finishing; plastic fabricators; and former gas station; auto body repair (with paint booths); vehicle maintenance; dry hazardous substances: multiple current and former USTs and ASTs, including a Historic or current Property uses involving the use of petroleum compounds or
- Property, the potential for additional, unidentified wells is likely. age of many of the Property buildings and the availability of municipal water to the Approximately 64 water wells have been documented on the Property. Based on the
- drainfield, or both has been documented at the Property; documentation indicating the to these systems. been discharged in significant quantities (e.g., greater than household chemical use) these systems on commercial parcels, the potential does exist for chemicals to have present on both residential and commercial parcels. removal or abandonment of these systems was not found. These systems were The presence of historical on-site septic system(s) or cesspools consisting of a tank, a Based on the document use of
- occupants likely utilized ASTs or USTs for heating fuel storage, prior to natural gas waste oil, have been identified on the Property. In addition, many former Property Multiple USTs, containing gasoline, motor oil, diesel fuel, transmission fluid, and
- two are currently under investigation. Three LUST sites have been reported on the Property. One site is reportedly closed;

		-	

- on historic aerial photographs. filling activities. In addition, surface debris was observed at many of the farmsteads aerial photographs, was no longer apparent on subsequent photos, possibly indicating A wetland, present on the southwest portion of the Property in the 1937 and 1945
- materials exists. Based on the age of the Property buildings, the potential for asbestos-containing
- and offsite contamination has been reported. identified as an active LUST site. Free-phase product has been detected at the site Mobile Southtown Service [Citgo], located west adjacent to the Property, was soil contamination and, therefore, groundwater contamination exists at the site. the Property, was identified as a closed LUST site; however the potential for residual following: Naegle Sign (Universal Outdoor, Inc.), formerly located east adjacent to Known, suspected, or potential impacts from adjacent Properties, including the
- 7629 Logan Avenue (Pioneer Plastics). approximately six to seven 55-gallon drums, stored on pallets, were observed behind During the Property inspection, conducted from the public access points,

several areas of the Property. These follow-up investigations will be scoped in separate documents. Based on these findings, follow-up investigations of soil and groundwater are recommended for




Table 1 Well Search Results Opus Development (Best Buy Campus)

Unique No.	Owner	Address	Street	Diameter (in)	Depth (ft)	Screened Interval	Slot Size	Aquifer	Static Water Level (ft BGS)	Use	Status
223225	Barrel Finish, Inc.	7630	Knox Ave S	4	60	56-60	NA	Quat	25	Domestic	Active
236435	Barrel Finish, Inc.	7630	Knox Ave S	4	65	60-65	NA	Quat	25	Industrial	Active
206216	Charles Tack	7614	Logan Ave S	2	70	67-70	060	Quat	31	Domestic	Active
206223	Century Masonic Lodge	7615	Logan Ave S	4	73	69-73	010	Quat	30	Public Supply	Sealed
206217	F.R. Lien Const.	7620	Logan Ave S	2	47	44-47	010	Quat	26	Domestic	Active
206218	Chuck Lack	7632	Logan Ave S	2	50	43-50 (6' screen?)	010	Quat	25	Domestic	Active
unknown	unknown	7645	Logan Ave S	4	55	unknown	unknown	unknown	37	Commercial	unknown
unknown	Bor Son Const.	7700	Logan Ave S	2	unknown	unknown	unknown	unknown	unknown	Commercial	unknown
206224	John Carroll	7701	Logan Ave S	2	55	49-55	018	Quat	31	Domestic	Active
unknown	Jas. Tack	7626-28	Logan Ave S	2	50	unknown	unknown	unknown	26	Domestic	unknown
unknown	Herman Johnson	7644-46	Logan Ave S	2	51	unknown	unknown	unknown	21	Domestic	unknown
unknown	Jungell & Johnson	7600	Morgan Ave S	3	60	56-60	unknown	unknown	30	Domestic	Sealed
unknown	Jungell & Johnson	7608	Morgan Ave S	3	57	unknown	unknown	unknown	30	Domestic	unknown
unknown	Keith Cowell	7609	Morgan Ave S	2	40	unknown	unknown	unknown	28	Domestic	Sealed
unknown	Jungell & Johnson	7614	Morgan Ave S	2	39	unknown	unknown	unknown	13	Domestic	Sealed
unknown	Jungell & Johnson	7615	Morgan Ave S	3	70	66-70	unknown	unknown	30	Domestic	Sealed
unknown	Jungell & Johnson	7620	Morgan Ave S	2	29	unknown	unknown	unknown	8	Domestic	Sealed
unknown	Jungell & Johnson	7621	Morgan Ave S	2	66	unknown	unknown	unknown	22	Domestic	Sealed
unknown	Jungell & Johnson	7624	Morgan Ave S	2	51	unknown	unknown	unknown	28	Domestic	unknown
unknown	Jungell & Johnson	7625	Morgan Ave S	2	51	unknown	unknown	unknown	30	Domestic	unknown
unknown	Jungell & Johnson	7628	Morgan Ave S	2	44	44-48	unknown	นทหทอพก	30	Domestic	Sealed

Unique No.	Owner	Address	Street	Diameter (in)	Depth (ft)	Screened Interval	Slot Size	Aquifer	Static Water Level (ft BGS)	Use	Status
223223	John Labo	7629	Morgan Ave S	2	51	48-51	010	Quat	30	Domestic	Active
unknown	Jungell & Johnson	7634	Morgan Ave S								
206219	B.K. Weekley	7645	Morgan Ave S	2	49	46-49 (6' screen)	010	Quat	27	Domestic	Active
223224	Repro Printing	7701	Morgan Ave S	2	60	57-60	NA	Quat	20	Domestic	Sealed
unknown	Al Mueller	7713	Morgan Ave S	2	62	unknown	unknown	unknown	30	Commercial	unknown
444231	Union Oil of Ca.	NA	NA	2	31	21-31	NA	Quat	25	Monitoring	Active
unknown	unknown	7601	Newton Ave S	2	52	unknown	unknown	unknown	35	Domestic	unknown
unknown	unknown	7611	Newton Ave S	2	54	unknown	unknown	unknown	30	Domestic	unknown
unknown	unknown	7620	Newton Ave S	unknown	unknown	unknown	unknown	unknown	unknown	Domestic	unknown
unknown	Robert Weber	7623	Newton Ave S	2	unknown	unknown	unknown	unknown	unknown	Domestic	unknown
unknown	Jacobson & Quist	7626	Newton Ave S	2	45	unknown	unknown	unknown	unknown	Domestic	unknown
unknown	unknown	7629	Newton Ave S	2	42	unknown	unknown	unknown	20	Domestic	Sealed
unknown	Jacobson & Quist	7632	Newton Ave S	2	39	35-39	unknown	unknown	18	Domestic	Sealed
unknown	unknown	7633	Newton Ave S	2	unknown	unknown	unknown	unknown	unknown	Domestic	unknown
unknown	Jacobson & Quist	7638	Newton Ave S	2	unknown	unknown	unknown	unknown	unknown	Domestic	unknown
unknown	Jacobson & Quist	7644	Newton Ave S	2	42	unknown	unknown	unknown	unknown	Domestic	unknown
unknown	John Saltzman	7701	Newton Ave S	unknown	unknown	unknown	unknown	unknown	unknown	Domestic	unknown
unknown	unknown	7701	Newton Ave S	2	65	unknown	unknown	unknown	35	unknown	unknown
unknown	Westwood Bldrs.	7701	Newton Ave S	2	56	unknown	unknown	unknown	27	Commercial	unknown
unknown	Jacobson & Quist	7634	Oiiver Ave S	2	64	unknown	unknown	unknown	unknown	Domestic	unknown
unknown	Jacobson & Quist	7600	Oliver Ave S	2	56	unknown	unknown	unknown	unknown	Domestic	unknown
unknown	Jacobson & Quist	7601	Oliver Ave S	2	unknown	unknown	unknown	unknown	unknown	Domestic	unknown
unknown	Jacobson & Quist	7604	Oliver Ave S	2	59	unknown	unknown	unknown	unknown	Domestic	unknown
unknown	D. D. McHardy	7609	Oliver Ave S	3	99	unknown	unknown	unknown	unknown	Domestic	unknown
unknown	Jacobson & Quist	7610	Oliver Ave S	2	60	56-60	unknown	unknown	45	Domestic	Sealed
unknown	Jacobson & Quist	7614	Oliver Ave S	2	56	unknown	unknown	unknown	unknown	Domestic	unknown

Unique No.	Owner	Address	Street	Diameter (in)	Depth (ft)	Screened Interval	Slot Size	Aquifer	Static Water Level (ft BGS)	Use	Status
unknown	Jacobson & Quist	7615	Oliver Ave S	2	40	unknown	unknown	unknown	38	Domestic	Sealed
unknown	Jacobson & Quist	7620	Oliver Ave S	2	40	unknown	unknown	unknown	37	Domestic	Sealed
unknown	A. Hermer	7621	Oliver Ave S	2	unknown	unknown	unknown	unknown	unknown	Domestic	unknown
unknown	Paul Ragatz	7624	Oliver Ave S	2	40	36-40	unknown	unknown	"none"	Domestic	Sealed
unknown	Jacobson & Quist	7624	Oliver Ave S	2	76	unknown	unknown	unknown	unknown	Domestic	unknown
unknown	Chas. Mapson	7627	Oliver Ave S	2	unknown	unknown	unknown	unknown	unknown	Domestic	unknown
unknown	Jacobson & Quist	7628	Oliver Ave S	2	47	unknown	unknown	unknown	unknown	Domestic	unknown
unknown	E. Labo	7633	Oliver Ave S	2	45	unknown	unknown	unknown	32	Domestic	Sealed
unknown	Jacobson & Quist	7638	Oliver Ave S	2	39	39-43	unknown	unknown	20	Domestic	unknown
unknown	Parsley - Gunderson	7644	Oliver Ave S	2	unknown	unknown	unknown	unknown	unknown	Domestic	unknown
unknown	Mark Bigler	7645	Oliver Ave S	2	40	35-40	unknown	unknown	20	Domestic	Sealed
unknown	Church of St. Richard	7601	Penn Ave	3	unknown	unknown	unknown	unknown	unknown	Domestic	unknown
unknown	unknown	7615	Penn Ave	2	unknown	unknown	unknown	unknown	unknown	Domestic	unknown
unknown	unknown	7621	Penn Ave	2	unknown	unknown	unknown	unknown	unknown	Domestic	unknown
unknown	unknown	7627	Penn Ave	2	50	unknown	unknown	unknown	38	Domestic	unknown
unknown	unknown	7633	Penn Ave	2	unknown	unknown	unknown	unknown	unknown	Domestic	unknown
unknown	unknown	7639	Penn Ave	2	50	unknown	unknown	unknown	30	Domestic	unknown
unknown	Eunice Davis	7649	Penn Ave	2	35	unknown	unknown	unknown	17	Domestic	Sealed
unknown	Labo & Son	1900	W 78th St	unknown	unknown	unknown	unknown	unknown	unknown	Commercial	unknown
206222	Lindahl Olds	1900	W 78th St	NA	220	NA	NA	PDC	40	Industrial	Active
unknown	Lindahl Olds	1900	W 78th St	4	unknown	unknown	unknown	unknown	unknown	Commercial	unknown
222969	NA	1922	W 78th St	4	56	52-56	010	Quat	30	Domestic	Active
unknown	Labo	2020	W 78th St	4	unknown	unknown	unknown	unknown	unknown	Commercial	unknown
unknown	Walser Buick	2100	W 78th St	4	200	196-200	unknown	unknown	50	Domestic	?Sealed
unknown	Labo	1916/1920	W 78th St	unknown	unknown	unknown	unknown	unknown	unknown	Commercial	unknown

Table 2A
West 77th Street
Commercial Property History Summary

Present- day Address	Land Use	Reference Date	Reference Number	Notes
				1962: Incinerator, well
				installation, and sewer service
2015/2017	A northwart buildings		3	permits (each building)
2013/201/	Apartment outrums	1963 to present	אם שם,	1963: Buildings constructed
and 2025	Soun Court Apartificins		71, 51	1971: Municipal water
				connection permit (each
				building)
				1961: Sewer service permits
				1962: Buildings constructed
2101,				1963: Water service permit
2109,	Apartment buildings	1062 to precent	TA, CD,	for 2109 (however, all
2115, and	"Diplomat Apartments"	1702 to present	AP, BR	addresses likely connected at
2121				this time)
				1968: Incinerator rep. permits
				(each address)

TA CD AP BR Tax Assessor City Directory Aerial Photograph Building Record

Table 2B W. 78th Street Commercial Property History Summary

	1920 (former address 1918)	1920 (Former address 1916)	1920 (former address 1914)	1900							0067	1000								Present- day Address
Address changed to 1920	Belt Line Bar—tavern	Labo and Son Contr.	Excavating contractors	Service, Inc.—garbage collection	Woodlake Canitary		Troom my Constitutions	Motors Co.; Lindahl Oldsmobile; Wally McCarthy Oldsmobile)	Car dealership (Lyndahl					,	room [car sales and servicing]—Labo (owner)	Garage, office, display				Land Use
	1956-1982	1952	1956	1956	1956			1962 to present							1947-1956					Reference Date
	CD, AP	CD, BR	CD	AP	CD, AP			BR, AP, CD, TA							BR, TA					Reference Number
	1956: Buildings present. Surface debris and dark surface patches apparent around buildings (1900 and 1920) 1967: water service permit	1952: septic tank and cesspool; "old well" (see Table 1)	1956: Buildings present. Surface debris and dark surface patches apparent around buildings (1900 and 1920).	1956: Surface debris and dark surface patches apparent around buildings (1900 and 1920)	1951: Surface debris apparent around building.	1999 (August): Notice of LUST (#12876) (letter from MPCA)	1977: Trough drain for new car stalls addition	1972: Remodel commercial building to auto service building	1968: Plumbing permit: Well (4") (see Table 1)	1967: Surface debris/storage south of 7701 Logan Ave. S.	1962: Storm sewer connection	1956: "City gas not available at this time"	1956: Sewer permit	around buildings (1900 and	1956: Surface debris and dark	plant"	1948: Plumbing permit: Twin	1947: septic tank and cesspool and well (see Table 1)	1947; Building construction	Notes

Table 2B cont. W. 78th Street Commercial Property History Summary

2022)	address	(former	2000 -		address 2020)	(former	2000	address 2018)	(former	2000	(former address 2016)	2000	1920		1920 (former address 1924/26)		1722)	1920 (former address		1920 (former address 1920)		Present- day Address
Caesar's Sauna/Steam Massage	Hair Salon	Swimming pool dealers	General equipment sales	Wood Stoves Unlimited	Constr. Equipment Mfg and building/bridge contr.	Penn Sheet Metal	Labo and Sons Constr	Electric Subs.	Rental store	Asphalt Co.	Rental Equipment — George McKasy (owner)	Cabinet makers	Car dealership—Wally McCarthy's Oldsmobile (fleet dept)		Restaurant	Beauty Salon	Vacant	Plumbing and heating	Piano & Organ Dealers	Heating and cooling contractors	Labo	Land Use
1974-1982	1972	1967	1956-62	1982	1962-1972	1956	1955-1959	1967	1962	1956	1967-1982	1956-1962	1982 to present		1956-77	1967-77	1962	1956	1967-77	1956-62	1952	Reference Date
BR, CD	CD	CD	CD	CD	CÐ	CD	BR	CD	CD	CD	BR, CD	CD	TA, CD, AP		CD, AP	CD, AP	CD	CD	CD, AP, BR	CD, AP	BR	Reference Number
1974: Water service permit							1955: sewer connection 1959: Well (4") (see Table 1)				1974: Water service permit		Parcel comprised of former addresses and buildings (1918, 1920, 1922, 1924, and likely 1914 and 1916).	1967: water service permit	1956: Buildings present. Surface debris and dark surface patches apparent around buildings (1900 and 1920)	1967: water service permit		1956: Buildings present. Surface debris and dark surface patches apparent around buildings (1900 and 1920)	1967: water service permit	1956: Buildings present. Surface debris and dark surface patches apparent around buildings (1900 and 1920)	1952: Septic tank and cesspool; "old well" (see Table 1)	Notes

147				

Table 2B cont. W. 78th Street Commercial Property History Summary

AP
75
TA, BR,
IA, DA
gp
BR
BR, AP
Manner
Reference

Table 2B cont.
W. 78th Street
Commercial Property History Summary

2100 (cont.)	2100	Present- day Address
Walser Buick, Inc.	Schmelz Volkswagen Sales and Service—auto sales, auto body and service shop	Land Use
1976 to present	1961-1976	Reference Date
BR, AP, CD, TA	TA, BR, CD	Reference Number
waste trap 1976: Install inflammable waste trap 1977: WRECKED—four stall commercial garage building; slab to remain 1978: Install paint filter system in paint booth 1982: Remove existing used car manager's station and build new facility 1982: Move garage-like structure to offsite location 1985: Outdoor storage debris to the east of the main building 1986: Remove two underground tanks: one 750- gallon gasoline and one 750- gallon diesel (see Table 3) 1987: Relocation of car wash and related demolition	1961: Building construction 1961: Install new well pump; 4" well located inside building near southeast corner (see Table 1) 1961: Sewer connection 1961: I,000-gallon gasoline UST install west of building (see Table 3) 1961: Gas pump (for use in conjunction with new car agency and not a pubic service station) 1962: Sewer connection (2nd connection) 1967: Construct four stall garage 1969: Water service permit 1972: Water service permit 1972: Water service permit 1972: WRECKED—used car office, partially consumed by fire 1976: Building permit for commercial building 1976: Remove 9 hydraulic lifts, and remove spray booth.	Notes

Table 2B cont. W. 78th Street Commercial Property History Summary

Present- day Address	Land Use	Reference Date	Reference Number	Notes
				1989: Remove 550-gallon drain oil and 1,000-gallon gas
				"tanks" (likely USTs); gas
				tank may be 1,000-gallon UST
				installed in 1961 (see above)
				(see Table 3)
				1989: Install lube equipment,
				three ASTs inside building
				(see Table 3)
				1989: Well abandonment
				record; well location shown at
				northeast corner inside "old
				building" (not able to locate, it
				may be the well mentioned
				previously in 1961, near the
				northeast corner of the
				building) (see Table 1)
				1994: LUST closure letter
				from MPCA (#1158)
				1997: Small building near
				west side of parcel is no longer
				present

Table 2C
Knox Avenue South
Commercial Property History Summary

Table 2C cont.

Knox Avenue South

Commercial Property History Summary

		7644			address 7638)	(former	7640		7634									n			7630											Address	Present-
Iowa Paint	Olson Tool Co. (Tool Room)	Toolkraft Inc.—machinists	Office and storage—Labo (owner)	Graphic Prep (lithographers/packaging)	Minnesota Flexible Corp- indoor home and heating specialists	Barrel Finish-warehouse	Office and storage—Labo (owner)	Allied Overhead Doors—garage door dealers	(0 11101)	Office and storage—Labo									finishing/reconditioning	Barrel Finish, Incmetal										Labo (owner)	Office and warehouse	Laint Coc	I and I lea
Present	1977-1988	1967-72	1963-1964	1977 to present	1972	1967	1963-1964	1967 to present		1963-1964										1963-1988				0						1963-1964		Date	Reference
TA	CD	CD	TA, BR	CD	CD	CD	TA, BR	CD	TA, BR	BR	BR								t	R R										TA, BR		Number	Reference
			1963: Sewer connection 1963: Water service 1964: Building construction			3	1963: Sewer connection 1963: Water service 1964: Building construction		1964: Building construction	1963: Water service	1963: Sewer connection	1985: Water service permit	1978: Water service permit, following aforementioned inspection	system	potentially to potable water	siphoning or backflow of	chemical use; concern with	1978: Inspection summary:	contract basis.	not to use outdoor areas for storage. Trash is handed on a	and Barrel Finish, Inc. agreed	are manufactured for resale	rotating drums. No products	parts, water, compound, and	method. Consists of loading	deburring by the tumbling	summary: subcontract metal	move to 7630. Operation	1964: Building construction	1963: Water service permit	1963: Sewer connection	Motes	Notes

Table 2D
Logan Avenue South
Commercial Property History Summary

Present- day	Land Use	Reference	Reference	Notes
Address		Date	TAGITIDEL	
7601	Logan Manor Apartments	1963 to present	BR, TA	1963: Water service permit 1963: Sewer connection
	,	•	CD, AP	1964: Building construction
				1958: Building construction
	Masonic Lodge Hall			
7615	commercial building-R-	1958 to present	BR, CD	1965: Water service permit
	C-S Masonic Corp.			1963: Well sealing record (see Table 1)
				1961/62: Building
	Office and storage—Labo	1961-62	BR	construction
	(Owner)			1962: Sewer connection
7620	Lease Properties	1965	BR	1965: Water service permit
7027	Olson Tool and Plastics- plastic molds	1967-1988	G	
	Pioneer Plastic, Inc (associated with 7635)	1995-1999	TA	One building, two addresses
	Office and storage—Labo	1961-62	BR	1961/62: Building construction
	(owler)			1962: Sewer connection
	Lease Properties	1965	BR	1965: Water service permit
	Laundry equipment	1967	CD	
7635	Address not listed (possibly associated with 7629)	1967-1982	CD	
	Olson Tool and Plastics (associated with 7629)	1988	CD	
	Pioneer Plastic, Inc.	1992	BR	1992: Construct enclosure for water tank (7635)
	(associated with 7629)	1995-1999	TA	One building, two addresses
				1959: Sewer connection
	Labo (owner)	1959-1963	TA, BR	1960: Building construction 1963: Sewer connection
1	Acme Glass—window and plate	1969-1972	BR, CD	1969: Water service permit
(former address	Carlson Thermoplastics, Inc.—plastic fabricators (associated with 7645)	1977	CD	
(0.0)	Erickson Brothers Brokerage Co.—mfrs reps	1982	CD	
	Olson Tool and Plastics	1988	CD	
	ASAP Mailing, and Carrier [sublet] (associated with	1995-1999	TA	

Table 2D cont. Logan Avenue South Commercial Property History Summary

	7701				7700											7645							Address	Present- day	
Outdoors Again	Archery shop—sporting goods	Office-McCarthy Oldsmobile	Williams & Associates – toy mfg. Casey & Casey Insurance Inc.	lawyer	Minneapolis—contr. and J & B Equipment Co.— conveyor systems	Hoffman Electric Co. of	Farm equipment dealers	Construction Co. (owner)	building—Bor-son	Office commercial	Labo (owner)	ASAP Mailing, and Carrier (sublet) (associated with 7639)	Olson Tool and Plastics	American Independent Tire Inc.	Carlson Thermoplastics, Inc.—plastic fabricators (associated with 7639)	Witts Specialty—metal finishing			vacant in 1962)	occupied in 1961; building	(Witts Specialty Finishing	Labo (owner)		Land Use	
1994 to present	1962-1988	1995-98	1988	1977-1982	1972		1967		1959-1963		1956	1995-1999	1988	1982	1972-1977	1967	1963	1963	1961	1960	1959	1959-1963	\$ 200	Reference Date	,
TA	BR, TA, CD	TA	CD	CD	CD		CD	BR	TA	BR	BR	TA	CD	CD	CD	G	BR	BR	BR	TA, BR	BR	BR		Reference Number	
	1962: Building construction 1963: Well (2") (well log from Village of Richfield) (see Table 1) 1963: Sewer connection 1969: Water service permit							1963: Water service permit	1960: Building construction	1959: Well (2") (see Table 1)							1963: Water service permit	1963: Sewer connection	1961: Two spray booths	1960: Building construction	1959: Sewer connect	1939: Well (4") (Well log from Village of Richfield) (see Table 1)	1050 W 11 (4)	Notes	

Table 2D cont. Logan Avenue South Commercial Property History Summary

		7708			Present- day Address
Oldmobile (Car wash and tire center)	Lindahl Oldsmobile; Wally	Interstate Products— wholesale farm equipment dealers	Hoffman Electric Co.	Office and storage—Borson Construction Co. (owner)	Land Use
1977 to present		1972	1967-1971	1963	Reference Date
TA		CD	CD, BR	TA, CD, BR	Reference Number
1986: Water connection (domestic)	1986:Sewer disconnect		1971: Water service permit	1963: Building constructed	Notes

Table 2E
Morgan Avenue South
Commercial Property History Summary

Present- day Address	Land Use Office and warehouse—	Reference Reference Date Number	
7701	Labo (owner) Water softener mfgr	1960-1961 1967	TA, BR
	Carpet layers	1972	8
	Repro Printing	1977-1999	TA, CD, BR
Former Addresses 7700-7750	Multi-tenant building, including: hair salons, office space, restaurants, etc. Tenants of note are listed separately below	1967-1985	CD, AP
Former Address 7700	Glendell Co.—oil filters	1972	CD
Former Address 7704	Macken Music and Entertainment Agency	1988	CD, AP
Former Address 7708	Motion pictures producers	1962	8
Former Address 7712	Picas & Points Inc.— typesetting	1988	CD, AP
Former Address 7716	Consolidated Sales and Mfg Co.—vending mach.	1962	
Former Address 7718	Remembrance Memorials—bronze makers	1962	a.
Former Address 7732	Twin City Industrial Tool Co.	1988	CD, AP
Former	Viking Speed Wash & Cleaners—self serve	1962-77	8
Address 7746/7748	Viking Cleaners and Launders	1988	£
Former Address 7745	Rollie's Barber Shop	1972-77	G

Table 2E cont. Morgan Avenue South Commercial Property History Summary

		Connection Court of the Court o	7	
Present- day Address	Land Use	Reference Date	Reference Number	Notes
Former				Northern portion of mall
Addresses 7700-7750				building (1989) no longer present, new building present
(address	New building	1997	AP	in similar location. Parcel
changes to				becomes part of 2000 W. 78th
2000 W. 78 th St.)				St.
				1961: Sewer permit
	Office and Storage—Labo	1961-1963	BR	1961: Water piped in from 7701 Mogan Ave. S.
	(owner)			1961/63: Building
7705				construction
	Coin Tronics	1967	CD	
	Interior Communications Systems	1977-1988	CD	
	Coffee Roastery Oule	1994-1998	TA	
	Al Muellers Archery	1961	BR	1961: Sewer connection
	Center—Archery Sales and	1961-1962	TA RR	1961: Well (2") (see Table 1)
7713	Instruction	1001 1002	111, 21	1962: Building construction
	Mary Whiting	1971	BR	Water service permit
	Furniture and carpet co.	1972-1982	CD	
	Canine School	1988-1998	CD, TA	
				1965: Sewer connection
	Auto hody repair/service			1965: Water service permit
	Lindahl Olds: Wally	1065_1008	TA, BR,	1965: Building construction
7725	McCarthy's Olds	1700 1770	AP	1987: Installation of
				automotive spray booth (2
				each)
	Abra—auto body and glass	Present		

Table 2F
Newton Avenue South
Commercial Property History Summary


		7701	Present- day Address
Walser Buick	Not listed	John Saltzman— Resident/Wood dealer	Land Use
1987 to present	1977-1988	1954-1968	Reference Date
BR	CD	BR, CD, AP	Reference Number
1987: Water disconnect 1987: Sewer disconnect 1987: WRECKED-single family home		1954: Septic tank and cesspool; old well (see Table 1) 1954: Dwelling and garage construction permit 1954: One 565-gallon gas tank [UST] and pump 1954/56: WRECKED-permit to demolish dwelling; however home was still apparent in 1967 aerial photograph 1956: Sewer connection 1959: Well (2") (see Table 1) 1962: Well (2") (different well than recorded in 1959) (See Table 1)	Notes

Table 2G
Penn Avenue
Commercial Property History Summary

	Commerc	141 1 10	ber of Trisco	Colliner can kroper by Theory Summary
Present- day Address	Land Use	Reference Date	Reference Number	Notes
	J	1995	BR	Sewer disconnection
	Kay Anderson & Sons	1995	BR	Water disconnection
10/7	Walser Auto	1995	BR	WRECKED-demolition of one building
	Car lot	1996-1998	TA	
			BR	1963: Sewer connection
			BR	1963: Water connection
	Southtown Shall and			1963/64: Building
	Southtown Shell—gas	1963-1977	TA, BR,	construction
	Station		9	1964: Oil burner permit (2)
7745				1970: 8,000-gallon UST
				1973: Oil burner permit
	Walser Import Auto			1990: Removal of four 6,000-
	Dealers; Walser Suzuki	1982 to present	CD, BR,	gallon USTs
	Auto Dealers; Walser		TA	
	Leasing; Walser Hyndai			

Table 3
UST/AST Summary
Opus Development (Best Buy Campus)

Parcel	Address	Facility No.	Tank Designation	Tank Type	Volume	Contents	Status	Install Date	Removal Date	Material
			001	UST	4000	Motor oil	removed	1/1/77	8/16/99	bare/paint/asph coat steel
			002	UST	2000	Motor oil	removed	1/1/77	8/16/99	bare/paint/asph coat steel
Wally McCarthy's Oldsmobile, Inc.	1900 W 78th St.	UST: 2179; LUST: 12876	003	UST	2000	Transmission fluid	removed	1/1/77	8/16/99	bare/paint/asph coat steel
Oldomopilo, mo.		2001. 12070	004	UST	2000	Waste oil	removed	1/1/77	8/16/99	bare/paint/asph coat steel
		1	005	UST	6000	Gasoline	removed	1/1/77	8/16/99	bare/paint/asph coat steel
			006	UST	6000	gasoline	removed	1/1/77	8/16/99	bare/paint/asph coat steel
			001	UST	2000	Gasoline	removed	7/1/62	1/1/89	bare/paint/asph coat steel
			002	UST	1500	Waste oil	removed	7/1/65	1/1/89	bare/paint/asph coat steel
			003	UST	1000	Motor oil	removed	7/9/85	1/1/89	bare/paint/asph coat steel
Walser Imports (now		UST: 2009	004	UST	1000	Waste oil	active	1/1/89	NA	galvanized steel
Motorworks BMW)	2000 W 78th St.	LUST: 13186	005	UST	4000	Gasoline	inactive	4/1/88	NA	bare/paint/asph coat steel
MOTOR DIVITY)		2031. 13160	006	UST	1000	Motor oil	inactive	4/1/88	NA	bare/paint/asph coat steel
			1001	AST	300	Transmission fluid	active	1/1/1900	NA	metal
			1002	AST	600	new oil	active	1/1/1900	NA	metal
parking lot (Walser			001	UST	1000	Gasoline	removed	10/6/86	10/4/99	bare/paint/asph coat steel
Corp.)	2016 W 78th St.	UST:4121	002	UST	500	diesel fuel	removed	1/1/68	10/4/99	bare/paint/asph coat steel
			003	UST	220	Waste oil	removed	1/1/68	10/4/99	bare/paint/asph coat steel
Schmelz Volkswagen Sales and Service (located west of building)	2100 W 78th St.	unknown	unknown	UST	1000	Gasoline	unknown, possibly removed	1961	1989?	unknown
Walser Buick, Inc.	2100 W 78th St.	unknown	unknown	3 ASTs	unknown	unknown (for lube work)	unknown	1989	unknown	unknown
Walser Buick, Inc.	2100 W 78th St.	unknown	unknown	UST?	· 1000	Gasoline	removed	unknown, possibly 1961 (see above)	1989	unknown
Walser Buick, Inc.	2100 W 78th St.	LUST: 1158	unknown	unknown	unknown	unknown	unknown	unknown	unknown	unknown
Walser Buick, Inc.	2100 W 78th St.	unknown	unknown	UST	750	diesel fuel	removed	unknown	1986	unknown
Walser Buick, Inc.	2100 W 78th St.	unknown	unknown	UST	750	Gasoline	removed	unknown	1986	unknown
			100	UST	4000	Gasoline	removed	1/1/1900		bare/paint/asph coat steel
Walser Buick Isuzu	7745 Penn Ave S.	UST: 3004	200	UST	4000	Gasoline	removed	1/1/1900		bare/paint/asph coat steel
TRAISEL DUICK ISUZU	1743 FeIIII AVE S.	051:3004	300	UST	8000	Gasoline	removed	1/1/1900		bare/paint/asph coat steel
	1	1 1	400	UST	6000	diesel fuel	removed	1/1/1900		bare/paint/asph coat steel



. 1

PROPERTY LAYOUT MAP 494/Penn Avenue Richfield,MN


Figure 2

0 Sealed Commercial Well (Confirmed location) **Current Features** Commercial Well (Approximate location) Commercial Well (Confirmed location) Historical Features Scale in Feet 400

NOTE: Residential Wells Not Depicted

UST = Underground Storage Tank

AST = Aboveground Storage Tank



Appendix A

Preliminary Phase I Environmental Assessment Checklist Northeast Quadrant of I-494 and Penn Avenue Richfield, Minnesota

I. Property Information

a summary of parcel addresses and ownership. features is shown on Figure 2. The Property consists of multiple parcels, see Appendix B for Property location map is shown on Figure 1. Property layout with existing and former

Property Name: Opus—Best Buy Corporate Campus

Address: Northeast quadrant of Penn Avenue and I-494, Richfield, Minnesota

County: Hennepin County

Township/Range/Section: Section 33, Township 28 North, Range 24 West

Property Owner: Multiple owners

Property Use: Mixed residential, commercial, and industrial use

II. Physical Setting

subsequent tables Information Resources: The following resources are numbered for use as references in

- ______ U.S. Geological Survey Topographic maps (years: 1993)
- 12 (see map, logs, and available sealing records in Appendix B) Minnesota Geological Survey Well Logs and Well Location Map, State Well Index

Published Geologic Reports Used:

w Atlas Series, Atlas C-4. University of Minnesota, St. Paul, Minnesota. Balaban, N.H. (Ed.). 1989. Geologic Atlas, Hennepin County, Minnesota, County

Surface Elevation: Approximately 830 to 850 feet above mean sea level (MSL) (Reference

Stratigraphy (soils and upper bedrock units): Approximately 180 feet of unconsolidated materials including sand, gravelly sand, loamy sand; overlain by thin deposits of silt loam, or organic sediment. Thick fill may be present in heavily developed areas. Clayey

till is present at depth. The uppermost bedrock unit beneath the Property is the Prairie du Chien Group (Reference 3, 2)

south/southeasterly towards the Minnesota River, a regional discharge feature. (Reference Anticipated Groundwater Depth/Flow Direction: The surficial water table is reportedly 20 to 30 feet below the ground surface in the vicinity of the Property; water table flow is

Regional Aquifer: Regional aquifers include the Prairie du Chien-Jordan, Franconia-Ironton-Galesville, and the Mt.Simon-Hinckley. (Reference 3).

approximately 0.6 miles northwest of the Property. Wood Lake is located approximately Nearest Surface Water Body (name and distance): An unnamed wetland is located 0.6 mile north-northeast of the property. (Reference 1).

to 1,000 feet; the nearest municipal well is located approximately 2 miles northeast of the from groundwater wells located throughout the city. The wells range in depth from 400 Municipal/Property Water Supply: The City of Richfield obtains its municipal water supply Property (Reference 7).

results of the well search. Based on the potential age of wells in the area, the presence of water availability to the Property, many Property buildings have or likely have utilized Property Well Search: Based on the dates of Property building construction and municipal Property building records, was conducted for the Property. Table I summarizes the A well search, utilizing Minnesota Geological Survey well logs and additional, unidentified wells is likely. private wells.

III. Property Land-Use History

The following resources are numbered for use as references in subsequent tables. Copies of pertinent historical documentation are in Appendix B.

Primary Resources:

- Aerial photos (years: 1937, 1945, 1951, 1956, 1962, 1967, 1971, 1975, 1985, 1989, and 1997) 4
- Sanborn Maps (years: no coverage)
- Historic maps (years: 1873, 1898, 1901, 1913, 1954, 1967, 1972, and 1980) 5
- Reverse city directories (years: 1956, 1962, 1967, 1972, 1977, 1982, and 1988) 9
- X Interviews
- part of this preliminary assessment. Addenda to this report will be provided Property Owner Representative(s): No owner interviews were conducted as

when access to the Property parcels is obtained and owner interviews are conducted.

- Engineering or public works departments
- State VIC project manager (name: Karen Kromar) (name: Water Utility staff, City of Richfield)
- 9 0 State LUST project manager (name: Edwin Balcos)
- State LUST project manager (name: Laura Kania)
- State LUST project manager (name: Mark Koplitz)

Supplementary Resources:

- Municipal or County Assessor's Records
- 13 **Building or City Inspection Department Records**
- the respective parcel's addendum report.) in time for this report. When received, any relevant information will be included in Local fire department records (Requested Fire Department records were not received

Original Property Development (year/use): The Property was originally developed for photographs, possibly indicating filling activities (Reference 4). area, apparent in 1937 through 1945, was no longer present on subsequent aerial debris/disturbances were apparent in the vicinity of many of these farmsteads. A wetland on the Property by the early 1950s (Reference 4). Areas of potential surface agricultural use prior to 1937 (Reference 4, 5). Approximately eight farmsteads were located

containing materials exists. occupants; many Property occupants likely utilized ASTs or USTs for heating fuel storage. to the Property at the time of early development. Historical documents indicate many early-1950s. Sanitary sewer, municipal water, and potentially natural gas were not available In addition, based on the age of many Property buildings, the potential for asbestos Property occupants utilized private wells and septic systems, including commercial Residential, commercial, and industrial development began on the Property beginning in the

parcel development is included in Appendix B. addresses and historical features are shown on Figure 2. A summary table of residential Table 2 summarizes the commercial parcel development history by address; associated refinishing; lithographers; machinists; and plastic fabricators (Reference 4, 6, 12, 13). station; garbage collection; asphalt company; drycleaners (two separate locations); metal chemicals were identified at the Property: auto body repair, auto service and sales; gas Based on the review of available historical information, the following historic uses of

Nearby Property Chronology (year, use, reference number): The surrounding area, originally Beginning in the early-1950s, land use shifted to commercial and residential developed for agricultural use prior to 1937, supported cultivated lands and farmsteads. development. (Reference 4, 5, 6)

of the Property and Woodlake Lutheran Church is located to the north. (Reference 4, 5, not changed significantly overtime. St. Richard's Catholic Church is located northwest buildings) and residential development since the late 1950s/early 1960s. Land use has North: The land north of the Property mainly supported multi-family (i.e., apartment

South: I-494 was constructed in the late-1950s. Land south of I-494 mainly supported commercial development, consisting of large retail stores. (Reference 4, 5, 6)

first apparent in the 1967 aerial photograph. The building was no longer present in 1997; large commercial building, reportedly occupied by an outdoor advertising company, was East: The land east of the Property consisted of a large wetland/pond up until the 1960s. East/northeast of the Property supported apartment buildings since the mid-1960s. a new commercial building was under construction in 1997. (Reference 4, 5, 6)

photographs. The area west/southwest of the Property has supported a gas station since Property. A potential industrial property was apparent west of the Property in the 1967 development in the mid-1960s. Apartment buildings are located west/northwest of the West: Development shifted from agricultural development to commercial/industrial aerial photograph; however, the property was no longer visible on subsequent the mid-1970s. (Reference 4, 5, 6)

IV. Property Area Regulatory History

Date Regulatory Database Searches Performed:

14 EDR: March 8, 2000

15 PTFE: March 24, 2000

16 MPCA LUST database: April 13, 2000

17 MPCA VIC database: April 13, 2000

Copies of these regulatory the EDR and PTFE searches are in Appendix C.

Was the Property identified on any ASTM regulatory lists searched? YES

No violations	Inactive?	RCRIS-SQG: MND981200017	7748 Morgan Ave S.	O'Donnell Cleaners
No violations	Active	RCRIS-SQG: MND985741362	7725 Morgan Ave S.	Abra Auto Body & Glass
No violations	Active	RCRIS-SQG: MND055473060	7701 Morgan Ave S	Repro Printing, Inc.
No violations	Active	RCRIS-SQG: MNR000017848	7635 Logan Ave S.	Pioneer Plastics, Inc.
No violations	Active	RCRIS-SQG: MND985682772	7645 Logan Ave S.	Leaseback Properties
probably did not migrate offsite			œ	
groundwater impacts, contamination			7643 Morgan Ave	
contamination onsite, potential for TCE			·;	Properties
MPCA indicated potential for TCE soil	Inactive	VIC: 3483	7634 Knox Ave	Leaseback
1 violation (Generator – all requirements)	Active	RCRIS-SQG: MND006260053	7630 Knox Ave S.	Barrel Finish, Inc.
# MANUEL MANUEL TAILED #	Inachive	001.0004	TO A CALLA ANY C. P.	Isuzu
1 +0-1	Inochina	MINE 2007	7715 Dans Aug C	Walsor Buick
No violations	Active	RCRIS-SQG:		
onsite.			0	
MPCA indicates no contaminated soil left				
(100 yd ³ of contaminated soil also removed).				
report prepared at time of tank removal				Inc.
Closed by MPCA based on assessment	Closed	LUST: 1158	2100 W 78th St.	Walser Buick,
3 tanks removed (date unknown)	Inactive	UST: 4121	2016 W 78 th St.	parking lot (Walser Corp.)
		MND982607145		
No violations	Active	RCRIS-SQG:		
2 active tanks	Active	AST: 2009		
removed 1/1/89,				Imports
3 active tanks, 2 inactive tanks, 3 tanks	Active	UST: 2009	2000 W 78th St.	Walser
Ongoing LUST investigation	Active	LUST:13186	2000 W 78th St.	Motorworks BMW
		MND022914642		
No violations	Active	RCRIS-SQG:		Inc.
6 tanks removed 8/16/99	Inactive	UST:2179		Oldsmobile,
requested an LSI				McCarthy's
Ongoing LUST investigation, MPCA has	Active	LUST: 12776	1900 W 78th St.	Wallv
Notes/Issues	Status	List: Site ID	Address	Parcel

Adjacent/Nearby Property listings (number of sites within ASTM radius area):

- 0 Federal NPL site list (≤1.0 miles).
- 0 Federal CERCLIS list (≤0.5 miles).
- 0 Federal RCRA non-CORRACTS TSD (≤0.5 miles).
 - 9 Federal RCRA CORRACTS TSD list (≤1.0 miles).
- Federal RCRA generators list (property and adjoining properties).
 - NR Federal ERNS list (property only).
- State list of hazardous waste sites identified for investigation or remediation (NPL or CERCLIS equivalents) (<1.0 miles).
 - State landfill and/or solid waste disposal site lists (≤0.5 miles).
 - 16 State leaking UST lists (≤0.5 miles).
- State registered UST list (property and adjoining properties).

Adjacent or Potentially Upgradient Sites:

to born antimatical for the second se	suspected	contamination is reported, the site is not suspected to have potential for impacting	contamination is reported, the site	
Based on MPCA closure of site, the fact that no residual contamination remains, and no offsite	that no resi	sure of site, the fact	Based on MPCA clo	
1 tank removed 10/23/90	Inactive	UST: 14532	(sidegradient)	
in place, no offsite contamination reported			<1/16 mile west	West
MPCA indicates no contaminated soil left	Closed	LUST: 3578	7610 Penn Ave S.	Century Court
	,	th the Property.	groundwater beneath the Property	
contamination is reported, the site is not suspected to have potential for impacting soil or	suspected	ported, the site is not	contamination is re	
Based on MPCA closure of site, the fact that no residual contamination remains, and no offsite	that no res	sure of site, the fact	Based on MPCA clo	
1 tank removed 10/23/90	Inactive	UST: 14531	(sidegradient)	
in place, no offsite contamination reported			<1/16 mile west	West
MPCA indicates no contaminated soil left	Closed	LUST: 3464	7600 Penn Ave S.	Century Court
		th the Property.	groundwater beneath the Property	
contamination is reported, the site is not suspected to have potential for impacting soil or	t suspected	ported, the site is not	contamination is re	
Based on MPCA closure of site, the fact that no residual contamination remains, and no offsite	that no res	sure of site, the fact	Based on MPCA clo	
Tank abandoned in place ("filled in")	Inactive	UST: 13870	(upgradient)	
in place, no offsite contamination reported			<1/8 mile north	Richard
MPCA indicates no contaminated soil left	Closed	LUST: 3406	7540 Penn Ave S.	Church of St.
	y.	soil or groundwater beneath the Property	soil or groundwater	
not suspected to have potential for impacting	JSTs, it is 1	Since the site has no history of leaking USTs, it is	Since the site has r	
			(upgradient)	Church
			<1/8 mile north	Lutheran
2 tanks removed 6/18/90	Inactive	UST: 13934	7525 Oliver Ave S	Woodlake
		soil or groundwater beneath the Property.	soil or groundwate	
not suspected to have potential for impacting	USTs, it is	no history of leaking l	Since the site has r	
			(sidegradient)	ç
			<1/16 mile east	
3 active tanks, 3 tanks removed 7/17/95	Active	UST: 2210	7611 Knox Ave S.	Fountainhead
	groundwat	have the potential for impacting soil or _!	have the potential	
ination at the site. Therefore, the site may	ter contam:	contamination and therefore, groundwater contamination at the site.	contamination and	
Although the MPCA closed the site, MPCA staff indicates that potential exists for residual soil	CA staff in	A closed the site, MP	Although the MPC	
requirements)		MND006207260		
2 violations reported (general – all	Inactive	RCRIS-SQG:		
7 tanks removed	Inactive	UST: 3194		
exists, no offsite contamination reported.			(sidegradient)	Outdoor, Inc.)
potential for residual soil contamination			<1/16 mile east	(Universal
MPCA indicated no soils were excavated,	Closed	LUST:9913	1700 W 78th St.	Naegle Sign
			Direction	
			Distance &	
Issues	Status	List: Site ID	Address/	Site

Century Court	7620 Penn Ave S	LUST: 3577	Closed	MPCA indicates no contaminated soil left
West	<1/16 mile west			in place, no offsite contamination reported
	(sidegradient)	UST: 14533	Inactive	1 tank removed 10/26/90
	Based on MPCA clo	sure of site, the fact	that no resi	closure of site, the fact that no residual contamination remains, and no offsite
	contamination is re	ported, the site is no	t suspected	contamination is reported, the site is not suspected to have potential for impacting soil or
	groundwater beneath the Property	th the Property.		
Century Court	7700 Penn Ave S.	UST: 14543	Inactive	1 tank removed 10/25/90
West	<1/16 mile west			
	(sidegradient)			
	Since site has no hi	story of leaking UST	's, it is not s	Since site has no history of leaking USTs, it is not suspected to have potential for impacting soil
	or groundwater beneath	leath the Property.		
Century Court	7710 Penn Ave S.	LUST: 3576	Closed	MPCA indicates no contaminated soil left
West	<1/16 mile west			in place, no offsite contamination reported
	(sidegradient)	UST: 14544	Inactive	1 tank removed 10/24/90
	Based on MPCA clo	sure of site, the fact	that no resi	closure of site, the fact that no residual contamination remains, and no offsite
	contamination is re	ported, the site is no	t suspected	contamination is reported, the site is not suspected to have potential for impacting soil or
	groundwater beneath the Property	th the Property.		
Century Court	7720 Penn Ave S.	LUST: 3577	Closed	MPCA indicates no contaminated soil left
West	<1/16 mile west			in place, no offsite contamination reported
	(sidegradient)	UST: 14533	Inactive	1 tank removed 10/25/90
	Based on MPCA clo	sure of site, the fact	that no resi	Based on MPCA closure of site, the fact that no residual contamination remains, and no offsite
	contamination is re	ported, the site is no	t suspected	contamination is reported, the site is not suspected to have potential for impacting soil or
	groundwater beneath the Property.	th the Property.		
Mobile	7744 Penn Ave S.	LUST: 181	Ongoing	MPCA indicates that contaminated soils
Southtown	<1/16 mile west			remain on site and reports contamination
Service	(sidegradient)			offsite
		UST: 2427	Active	4 active tanks, 6 tanks removed
	The investigation fo	The investigation for this site is ongoing.	r. Free-pha	Free-phase product has been detected at the site and
	offsite contamination	offsite contamination has been reported.		Since the site is located adjacent and sidegradient to
		ite has the potential	for impactin	site has the potential for impacting soil and groundwater at the Property.
Goodyear Auto	2815 West 78th St	UST: 1626	Inactive	1 tank removed 5/23/96
Service Center	<1/8 mile south	RCRIS-SQG:	Active?	No violations
	(downgradient)	MND149985111		
	Since site has no history of leaking	story of leaking USTs,	s, and is loc	and is located downgradient of the Property, it is not
	suspected to have p	suspected to have potential for impacting		groundwater beneath the Property.
Montgomery	7831 Southtown	UST: 1611	Active	1 active tank, 7 tanks removed
Ward	Center	RCRIS-SQG:	Active	No violations
	<1/8 mile south	MND149836405		
	(downgradient)			
	Since site has no hi	story of leaking UST	s, and is loc	Since site has no history of leaking USTs, and is located downgradient of the Property, it is not
	suspected to have p	otential for impactin	g soil or gro	suspected to have potential for impacting soil or groundwater heneath the Property.

< **Previous Environmental Investigations**

Available previous investigation reports are reproduced in Appendix D

Wally McCarthy Oldsmobile Site

Morgan Ave. S., Richfield, Minnesota. Assessment, Burton Lindahl & Wally McCarthy Properties, 1900 W. 78th St. and 7725 Meisch & Associates (Meisch). October 14, 1999. Phase I Environmental Site

site inspection. concerning hazardous material storage, generation, and disposal; interview employees; Description of work completed: review aerial photographs; review regulatory listings

asbestos containing material observed in thermal system insulation. Meisch hydrocarbon impacts. recommended a Phase II Environmental Site Assessment (ESA) of potential petroleum oil stained floor in service area observed, floor drains in service area observed, potential Report conclusions: Former petroleum storage tank basins and dispensers were identified,

the investigation indicated that "significant" impacts to shallow groundwater were not near floor drains, a former dispenser island, and adjacent to the building. Conclusions of present, and soil contamination, although observed, did not "appear to extend to great reported. The investigation included placing 10 shallow geoprobe or hand auger borings Meisch also conducted a limited Phase II ESA, results of which have not been formally

McCarthy's Oldsmobile and Aurora, 1900 W. 78th St., Richfield, Minnesota Meisch. September 20, 1999. Excavation Worksheet for Petroleum Release Sites, Wally

Description of work completed: 6 USTs were removed from site. No soil was excavated

evidence of release from tanks. Groundwater was not encountered Report conclusions: Evidence of release observed under dispenser for tanks 5 and 6. No

Leaseback Properties Site

that TCE may be present in the groundwater, but she did not think it had migrated offsite the site that involved the use of solvents, including trichloroethylene (TCE). She suspected summary information. Ms. Kromar indicated that, at one time, manufacturing took place on this report was completed. The MPCA project manager, Karen Kromar was contacted for the VIC program on August 26, 1992. No site reports were available for review at the time Nearby domestic wells were sampled, but she did not think they had been impacted The Leaseback Properties is an inactive site in the MPCA's VIC program. The site entered

Walser Buick Site

was contacted for summary information. Mr. Balcos indicated that USTs were removed from for review at the time this report was completed. The MPCA project manager, Edwin Balcos the site in 1989, and that a tank assessment report was completed at that time. He stated that Walser Buick is a LUST site that was closed June 14, 1994. No site reports were available approximately 100 yd3 of soil were excavated at the time of tank removal and no residual inactive until 1994, when it was closed based on the results of the 1989 tank removal and contamination was left in place. No follow up monitoring was conducted. The file was assessment.

Motorwerks BMW Site

site reports were available for review at the time this report was completed. According to the BMW is located on a parcel that was formerly Walser Imports, a registered UST facility. No Motorwerks BMW is a LUST site, that is the subject of ongoing investigation. Motorwerks MPCA LUST database, no contaminated soils remain at the site, and contamination has not migrated offsite.

VI. Property Inspection

Name of Environmental Professional: Karlene French and Jessica Fitzpatrick

from public access points. Individual parcel inspections will be conducted as access to each parcel is granted; addenda to this report will be provided following the parcel inspections. The Property inspection for this preliminary assessment was conducted on March 9, 2000 Existing Property features are shown in the Property layout on Figure 2. Photographs obtained during the Property inspection are in Appendix E.

also located to the north. FountainHead apartments and Gallyan's retail store are located east multi-family housing (Colony Apartments) is located north of the Property; two churches are The Property is located in an area of mixed commercial and residential use. Residential and of the Property; I-494 is located south, with retail complexes beyond; and Century Court apartments and Citgo gas station are located west.

family housing (duplexes and apartment buildings), and commercial businesses, including car station was also observed on the southwest corner of Knox Avenue South and W. 77th Street. which was enclosed by a fence. No outdoor ASTs were observed at either the residential or During the Property inspection, most outdoor areas of the Property could be observed from the public access points, with the exception of the yard behind 7708 Knox Avenue South, The Property consists of multiple parcels that currently support residential homes, multicommercial parcels. Six to seven 55-gallon drums were observed to be stored on pallets dealerships and associated auto repair facilities, metal finishers, and plastic fabricators. list of these parcels and their current occupants are included in Appendix B. A city lift outside 7629 Logan Avenue (Pioneer Plastics).

VII. Interviews

Property Owner/Occupant (key Property manager) Interview

Not conducted during the preliminary assessment.

Local Government Interview

Date of Interview: April 14, 2000

Local Government Office: City of Richfield, Water Utilities

Staff Name: staff

Telephone Number: 612-861-9165

approximately 2 miles northeast of the Property. range in depth from 400 to 1,000 feet; the nearest municipal well is located municipal water supply from groundwater wells located throughout the city. The wells Especially Relevant Information from Interviews: The City of Richfield obtains its

State Government Interview

Date of Interview: April 13, 2000

State Government Office: Minnesota Pollution Control Agency

Staff Name: Karen Kromar

Telephone Number: (651) 297-3080

according to MPCA Website), located on the Property. Leaseback Properties (VIC Site 3483 according to PTFE, Project Number 3220

impacted by contamination. The site is inactive. domestic wells were sampled during pervious investigations and that they were not groundwater and that contamination did not migrate offsite. trichloroethylene (TCE) was done on site. She thought that TCE may be present in the conditions on site, but thought that manufacturing using solvents including Especially Relevant Information from Interviews: Ms. Kromar could not recall the exact She believed that nearby

State Government Interview

Date of Interview: April 13, 2000

State Government Office: Minnesota Pollution Control Agency

Staff Name: Edwin Balcos

Telephone Number: (651) 297-8661

Walser Buick Site (LUST Site 1158) located on the Property

treated. A Tank Assessment report was completed at the time of the tank removal. No Especially Relevant Information from Interviews: Mr. Balcos said the tanks were removed in 1989 and that approximately 100 yards³ of soil were excavated and thermally residual contamination was left in place. No follow up monitoring was conducted. The impacts to groundwater were reported and no offsite contamination was reported.

file was inactive until picked up by Mr. Balcos in 1994. The site was closed on June 14, 1994 on the basis of the 1989 Assessment Report.

State Government Interview

Date of Interview: April 13, 2000

State Government Office: Minnesota Pollution Control Agency

Staff Name: Laura Kania

Telephone Number: (651) 297-8600

Naegle Sign (Universal Outdoors) (LUST Site 9913), located adjacent to the

Property.

left on site, which may have the potential for impacting groundwater. She stated that she Especially Relevant Information from Interviews: Ms. Kania did not believe there were any impacts to groundwater, however, she did not think that any contaminated soil had been removed during the tank removals. She believes that residual contamination was guarantee that the vertical extent was defined. She said that contamination had not believed the horizontal extent of contamination was defined however, could not migrated off site. The site was closed June 13, 1997.

State Government Interview

Date of Interview: April 14, 2000

State Government Office: Minnesota Pollution Control Agency

Staff Name: Mark Koplitz

Telephone Number: (651) 296-7999

Church of St. Richard (LUST Site 3406), Century Court West (LUST Sites 3464,

3575, 3576, 3577, and 3578), Mobile Southtown Service (LUST Site 181); all are located adjacent to the Property.

Especially Relevant Information from Interviews:

Church of St Richard: Mr. Koplitz did not believe there were any impacts to groundwater and stated that no residual contamination was left on site. He also stated that no impacts were reported off site. The site was closed April 4, 1991.

and stated that no residual contamination was left on site from any of the tanks. He also Century Court West: Mr. Koplitz did not believe there were any impacts to groundwater stated that no impacts were reported off site. The sites were closed between May 24, 1991, and April 21, 1992. Mobile Southtown Service: Mr. Koplitz stated that the site is still open and is presently in monitoring well #4. Mr. Koplitz believes that passive product recovery was utilized at contamination remains on site, groundwater has been impacted, and contamination has migrated off site. In August 1994, 7 inches of free-phase product was measured in a monitoring phase. Seven or eight wells are located on or near the site. Residual Groundwater flow is to the south, toward Interstate Highway 494.

VIII. Documentation of Data Failure

Historical documentation dated prior to 1873 was not readily ascertainable for the Property,

time periods: Data gaps of greater than five years in historical documentation are present for the following

1873 to 1898 Property uses did not change during this period.

1901 to 1913 Property uses did not change during this period.

1913 to 1937 Property uses did not change during this period.

1937 to 1945 Property uses did not change during this period.

access to the Property buildings is granted. from public access points. Onsite inspections and owner interviews will be conducted when The Property inspection for this preliminary assessment was conducted on March 9, 2000

IX. Findings

that apply to the Assessment are described in Appendix F. Agreement. Company qualifications, special terms, conditions, limitations, and exceptions Program Guidance Document #8, and July 1999 Opus Northwest, LLC Master Services Barr performed this Assessment in April 2000 in conformance with the Practice, MPCA VIC

with the Property, except for the following: The Assessment revealed no evidence of recognized environmental conditions in connection

- lithographers. cleaning; metal finishing; garbage collection; metal finishing; plastic fabricators; and former gas station; auto body repair (paint booths); vehicle maintenance; dry hazardous substances: multiple current and former USTs and ASTs, including a Historic or current Property uses involving the use of petroleum compounds or
- Property, the potential for additional, unidentified wells is likely. age of many of the Property buildings and the availability of municipal water to the Approximately 64 water wells have been documented on the Property. Based on the
- document use of these systems on commercial and industrial parcels, the potential present on both residential and commercial/industrial parcels. Based on the greater than household chemical use) to these systems does exist for chemicals to have been discharged in significant quantities (e.g., removal or abandonment of these systems was not found. These systems were drainfield, or both has been documented at the Property; documentation indicating the The presence of historical on-site septic system(s) or cesspools consisting of a tank, a

- occupants likely utilized ASTs or USTs for heating fuel storage, prior to natural gas waste oil, have been identified on the Property. In addition, many former Property Multiple USTs, containing gasoline, motor oil, diesel fuel, transmission fluid, and
- Three LUST sites have been reported on the Property. One site is reportedly closed; two are currently under investigation.
- aerial photographs, was no longer apparent on subsequent photos, possibly indicating filling activities. In addition, surface debris was observed at many of the farmsteads A wetland, present on the southwest portion of the Property in the 1937 and 1945 on historic aerial photographs.
- Based on the age of the Property buildings, the potential for asbestos-containing materials exists.
- the Property, was identified as a closed LUST site; however the potential for residual following: Naegle Sign (Universal Outdoor, Inc.), formerly located east adjacent to identified as an active LUST site. Free-phase product has been detected at the site soil contamination and, therefore, groundwater contamination, exists at the site. Known, suspected, or potential impacts from adjacent Properties, including the Mobile Southtown Service [Citgo], located west adjacent to the Property, was and offsite contamination has been reported.
- approximately six to seven 55-gallon drums, stored on pallets, were observed behind During the Property inspection, conducted from the public access points, 7629 Logan Avenue (Pioneer Plastics).

Appendix B

Historical Documentation


SUMM, NALYSIS

Commercial Site Acquisitions - Best Buy Headquarters

Map Reference Number	PID	Property Owner (Use)	Property Address	Street Name	Property Type	Approx. Parcel Size (land sf)
	Territoria	1,48,41	4 1.1 1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	130 1 2 2 2 2		18,900
-7.4			== **			
noneny, o i est.	make in the second	e januaria de la secono dela secono de la secono dela secono de la secono dela secono de la secono dela secono de la secono dela secono de la secono de la secono dela secono dela secono de la secono de la secono de la secono dela secono de la secono dela secono de la secono dela secono de la secono dela secono	71.1	200 VV VS VI		1/8/7(80 11/24
	land constitution and the cons	performance Proceeding (2010) the experimental Community of the Community			all states of	BARRIAD IV POSIÇÃ
71	3302824340014	Anita S & J Companies (Ploneer Plastics)	7629	Logan Ave. South	1	14,960
72	3302824340015	Ed Cirki (ASAP Mailing Services)	7639	Logan Ave. South	1	22,848
73	3302824340002	Dall Foods Inc (Tom Thumb)		Knox Ave. South	С	12,880
74	3302824340003	William Stiles (Nichol's Electric)	i de	Knox Ave. South	C	8,540
		The Charles	340	Tulox/110. Codal	-	0,040
	1 = 322 7 ** 72		4		F. S. S.	
76	3302824340009	Leaseback Prop. Ltd. Partner	7626	Knox Ave. South		42,280
						1. 17.17.
		APPENDENCE OF SECURITY OF SECU				
	entry of making an	September 1997		To be seen		
neral s		error (Salaran)				7.5
90	3302824330094	Leaseback Prop. Ltd. Partner	7701	Morgan Ave. South		6,042
91	3302824330095	Jon & Sandra Lonneman	7705	Morgan Ave. South	С	
92	3302824330077	Mary L. Whiting		Morgan Ave. South	C	11,200 10,050
			4.7			
95	3302824330005	Mliton Westlund (Weston Associates)	7700	Logan Ave. South	С	8,710
	4	r i joy eo mai	181 AS	J		
			11			
98	3302824340007	Holmes Limited Partnership (Outdoors Again)	7701	Logan Ave. South	c	12,600

SUMMARY ANALYSIS Residential Site Acquisitions - Best Buy Headquarters

Map Reference	OIA	Property Owner	Property Address	Street Name	Property Type **	Approx. Parcel Size
1 Author	3302824330037	Church of St. Richard	7601	Penn Ave. South	4.0 R 象别	新學录9,025
2	3302824330036	Church of St. Richard (Greg Esty)	6092	Penn Ave. South	CAL H ACK	924 g 9,039
က	3302824330035	Mohamad & Beebee Sharief	7615	Penn Ave. South	œ	0706
4	3302824330034	Gladys H. Jensen	1297	Penn Ave. South	E C	0,00
2	3302824330033	James Lang		Penn Ave. South	acres L	2000
9 1	3302824330032	Somboun & vy Vorasane	7630	Penn Ave South	0	6000
	3302824330031	Oyning & Micrael Higgs		Penn Ave. South	CALL RESERVE	06201 34
	3302824330021	Sylvant & Alice Stotesberv	7600	Oliver Ave. South	æ	E 12 428
٩	3302824330022	John & Helen Cretzmeyer		Oliver Ave. South	96 H	€5₹7,429
=	3302824330023	Christopher M. Hankins	7610	Oliver Ave. South ***	R	7 7 429
12	3302824330024	Ann Louise Strub Trustee (Joseph)		Oliver Ave. South	. KF B 15.	一学了430
13	3302824330025	Esther L. Link (Esther & Thomas Haley)	7620		R + SR	* * 7.430
14	3302824330026	Paul F. & Louise J. Ragatz	सा	Ofiver Ave. South	表.H. 表	28 KT 431
15	3302824330027	Bankers Trust Co. of CA (Lucretia Smith & Thomas Brothen)	7628	A We	В	264.73 A3C
16	3302824330028	Robert & Loraine Guthe		Ave.	H C	28/1/35
17	3302824330029	Jason & Demina Popowski	7638	Oliver Ave. South	н	F. Sh. 4.33
8	3302824330030	Vuthy & Ra Kour	7601	Oliver Ave. South		200 0
6	3302824330064	HI Sedon & M Sedon		Oliver Ave South	2 10 C 2 10 C 2	- Serto 037
8 6	3302824330063	Barbara L. Gresbink		Oliver Ave. South	R	\$ \$0.10 O37
3 8	3302824330089	Elizabeth and Wendy Adams	7621	Oliver Ave. South	H 4	AND 10,038
3 8	3302824330087	James & Catherine Bergin	7627	Oliver Ave. South	P. T. R. ME.	980 OLWEN
24	3302824330062	Tracy and Kenneth Tracy	7633	Oliver Ave. South	· · · · · · · · · · · · · · · · · · ·	PC 10,040
55	3302824330061	Florence Laverne Smith	7639	Oliver Ave. South Re-	R. W.	3470,040
56	3302824330060	William & Mary Topero	7645	Oliver Ave. South 🕏 🔭	2. 10 日 300	302 6 S S S S S S S S S S S S S S S S S S
27	3302824330052	Todd W. Anondson	7600	Newton Ave. South	は新田田の	## (10 032)
28	3302824330053	Gisəla & Leonard Hardie Jr.	2092	Newton Ave. South C	新州田海	SEO 613
23	3302824330054	Rueban & Carol Tulikangas	7614	Newton Ave. South	CAN H SEC	250,011
œ	3302824330055	Levina J. Eischen 😭 🕬	7620		B. B.	10,038
31	3302824330056	John & Lavone Tinker	7626	Newton Ave. South #	S. C. H. S. S.	620 8 11 8 12 6
83	3302824330057	L. Abrahamson (James Tripp & Margaret Knutson)	7632	Newton Ave. South	1	Opp no de
83	3302824330068	Joan M. Fuller	A CONTRACTOR	Mawnon Ave. South &	Transfer of	OZA D MINES
8 8	3308284330059	Lois A. Lovdal	7601	Newton Ave. Court	DE DAME	THE PARTY OF THE
8 8	3302824330078	The Di Nelson (Daretta Honer)	7805	A	REFEREN	678 8 479
8 6	3302624330019	M. Miller & P. I Miller (Mark Miller)	7611	Newton Ave. South	B M	18.42% B.479
5 8	3302824330081	Hans Van Schaden	7617	Newton Ave. South	1000	(6条件8 480
8 8	3302824330082	-	7623	Newton Ave.: South :	P. C. B. Sec.	新新 8,481
40	3302824330083	-	7629	Newton Ave. South	1.2.1 R 機能	-TME 8,481
41	3302824330084	Gary & Patricia Hughes	7633	Newton Ave. South	B. B.	条 3 年 8 4 8 1
42	3302824330085	Elmer R. Seaberg (Mary Seaberg)	7639 & 7641	Newton Ave. South	CH C	070,040
43	3302824330086	_	7643 & 7645	Newton Ave. South	D C	**************************************
44	3302824330038		7600	Morgan Ave. South	¥.E	965,6
45	3302824330039	$\overline{}$	7608	Morgan Ave. South	6	8,296
46	3302824330040	-+	7614	Morgan Ave. South		FE 8,296
47	3302824330041	_	7620	Morgan Ave. South	E C	982'8 8'58e
8	3302824330042	_	7624	Morgan Ave. South	H	98788
£ [3302824330043	Hoger & Ione Holstad	7637	Morgan Ave South	0 2	SOC BIREFINS
3 2	3302824330044	Margareta El agermeier	7638	Morgan Ave. South	D 28.00	₹ E 10,035
25	3302824330046	Nirmalla & Doodnauth Dial	7642	7642 Morgan Ave. South	D	- 10,035
53	3302824330090	David Bakke & Lydia Bakke	7601	Morgan Ave. South	A Re	10,035
22	3302824330091	Chris & Chrisse Borneman	2609	Morgan Ave. South ::	金属 日本の	8860年表
55		Stanley & Lorraine Schreyer	7615	Morgan	R	202,818
26	3302824330048	Maurice & Sandra Engen	7621	Morgan	B AN	公司 8,702
22	3302824330049	Donna & Daniel Koch	7625	Morgan Ave.	В	4.87.8702
28	3302824330050	$\overline{}$	7629	Morgan	H SEC	WW 8,702
22	3302824330051	Genet & Roman Abebe	7639		O	F. 200,041
09	3302824330004		/645 & /64/	Morgan Ave.	2	13,034
61	3302824330001	_	7608 & 7610	76th Street West		22 7 1 1 2 2 2 2 1 1 2 2 2 2 2 2 2 2 2 2
29 8	3302824330002	-	7608 & 7610		0 0	+01 0 \$ 10 c
2 2	3302824330015	_	7620	Logari Ave. South	0	2,000 2,000
# F	3302824330016	Jon & Mary Jo Strait	7626 & 7628		D	(表) 9.812
99	3302824330018		7632	Logan Ave. South	D	4.813
67	3302824330019	_	7636 & 7638	Logan Ave. South	٥	图 48的9,814,
89	3302824330020	Kevin L. Anderson Et al	7644	Logan Ave. South	۵	9,815
		TOTALS / AVERAGE				624,422



1-494






Campus NE Quadrant, 494 and Penn Avenue Richfield, Minnesota


Opus-Best Buy Corporate

1937

Project Number: 23/23 C01 PHI










1945

Project Number: 23/23 C01 PHI









1951

Project Number: 23/23 C01 PHI









1956

Project Number: 23/23 C01 PHI




×






1962

Project Number: 23/23 C01 PHI








1967

Project Number: 23/23 C01 PHI









1975

Project Number: 23/23 C01 PHI








1985

Project Number: 23/23 C01 PHI








1989

Project Number: 23/23 C01 PHI

Approximate Scale 1:1,800 (1"=150')







1997

Project Number: 23/23 C01 PHI

