



# Minnesota Pollution Control Agency

October 23, 2000

**CERTIFIED MAIL NO. Z 267 206 671  
RETURN RECEIPT REQUESTED**

Mr. Albert Storkamp  
Storkamp Garage  
13791 260<sup>th</sup> Avenue  
Pierz, MN 56364

RE: Petroleum Storage Tank Release Investigation and Corrective Action  
Site: Storkamp Garage, Highway 25 S, Genola  
Site ID#: LEAK00011764

Dear Mr. Storkamp:

On September 9, 1998, the Minnesota Pollution Control Agency (MPCA) staff was notified that a release of petroleum occurred from storage tank facilities that you own and/or operate at the site referenced above.

A recent review of our files indicates that we have not heard from you whether you intend to investigate and if necessary, clean up the petroleum contamination at this site. We again ask that you respond verbally or in writing to this letter and describe the status of your investigation and/or cleanup, or explain why no action has been taken. You must respond within 30 days of receipt of this letter. Failure to do so may result in reduced reimbursement from the Petrofund and/or enforcement action taken against you by the MPCA.

If you have questions regarding the actions requested by the MPCA, or if you conclude that the release is not from any tank which you have owned or operated, please call me at (218) 828-6118. Otherwise, I look forward to receiving your reply.

If you have not already done so, we recommend that you hire a qualified consulting firm registered with the Petro Board that has experience in conducting petroleum release site investigations and in proposing and implementing appropriate corrective actions. A list of registered contractors is available from the Department of Commerce. Please note that, under Minn. R. 2890 (Supp. 1997), you must solicit a minimum of two competitive proposals on a form prescribed by the Petro Board to ensure that the consulting costs are reasonable. Questions about bidding requirements should be directed to Petro Board staff. The phone number for the Department of Commerce and the Petro Board staff is (651) 297-1119.

Official File Stamp	
File Name _____	
File Number _____	
Page # _____	Staff _____
Category _____	

Mr. Albert Storkamp

Page 2

October 23, 2000

Please refer to MPCA fact sheets for information regarding the scope of investigations required at petroleum release sites. MPCA staff requires that the site investigation fully define the extent and magnitude of soil and ground water contamination caused by the release. We reserve the right to reject proposed corrective actions if the requirements of the site investigation have not been fulfilled. If you have any questions concerning this letter or need additional information, please call me at (218) 828-6118. Please reference the above LEAK # in all correspondence.

Sincerely,



Sandra L. Miller-Moren

Project Manager

Remediation Unit

North District – Brainerd Subdistrict Office

SLM:dlp

cc: Leonard Wimmer, City Clerk, Genola  
Roger Kuklok, Morrison County Solid Waste Officer, Little Falls  
Jan Deick, Northern Environmental, Brainerd

SENDER: COMPLETE THIS SECTION		COMPLETE THIS SECTION ON DELIVERY	
<input type="checkbox"/> Complete items 1, 2, and 3. Also complete item 4 if Restricted Delivery is desired. <input type="checkbox"/> Print your name and address on the reverse so that we can return the card to you. <input type="checkbox"/> Attach this card to the back of the mailpiece, or on the front if space permits. S. MILLER		A. Received by (Please Print Clearly) <b>ALBERT STORKAMP</b> B. Date of Delivery <b>10-26-00</b> C. Signature <i>[Signature]</i> <input type="checkbox"/> Agent <input checked="" type="checkbox"/> Address	
1. Article Addressed to:  MR. ALBERT STORKAMP 13791 260th AVE PIERZ MN 56364  <div style="text-align: right; font-size: 2em; font-family: cursive;">11764</div>		D. Is delivery address different from item 1? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No If YES, enter delivery address below:	
2. Article Number (Copy from service label) Z 267 206 671		3. Service Type <input checked="" type="checkbox"/> Certified Mail <input type="checkbox"/> Express Mail <input type="checkbox"/> Registered <input type="checkbox"/> Return Receipt for Merchandise <input type="checkbox"/> Insured Mail <input type="checkbox"/> C.O.D.	
		4. Restricted Delivery? (Extra Fee) <input type="checkbox"/> Yes	

PS Form 3811, July 1999

Domestic Return Receipt

102595-00-M-0952

S. Miller-Moren  
Z 267 206 671

US Postal Service  
**Receipt for Certified Mail**  
 No Insurance Coverage Provided.  
 Do not use for International Mail (See reverse).

Sent to	
MR ALBERT STORKAMP	
Street & Number	
13791 260th AVE	
Post Office, State, & ZIP Code	
PIERZ MN 56364	
Postage	\$ .33
Certified Fee	1.40
Special Delivery Fee	
Restricted Delivery Fee	
Return Receipt Showing to Whom & Date Delivered	1.25
Return Receipt Showing to Whom, Date, & Addressee's Address	
<b>TOTAL Postage &amp; Fees</b>	<b>\$ 2.98</b>
Postmark or Date	

PS Form 3800, April 1995