

Leaksite ID# 4981	Tank Facility ID
INTERNATIONAL PLAZA	INTERNATIONAL PLAZA
Site Name	Responsible Party

LEAKSITE REMARKS

- 10/17/91: DKM-Leak notification - Chuck Bohrer (RP; 854-8894).
02/03/92: DKM-Kevin Pierson (TCT) called with question on parameters to analyze for in the elevator shaft ground water. THC as FO, VOC's. Also, PCB's if present in the hydraulic oil.
02/05/92: DKM-Standard Letter mailed.
02/10/92: DKM-Received fax of workplan from TCT.
02/12/92: DKM-Called Chuck Bohrer (RP), he should recover free product ASAP, I will be sending him letter stating this requirement. Also, we do not review workplans. He should go ahead with RI. Two bids are required for reimbursement.
02/18/92: DKM-MAILED "Free Product" letter.
02/26/92: DKM-RECEIVED Closure Request report dated 2/21/92, from TCT.
02/28/92: DKM-Submitted report dated 2/21/92 for hydro review. (SCT #1)
03/02/92: DKM-Called Kevin Pierson (TCT), regarding need for final water analysis following pumping of water to sanitary sewer. He said sample has already been taken; will send in results. No written response from MPCA will be sent.
08/19/92: DKM-Kevin Pierson (TCT) called, regarding status. I reminded him of 3/2/92 phone conversation. He will send in results.
10/14/92: DKM-Called Kevin Pierson (TCT), still waiting for water analysis. Kevin will send in results w/ closure report.
04/29/93: DKM-RECEIVED Closure Request report dated 3/31/92, including water quality results requested 3/2/92. Submit for hydro review (SCT #2).
07/17/93: SCT-Completed review. Recommended closure.
07/20/93: DKM-Submit "Closure" letter for typing.
07/27/93: TSL-MAILED Site Closure letter.

End of Remarks