

WETLAND DETERMINATION DATA FORM - Northcentral and Northeast Region

Project/Site: Sandpiper City/County: Cass Sampling Date: 06/10/2014
 Applicant/Owner: Enbridge State: MN Sampling Point: CA084_512h1U
 Investigator(s): ZCW Section, Township, Range: _____
 Landform (hillslope, terrace, etc.): Sideslope Local relief (concave, convex, none): Convex/Linear
 Slope (%): 2 Lat.: _____ Long.: _____ Datum: _____
 Soil Map Unit Name: _____ NWI Classification: _____
 Are climatic/hydrologic conditions of the site typical for this time of the year? No (If no, explain in remarks)
 Are vegetation _____, soil _____, or hydrology _____ significantly disturbed? Are "normal
 Are vegetation _____, soil _____, or hydrology _____ naturally problematic? circumstances" present? Yes
 (If needed, explain any answers in remarks)

SUMMARY OF FINDINGS

Hydrophytic vegetation present? <u>N</u> Hydric soil present? <u>N</u> Indicators of wetland hydrology present? <u>N</u>	Is the sampled area within a wetland? <u>N</u> If yes, optional wetland site ID: _____
Remarks: (Explain alternative procedures here or in a separate report.) Minnesota Climatology Working Group indicates prior three months are below normal precipitation (dry) based on a wetland delineation precipitation data retrieval by location.	

HYDROLOGY

Primary Indicators (minimum of one is required; check all that apply) ☐ Surface Water (A1) ☐ High Water Table (A2) ☐ Saturation (A3) ☐ Water Marks (B1) ☐ Sediment Deposits (B2) ☐ Drift Deposits (B3) ☐ Algal Mat or Crust (B4) ☐ Iron Deposits (B5) ☐ Inundation Visible on Aerial Imagery (B7) ☐ Sparsely Vegetated Concave Surface (B8) ☐ Water-Stained Leaves (B9) ☐ Aquatic Fauna (B13) ☐ Marl Deposits (B15) ☐ Hydrogen Sulfide Odor (C1) ☐ Oxidized Rhizospheres on Living Roots (C3) ☐ Presence of Reduced Iron (C4) ☐ Recent Iron Reduction in Tilled Soils (C6) ☐ Thin Muck Surface (C7) ☐ Other (Explain in Remarks)	Secondary Indicators (minimum of two required) ☐ Surface Soil Cracks (B6) ☐ Drainage Patterns (B10) ☐ Moss Trim Lines (B16) ☐ Dry-Season Water Table (C2) ☐ Crayfish Burrows (C8) ☐ Saturation Visible on Aerial Imagery (C9) ☐ Stunted or Stressed Plants (D1) ☐ Geomorphic Position (D2) ☐ Shallow Aquitard (D3) ☐ FAC-Neutral Test (D5) ☐ Microtopographic Relief (D4)
Field Observations: Surface water present? Yes <u>X</u> No <u>X</u> Depth (inches): _____ Water table present? Yes <u>X</u> No _____ Depth (inches): <u>19</u> Saturation present? Yes <u>X</u> No _____ Depth (inches): <u>16</u> (includes capillary fringe)	Indicators of wetland hydrology present? <u>N</u>
Describe recorded data (stream gauge, monitoring well, aerial photos, previous inspections), if available:	
Remarks:	