

WETLAND DETERMINATION DATA FORM - Northcentral and Northeast Region

Project/Site: SPP City/County: Cass Sampling Date: 9/19/2014
 Applicant/Owner: Enbridge State: MN Sampling Point: CAC5001_510a1W
 Investigator(s): NTT/BEH Section, Township, Range: _____
 Landform (hillslope, terrace, etc.): Dip Local relief (concave, convex, none) CC
 Slope (%): 3 - 7% Lat.: 46.789725 Long.: -94.774728 Datum: _____
 Soil Map Unit Name: 202 NWI Classification: PSS1C
 Are climatic/hydrologic conditions of the site typical for this time of the year? ☒ (If no, explain in remarks)
 Are vegetation ☐, soil ☐, or hydrology ☐ significantly disturbed? Are "normal
 Are vegetation ☐, soil ☐, or hydrology ☐ naturally problematic? circumstances" present? ☒
 (If needed, explain any answers in remarks)

SUMMARY OF FINDINGS

Hydrophytic vegetation present? <u>Y</u> Hydric soil present? <u>Y</u> Indicators of wetland hydrology present? <u>Y</u>	Is the sampled area within a wetland? <u>Y</u> If yes, optional wetland site ID: _____
Remarks: (Explain alternative procedures here or in a separate report.) The wetland is an alder thicket that runs along a roadside. Vegetation is dominated by alder with ferns in the ground layer.	

HYDROLOGY

Primary Indicators (minimum of one is required; check all that apply)		Secondary Indicators (minimum of two required)	
☐ Surface Water (A1) ☐ High Water Table (A2) ☐ Saturation (A3) ☐ Water Marks (B1) ☐ Sediment Deposits (B2) ☐ Drift Deposits (B3) ☐ Algal Mat or Crust (B4) ☐ Iron Deposits (B5) ☐ Inundation Visible on Aerial Imagery (B7) ☐ Sparsely Vegetated Concave Surface (B8)	☐ Water-Stained Leaves (B9) ☐ Aquatic Fauna (B13) ☐ Marl Deposits (B15) ☐ Hydrogen Sulfide Odor (C1) ☐ Oxidized Rhizospheres on Living Roots (C3) ☐ Presence of Reduced Iron (C4) ☐ Recent Iron Reduction in Tilled Soils (C6) ☐ Thin Muck Surface (C7) ☐ Other (Explain in Remarks)	☐ Surface Soil Cracks (B6) ☐ Drainage Patterns (B10) ☐ Moss Trim Lines (B16) ☐ Dry-Season Water Table (C2) ☐ Crayfish Burrows (C8) ☐ Saturation Visible on Aerial Imagery (C9) ☐ Stunted or Stressed Plants (D1) ☒ Geomorphic Position (D2) ☐ Shallow Aquitard (D3) ☐ Microtopographic Relief (D4) ☒ FAC-Neutral Test (D5)	
Field Observations: Surface water present? Yes ☐ Depth (inches): _____ Water table present? Yes ☐ Depth (inches): _____ Saturation present? Yes ☐ Depth (inches): _____ (includes capillary fringe)		Indicators of wetland hydrology present? <u>Y</u>	
Describe recorded data (stream gauge, monitoring well, aerial photos, previous inspections), if available:			
Remarks: No primary hydrology indicators were observed. Wetland hydrology is assumed based on vegetation and landscape position.			