WETLAND DETERMINATION DATA FORM
Great Plains Region

Project/Site:	L3R		Date: 06/28/14
Applicant:	Enbridge		County: Kittson
Investigators:	BCS/BEH	Subregion (MLRA or LRR): MLRA 56	State: MN
Soil Unit:	I248A	NWI Classification:	
Landform:	Talf	Local Relief: LL	Sample Point: **u-160n50w15-b1**
Slope (%):	0 - 2%	Latitude: 48.68892855 Longitude: -97.0933244492 Datum:	
Are climatic/hydrologic conditions on the site typical for this time of year? (If no, explain in remarks)		☐Yes ☑ No	Section:
Are Vegetation ☐ Soil ☑ or Hydrology ☐ignificantly disturbed?		Are normal circumstances present?	Township:
Are Vegetation ☐ Soil ☐ or Hydrology ☐aturally problematic?		☑ Yes ☐No	Range: Dir:

SUMMARY OF FINDINGS

Hydrophytic Vegetation Present? No — Hydric Soils Present? No

Wetland Hydrology Present? Yes — Is This Sampling Point Within A Wetland? **No**

Remarks: The upland sample point is located in a CRP field which is dominated by big bluestem and timothy. The area is adjacent to a pre-existing pipeline corridor and appears to lie over spoil from previous construction activities, which have significantly disturbed the soil.

HYDROLOGY

Wetland Hydrology Indicators (Check all that apply; Minimum of one primary or two secondary required):

Primary:
- ☐ A1 - Surface Water
- ☑ A2 - High Water Table
- ☑ A3 - Saturation
- ☐ B1 - Water Marks
- ☐ B2 - Sediment Deposits
- ☐ B3 - Drift Deposits
- ☐ B4 - Algal Mat or Crust
- ☐ B5 - Iron Deposits
- ☐ B7 - Inundation Visible on Aerial Imagery
- ☐ B9 - Water-Stained Leaves
- ☐ B11 - Salt Crust
- ☐ B13 - Aquatic Fauna
- ☐ C1 - Hydrogen Sulfide Odor
- ☐ C2 - Dry Season Water Table
- ☐ C3 - Oxidized Rhizospheres on Living Roots (not till
- ☐ C4 - Presence of Reduced Iron
- ☐ C7 - Thin Muck Surface
- ☐ Other (Explain)

Secondary:
- ☐ B6 - Surface Soil Cracks
- ☐ B8 - Sparsely Vegetated Concave Surface
- ☐ B10 - Drainage Patterns
- ☐ C3 - Oxidized Rhizospheres on Living Roots (tilled)
- ☐ C8 - Crayfish Burrows
- ☐ C9 - Saturation Visible on Aerial Imagery
- ☐ D2 - Geomorphic Position
- ☐ D5 - FAC-Neutral Test
- ☐ D7 - Frost-Heaved Hummocks (LRR F)

Field Observations:

Surface Water Present?	Yes	☐	Depth:	(in.)
Water Table Present?	Yes	☑	Depth: 8	(in.)
Saturation Present?	Yes	☑	Depth: 6	(in.)

Wetland Hydrology Present? Y

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks: Saturation is present at 6 inches, and a high water table is present at 8 inches. Recent heavy rainfall has likely elevated the water table in the area.

SOILS

Profile Description (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

(Type: C=Concentration, D=Depletion, RM=Reduced Matrix, CS=Covered/Coated Sand Grains; Location: PL=Pore Lining, M=Matrix)

Depth (In.)	Matrix Color (Moist)		%	Mottles Color (Moist)		%	Type	Location	Texture	Remarks
0-7	Hue_10YR	2/1	100						C	
7-15	Hue_10YR	2/1	60						C	
7-15	Hue_2.5Y	5/3	38	Hue_10YR	6/6	2	C	M	C	
15-21	Hue_2.5Y	2.5/1	90						C	
15-21	Hue_2.5Y	5/3	10						C	

NRCS Hydric Soil Field Indicators (check here if indicators are not present): ☐

- ☐ A1- Histosol
- ☐ A2 - Histic Epipedon
- ☐ A3 - Black Histic
- ☐ A4 - Hydrogen Sulfide
- ☐ A5 - Stratified Layers (LRR F)
- ☐ A9 - 1 cm Muck (LRR FGH)
- ☐ A11 - Depleted Below Dark Surface
- ☐ A12 - Thick Dark Surface
- ☐ S1 - Sandy Mucky Mineral
- ☐ S2 - 2.5 cm Mucky Peat or Peat (LRR G, H)
- ☐ S3 - 5 cm Mucky Peat or Peat (LRR F)
- ☐ S4 - Sandy Gleyed Matrix
- ☐ S5 - Sandy Redox
- ☐ S6 - Stripped Matrix
- ☐ F1 - Loamy Mucky Mineral
- ☐ F2 - Loamy Gleyed Matrix
- ☐ F3 - Depleted Matrix
- ☐ F6 - Redox Dark Surface
- ☐ F7 - Depleted Dark Surface
- ☐ F8 - Redox Depressions
- ☐ F16 - High Plains Depressions (MLRA 72, 73 of LRR H)

Indicators for Problematic Soils[1]
- ☐ A9 - 1 cm Muck (LRR I, J)
- ☐ A16 - Cost Prairie Redox (LRR F, G, H)
- ☐ S7 - Dark Surface (LRR G)
- ☐ F16 - High Plains Depressions (LRR H, outisde MLRA 72, 73)
- ☐ F18 - Reduced Vertic
- ☐ TF2 - Red Parent Material
- ☐ TF12 - Very Shallow Dark Surface
- ☐ Other (Explain in Remarks)

[1]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer Type: Depth: — **Hydric Soil Present?** N

Remarks: The soil profile consists of a dark clay surface layer over a dark clay which is significantly mixed with a lighter clay containing 2% redox. The soil appears to be disturbed by past construction activities. No hydric soil indicators were observed.

WETLAND DETERMINATION DATA FORM
Great Plains Region

Project/Site: L3R | Sample Point: u-160n50w15-b1

VEGETATION (Species identified in all uppercase are non-native species.)

Tree Stratum (Plot size: 30 ft. radius)

	Species Name	% Cover	Dominant	Ind.Status
1.				
2.				
3.				
4.				
5.				
6.				
7.				
8.				
9.				
10.				
	Total Cover =	0		

Sapling/Shrub Stratum (Plot size: 15 ft. radius)

1.				
2.				
3.				
4.				
5.				
6.				
7.				
8.				
9.				
10.				
	Total Cover =	0		

Herb Stratum (Plot size: 5 ft. radius)

1.	*Andropogon gerardii*	35	Y	FACU
2.	*Phleum pratense*	35	Y	FACU
3.	*Elymus trachycaulus*	15	N	FACU
4.	*Cirsium arvense*	5	N	FACU
5.	*Melilotus officinalis*	2	N	FACU
6				
7.				
8.				
9.				
10.				
11.				
12.				
13.				
14.				
15.				
	Total Cover =	92		

Woody Vine Stratum (Plot size: 30 ft. radius)

1.				
2.				
3.				
5.				
4.				
	Total Cover =	0		

Dominance Test Worksheet

Number of Dominant Species that are OBL, FACW, or FAC: 0 (A)

Total Number of Dominant Species Across All Strata: 2 (B)

Percent of Dominant Species That Are OBL, FACW, or FAC: ***0.0%*** (A/B)

Prevalence Index Worksheet

Total % Cover of:		Multiply by:	
OBL spp.	0	x 1 =	0
FACW spp.	0	x 2 =	0
FAC spp.	0	x 3 =	0
FACU spp.	92	x 4 =	368
UPL spp.	0	x 5 =	0
Total	92 (A)		368 (B)

Prevalence Index = B/A = ***4.000***

Hydrophytic Vegetation Indicators:

_____ Rapid Test for Hydrophytic Vegetation
_____ Dominance Test is > 50%
_____ Prevalence Index is ≤ 3.0 *
_____ Morphological Adaptations (Explain) *
_____ Problem Hydrophytic Vegetation (Explain) *

* Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.

Definitions of Vegetation Strata:

Tree - Woody plants 3 in. (7.6cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/Shrub - Woody plants less than 3 in. DBH, regardless of height.

Herb - All herbaceous (non-woody) plants, regardless of size.

Woody Vines - All woody vines, regardless of height.

Hydrophytic Vegetation Present? N

Remarks: The upland sample point is dominated by big bluestem, timothy, and slender wheatgrass.

Additional Remarks: