WETLAND DETERMINATION DATA FORM - North Central and Northeast Region

Project/Site: SPP City/County: Wadena Sampling Date: 2015-07-20

Applicant/Owner: Enbridge State: Minnesota Sampling Point: WA002b1U

Investigator(s): ACM/BCS Section, Township, Range:

Landform (hillslope, terrace, etc.): rise Local Relief (concave, convex, none): VV Slope (%): 0-2

Subregion (LRR or MLRA): LRR K Latitude: 46.8007720169... Longitude: -94.92551165... Datum: Minnesota State ...

Soil Map Unit Name: 458E NWI Classification: PSS1C

Are climatic/hydrologic conditions on the site typical for this time of year? (if no, explain in Remarks): Yes

Are Vegetation No, Soil No, or Hydrology No significantly disturbed? Are "Normal Circumstances" present? Yes

Are Vegetation No, Soil No, or Hydrology No naturally problematic? (If needed, explain any answers in Remarks)

SUMMARY OF FINDINGS - **Attach site map showing sampling point locations, transects, important features, etc.**

Hydrophytic Vegetation Present?	No	**Is the Sampled Area**	
Hydric Soil Present?	No	**within a Wetland?**	No
Wetland Hydrology Present?	No	If yes, optional Wetland Site ID:	

Remarks: (Explain alternative procedures here or in a separate report.)

Upland sample area located within a bur oak forest in a mapped NWI; the wetland exists just outside of the survey corridor to the southwest.

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one is required; check all that apply)

- ____ Surface Water (A1)
- ____ High Water Table (A2)
- ____ Saturation (A3)
- ____ Water Marks (B1)
- ____ Sediment Deposits (B2)
- ____ Drift Deposits (B3)
- ____ Algal Mat or Crust (B4)
- ____ Iron Deposits (B5)
- ____ Inundation Visible on Aerial Imagery (B7)
- ____ Sparsely Vegetated Concave Surface (B8)
- ____ Water-Stained Leaves (B9)
- ____ Aquatic Fauna (B13)
- ____ Marl Deposits (B15)
- ____ Hydrogen Sulfide Odor (C1)
- ____ Oxidized Rhizospheres on Living Roots (C3)
- ____ Presence of Reduced Iron (C4)
- ____ Recent Iron Reduction in Tilled Soils (C6)
- ____ Thin Muck Surface (C7)
- ____ Other (Explain in Remarks)

Secondary Indicators (minimum of two required)

- ____ Surface Soil Cracks (B6)
- ____ Drainage Patterns (B10)
- ____ Moss Trim Lines (B16)
- ____ Dry-Season Water Table (C2)
- ____ Crayfish Burrows (C8)
- ____ Saturation Visible on Aerial Imagery (C9)
- ____ Stunted/Stressed Plants (D1)
- ____ Geomorphic Position (D2)
- ____ Shallow Aquitard (D3)
- ____ Microtopographic Relief (D4)
- ____ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present?	No	Depth (inches) ____
Water Table Present?	No	Depth (inches) ____
Saturation Present? (includes capillary fringe)	No	Depth (inches) ____

Wetland Hydrology Present? No

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:

No primary or secondary wetland hydrology indicators were observed.

VEGETATION - Use scientific names of plants.

Sampling Point: WA002b1U

Tree Stratum (Plot Size: 30 ft)	Absolute % Cover	Dominant Species?	Indicator Status
1. Quercus macrocarpa	50.00	Yes	FACU
2. Pinus resinosa	10.00	No	FACU
3. Quercus rubra	5.00	No	FACU
4.	5.00	No	FACU
5.			
6. Populus tremuloides			
7.			
	70	= Total Cover	
Sapling/Shrub Stratum (Plot Size: 15 ft)			
1. Quercus macrocarpa	5.00	Yes	FACU
2. Amelanchier alnifolia	5.00	Yes	FACU
3. Viburnum rafinesquianum	5.00	Yes	
4. Corylus cornuta	2.00	No	FACU
5.			
6.			
7.			
	17	= Total Cover	
Herb Stratum (Plot Size: 5 ft)			
1. Quercus macrocarpa	10.00	Yes	FACU
2. Aralia nudicaulis	5.00	No	FACU
3. Corylus cornuta	5.00	No	FACU
4. Maianthemum canadense	2.00	No	FACU
5. Toxicodendron rydbergii	2.00	No	FAC
6. Amelanchier alnifolia	2.00	No	FACU
7. Rubus pubescens	1.00	No	FACW
8.			
9.			
10.			
11.			
12.			
	27	= Total Cover	
Woody Vine Stratum (Plot Size: 30 ft)			
1.			
2.			
3.			
4.			
	0	=Total Cover	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC: 0 (A)

Total Number of Dominant Species Across All Strata: 3 (B)

Percent of Dominant Species That Are OBL, FACW, or FAC: 0 (A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply by:	
OBL species	0.00	x 1	0
FACW species	1.00	x 2	2
FACU species	2.00	x 3	424
UPL species	5.00	x 4	25
Column Totals	114 (A)		457 (B)

Prevalence Index = B/A = 4.0087719...

Hydrophytic Vegetation Indicators:

____ 1 - Rapid Test for Hydrophytic Vegetation

no 2 - Dominance Test is > 50%

no 3 - Prevalence Index is ≤ 3.0[1]

____ 4 - Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)

Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.

Definitions of Vegetation Strata:

Tree - Woody plants 3 in. (.76 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/Shrub - Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall.

Herb - All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody vines - All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present? ____

Remarks: (include photo numbers here or on a separate sheet.)

Sample area is dominated by bur oak.

SOIL

Sampling Point: WA002b1U

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth	Matrix		Redox Features					
(inches)	Color (moist)	%	Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
0-16	10YR 2 1	100					FSL	
16-24	10YR 2 1	80					FSL	
16-24	2.5Y 6 3	20					FSL	Mixed matrix.

[1]Type: C=Concentration, D=Depletion, RM=Reduced Matrix, MS=Masked Sand Grains.

[2]Location: PL=Pore Lining, M=Matrix.

Hydric Soil Indicators:

- ☐ Histosol (A1)
- ☐ Histic Epipedon (A2)
- ☐ Black Histic (A3)
- ☐ Hydrogen Sulfide (A4)
- ☐ Stratified Layers (A5)
- ☐ Depleted Below Dark Surface (A11)
- ☐ Thick Dark Surface (A12)
- ☐ Sandy Mucky Mineral (S1)
- ☐ Sandy Gleyed Matrix (S4)
- ☐ Sandy Redox (S5)
- ☐ Stripped Matrix (S6)
- ☐ Dark Surface (S7) **(LRR R, MLRA 149B)**
- ☐ Polyvalue Below Surface (S8) **(LRR R, MLRA 149B)**
- ☐ Thin Dark Surface (S9) **(LRR R, MLRA 149B)**
- ☐ Loamy Mucky Mineral (F1) **(LRR K, L)**
- ☐ Loamy Gleyed Matrix (F2)
- ☐ Depleted Matrix (F3)
- ☐ Redox Dark Surface (F6)
- ☐ Depleted Dark Surface (F7)
- ☐ Redox Depressions (F8)

Indicators for Problematic Hydric Soil[3]:

- ☐ 2 cm Muck (A10) (**LRR K, L, MLRA 149B**)
- ☐ Coast Prairie Redox (A16)(**LRR K, L, R**)
- ☐ 5 cm Mucky Peat or Peat (S3) (**LRR K, L, R**)
- ☐ Dark Surface (S7) (**LRR K, M**)
- ☐ Polyvalue Below Surface (S8) **(LRR K, L)**
- ☐ Thin Dark Surface (S9) (**LRR K, L**)
- ☐ Iron-Maganese Masses (F12) (LRR K, L, R)
- ☐ Piedmont Floodplain Soils (F19) **(MLRA 149B)**
- ☐ Mesic Spodic (TA6) **(MLRA 144A, 145, 149B)**
- ☐ Red Parent Material (F21)
- ☐ Very Shallow Dark Surface (TF12)
- ☐ Other (explain in remarks)

Restrictive Layer (if observed): ☐

Type: _____

Depth (inches): _____

Hydric Soil Present? No

Remarks:

The observed profile consists of a black fine sandy loam underlain by a mixed fine sandy loam.