

STATE OF MINNESOTA

Department of Public Safety - Division of Emergency Management
444 Cedar St. Suite 223 St. Paul, MN 55101

MINNESOTA DUTY OFFICER

HAZARDOUS MATERIAL INCIDENT REPORT: TANKS

Report #:	Report Date: 6/20/02	Report Time:	DO#:
-----------	----------------------	--------------	------

Caller Information:

Name: Nancy Badle
Company: MNDOT
Address: 395 John Ireland Blvd

Responsible Party/Property Owner:

Name:
Company:
Address:

City: St. Paul
Phone: 284-3781
Alt. Phone:

Ext:
Ext:

State: MN
Zip: 55155

City:
Phone:
Alt. Phone:

State:
Ext: Zip
Ext:

Site Location:

Site Name: Phillips 66 MNDOT Site

Site Address: 1181 W Hwy 210

Site City: Baxter

Site County: Crow Wing

Site Zip: 56401

Site Information:

Discovery Date: 6/20/02

Discovery Time:

Previously Reported Site?

Leak #:

Tank Information:

ENTERED JUL 25 2002

NO Letter
File Only

Native Soil Type: Sand

Monitoring Wells on Site?:

Contaminated Soil Excavated?

Ground Water Encountered?: yes

Free Product Found? NO

Highest Vapor Reading: None

Surface Water Nearby?:

Site Water Source: man

Quantity:

Able to dig out Contamination?

Depth to Ground Water: 20'

Stained Soils?: NO

Petroleum Odors?: yes

Analytical Results:

If this incident involves an A.S.T. is there secondary containment around the tank.

Narrative: MNDOT doing assessment along Hwy 210 for future bike trail. In front of Phillips 66 (former Lakeland Ready mix) detected sheets Petro in ground H₂O. 990 ppb DEO. This is also adjacent to Brainerd Superfund site but MNDOT felt they were staying out of that.

ANY QUESTIONS PLEASE CONTACT THE MINNESOTA DUTY OFFICER AT 651-649-5451 OR 800-422-0798

MPCA Project Manager:

3m

Leak Number:

14878

71-85
96-Present Grassford.

Brainerd.

STATE OF MINNESOTA

Department of Public Safety - Division of Emergency Management
444 Cedar St. Suite 223 St. Paul, MN 55101

MINNESOTA DUTY OFFICER

Report #: 38741

Report Date: 6/20/2002

Report Time: 15:38

DO#: 22

CALLER INFORMATION

Contact: Nancy Radle

Company: MnDOT - St. Paul, John Ireland

Address: 395 John Ireland Blvd

City: St. Paul

State: MN Zip: 55155-

Phone: (651) 284-3781 Ext:

Alt phone:

Ext:

Have local police and/or fire been notified?

NARRATIVE

Ground water Analysis for a boring. This is next door the Brainerd Tie plant (Superfund)

MNDOT looked at it
but they were
staying out of
it

INCIDENT REPORT: TANK

RESPONSIBLE PARTY/PROPERTY OWNER

Name: unk

Company:

Address:

City:

State

Zip

Phone:

Ext

Alt. phone:

Ext

SITE LOCATION

Name: former Ready MIX property

Address: 1181 W Trunk HWY 210

City: BAXTER

County CROW WING

Zip: 56401

SITE INFORMATION

Discovery date 6/20/200

Discovery time: 14:00

Previously reported site? UNKNO

Leak #: 0

TANK INFORMATION

Number/Size of Tank(s)

Tank Contents

Age of Tank(s)

Type of Tank

Native soil type: sand

Surface water nearby? No

Monitoring wells on site? No

Site water source: Municipal

Contaminated soil excavated?

Quantity:

Able to dig out contamination?

Ground water encountered? Yes

Depth to ground water: 20 ft

Free product found? No

Stained soils? No

Petroleum odors? Yes

Highest vapor reading: none

Analytical results:

If this incident involves an A.S.T. Is there secondary containment around the tank?

If a Phase I or Phase II site assessment is being done, is it tank related Unknown

MPCA Project Manager: _____

Leak Number: _____

ANY QUESTIONS - PLEASE CONTACT THE MN DUTY OFFICER AT 651-649-5451 OR 800-422-0798

Lakeland Ready Mix is closed but

Very close to Active Phillips 66 also - 1181 W Trunk Hwy 210.

No VOC's in soil

990 ppb DRO
Geo - ND.

PH 12234 Soft touch concrete
center
MNDOT

UN03 MNDOT
doing there road
work 1/2 mile
trial.

Notifications**Report #:**
38741**ReportDate:**
6/20/2002**ReportTime:**
15:38**DO:**
22

In:	Out:	Link:	Date:	Time:	Agency:	County:	Method of Contact:
☐	☒	☐	6/20/2002	15:42	MPCA Metro		Fax
Narrative:							

In:	Out:	Link:	Date:	Time:	Agency:	County:	Method of Contact:
☐	☒	☐	6/20/2002	15:43	MPCA Region 2		Fax
Narrative:							