

**HYDROLOGIST REVIEW SUBMITTAL**

PRIORITY: III

UNIT No.: I

SITE NAME: SINCLAIR STATION

CITY: Richfield

LEAK No. : 2572

NAME OF REPORT : RI REPORT

PROJECT MANAGER: MEK

DATE MPCA RECEIVED : 04/12/91

HYDROLOGIST : LRQ

DATE HYDRO RECEIVED: 5/10/91

DATE HYDRO REVIEWED: \_\_\_\_\_

**PRIORITY SYSTEM (CHECK ONE)**

I IMMEDIATE PRIORITY	II MEDIUM PRIORITY	III GENERAL PRIORITY
<input type="checkbox"/> ACTUAL/POTENTIAL DRINKING WATER IMPACT EMERGENCY, Vapor impact(s) <input type="checkbox"/> FREE PRODUCT Recovery not begun Pre 5/19/90 PTR <input type="checkbox"/> DUE DATE LETTER <input type="checkbox"/> RI complete, establish clean up goal. <input type="checkbox"/> LEGISLATIVE INQUIRY <input type="checkbox"/> OTHER, explain	<input type="checkbox"/> RI IN HYDRO SENSITIVE AREA. <input type="checkbox"/> STATE CONTRACTORS <input type="checkbox"/> CAD during field season <input type="checkbox"/> RI/CAD FREE PRODUCT Recovery begun Post 5/19/90 PTR <input type="checkbox"/> OTHER, explain	<input type="checkbox"/> PROGRESS/MONITORING REPORT <input checked="" type="checkbox"/> RI REPORT <input type="checkbox"/> CAD PROPOSAL <input checked="" type="checkbox"/> CLOSURE REPORT ? <input type="checkbox"/> OTHER, explain

COMMENTS:

4 MONITORING WELLS  
6W SAMPLES IN ALL WELLS ND (6W at 35')  
300 yds Soil Removed  
EMECOTECH RECOMMENDS NO ADDITIONAL WORK!