

FACILITY INFORMATION

MPCA ID: TNK3176 Exempt: N
 SIC: 5541
 Facility Type:
 SERVICE STATION
 Date Form Received: 05/05/86

Name of Tank Site: ELSENS SERVICE GARAGE INC		Name of Owner: UNOCAL.	
Tank Site Address: 7730 PORTLAND AVE S		Mailing Address: 1650 E GOLF RD	
City: RICHFIELD		City: SCHAUMBURG	State: IL
Zip: 55423	Phone: 6128698048	County:27 Hennepin	Zip: 60196
		Phone: 3128857676	
Twp: 28 Rng: 24W Section: 34			

FACILITY REMARKS

The following comment was entered on: 05/05/86
 *SECTION C LEGAL DESC - S 1/2
 TANKS REMOVED AND PROPERLY DISPOSED PER FORM 12/14/87

TANK INFORMATION

TANK STATUS: REMOVED

MPCA Storage Tank Database System —Underground Tank Information					
Tank Number	Install Date	Capacity (Gallons)	Material Of Construction	Corrosion Protection	
001	07/01/78	1,500	ASPHALT COATED STEEL	Tank N	Pipe N
Piping Material	Piping Protect	Dispenser Type	Substance Stored	Secondary Containment	
STEEL/IRON		SUBMERSIBLE	Waste Oil	Tank N	Pipe N
RELEASE DETECTION (Choose all that apply by putting a Y in box)					
Y	Tank Tightness Testing & Inventory Control	N	Vapor Monitoring		
N	Interstitial Monitoring (Double Wall Tank)	N	Automatic Line Leak Detection		
N	Interstitial Monitoring (Secondary Containment)	N	Automatic Tank Gauging		
N	Manual Tank Gauging (Less than 1001 gallons)	N	Ground Water Monitoring		
N	Manual Tank Gauging & Tank Tightness Test (1001 to 2000 gallons)	N	Line Tightness Test		
		N	Other Methods (see Comments)		
Installer Number:			Signature:		
Remover Number:			Signature:		
Assurance Method: UNKNOWN			Insurer Name:		

INFORMATION ON MPCA ID: 3176

Facility Name ELSENS SERVICE GARAGE INC

TANK INFORMATION

TANK STATUS: REMOVED

MPCA Storage Tank Database System —Underground Tank Information					
Tank Number	Install Date	Capacity (Gallons)	Material Of Construction	Corrosion Protection	
				Tank	Pipe
002	04/01/60	4,000	BARE/PAINT/ASPH COAT STEEL	N	N
Piping Material	Piping Protect	Dispenser Type	Substance Stored	Secondary Containment	
				Tank	Pipe
STEEL/IRON		SUCTION	Gasoline	N	
RELEASE DETECTION (Choose all that apply by putting a Y in box)					
Y	Tank Tightness Testing & Inventory Control		N	Vapor Monitoring	
N	Interstitial Monitoring (Double Wall Tank)		N	Automatic Line Leak Detection	
N	Interstitial Monitoring (Secondary Containment)		N	Automatic Tank Gauging	
N	Manual Tank Gauging (Less than 1001 gallons)		N	Ground Water Monitoring	
N	Manual Tank Gauging & Tank Tightness Test (1001 to 2000 gallons)		N	Line Tightness Test	
			N	Other Methods (see Comments)	
Installer Number:			Signature:		
Remover Number:			Signature:		
Assurance Method: UNKNOWN			Insurer Name:		

TANK INFORMATION

TANK STATUS: REMOVED

MPCA Storage Tank Database System —Underground Tank Information					
Tank Number	Install Date	Capacity (Gallons)	Material Of Construction	Corrosion Protection	
				Tank	Pipe
003	04/01/60	4,000	BARE/PAINT/ASPH COAT STEEL	N	N
Piping Material	Piping Protect	Dispenser Type	Substance Stored	Secondary Containment	
				Tank	Pipe
STEEL/IRON		SUCTION	Unleaded Gasoline	N	
RELEASE DETECTION (Choose all that apply by putting a Y in box)					
Y	Tank Tightness Testing & Inventory Control		N	Vapor Monitoring	
N	Interstitial Monitoring (Double Wall Tank)		N	Automatic Line Leak Detection	
N	Interstitial Monitoring (Secondary Containment)		N	Automatic Tank Gauging	
N	Manual Tank Gauging (Less than 1001 gallons)		N	Ground Water Monitoring	
N	Manual Tank Gauging & Tank Tightness Test (1001 to 2000 gallons)		N	Line Tightness Test	
			N	Other Methods (see Comments)	
Installer Number:			Signature:		
Remover Number:			Signature:		
Assurance Method: UNKNOWN			Insurer Name:		

INFORMATION ON MPCA ID: 3176

Facility Name ELSENS SERVICE GARAGE INC

TANK INFORMATION

TANK STATUS: REMOVED

MPCA Storage Tank Database System —Underground Tank Information					
Tank Number	Install Date	Capacity (Gallons)	Material Of Construction	Corrosion Protection	
				Tank	Pipe
004	04/01/60	4,000	BARE/PAINT/ASPH COAT STEEL	N	N
Piping Material	Piping Protect	Dispenser Type	Substance Stored	Secondary Containment	
				Tank	Pipe
STEEL/IRON		SUCTION	Unleaded Gasoline	N	
RELEASE DETECTION (Choose all that apply by putting a Y in box)					
Y	Tank Tightness Testing & Inventory Control		N	Vapor Monitoring	
N	Interstitial Monitoring (Double Wall Tank)		N	Automatic Line Leak Detection	
N	Interstitial Monitoring (Secondary Containment)		N	Automatic Tank Gauging	
N	Manual Tank Gauging (Less than 1001 gallons)		N	Ground Water Monitoring	
N	Manual Tank Gauging & Tank Tightness Test (1001 to 2000 gallons)		N	Line Tightness Test	
			N	Other Methods (see Comments)	
Installer Number:			Signature:		
Remover Number:			Signature:		
Assurance Method: UNKNOWN			Insurer Name:		

TANK INFORMATION

TANK STATUS: REMOVED

MPCA Storage Tank Database System —Underground Tank Information					
Tank Number	Install Date	Capacity (Gallons)	Material Of Construction	Corrosion Protection	
				Tank	Pipe
005	04/01/60	4,000	BARE/PAINT/ASPH COAT STEEL	N	N
Piping Material	Piping Protect	Dispenser Type	Substance Stored	Secondary Containment	
				Tank	Pipe
STEEL/IRON		SUCTION	Fuel Oil (N	
RELEASE DETECTION (Choose all that apply by putting a Y in box)					
Y	Tank Tightness Testing & Inventory Control		N	Vapor Monitoring	
N	Interstitial Monitoring (Double Wall Tank)		N	Automatic Line Leak Detection	
N	Interstitial Monitoring (Secondary Containment)		N	Automatic Tank Gauging	
N	Manual Tank Gauging (Less than 1001 gallons)		N	Ground Water Monitoring	
N	Manual Tank Gauging & Tank Tightness Test (1001 to 2000 gallons)		N	Line Tightness Test	
			N	Other Methods (see Comments)	
Installer Number:			Signature:		
Remover Number:			Signature:		
Assurance Method: UNKNOWN			Insurer Name:		

INFORMATION ON MPCA ID: 3176

Facility Name ELSENS SERVICE GARAGE INC

TANK INFORMATION

TANK STATUS: ACTIVE

MPCA Storage Tank Database System —Underground Tank Information					
Tank Number	Install Date	Capacity (Gallons)	Material Of Construction	Corrosion Protection	
Tank	Pipe			Tank	Pipe
006	04/01/60	40	BARE/PAINT/ASPH COAT STEEL	N	N
Piping Material	Piping Protect	Dispenser Type	Substance Stored	Secondary Containment	
Tank	Pipe			Tank	Pipe
STEEL/IRON		GRAVITY	Other(HYDRAULIC OIL	N	
RELEASE DETECTION (Choose all that apply by putting a Y in box)					
N	Tank Tightness Testing & Inventory Control	N	Vapor Monitoring		
N	Interstitial Monitoring (Double Wall Tank)	N	Automatic Line Leak Detection		
N	Interstitial Monitoring (Secondary Containment)	N	Automatic Tank Gauging		
N	Manual Tank Gauging (Less than 1001 gallons)	N	Ground Water Monitoring		
N	Manual Tank Gauging & Tank Tightness Test (1001 to 2000 gallons)	N	Line Tightness Test		
		N	Other Methods (see Comments)		
Installer Number:			Signature:		
Remover Number:			Signature:		
Assurance Method: UNKNOWN			Insurer Name:		

TANK INFORMATION

TANK STATUS: REMOVED

MPCA Storage Tank Database System —Underground Tank Information					
Tank Number	Install Date	Capacity (Gallons)	Material Of Construction	Corrosion Protection	
Tank	Pipe			Tank	Pipe
007	01/01/80	9,000	FIBERGLASS	N	N
Piping Material	Piping Protect	Dispenser Type	Substance Stored	Secondary Containment	
Tank	Pipe			Tank	Pipe
OTHER		SUCTION	Diesel (N	
RELEASE DETECTION (Choose all that apply by putting a Y in box)					
Y	Tank Tightness Testing & Inventory Control	N	Vapor Monitoring		
N	Interstitial Monitoring (Double Wall Tank)	N	Automatic Line Leak Detection		
N	Interstitial Monitoring (Secondary Containment)	N	Automatic Tank Gauging		
N	Manual Tank Gauging (Less than 1001 gallons)	N	Ground Water Monitoring		
N	Manual Tank Gauging & Tank Tightness Test (1001 to 2000 gallons)	N	Line Tightness Test		
		N	Other Methods (see Comments)		
Installer Number:			Signature:		
Remover Number:			Signature:		
Assurance Method: UNKNOWN			Insurer Name:		

INFORMATION ON MPCA ID: 3176

Facility Name ELSENS SERVICE GARAGE INC

TANK INFORMATION

TANK STATUS: REMOVED

MPCA Storage Tank Database System —Underground Tank Information					
Tank Number	Install Date	Capacity (Gallons)	Material Of Construction	Corrosion Protection	
				Tank	Pipe
008	01/01/00	550	BARE/PAINT/ASPH COAT STEEL	N	N
Piping Material	Piping Protect	Dispenser Type	Substance Stored	Secondary Containment	
				Tank	Pipe
GALVANIZED STEEL		SUCTION	Waste Oil	N	
RELEASE DETECTION (Choose all that apply by putting a Y in box)					
N	Tank Tightness Testing & Inventory Control		N	Vapor Monitoring	
N	Interstitial Monitoring (Double Wall Tank)		N	Automatic Line Leak Detection	
N	Interstitial Monitoring (Secondary Containment)		N	Automatic Tank Gauging	
N	Manual Tank Gauging (Less than 1001 gallons)		N	Ground Water Monitoring	
N	Manual Tank Gauging & Tank Tightness Test (1001 to 2000 gallons)		N	Line Tightness Test	
			N	Other Methods (see Comments)	
Installer Number:			Signature:		
Remover Number:			Signature:		
Assurance Method: UNKNOWN			Insurer Name:		

TANK INFORMATION

TANK STATUS: REMOVED

MPCA Storage Tank Database System —Underground Tank Information					
Tank Number	Install Date	Capacity (Gallons)	Material Of Construction	Corrosion Protection	
				Tank	Pipe
009	01/01/00	550	BARE/PAINT/ASPH COAT STEEL	N	N
Piping Material	Piping Protect	Dispenser Type	Substance Stored	Secondary Containment	
				Tank	Pipe
GALVANIZED STEEL		SUCTION	Waste Oil	N	
RELEASE DETECTION (Choose all that apply by putting a Y in box)					
N	Tank Tightness Testing & Inventory Control		N	Vapor Monitoring	
N	Interstitial Monitoring (Double Wall Tank)		N	Automatic Line Leak Detection	
N	Interstitial Monitoring (Secondary Containment)		N	Automatic Tank Gauging	
N	Manual Tank Gauging (Less than 1001 gallons)		N	Ground Water Monitoring	
N	Manual Tank Gauging & Tank Tightness Test (1001 to 2000 gallons)		N	Line Tightness Test	
			N	Other Methods (see Comments)	
Installer Number:			Signature:		
Remover Number:			Signature:		
Assurance Method: UNKNOWN			Insurer Name:		

INFORMATION ON MPCA ID: 3176

Facility Name ELSENS SERVICE GARAGE INC

