

HYDROLOGIST REVIEW SUBMITTAL

PRIORITY: 1

UNIT No.: 1

SITE NAME: International Plaza

CITY: Bloomington

LEAK No.: 4981

NAME OF REPORT: Project Status Report

PROJECT MANAGER: DKM

DATE MPCA RECEIVED: 2/26/92

HYDROLOGIST: SCT

DATE HYDRO RECEIVED: 2/28/92

PRIORITY SYSTEM		
I: IMMEDIATE PRIORITY	II: MEDIUM PRIORITY	III: GENERAL
<input type="checkbox"/> EMERGENCY: drinking water impact <input type="checkbox"/> vapor impact <input type="checkbox"/> <input checked="" type="checkbox"/> FREE PRODUCT <input checked="" type="checkbox"/> OTHER, explain Close Request	<input type="checkbox"/> RI/CAD free product recovery begun <input type="checkbox"/> RI/CAD - CA required <input type="checkbox"/> RI/CAD - monitoring/ no action <input type="checkbox"/> OTHER, explain	<input type="checkbox"/> PROGRESS/MONITORING REPORT <input type="checkbox"/> CLOSURE REPORT <input type="checkbox"/> OTHER, explain

COMMENTS:

3/2/92: Call Kevin Pierson (TCT), requested water analysis following final pumping of water to sanitary sewer. Already done, will send in results.
(No written response necessary) DKM