

Preferred id: 51895

Interest Name: Bloomington Acura Subaru

Address: 7801 LYNDAL AVE S

City: BLOOMINGTON

State: MN

Zip: 55431

Phone: 6128816200

Interest Remarks

RP to call city re: sewer. Most oil is in oil trap. Some may have drained to sewer. RP to call contractor with Vac truck and Safety Kleen for clean up.

Poor Image

TALES (Tanks, Leaks, Spills, Soil Treatments) (2.17) - PRODUCTION

File Edit Rows Reports Maintenance Tools Window Help

Spill Tracking

Preferred Id: 51895 Interest Name: Bloomington Acura Subaru

Spill Track | Spill Prevention | Spill Actions | Work Orders | Land Treatments | Thermal Treatments

Spill Initial Information

Spill Reported By: Company-RP Project Manager: Faus, Kevin B
Report By Override Desc: Company-RP Phone: () -
Report Taken By: Faus, Kevin B Spill Date: 04/26/2000
Reported Date: 04/26/2000 Spill Closure: Response Completed
Initial Cause: Equipment Failure Site Closure Date: 04/26/2000
Init. Cause Override Desc: Equipment Failure Archive Lot:
Initial Source: UST Archive Box:

Incident Affected

Spill Incident Affected	Last Update
Street, Parking Lot	05/04/2000

Product Released

Spill Product	Quantity	Units	Accuracy
Motor/Lube Oil, Tra	200	Gallons	Estimated

Ready

Interest Type: Spill Site

Preferred Id: 51895

Name: Bloomington Acura Subaru

Interest End Date: 00/00/0000

Address: 7801 LYNDAL AVE S

Active Flag:

Phone: (612) 881-6200 x

City Name: BLOOMINGTON MN

Zip Code: 55431-

Comments: Pump from 1000 ga UST malfunctioned, spraying product inside shop. Floor drain impacted. Now diked, but is full, so sewer was impacted: will call city of Bloomington.

Township:

County: Hennepin

MPCA Region: M EPA Region: 5

