

Re-open
Katriina - send
SL w/ #
8345
Thanks

SV

STATE OF MINNESOTA
DEPARTMENT OF PUBLIC SAFETY - DIVISION OF EMERGENCY MANAGEMENT
8-5 STATE CAPITOL, SAINT PAUL, MN 55155-1049

**MINNESOTA DUTY OFFICER
HAZARDOUS MATERIALS INCIDENT REPORT: TANKS**

REPORT DATE: 9/3 TIME: 948 DUTY OFFICER:

| | | | |
|---|-------------------|--|-------------------|
| REPORTED BY: | | RESPONSIBLE PARTY/PROPERTY OWNER: | |
| NAME: <u>Scott Lapham</u> | | CONTACT: <u>Robert Fisher</u> | |
| CO: <u>Arcadis, Gerharty & Miller</u> | | CO: <u>Boker's Inc.</u> | |
| ADDRESS: <u>105 5th Ave S.</u> | | ADDRESS: <u>310A Snelling Ave</u> | |
| CITY: <u>Mpls.</u> | STATE: | CITY: <u>Mpls</u> | STATE: |
| PHONE: <u>339-9434</u> | ZIP: <u>55401</u> | PHONE: <u>729-9365</u> | ZIP: <u>55406</u> |
| ALT. PHONE: | | ALT. PHONE: <u>unknown</u> | <u>unknown</u> |

DISCOVERY DATE: 9-2-98 TIME: 1100 PREVIOUSLY REPORTED SITE? Y / N / UNK -LEAK# unk. 8345

SITE NAME & ADDRESS: Same at 310A Snelling 729-9365

CITY: Mpls ZIP: 55406 COUNTY: Hennepin

| NUMBER/SIZE OF TANK'S: | TANK CONTENTS: | AGE OF TANK'S: | TYPE: |
|------------------------|----------------|----------------|-----------------------------------|
| @ | | | U.S.T / A.S.T.- STEEL/FIBRE GLASS |
| @ | | | U.S.T / A.S.T.- STEEL/FIBRE GLASS |
| @ | | | U.S.T / A.S.T.- STEEL/FIBRE GLASS |
| @ | | | U.S.T / A.S.T.- STEEL/FIBRE GLASS |

NATIVE SOIL TYPE: Silty Sand SURFACE WATER NEARBY? Y / N / UNK

ARE THERE ANY MONITORING WELLS ON SITE? Y / N / UNK

WHAT IS THE SITE WATER SOURCE: MUNICIPAL / PRIVATE WELL / UNK

CONTAMINATED SOIL EXCAVATED? Y / N / UNK QUANTITY: Stack piled 250 cu. yds.

ABLE TO DIG OUT OF CONTAMINATION?: Y / N / UNK

GROUND WATER ENCOUNTERED? Y / N / UNK DEPTH TO GROUND WATER?: Perched at 14 feet

FREE PRODUCT FOUND? Y / N STAINED SOILS? Y / N PETROLEUM ODORS? Y / N

HIGHEST VAPOR READING: Sheen 300-400 ppm ANALYTICAL RESULTS: to be submitted

NARRATIVE: tank (20,000 Fuel oil) removed 2 years ago. Site under construction now and contamination found during excavation. A sheen was seen on surface of groundwater. Soil excavated and stack piled.

DUTY OFFICER NOTIFICATIONS MADE: (AGENCY, NAME, TIME)

MPCA TANKS, ATTN: STACEY VAN PATTON - FAX

ANY QUESTIONS? CONTACT THE MINNESOTA DUTY OFFICER AT 649-5451 OR 1-800-422-0798

This Space For MPCA Use Only:
MPCA PROJECT MANAGER: SHV LEAK NUMBER: 8345

Who Took: _____

PM: _____

Priority: _____ High
_____ Action
_____ No action

Action: _____ Advise
_____ Visit by _____
_____ State money spent
_____ File
_____ No File

REMARKS: *Trailsprer also found on property and contamination found with that but also found contamination w/ tank.
Railway on West end.
Ground H₂O may be flowing NNW, local flow pattern.*

Copy To? _____

Send Packet?

- _____ Disposal Packet
- _____ Reporting Packet
- _____ Spill Bill Packet
- _____ VIC Packet
- _____ VPIC Packet
- _____ Other _____

Quickie Closure:(circle one)

Why Closed:

- 1--Referred to LEAKS
- 2--Referred to RCRA
- 3--Referred to AQ
- 4--Referred to WQ
- 5--Referred to VIC

- 6--Referred to local/county
- 7--Referred to Region
- 8--Referred to GWSW
- 9--Response Completed

- 10--No Response Necessary
- 11--Closed for other reasons (see remarks)
- 12--AG Lead

SPILL # _____

To: MPCA (MET) OFFICE

STATE OF MINNESOTA

DEPARTMENT OF PUBLIC SAFETY - DIVISION OF EMERGENCY MANAGEMENT
8-5 STATE CAPITOL, SAINT PAUL, MN 55155-1049

makecopy - Kelly

Laurie -
Review & see if
same contamination
as 8345. Thanks.

MINNESOTA DUTY OFFICER HAZARDOUS MATERIALS INCIDENT REPORT

REPORT DATE: 9/3 TIME: 948 DUTY OFFICER: _____

| | | | |
|--------------------------------|-------------------------------|--|-----------------------------------|
| REPORTED BY: | | RESPONSIBLE PARTY/PROPERTY OWNER: | |
| NAME: <u>Scott Lapham</u> | CONTACT: <u>Robert Fisher</u> | CO: <u>Boker's Inc.</u> | ADDRESS: <u>3104 Snelling Ave</u> |
| ADDRESS: <u>105 5th Ave S.</u> | CITY: <u>Mpls</u> | STATE: _____ | PHONE: <u>729-?</u> |
| CITY: <u>Mpls</u> | STATE: _____ | ZIP: <u>55401</u> | ALT. PHONE: <u>unknown</u> |
| PHONE: <u>339-9434</u> | ZIP: <u>55401</u> | PHONE: <u>729-?</u> | ALT. PHONE: <u>unknown</u> |
| ALT. PHONE: _____ | | | |

DISCOVERY DATE: 9-2-98 TIME: 1100 PREVIOUSLY REPORTED SITE? N / UNK -LEAK# unk. 8345

SITE NAME & ADDRESS: Same at 3104 Snelling

CITY: Mpls ZIP: _____ COUNTY: Hennepin

| NUMBER/SIZE OF TANK'S: | TANK CONTENTS: | AGE OF TANK'S: | TYPE: |
|------------------------|----------------|----------------|------------------------------------|
| @ | | | U.S.T / A.S.T. - STEEL/FIBRE GLASS |
| @ | | | U.S.T / A.S.T. - STEEL/FIBRE GLASS |
| @ | | | U.S.T / A.S.T. - STEEL/FIBRE GLASS |
| @ | | | U.S.T / A.S.T. - STEEL/FIBRE GLASS |

NATIVE SOIL TYPE: Silty Sand SURFACE WATER NEARBY? Y / UNK

ARE THERE ANY MONITORING WELLS ON SITE? Y / UNK

WHAT IS THE SITE WATER SOURCE: MUNICIPAL / PRIVATE WELL / UNK

CONTAMINATED SOIL EXCAVATED? Y / UNK QUANTITY: Stack piled 250 cu. yds.

ABLE TO DIG OUT OF CONTAMINATION?: Y / UNK

GROUND WATER ENCOUNTERED? Y / UNK DEPTH TO GROUND WATER?: Perched at 14 feet

FREE PRODUCT FOUND? Y / UNK STAINED SOILS?: Y / UNK PETROLEUM ODORS?: Y / UNK

HIGHEST VAPOR READING: 300-400 ppm ANALYTICAL RESULTS: to be submitted

NARRATIVE: tank (20,000 Fuel oil) removed 2 years ago. Site under construction now and contamination found during excavation. A sheen was seen on surface of groundwater. Soil excavated and stack piled.

DUTY OFFICER NOTIFICATIONS MADE: (AGENCY, NAME, TIME)

| | |
|--|--|
| MPCA TANKS, ATTN.: STACEY VAN PATTON - FAX | |
|--|--|

ANY QUESTIONS? CONTACT THE MINNESOTA DUTY OFFICER AT 649-5451 OR 1-800-422-0798

This Space For MPCA Use Only:
MPCA PROJECT MANAGER: _____ LEAK NUMBER: _____

WATER

Groundwater in excavation:

Gas? at 20', 5 ppm.

Free product present:

Depth to groundwater:

City water/wells private/municipal:

Surface water:

VAPORS

Sewers/buildings:

SITE INFORMATION

Description of area:

Previous release(s):

INSTRUCTION GIVEN

- Hire consultant
- Submit report
- Staff will call
- Contact staff

CONTACTS

- Local Fire/Police
- Local Officials
- Regional Staff
- Other

CONCLUSIONS AND OTHER RELATED INFORMATION

STATE OF MINNESOTA

DEPARTMENT OF PUBLIC SAFETY - DIVISION OF EMERGENCY MANAGEMENT
85 STATE CAPITOL SAINT PAUL 55155-1049

JMH
8345
Jean Hanson
Project Mgr

MINNESOTA DUTY OFFICER HAZARDOUS MATERIAL INCIDENT REPORT: TANKS

REPORT DATE: 5-5-95 TIME: 1504 DUTY OFFICER: Larry RECORD#:

REPORTED BY:

NAME: John Carlson
C/O: Braun Intertech
ADDRESS:
CITY: STATE:
PHONE: 683-8760 ZIP:
ALT. PHONE:

SUSPECTED SOURCE/RESPONSIBLE PARTY:

CONTACT: William Tedlund
C/O: Baker's INC
ADDRESS: 3104 Snelling Ave
CITY: Mpls STATE: MN
PHONE: 729-9365 ZIP: 55406
ALT. PHONE:

DISCOVERY DATE: 5-4-95 7:55-95 TIME: _____
 SITE NAME & LOCATION: Same as Source

LEGAL: _____ SECTION: _____ TOWNSHIP: _____ RANGE: _____
 NUMBER/SIZE OF TANK(S): 2,000 -- Taken out in 1986
 TANK CONTENTS: Fuel oil
 NATIVE SOIL TYPE: Sandy Soil

PREVIOUSLY REPORTED SITE?: YES / NO / UNKNOWN LEAK #: 8345
 CONTAMINATED SOIL EXCAVATED?: YES / NO / UNKNOWN QUANTITY: _____
 GROUND WATER ENCOUNTERED?: YES / NO / UNKNOWN DEPTH TO GW: 20'
 FREE PRODUCT FOUND?: YES / NO
 STAINED SOIL?: YES / NO -- PETROLEUM ODORS: YES / NO
 HIGH VAPOR READINGS: _____ ANALYTICAL RESULTS: _____

NARRATIVE: doing a Geotech Evaluation. Did 9 Borings. 4 of which were screened by an Environmental Technician found a High Reading of 172 ppm found Spm at 20' Soil was wet But unsure.

HAS MATERIAL ESCAPED FACILITY PROPERTY?: YES / NO / UNKNOWN *If they were at ground water interface*
 **IS THIS A BUSINESS OR GOVERNMENT FACILITY REPORTING IN COMPLIANCE WITH SARA TITLE III, SECTION 304?: YES / NO / UNKNOWN
 (IF YES, COMPLETE PAGE TWO: SARA SUPPLEMENT)

DUTY OFFICER NOTIFICATIONS MADE (AGENCY, NAME, TIME)

| | |
|--------------------------|--|
| MPCA TANKS - Jeli - 1509 | |
| MPCA TANKS - FAX | |
| EM-1/6 Mail | |
| | |