



Minnesota Pollution Control Agency

520 Lafayette Road North | St. Paul, Minnesota 55155-4194 | 651-296-6300
800-657-3864 | 651-282-5332 TTY | www.pca.state.mn.us | Equal Opportunity Employer

December 11, 2013

Ms. Maria Olson
Mille Lacs Oil Company
102 Main Street
Cambridge, MN 55088

RE: Request For Additional Work
Site: Former Union 76, 329 East First Avenue South, Cambridge, Isanti County
Site ID#: LEAK0008001

Dear Ms. Olson:

The Minnesota Pollution Control Agency (MPCA) has reviewed the report titled, Focused Investigation Report, dated August 31, 2013, prepared by Liesch, your environmental consultant. Based upon information provided in the report, it has been determined that additional work is required at the above-referenced site. Specifically, the following activities should be conducted:

Groundwater Monitoring

Sample monitoring wells according to the following schedule:

Quarterly: MWs 1, 3, 6, 7, 8, 9, and 10

Semi-annually: MW-11

Annually: MW-6A

Measure groundwater elevations in all wells, quarterly.

Conduct monthly LNAPL checks.

Corrective Action/Reporting


Prepare MPCA Guidance Document 7-02 Conceptual Corrective Action Design Report (CCAD) with your recommendations for corrective action and updated monitoring results.


Submit the CCAD within three months receipt of this letter.

Failure to meet this deadline in a timely manner may result in reductions in Petrofund reimbursement or lead to MPCA enforcement actions.

If you have any questions regarding this letter, please contact Andy Eddy, Project Manager, at 651-757-2331 or andrew.eddy@state.mn.us, or Audrey Van Cleve, Hydrogeologist, at 651-757-2792 or audrey.van.cleve@state.mn.us.

Sincerely,


Andy Eddy
Project Manager
Petroleum Remediation Section
Remediation Division


Audrey Van Cleve
Hydrogeologist
Petroleum Remediation Section
Remediation Division

AJE:ls

cc: Aaron Benker, Wenck