

1.0 Report Purpose, Process, and Watershed Overview	3
St. Louis River Watershed Zones.....	4
St. Louis Watershed Characterization.....	6
Bedrock and Glacial geologic history of the St. Louis River Basin.....	6
Geomorphology Overview.....	8
Water Quality and Establishment of Reference Conditions.....	11
Overview of Biological Conditions.....	15
2.0 Biological Impairments in the St. Louis River 8HUC Watershed	18
3.0 Background on Stressors and Applicable Standards	21
Water Quality Stressors	
Water Temperature.....	21
Dissolved Oxygen.....	22
Nutrients and River Eutrophication.....	23
Altered pH.....	25
Specific conductivity	26
Sulfate	29
Chloride.....	33
Suspended Sediment and Turbidity.....	35
Nitrogen (Nitrate Toxicity)	38
Ammonia-N Toxicity.....	39
Metals Toxicity.....	40
Aluminum	41
Iron.....	42
Cadmium.....	44
Arsenic.....	44
Copper.....	45
Lead.....	46
Zinc.....	48
Nickel, Chromium, and Selenium.....	
Physical Stressors	
Hydrology.....	49
Stream Road Crossing Density.....	51
Stream Channelization.....	53
Impoundments.....	56
Impervious Surfaces.....	60
Percent Agricultural Land.....	62
Discharges and Withdrawals.....	63
Percent Mine Features.....	64
Poor Physical Habitat Conditions.....	66
4.0 Overview of Analysis Tools Used to Evaluate Stressors	68
5.0 Evaluation of Candidate Causes for Impairment	70
<i>Duluth Urban Trout Streams</i>	70
Kingsbury Creek	72
Elevated Water Temperatures.....	74
Dissolved Oxygen.....	78
Total Suspended Solids & Turbidity.....	83
Chloride and Specific Conductivity.....	97
Poor Physical Habitat Conditions.....	108
Metals (Lead and Copper)	112

Summary of Kingsbury Creek Stressor ID Results.....	117
Miller Creek	118
Total Suspended Solids & Turbidity.....	120
Chloride and Specific Conductivity.....	126
Summary of Miller Creek Stressor ID Results.....	137
<i>Mille Lacs North Shore Highlands</i>	138
Otter Creek	138
Elevated Water Temperatures.....	141
Poor Physical Habitat Conditions.....	144
Summary of Otter Creek Stressor ID Results.....	148
<i>Meadowlands Floodwood Peat Bog</i>	149
St. Louis River	150
Poor Physical Habitat Conditions.....	152
Summary of St. Louis River Stressor ID Results.....	156
Skunk Creek	157
Dissolved Oxygen.....	159
Poor Physical Habitat Conditions.....	163
Summary of Skunk Creek Stressor ID Results.....	168
Vaara Creek	
Dissolved Oxygen.....	169
Poor Physical Habitat Conditions.....	174
Summary of Vaara Creek Stressor ID Results.....	178
Sand Creek	179
Total Suspended Solids & Turbidity.....	182
Poor Physical Habitat Conditions.....	188
Summary of Sand Creek Stressor ID Results.....	191
Stony Creek	192
Dissolved Oxygen.....	194
Total Suspended Solids & Turbidity.....	200
Poor Physical Habitat Conditions.....	208
Unnamed Tributary to St. Louis River	216
Low Streamflow.....	218
Poor Physical Habitat Conditions.....	219
Summary of Unnamed Trib to St. Louis River Stressor ID Results.....	223
Little Swan Creek	224
Elevated Water Temperatures.....	225
Low Dissolved Oxygen.....	229
Total Suspended Solids & Turbidity.....	232
Poor Physical Habitat Conditions.....	236
Summary of Little Swan Creek Stressor ID Results.....	240
<i>Makinen Lakes</i>	241
Water Hen Creek / Water Hen River	242
Low Dissolved Oxygen.....	244
Summary of Water Hen Creek Stressor ID Results.....	250
Paleface Creek	251
Low Dissolved Oxygen.....	253
Summary of Paleface Creek Stressor ID Results.....	256

<i>Laurentian Uplands – Partridge River Watershed Zone</i>	257
Wyman Creek	257
Iron Toxicity / Iron Precipitate.....	259
Elevated Water Temperatures.....	262
Low Dissolved Oxygen.....	269
Total Suspended Solids & Turbidity.....	275
Sulfate Toxicity.....	280
Summary of Wyman Creek Stressor ID Results.....	284
<i>Nashwauk Uplands – Embarrass River Watershed Zone</i>	285
Spring Mine Creek	286
Dissolved Oxygen.....	289
Specific Conductance / Sulfate Toxicity.....	296
Summary of Spring Mine Creek Stressor ID Results.....	308
Ely Creek	309
Poor Physical Habitat Conditions.....	311
Low Dissolved Oxygen.....	316
Summary of Wyman Creek Stressor ID Results.....	320
Embarrass River	321
Dissolved Oxygen.....	323
Sulfate Toxicity.....	330
Summary of Embarrass River Stressor ID Results.....	330
<i>Virginia Mesabi Range Watershed Zone</i>	331
Unnamed Tributary to East Two River (Manganika Creek)	331
Dissolved Oxygen.....	334
Specific conductivity.....	339
Sulfate Toxicity.....	343
Total Suspended Solids & Turbidity.....	348
Elevated pH.....	353
Ammonia Toxicity.....	355
Summary of Manganika Creek Stressor ID Results.....	359
Elbow Creek	360
Dissolved Oxygen.....	363
Sulfate Toxicity.....	372
Specific conductivity.....	376
Nitrate Toxicity.....	385
Ammonia Toxicity.....	390
Poor Physical Habitat Conditions.....	392
Summary of Elbow Creek Stressor ID Results.....	396
<i>West Two McQuade Moraines Watershed Zone</i>	397
West Two River	397
Dissolved Oxygen.....	400
Specific Conductance / Sulfate Toxicity.....	407
Summary of West Two River Stressor ID Results.....	419
Unnamed Tributary to McQuade Lake (Kinney Creek)	420
Dissolved Oxygen.....	422
Specific Conductance.....	428
Sulfate Toxicity.....	372
Summary of Kinney Creek Stressor ID Results.....	419

<i>Swan River – Hibbing Watershed Zone</i>	438
East Swan Creek	438
Elevated Water Temperatures.....	441
Specific Conductance.....	444
Nitrate and Ammonia Toxicity.....	450
Summary of East Swan Creek Stressor ID Results.....	455
Swan River	455
Total Suspended Solids & Turbidity.....	458
Poor Physical Habitat Conditions.....	465
6.0 Stressor ID Summary and Recommendations for Future Monitoring	472
Summary of Stressor ID Results for all biota-impaired streams of the SLRW.....	473

